

**P10**

INTERNATIONAL TRUCK AND ENGINE CORPORATION

G/P  
V/N 14968 KG  
W/B (33000 LB)

R/V

FRONT AXLE 2 3 4 5 6 7

G/P  
A/N 4535 KG 10432  
W/B (10000 LB) (23000  
R/E

KG  
LB)

VIN 1HTWCAAN87J470169

DATE 09-2006

2025/12/08  
10:22

PLATE MANFACTURES

**P11**

INTERNATIONAL TRUCK AND ENGINE CORPORATION  
WARRENVILLE, ILLINOIS **INTERNATIONAL®**

VIN

1HTWCAAN87J470169

MODEL

7400 SBA 4X2

W.B.

445

DATE MFG.

09-2006

PLATE MANUFACTURES

KG  
LB)



MADE IN THE UNITED STATES OF AMERICA

PLATE MANUFACTURES



NUMBER UNIT



ODOMETER



TRUCK FT



TRUCK LF



TRUCK RF



TRUCK LR



TRUCK RR



TRUCK RE



LOGO COMPANY



STICKER INSPECTION



INTERIOR



INTERIOR CONSOLE



INTERIOR STEERING WHEEL



INTERIOR HEADLINER




INTERIOR PANEL TRIM LS DOORS



DAMAGE BUMPER FT



DAMAGE BUMPER FT



DAMAGE BUMPER FT



DAMAGE BUMPER FT




DAMAGE BUMPER FT



DAMAGE HALF FENDER LS FENDERS



DAMAGE HALF FENDER LS FENDERS



DAMAGE HALF FENDER LS FENDERS



UNDERCARRIAGE FT



DAMAGE HALF FENDER LS FENDERS



DAMAGE AXLE FT




DAMAGE AXLE FT



DAMAGE WHEEL/TIRE RS FRONT WHEELS



DAMAGE AXLE FT




DAMAGE WHEEL/TIRE RS FRONT WHEELS



DAMAGE PANEL DOOR FRAME RS CAB



DAMAGE PANEL DOOR FRAME RS CAB



DAMAGE PANEL DOOR FRAME RS CAB




DAMAGE MIRROR RS DOORS




DAMAGE MIRROR RS DOORS



DAMAGE STEPS ATS ONE BOX



DAMAGE STEPS ATS ONE BOX



DAMAGE STEPS ATS ONE BOX




DAMAGE EXHAUST




DAMAGE EXHAUST



DAMAGE PANEL BACK/CORNER RS CAB




DAMAGE PANEL BACK/CORNER RS CAB



DAMAGE PANEL BACK/CORNER RS CAB



DAMAGE TANK FEED



DAMAGE TANK FEED



DAMAGE TANK FEED



DAMAGE TANK FEED



2025/12/08  
10:29

DAMAGE TANK FEED