

**Sedgwick**  
**131 Saundersville Road**  
**Hendersonville, TN 37075**

**Phone: (615) 590-1550 Phone: (615) 000-0000**

Address: Fesslers Lane  
City/State/Zip: Nashville, TN 37210615  
Phone: 615-764-9327  
Cell Phone: - -  
Purchase Order:  
Customer Number: 069710001315  
Claim Contact: Rick  
Contact Title: Insured  
Contact Phone: (312) 673-8330 x  
Contact Email: saftey@denalifreight.com

VIN: 5V8VC5321MT110015  
Style: Not Applicable  
Plate/State: 791466ST - IL  
WMI: FIN:  
Odometer:  
Color:  
Date Of Loss: 1/26/2026  
Authorized By:  
Claim Number: E2J53281  
RO:



Photo of Front




Photo of Left



Photo of Rear



Photo of Right



Trailer identification Plate.



Vanguard information labels

MFG: Vanguard  
 DOM: 11/2020  
 Vin: 5V8VC5321MT110015  
 Type: Trailer 53'



Unit# DF003



view down the bottom left rail to show the bow.



unrelated prior damage. Front left 3 panels.



place of impact, bottom left rail, panels, crossmembers, floor.



Left side view of impact area



View of damaged panels

upper rail is damaged. the roof is damaged as well.



view from the rear of the trailer looking towards the front to show the deformation of the trailer.



this is a view from the right side at the back looking down the lower right rail. No damage



Same location looking down the right side. The arrows indicate where the right side and upper rail have bowed out from the impact to the left side pushing the right side out.



Standing at the right front looking down the right side.




Upper right rail is bent



interior: looking at the left side impact damage.



Overall view of the interior



area of impact: floor, inner panels, inner post are damaged and separated.

over view of inside damage



roof, is damaged and has started to separate. Vanguard trailers have a one piece roof.

Roof damage



Standing at the front lookin out to the back.



Right side directly across from the impact, signs of bowing are starting at the floor moving up the wall



Right side shows signs it is starting to bow from the impact.



Overall view of the roof damage



view from the left side showing around 16 floor crossmembers are damaged, as well as the flooring, and left side trailer wiring.



View of the rear axle set. they appear strait and undamaged.



lower damages



LP: Illinois 791466 SP



Rear impact bar



rear view of the axle and tire sets





Right side tire set



Over all great condition. Around 8/32nds



Jack set. no damage



View from underneath.



Hitch plate