

MANUFACTURED BY:	DAIMLER VEH. COMERC. MEXICO	GAWR/PNBE	GAWR/PNBE	TIRES	RIMS	KPA COLD	PSI COLD	"S"
DATE OF MFR.	05/19	KGS	LBS			758	110	S
GVWR/PNBV-KG.	23,745	FRONT AXLE	5,601	12,350	295/75R22.5(G)	22.5X8.25	758	110
GVWR/PNBV-LBS.	52,350	1ST INT AXLE	9,072	20,000	295/75R22.5(G)	22.5X8.25		
THIS VEHICLE COMPLIES WITH ALL APPLICABLE FEDERAL MOTOR VEHICLE SAFETY STANDARDS IN EFFECT AT THE DATE OF MANUFACTURE SHOWN ABOVE.		2ND INT AXLE						
VEHICLE ID NO: 3AKJHHDRALSLP9072		3RD INT AXLE						
TYPE: TRUCK/TRACTOR TT/CT		4TH INT AXLE						
COUNTRY OF ORIGIN: MEXICO		5TH INT AXLE						
		6TH INT AXLE						
		REAR AXLE	9,072	20,000	295/75R22.5(G)	22.5X8.25	758	110

FREIGHTLINER


VIN PLATE OFF LF FRONT DOOR

VEHICLE EMISSION CONTROL INFORMATION
 Manufactured By: DAIMLER VEHICULOS COMERCIALES MEXICO Date of Manufacture: 05/19
 VIN/VN: 3AKJHHDRALSLP9072 REGULATORY CLASS: High-roof sleeper cab tractors above 26,000
 VEH FAMILY CO: LDTN2TRAC14C pounds GVWR
 GVWR/PNBV-KG: 23,745
 GVWR/PNBV-LBS: 52,350 EMISSION CONTROL IDENTIFIERS:

THIS VEHICLE COMPLIES WITH U.S. EPA AND CALIFORNIA REGULATIONS FOR 2020 HEAVY DUTY VEHICLES. See owner's manual for proper maintenance of this vehicle.

FREIGHTLINER

VIN PLATE OFF LF FRONT DOOR JAMB



ODOMETER OFF OIL CHANGE SERVICE



LF FRONT



RT FRONT



RT REAR



LF REAR



CENTER DASH



RT SIDE DASH



STEERING WHEEL CONTROLS



RT SIDE OVERHEAD CONSOLE



LF SIDE OVERHEAD CONSOLE



LF SIDE DASH



LF FRONT DOOR INNER PANEL



RT REAR OF SLEEPER



LF SIDE REAR OF SLEEPER




LF REAR DAMAGE



LF REAR CORNER DAMAGE



LF SIDE DAMAGE



LF FRONT CORNER DAMAGE



RT FRONT CORNER DAMAGE



FRONT DAMAGE



RT SIDE DAMAGE



REAR DAMAGE



REAR VIEW TO SHOW RT SIDE SWAY



LF REAR SWAY



LF REAR DUALS BOTH INNER & OUTER ALUMINUM WHEELS



LF REAR FRONT SIZE



RT REAR TIRE SIZE



LF FRONT TIRE SIZE