



Photo 001: Showing discoloration of boom and rear of excavator.



Photo 002: Showing Discoloration and oxidation of engine cover.



Photo 003: Showing oxidation on cab and mass loss of window glass.



Photo 004: Showing Discoloration and mass loss of cab glass.



Photo 005: Showing Discoloration and oxidation on hydraulic pump compartment door, area of origin.



Photo 006: Showing total mass loss of hydraulic hoses and oxidation and discoloration to inside compartment.



Photo 007: Showing radiator, batteries and air intake with no visible fire effects.



Photo 008: Showing severe oxidation around hydraulic pump compartment extending across the top of engine compartment.



Photo 009: Showing oxidation on cab with mass loss of cab glass.




Photo 010: Showing minor mass loss of components on top of engine, fire movement from left to right of photo.