



VIN of 2023 freightliner tractor VIN: 3AKJHHDR0PSUP4928.




VIN of 2023 freightliner tractor VIN: 3AKJHHDR0PSUP4928.



VIN of 2023 freightliner tractor VIN: 3AKJHHDR0PSUP4928.




VIN of 2023 freightliner tractor VIN: 3AKJHHDR0PSUP4928.





VIN of 2023 freightliner tractor VIN: 3AKJHHDR0PSUP4928.



ID tag for mounted body of 2023 freightliner tractor VIN: 3AKJHHDR0PSUP4928.





License plate of 2023 freightliner tractor VIN: 3AKJHHDR0PSUP4928.



Identification tags of make and model of the unit of 2023 freightliner tractor VIN: 3AKJHHDR0PSUP4928.

**FMCSA ANNUAL VEHICLE INSPECTION LABEL**  
A RECORD OF THIS VEHICLE'S ANNUAL VEHICLE REPORT IS  
MAINTAINED AT: ☒ MOTOR CARRIER ☐ OTHER ENTITY

**Darwish Company LLC.**  
1256151 Highway Dr.  
Vanu, CA 94581  
9516426062  
4976891

**MONTH:**  
JAN ☒ JULY ☐  
FEB ☐ AUG ☐  
MAR ☐ SEPT ☐  
APR ☐ OCT ☐  
MAY ☐ NOV ☐  
JUNE ☐ DEC ☐

**YEAR:**  
2024 ☒ 2025 ☐  
2026 ☐ 2027 ☐

**CERTIFICATION:** THIS VEHICLE HAS PASSED AN INSPECTION IN  
ACCORDANCE WITH 49CFR 396.17 THROUGH 396.23.



Identification tags of make and model of the unit of 2023 freightliner tractor VIN: 3AKJHHDR0PSUP4928.



Truck company name lettering-unit numbers of 2023 freightliner tractor VIN: 3AKJHHDR0PSUP4928.



Truck company name lettering-unit numbers of 2023 freightliner tractor VIN: 3AKJHHDR0PSUP4928.





Driver side of vehicle of 2023 freightliner tractor VIN: 3AKJHHDR0PSUP4928.





Driver side of vehicle of 2023 freightliner tractor VIN: 3AKJHHDR0PSUP4928.



Driver side of vehicle of 2023 freightliner tractor VIN: 3AKJHHDR0PSUP4928.





Driver side of vehicle of 2023 freightliner tractor VIN: 3AKJHHDR0PSUP4928.



Driver side of vehicle of 2023 freightliner tractor VIN: 3AKJHHDR0PSUP4928.





Driver side of vehicle of 2023 freightliner tractor VIN: 3AKJHHDR0PSUP4928.



Driver side of vehicle of 2023 freightliner tractor VIN: 3AKJHHDR0PSUP4928.





Passenger side of vehicle of 2023 freightliner tractor VIN: 3AKJHHDR0PSUP4928.



Passenger side of vehicle of 2023 freightliner tractor VIN: 3AKJHHDR0PSUP4928.





Passenger side of vehicle of 2023 freightliner tractor VIN: 3AKJHHDR0PSUP4928.



Passenger side of vehicle of 2023 freightliner tractor VIN: 3AKJHHDR0PSUP4928.





Passenger side of vehicle of 2023 freightliner tractor VIN: 3AKJHHDR0PSUP4928.





Front of vehicle of 2023 freightliner tractor VIN: 3AKJHHDR0PSUP4928.



Front of vehicle of 2023 freightliner tractor VIN: 3AKJHHDR0PSUP4928.



Front of vehicle of 2023 freightliner tractor VIN: 3AKJHHDR0PSUP4928.





Front of vehicle of 2023 freightliner tractor VIN: 3AKJHHDR0PSUP4928.



Front of vehicle of 2023 freightliner tractor VIN: 3AKJHHDR0PSUP4928.





Rear of vehicle of 2023 freightliner tractor VIN: 3AKJHHDR0PSUP4928.





Rear of vehicle of 2023 freightliner tractor VIN: 3AKJHHDR0PSUP4928.





Tire tread depth of 2023 freightliner tractor VIN: 3AKJHHDR0PSUP4928.





Tire tread depth of 2023 freightliner tractor VIN: 3AKJHHDR0PSUP4928.





Wheels of 2023 freightliner tractor VIN: 3AKJHHDR0PSUP4928.





Wheels of 2023 freightliner tractor VIN: 3AKJHHDR0PSUP4928.





Wheels of 2023 freightliner tractor VIN: 3AKJHHDR0PSUP4928.





Wheels of 2023 freightliner tractor VIN: 3AKJHHDR0PSUP4928.





Damage noted to driver side of vehicle of 2023 freightliner tractor VIN: 3AKJHHDR0PSUP4928.





Damage noted to driver side of vehicle of 2023 freightliner tractor VIN: 3AKJHHDR0PSUP4928.





Damage noted to driver side of vehicle of 2023 freightliner tractor VIN: 3AKJHHDR0PSUP4928.





Damage noted to driver side of vehicle of 2023 freightliner tractor VIN: 3AKJHHDR0PSUP4928.





Damage noted to driver side of vehicle of 2023 freightliner tractor VIN: 3AKJHHDR0PSUP4928.





Damage noted to driver side of vehicle of 2023 freightliner tractor VIN: 3AKJHHDR0PSUP4928.





Damage noted to driver side of vehicle of 2023 freightliner tractor VIN: 3AKJHHDR0PSUP4928.





Damage noted to passenger side of vehicle of 2023 freightliner tractor VIN: 3AKJHHDR0PSUP4928.






Damage noted to passenger side of vehicle of 2023 freightliner tractor VIN: 3AKJHHDR0PSUP4928.






Damage noted to rear of vehicle of 2023 freightliner tractor VIN: 3AKJHHDR0PSUP4928.





Damage noted to rear of vehicle of 2023 freightliner tractor VIN: 3AKJHHDR0PSUP4928.






Damage noted to rear of vehicle of 2023 freightliner tractor VIN: 3AKJHHDR0PSUP4928.





Damage noted to rear of vehicle of 2023 freightliner tractor VIN: 3AKJHHDR0PSUP4928.





Damage noted to rear of vehicle of 2023 freightliner tractor VIN: 3AKJHHDR0PSUP4928.





Damage noted to rear of vehicle of 2023 freightliner tractor VIN: 3AKJHHDR0PSUP4928.






Damage noted to rear of vehicle of 2023 freightliner tractor VIN: 3AKJHHDR0PSUP4928.





Damage noted to rear of vehicle of 2023 freightliner tractor VIN: 3AKJHHDR0PSUP4928.





Damage noted to rear of vehicle of 2023 freightliner tractor VIN: 3AKJHHDR0PSUP4928.





Damage noted to rear of vehicle of 2023 freightliner tractor VIN: 3AKJHHDR0PSUP4928.





Damage noted to rear of vehicle of 2023 freightliner tractor VIN: 3AKJHHDR0PSUP4928.





Damage noted to rear of vehicle of 2023 freightliner tractor VIN: 3AKJHHDR0PSUP4928.





Damage noted to rear of vehicle of 2023 freightliner tractor VIN: 3AKJHHDR0PSUP4928.





Damage noted to rear of vehicle of 2023 freightliner tractor VIN: 3AKJHHDR0PSUP4928.





Damage noted to rear of vehicle of 2023 freightliner tractor VIN: 3AKJHHDR0PSUP4928.



Inside of cab.





Inside of cab.



Inside of cab.






Inside of cab.



Inside of cab.





Inside of cab.



Gas tank.





Gas tank.



## Dash





Cab



Cab





Cab



Dash.





Due to the damage the hood would not open.

Also, the unit did not start and there was no mileage sticker. There was no mileage reading.