

Claim Photo

Our File Number: 277-066353
Adjuster: Timothy Handy
Insured: Dycom Industries
Date of Loss: 01/08/2026
Customer File Number: 009080-028965-AD-01
Policy Number:



Photo: 1

Date Taken:
01/22/2026

Taken By:
Preston Baylor

Description:
No information on the tag




Photo: 2

Date Taken:
01/22/2026

Taken By:
Preston Baylor

Description:
Information tag

Claim Photo

Our File Number: 277-066353
Adjuster: Timothy Handy
Insured: Dycom Industries
Date of Loss: 01/08/2026
Customer File Number: 009080-028965-AD-01
Policy Number:



Photo: 3

Date Taken:
01/22/2026

Taken By:
Preston Baylor

Description:
Engine information tag



Photo: 4

Date Taken:
01/22/2026

Taken By:
Preston Baylor

Description:
Information tag

Claim Photo

Our File Number: 277-066353
Adjuster: Timothy Handy
Insured: Dycom Industries
Date of Loss: 01/08/2026
Customer File Number: 009080-028965-AD-01
Policy Number:



Photo: 5

Date Taken:
01/22/2026

Taken By:
Preston Baylor

Description:
The gauges do not operate



Photo: 6

Date Taken:
01/22/2026

Taken By:
Preston Baylor

Description:
Front to rear view

Claim Photo

Our File Number: 277-066353
Adjuster: Timothy Handy
Insured: Dycom Industries
Date of Loss: 01/08/2026
Customer File Number: 009080-028965-AD-01
Policy Number:



Photo: 7

Date Taken:
01/22/2026

Taken By:
Preston Baylor

Description:
Rear to front view



Photo: 8

Date Taken:
01/22/2026

Taken By:
Preston Baylor

Description:
Front to rear view

Claim Photo

Our File Number: 277-066353
Adjuster: Timothy Handy
Insured: Dycom Industries
Date of Loss: 01/08/2026
Customer File Number: 009080-028965-AD-01
Policy Number:



Photo: 9

Date Taken:
01/22/2026

Taken By:
Preston Baylor

Description:
Rear to front view



Photo: 10

Date Taken:
01/22/2026

Taken By:
Preston Baylor

Description:
Engine
compartment - right
side

Claim Photo

Our File Number: 277-066353
Adjuster: Timothy Handy
Insured: Dycom Industries
Date of Loss: 01/08/2026
Customer File Number: 009080-028965-AD-01
Policy Number:



Photo: 11

Date Taken:
01/22/2026

Taken By:
Preston Baylor

Description:
Engine
compartment - right
side



Photo: 12

Date Taken:
01/22/2026

Taken By:
Preston Baylor

Description:
Right side tire

Claim Photo

Our File Number: 277-066353
Adjuster: Timothy Handy
Insured: Dycom Industries
Date of Loss: 01/08/2026
Customer File Number: 009080-028965-AD-01
Policy Number:



Photo: 13

Date Taken:
01/22/2026

Taken By:
Preston Baylor

Description:
Tire tread
measurment



Photo: 14

Date Taken:
01/22/2026

Taken By:
Preston Baylor

Description:
Left side tire

Claim Photo

Our File Number: 277-066353
Adjuster: Timothy Handy
Insured: Dycom Industries
Date of Loss: 01/08/2026
Customer File Number: 009080-028965-AD-01
Policy Number:



Photo: 15

Date Taken:
01/22/2026

Taken By:
Preston Baylor

Description:
Tire tread
measurment



Photo: 16

Date Taken:
01/22/2026

Taken By:
Preston Baylor

Description:
New trailer tongue

Claim Photo

Our File Number: 277-066353
Adjuster: Timothy Handy
Insured: Dycom Industries
Date of Loss: 01/08/2026
Customer File Number: 009080-028965-AD-01
Policy Number:



Photo: 17

Date Taken:
01/22/2026

Taken By:
Preston Baylor

Description:
Damage hitch



Photo: 18

Date Taken:
01/22/2026

Taken By:
Preston Baylor

Description:
Damaged trialer tongue

Claim Photo

Our File Number: 277-066353
Adjuster: Timothy Handy
Insured: Dycom Industries
Date of Loss: 01/08/2026
Customer File Number: 009080-028965-AD-01
Policy Number:

cia
CUSTARD
INSURANCE ADJUSTERS



Photo: 19

Date Taken:
01/22/2026

Taken By:
Preston Baylor

Description:
Damage to the rear



Photo: 20

Date Taken:
01/22/2026

Taken By:
Preston Baylor

Description:
Bottom cooling
radiator damaged

Claim Photo

Our File Number: 277-066353
Adjuster: Timothy Handy
Insured: Dycom Industries
Date of Loss: 01/08/2026
Customer File Number: 009080-028965-AD-01
Policy Number:



Photo: 21

Date Taken:
01/22/2026

Taken By:
Preston Baylor

Description:
Wiribg damaged



Photo: 22

Date Taken:
01/22/2026

Taken By:
Preston Baylor

Description:
Damaged parts

Claim Photo

Our File Number: 277-066353
Adjuster: Timothy Handy
Insured: Dycom Industries
Date of Loss: 01/08/2026
Customer File Number: 009080-028965-AD-01
Policy Number:



Photo: 23

Date Taken:
01/22/2026

Taken By:
Preston Baylor

Description:
Bottom radiator information tag



Photo: 24

Date Taken:
01/22/2026

Taken By:
Preston Baylor

Description:
No visual damage to the top radiator

Claim Photo

Our File Number: 277-066353
Adjuster: Timothy Handy
Insured: Dycom Industries
Date of Loss: 01/08/2026
Customer File Number: 009080-028965-AD-01
Policy Number:



Photo: 25

Date Taken:
01/22/2026

Taken By:
Preston Baylor

Description:
No visual damage noted




Photo: 26

Date Taken:
01/22/2026

Taken By:
Preston Baylor

Description:
No visual damage noted

Claim Photo

Our File Number: 277-066353
Adjuster: Timothy Handy
Insured: Dycom Industries
Date of Loss: 01/08/2026
Customer File Number: 009080-028965-AD-01
Policy Number:



Photo: 27

Date Taken:
01/22/2026

Taken By:
Preston Baylor

Description:
No visual damage
noted underside



Photo: 28

Date Taken:
01/22/2026

Taken By:
Preston Baylor

Description:
No visual damage
noted underside

Claim Photo

Our File Number: 277-066353
Adjuster: Timothy Handy
Insured: Dycom Industries
Date of Loss: 01/08/2026
Customer File Number: 009080-028965-AD-01
Policy Number:



Photo: 29

Date Taken:
01/22/2026

Taken By:
Preston Baylor

Description:
Damaged parts