

Claim Photo

Our File Number: 297-017872
Adjuster: Scott Syner
Insured: L & R Precast
Date of Loss: 12/16/2025
Customer File Number: 25AQ1-03797
Policy Number:




Photo: 1

Date Taken:
12/16/2025

Taken By:
Insured

Description:
Photo submitted by
client




Photo: 2

Date Taken:
12/16/2025

Taken By:
Insured

Description:
Photo submitted by
client

Claim Photo

Our File Number: 297-017872
Adjuster: Scott Syner
Insured: L & R Precast
Date of Loss: 12/16/2025
Customer File Number: 25AQ1-03797
Policy Number:




Photo: 3

Date Taken:
12/16/2025

Taken By:
Insured

Description:
Photo submitted by
client



Photo: 4

Date Taken:
12/24/2025

Taken By:
Ricardo De Leon

Description:
Inspected of 2017
Freightliner cement
truck located at
Capital Towing 512
N. Midway Rd.
Weslaco, TX
78596. Front view

Claim Photo

Our File Number: 297-017872
Adjuster: Scott Syner
Insured: L & R Precast
Date of Loss: 12/16/2025
Customer File Number: 25AQ1-03797
Policy Number:



Photo: 5
Date Taken: 12/24/2025
Taken By: Ricardo De Leon
Description: Front left




Photo: 6
Date Taken: 12/24/2025
Taken By: Ricardo De Leon
Description: VIN number verified

Claim Photo

Our File Number: 297-017872
Adjuster: Scott Syner
Insured: L & R Precast
Date of Loss: 12/16/2025
Customer File Number: 25AQ1-03797
Policy Number:



Photo: 7

Date Taken:
12/24/2025

Taken By:
Ricardo De Leon

Description:
Specs on door
frame




Photo: 8

Date Taken:
12/24/2025

Taken By:
Ricardo De Leon

Description:
Manufactured date
06-16

Claim Photo

Our File Number: 297-017872
Adjuster: Scott Syner
Insured: L & R Precast
Date of Loss: 12/16/2025
Customer File Number: 25AQ1-03797
Policy Number:



Photo: 9
Date Taken: 12/24/2025
Taken By: Ricardo De Leon
Description: Additional specs on door frame



Photo: 10
Date Taken: 12/24/2025
Taken By: Ricardo De Leon
Description: Specs on door frame

Claim Photo

Our File Number: 297-017872
Adjuster: Scott Syner
Insured: L & R Precast
Date of Loss: 12/16/2025
Customer File Number: 25AQ1-03797
Policy Number:




Photo: 11

Date Taken:
12/24/2025

Taken By:
Ricardo De Leon

Description:
Interior cab




Photo: 12

Date Taken:
12/24/2025

Taken By:
Ricardo De Leon

Description:
Front right seat

Claim Photo

Our File Number: 297-017872
Adjuster: Scott Syner
Insured: L & R Precast
Date of Loss: 12/16/2025
Customer File Number: 25AQ1-03797
Policy Number:



Photo: 13

Date Taken:
12/24/2025

Taken By:
Ricardo De Leon

Description:
Front left



Photo: 14

Date Taken:
12/24/2025

Taken By:
Ricardo De Leon

Description:
Left side

Claim Photo

Our File Number: 297-017872
Adjuster: Scott Syner
Insured: L & R Precast
Date of Loss: 12/16/2025
Customer File Number: 25AQ1-03797
Policy Number:



Photo: 15

Date Taken:
12/24/2025

Taken By:
Ricardo De Leon

Description:
Front right




Photo: 16

Date Taken:
12/24/2025

Taken By:
Ricardo De Leon

Description:
Right side

Claim Photo

Our File Number: 297-017872
Adjuster: Scott Syner
Insured: L & R Precast
Date of Loss: 12/16/2025
Customer File Number: 25AQ1-03797
Policy Number:



Photo: 17

Date Taken:
12/24/2025

Taken By:
Ricardo De Leon

Description:
Right side decals



Photo: 18

Date Taken:
12/24/2025

Taken By:
Ricardo De Leon

Description:
Right side cement
mixer

Claim Photo

Our File Number: 297-017872
Adjuster: Scott Syner
Insured: L & R Precast
Date of Loss: 12/16/2025
Customer File Number: 25AQ1-03797
Policy Number:



Photo: 19

Date Taken:
12/24/2025

Taken By:
Ricardo De Leon

Description:
Right side cement
mixer



Photo: 20

Date Taken:
12/24/2025

Taken By:
Ricardo De Leon

Description:
Rear right view

Claim Photo

Our File Number: 297-017872
Adjuster: Scott Syner
Insured: L & R Precast
Date of Loss: 12/16/2025
Customer File Number: 25AQ1-03797
Policy Number:



Photo: 21

Date Taken:
12/24/2025

Taken By:
Ricardo De Leon

Description:
Rear right




Photo: 22

Date Taken:
12/24/2025

Taken By:
Ricardo De Leon

Description:
Front axle on the
ground

Claim Photo

Our File Number: 297-017872
Adjuster: Scott Syner
Insured: L & R Precast
Date of Loss: 12/16/2025
Customer File Number: 25AQ1-03797
Policy Number:



Photo: 23

Date Taken:
12/24/2025

Taken By:
Ricardo De Leon

Description:
Rear right view



Photo: 24

Date Taken:
12/24/2025

Taken By:
Ricardo De Leon

Description:
Rear view

Claim Photo

Our File Number: 297-017872
Adjuster: Scott Syner
Insured: L & R Precast
Date of Loss: 12/16/2025
Customer File Number: 25AQ1-03797
Policy Number:



Photo: 25

Date Taken:
12/24/2025

Taken By:
Ricardo De Leon

Description:
Rear left



Photo: 26

Date Taken:
12/24/2025

Taken By:
Ricardo De Leon

Description:
Front right tire
tread

Claim Photo

Our File Number: 297-017872
Adjuster: Scott Syner
Insured: L & R Precast
Date of Loss: 12/16/2025
Customer File Number: 25AQ1-03797
Policy Number:



Photo: 27

Date Taken:
12/24/2025

Taken By:
Ricardo De Leon

Description:
Front left tire tread



Photo: 28

Date Taken:
12/24/2025

Taken By:
Ricardo De Leon

Description:
Rear left - front
outer tire tread

Claim Photo

Our File Number: 297-017872
Adjuster: Scott Syner
Insured: L & R Precast
Date of Loss: 12/16/2025
Customer File Number: 25AQ1-03797
Policy Number:



Photo: 29

Date Taken:
12/24/2025

Taken By:
Ricardo De Leon

Description:
Rear left - front
inner tire tread



Photo: 30

Date Taken:
12/24/2025

Taken By:
Ricardo De Leon

Description:
Rear left - back
outer tire tread

Claim Photo

Our File Number: 297-017872
Adjuster: Scott Syner
Insured: L & R Precast
Date of Loss: 12/16/2025
Customer File Number: 25AQ1-03797
Policy Number:



Photo: 31

Date Taken:
12/24/2025

Taken By:
Ricardo De Leon

Description:
Rear left - back
inner tire tread



Photo: 32

Date Taken:
12/24/2025

Taken By:
Ricardo De Leon

Description:
Rear right - front
outer tire tread

Claim Photo

Our File Number: 297-017872
Adjuster: Scott Syner
Insured: L & R Precast
Date of Loss: 12/16/2025
Customer File Number: 25AQ1-03797
Policy Number:



Photo: 33

Date Taken:
12/24/2025

Taken By:
Ricardo De Leon

Description:
Rear right - front
inner tire tread



Photo: 34

Date Taken:
12/24/2025

Taken By:
Ricardo De Leon

Description:
Rear right - back
outer tire tread

Claim Photo

Our File Number: 297-017872
Adjuster: Scott Syner
Insured: L & R Precast
Date of Loss: 12/16/2025
Customer File Number: 25AQ1-03797
Policy Number:



Photo: 35

Date Taken:
12/24/2025

Taken By:
Ricardo De Leon

Description:
Rear right - back
inner tire tread



Photo: 36

Date Taken:
12/24/2025

Taken By:
Ricardo De Leon

Description:
View underneath
cement mixer

Claim Photo

Our File Number: 297-017872
Adjuster: Scott Syner
Insured: L & R Precast
Date of Loss: 12/16/2025
Customer File Number: 25AQ1-03797
Policy Number:



Photo: 37

Date Taken:
12/24/2025

Taken By:
Ricardo De Leon

Description:
Plate number



Photo: 38

Date Taken:
12/24/2025

Taken By:
Ricardo De Leon

Description:
Rear cement mixer

Claim Photo

Our File Number: 297-017872
Adjuster: Scott Syner
Insured: L & R Precast
Date of Loss: 12/16/2025
Customer File Number: 25AQ1-03797
Policy Number:




Photo: 39

Date Taken:
12/24/2025

Taken By:
Ricardo De Leon

Description:
Rear left



Photo: 40

Date Taken:
12/24/2025

Taken By:
Ricardo De Leon

Description:
View of frame
underneath