























Damage noted to 1995 Hitachi EX200LC-2 Crawler Excavator . - 01/30/2026 11:47 AM




Damage noted to 1995 Hitachi EX200LC-2 Crawler Excavator . - 01/30/2026 11:47 AM



Damage noted to 1995 Hitachi EX200LC-2 Crawler Excavator . - 01/30/2026 11:47 AM



Damage noted to 1995 Hitachi EX200LC-2 Crawler Excavator . - 01/30/2026 11:47 AM






Damage noted to 1995 Hitachi EX200LC-2 Crawler Excavator . - 01/30/2026 11:47 AM



Damage noted to 1995 Hitachi EX200LC-2 Crawler Excavator . - 01/30/2026 11:47 AM



Damage noted to 1995 Hitachi EX200LC-2 Crawler Excavator . - 01/30/2026 11:47 AM





Damage noted to 1995 Hitachi EX200LC-2 Crawler Excavator . - 01/30/2026 11:48 AM







Damage noted to 1995 Hitachi EX200LC-2 Crawler Excavator . - 01/30/2026 11:49 AM



Damage noted to 1995 Hitachi EX200LC-2 Crawler Excavator . - 01/30/2026 11:49 AM













Damage noted to 1995 Hitachi EX200LC-2 Crawler Excavator . - 01/30/2026 11:49 AM



Damage noted to 1995 Hitachi EX200LC-2 Crawler Excavator . - 01/30/2026 11:47 AM



Damage noted to 1995 Hitachi EX200LC-2 Crawler Excavator . - 01/30/2026 11:47 AM



Damage noted to 1995 Hitachi EX200LC-2 Crawler Excavator . - 01/30/2026 11:47 AM



Complete damage.

No hour meter located.

Unable to open doors on engine compartment.