




Claim Reference Id	: TD6217-1-1-486
File Name	: PHOTO1
File Date	: 12/17/2025
Label	: TD6217-1-1-486 Passenger Side Back Rear
Note	: Style:2019,KENW,KENWORTH CONSTRUCTION T880 LossDate:11/26/2025 PolicyNumber:FB9459 ClaimRepresentative:LITTLE VIN:1XKZDP9X2KJ302489 InsuranceCompany:ACUIITY, A MUTUAL INSURANCE COMPANY InsuredIsOwner:Y Estimator:John,Marsh
Photo Location	:
Photo Taken By	: John Marsh
Estimate Indicator	: E01



Claim Reference Id	: TD6217-1-1-486
File Name	: PHOTO2
File Date	: 12/17/2025
Label	: TD6217-1-1-486 Damage 4 2025.5429
Note	: Style:2019,KENW,KENWORTH CONSTRUCTION T880 LossDate:11/26/2025 PolicyNumber:FB9459 ClaimRepresentative:LITTLE VIN:1XKZDP9X2KJ302489 InsuranceCompany:ACUITY, A MUTUAL INSURANCE COMPANY InsuredIsOwner:Y Estimator:John,Marsh
Photo Location	:
Photo Taken By	: John Marsh
Estimate Indicator	: E01



Claim Reference Id	: TD6217-1-1-486
File Name	: PHOTO3
File Date	: 12/17/2025
Label	: TD6217-1-1-486 Driver Side Step-up 2025.
Note	: Style:2019,KENW,KENWORTH CONSTRUCTION T880 LossDate:11/26/2025 PolicyNumber:FB9459 ClaimRepresentative:LITTLE VIN:1XKZDP9X2KJ302489 InsuranceCompany:ACUIITY, A MUTUAL INSURANCE COMPANY InsuredIsOwner:Y Estimator:John,Marsh
Photo Location	:
Photo Taken By	: John Marsh
Estimate Indicator	: E01



Claim Reference Id	: TD6217-1-1-486
File Name	: PHOTO4
File Date	: 12/17/2025
Label	: TD6217-1-1-486 Driver Side Back Rear Out
Note	: Style:2019,KENW,KENWORTH CONSTRUCTION T880 LossDate:11/26/2025 PolicyNumber:FB9459 ClaimRepresentative:LITTLE VIN:1XKZDP9X2KJ302489 InsuranceCompany:ACUIITY, A MUTUAL INSURANCE COMPANY InsuredIsOwner:Y Estimator:John,Marsh
Photo Location	:
Photo Taken By	: John Marsh
Estimate Indicator	: E01



Claim Reference Id	: TD6217-1-1-486
File Name	: PHOTO5
File Date	: 12/17/2025
Label	: TD6217-1-1-486 Passenger Side Seat Full
Note	: Style:2019,KENW,KENWORTH CONSTRUCTION T880 LossDate:11/26/2025 PolicyNumber:FB9459 ClaimRepresentative:LITTLE VIN:1XKZDP9X2KJ302489 InsuranceCompany:ACUIITY, A MUTUAL INSURANCE COMPANY InsuredIsOwner:Y Estimator:John,Marsh
Photo Location	:
Photo Taken By	: John Marsh
Estimate Indicator	: E01



Claim Reference Id	: TD6217-1-1-486
File Name	: PHOTO6
File Date	: 12/17/2025
Label	: TD6217-1-1-486 Exhaust Stack 2 20 25.5429
Note	: Style:2019,KENW,KENWORTH CONSTRUC TION T880 LossDate:11/26/2025 Polic yNumber:FB9459 ClaimRepresentative: LITTLE VIN:1XKZDP9X2KJ302489 Insura nceCompany:ACUITY, A MUTUAL INSURAN CE COMPANY InsuredIsOwner:Y Estimat or:John,Marsh
Photo Location	:
Photo Taken By	: John Marsh
Estimate Indicator	: E01



Claim Reference Id	: TD6217-1-1-486
File Name	: PHOTO7
File Date	: 12/17/2025
Label	: TD6217-1-1-486 Passenger Side Interior F
Note	: Style:2019,KENW,KENWORTH CONSTRUCTION T880 LossDate:11/26/2025 PolicyNumber:FB9459 ClaimRepresentative:LITTLE VIN:1XKZDP9X2KJ302489 InsuranceCompany:ACUIITY, A MUTUAL INSURANCE COMPANY InsuredIsOwner:Y Estimator:John,Marsh
Photo Location	:
Photo Taken By	: John Marsh
Estimate Indicator	: E01



Claim Reference Id	: TD6217-1-1-486
File Name	: PHOTO8
File Date	: 12/17/2025
Label	: TD6217-1-1-486 Driver Side Front Wheel a
Note	: Style:2019,KENW,KENWORTH CONSTRUCTION T880 LossDate:11/26/2025 PolicyNumber:FB9459 ClaimRepresentative:LITTLE VIN:1XKZDP9X2KJ302489 InsuranceCompany:ACUIITY, A MUTUAL INSURANCE COMPANY InsuredIsOwner:Y Estimator:John,Marsh
Photo Location	:
Photo Taken By	: John Marsh
Estimate Indicator	: E01



Claim Reference Id	: TD6217-1-1-486
File Name	: PHOTO9
File Date	: 12/17/2025
Label	: TD6217-1-1-486 Passenger Side Front Corn
Note	: Style:2019,KENW,KENWORTH CONSTRUCTION T880 LossDate:11/26/2025 PolicyNumber:FB9459 ClaimRepresentative:LITTLE VIN:1XKZDP9X2KJ302489 InsuranceCompany:ACUIITY, A MUTUAL INSURANCE COMPANY InsuredIsOwner:Y Estimator:John,Marsh
Photo Location	:
Photo Taken By	: John Marsh
Estimate Indicator	: E01



Claim Reference Id	: TD6217-1-1-486
File Name	: PHOTO10
File Date	: 12/17/2025
Label	: TD6217-1-1-486 Driver Side Engine Full V
Note	: Style:2019,KENW,KENWORTH CONSTRUCTION T880 LossDate:11/26/2025 PolicyNumber:FB9459 ClaimRepresentative:LITTLE VIN:1XKZDP9X2KJ302489 InsuranceCompany:ACUITY, A MUTUAL INSURANCE COMPANY InsuredIsOwner:Y Estimator:John,Marsh
Photo Location	:
Photo Taken By	: John Marsh
Estimate Indicator	: E01



Claim Reference Id	: TD6217-1-1-486
File Name	: PHOTO11
File Date	: 12/17/2025
Label	: TD6217-1-1-486 Dashboard Full Vie w 2025.
Note	: Style:2019,KENW,KENWORTH CONSTRUC TION T880 LossDate:11/26/2025 Polic yNumber:FB9459 ClaimRepresentative: LITTLE VIN:1XKZDP9X2KJ302489 Insura nceCompany:ACUITY, A MUTUAL INSURAN CE COMPANY InsuredIsOwner:Y Estimat or:John,Marsh
Photo Location	:
Photo Taken By	: John Marsh
Estimate Indicator	: E01



Claim Reference Id	: TD6217-1-1-486
File Name	: PHOTO12
File Date	: 12/17/2025
Label	: TD6217-1-1-486 Passenger Side Forward Re
Note	: Style:2019,KENW,KENWORTH CONSTRUCTION T880 LossDate:11/26/2025 PolicyNumber:FB9459 ClaimRepresentative:LITTLE VIN:1XKZDP9X2KJ302489 InsuranceCompany:ACUIITY, A MUTUAL INSURANCE COMPANY InsuredIsOwner:Y Estimator:John,Marsh
Photo Location	:
Photo Taken By	: John Marsh
Estimate Indicator	: E01



Claim Reference Id	: TD6217-1-1-486
File Name	: PHOTO13
File Date	: 12/17/2025
Label	: TD6217-1-1-486 Engine VIN 2025.54 29
Note	: Style:2019,KENW,KENWORTH CONSTRU TION T880 LossDate:11/26/2025 Polic yNumber:FB9459 ClaimRepresentative: LITTLE VIN:1XKZDP9X2KJ302489 Insura nceCompany:ACUITY, A MUTUAL INSURAN CE COMPANY InsuredIsOwner:Y Estimat or:John,Marsh
Photo Location	:
Photo Taken By	: John Marsh
Estimate Indicator	: E01



Claim Reference Id	: TD6217-1-1-486
File Name	: PHOTO14
File Date	: 12/17/2025
Label	: TD6217-1-1-486 Steering Wheel 2025.5429
Note	: Style:2019,KENW,KENWORTH CONSTRUCTION T880 LossDate:11/26/2025 PolicyNumber:FB9459 ClaimRepresentative:LITTLE VIN:1XKZDP9X2KJ302489 InsuranceCompany:ACUIITY, A MUTUAL INSURANCE COMPANY InsuredIsOwner:Y Estimator:John,Marsh
Photo Location	:
Photo Taken By	: John Marsh
Estimate Indicator	: E01



Claim Reference Id	: TD6217-1-1-486
File Name	: PHOTO15
File Date	: 12/17/2025
Label	: TD6217-1-1-486 Gear Shift 2025.54 29
Note	: Style:2019,KENW,KENWORTH CONSTRU TION T880 LossDate:11/26/2025 Polic yNumber:FB9459 ClaimRepresentative: LITTLE VIN:1XKZDP9X2KJ302489 Insura nceCompany:ACUITY, A MUTUAL INSURAN CE COMPANY InsuredIsOwner:Y Estimat or:John,Marsh
Photo Location	:
Photo Taken By	: John Marsh
Estimate Indicator	: E01



Claim Reference Id	: TD6217-1-1-486
File Name	: PHOTO16
File Date	: 12/17/2025
Label	: TD6217-1-1-486 Passenger Side Ste
	p-up 20
Note	: Style:2019,KENW,KENWORTH CONSTRUC TION T880 LossDate:11/26/2025 Polic yNumber:FB9459 ClaimRepresentative: LITTLE VIN:1XKZDP9X2KJ302489 Insura nceCompany:ACUITY, A MUTUAL INSURAN CE COMPANY InsuredIsOwner:Y Estimat or:John,Marsh
Photo Location	:
Photo Taken By	: John Marsh
Estimate Indicator	: E01




Claim Reference Id	: TD6217-1-1-486
File Name	: PHOTO17
File Date	: 12/17/2025
Label	: TD6217-1-1-486 Exhaust Stack 1 20 25.5429
Note	: Style:2019,KENW,KENWORTH CONSTRUC TION T880 LossDate:11/26/2025 Polic yNumber:FB9459 ClaimRepresentative: LITTLE VIN:1XKZDP9X2KJ302489 Insura nceCompany:ACUITY, A MUTUAL INSURAN CE COMPANY InsuredIsOwner:Y Estimat or:John,Marsh
Photo Location	:
Photo Taken By	: John Marsh
Estimate Indicator	: E01



Claim Reference Id	: TD6217-1-1-486
File Name	: PHOTO18
File Date	: 12/17/2025
Label	: TD6217-1-1-486 Driver Side Rear Corner F
Note	: Style:2019,KENW,KENWORTH CONSTRUCTION T880 LossDate:11/26/2025 PolicyNumber:FB9459 ClaimRepresentative:LITTLE VIN:1XKZDP9X2KJ302489 InsuranceCompany:ACUIITY, A MUTUAL INSURANCE COMPANY InsuredIsOwner:Y Estimator:John,Marsh
Photo Location	:
Photo Taken By	: John Marsh
Estimate Indicator	: E01



Claim Reference Id	: TD6217-1-1-486
File Name	: PHOTO19
File Date	: 12/17/2025
Label	: TD6217-1-1-486 Passenger Side Back Rear
Note	: Style:2019,KENW,KENWORTH CONSTRUCTION T880 LossDate:11/26/2025 PolicyNumber:FB9459 ClaimRepresentative:LITTLE VIN:1XKZDP9X2KJ302489 InsuranceCompany:ACUIITY, A MUTUAL INSURANCE COMPANY InsuredIsOwner:Y Estimator:John,Marsh
Photo Location	:
Photo Taken By	: John Marsh
Estimate Indicator	: E01



Claim Reference Id	: TD6217-1-1-486
File Name	: PHOTO20
File Date	: 12/17/2025
Label	: TD6217-1-1-486 Driver Side Doorja mb VIN
Note	: Style:2019,KENW,KENWORTH CONSTRUC TION T880 LossDate:11/26/2025 Polic yNumber:FB9459 ClaimRepresentative: LITTLE VIN:1XKZDP9X2KJ302489 Insura nceCompany:ACUITY, A MUTUAL INSURAN CE COMPANY InsuredIsOwner:Y Estimat or:John,Marsh
Photo Location	:
Photo Taken By	: John Marsh
Estimate Indicator	: E01



Claim Reference Id	: TD6217-1-1-486
File Name	: PHOTO21
File Date	: 12/17/2025
Label	: TD6217-1-1-486 Driver Side Forward Rear
Note	: Style:2019,KENW,KENWORTH CONSTRUCTION T880 LossDate:11/26/2025 PolicyNumber:FB9459 ClaimRepresentative:LITTLE VIN:1XKZDP9X2KJ302489 InsuranceCompany:ACUIITY, A MUTUAL INSURANCE COMPANY InsuredIsOwner:Y Estimator:John,Marsh
Photo Location	:
Photo Taken By	: John Marsh
Estimate Indicator	: E01



Claim Reference Id	: TD6217-1-1-486
File Name	: PHOTO22
File Date	: 12/17/2025
Label	: TD6217-1-1-486 Driver Side Seat Full View
Note	: Style:2019,KENW,KENWORTH CONSTRUCTION T880 LossDate:11/26/2025 PolicyNumber:FB9459 ClaimRepresentative:LITTLE VIN:1XKZDP9X2KJ302489 InsuranceCompany:ACUIITY, A MUTUAL INSURANCE COMPANY InsuredIsOwner:Y Estimator:John,Marsh
Photo Location	:
Photo Taken By	: John Marsh
Estimate Indicator	: E01



Claim Reference Id	: TD6217-1-1-486
File Name	: PHOTO23
File Date	: 12/17/2025
Label	: TD6217-1-1-486 Damage 2 2025.5429
Note	: Style:2019,KENW,KENWORTH CONSTRUCTION T880 LossDate:11/26/2025 PolicyNumber:FB9459 ClaimRepresentative:LITTLE VIN:1XKZDP9X2KJ302489 InsuranceCompany:ACUITY, A MUTUAL INSURANCE COMPANY InsuredIsOwner:Y Estimator:John,Marsh
Photo Location	:
Photo Taken By	: John Marsh
Estimate Indicator	: E01



Claim Reference Id	: TD6217-1-1-486
File Name	: PHOTO24
File Date	: 12/17/2025
Label	: TD6217-1-1-486 Driver Side Forward Rear
Note	: Style:2019,KENW,KENWORTH CONSTRUCTION T880 LossDate:11/26/2025 PolicyNumber:FB9459 ClaimRepresentative:LITTLE VIN:1XKZDP9X2KJ302489 InsuranceCompany:ACUIITY, A MUTUAL INSURANCE COMPANY InsuredIsOwner:Y Estimator:John,Marsh
Photo Location	:
Photo Taken By	: John Marsh
Estimate Indicator	: E01



Claim Reference Id	: TD6217-1-1-486
File Name	: PHOTO25
File Date	: 12/17/2025
Label	: TD6217-1-1-486 Passenger Side Forward Re
Note	: Style:2019,KENW,KENWORTH CONSTRUCTION T880 LossDate:11/26/2025 PolicyNumber:FB9459 ClaimRepresentative:LITTLE VIN:1XKZDP9X2KJ302489 InsuranceCompany:ACUIITY, A MUTUAL INSURANCE COMPANY InsuredIsOwner:Y Estimator:John,Marsh
Photo Location	:
Photo Taken By	: John Marsh
Estimate Indicator	: E01



Claim Reference Id	: TD6217-1-1-486
File Name	: PHOTO26
File Date	: 12/17/2025
Label	: TD6217-1-1-486 Driver Side Front Tire Tr
Note	: Style:2019,KENW,KENWORTH CONSTRU TION T880 LossDate:11/26/2025 Polic yNumber:FB9459 ClaimRepresentative: LITTLE VIN:1XKZDP9X2KJ302489 Insura nceCompany:ACUITY, A MUTUAL INSURAN CE COMPANY InsuredIsOwner:Y Estimat or:John,Marsh
Photo Location	:
Photo Taken By	: John Marsh
Estimate Indicator	: E01



Claim Reference Id	: TD6217-1-1-486
File Name	: PHOTO27
File Date	: 12/17/2025
Label	: TD6217-1-1-486 Engine Brake Switch 2025.
Note	: Style:2019,KENW,KENWORTH CONSTRUCTION T880 LossDate:11/26/2025 PolicyNumber:FB9459 ClaimRepresentative:LITTLE VIN:1XKZDP9X2KJ302489 InsuranceCompany:ACUIITY, A MUTUAL INSURANCE COMPANY InsuredIsOwner:Y Estimator:John,Marsh
Photo Location	:
Photo Taken By	: John Marsh
Estimate Indicator	: E01



Claim Reference Id	: TD6217-1-1-486
File Name	: PHOTO28
File Date	: 12/17/2025
Label	: TD6217-1-1-486 Damage 5 2025.5429
Note	: Style:2019,KENW,KENWORTH CONSTRUCTION T880 LossDate:11/26/2025 PolicyNumber:FB9459 ClaimRepresentative:LITTLE VIN:1XKZDP9X2KJ302489 InsuranceCompany:ACUITY, A MUTUAL INSURANCE COMPANY InsuredIsOwner:Y Estimator:John,Marsh
Photo Location	:
Photo Taken By	: John Marsh
Estimate Indicator	: E01



Claim Reference Id	: TD6217-1-1-486
File Name	: PHOTO29
File Date	: 12/17/2025
Label	: TD6217-1-1-486 Front Full View 2025.5429
Note	: Style:2019,KENW,KENWORTH CONSTRUCTION T880 LossDate:11/26/2025 PolicyNumber:FB9459 ClaimRepresentative:LITTLE VIN:1XKZDP9X2KJ302489 InsuranceCompany:ACUITY, A MUTUAL INSURANCE COMPANY InsuredIsOwner:Y Estimator:John,Marsh
Photo Location	:
Photo Taken By	: John Marsh
Estimate Indicator	: E01



Claim Reference Id	: TD6217-1-1-486
File Name	: PHOTO30
File Date	: 12/17/2025
Label	: TD6217-1-1-486 Rear Full View2025.5429
Note	: Style:2019,KENW,KENWORTH CONSTRUCTION T880 LossDate:11/26/2025 PolicyNumber:FB9459 ClaimRepresentative:LITTLE VIN:1XKZDP9X2KJ302489 InsuranceCompany:ACUIITY, A MUTUAL INSURANCE COMPANY InsuredIsOwner:Y Estimator:John,Marsh
Photo Location	:
Photo Taken By	: John Marsh
Estimate Indicator	: E01



Claim Reference Id	: TD6217-1-1-486
File Name	: PHOTO31
File Date	: 12/17/2025
Label	: TD6217-1-1-486 Passenger Side Eng ine Ful
Note	: Style:2019,KENW,KENWORTH CONSTRUC TION T880 LossDate:11/26/2025 Polic yNumber:FB9459 ClaimRepresentative: LITTLE VIN:1XKZDP9X2KJ302489 Insura nceCompany:ACUITY, A MUTUAL INSURAN CE COMPANY InsuredIsOwner:Y Estimat or:John,Marsh
Photo Location	:
Photo Taken By	: John Marsh
Estimate Indicator	: E01



Claim Reference Id	: TD6217-1-1-486
File Name	: PHOTO32
File Date	: 12/17/2025
Label	: TD6217-1-1-486 Fifth Wheel Area 2 025.542
Note	: Style:2019,KENW,KENWORTH CONSTRU TION T880 LossDate:11/26/2025 Polic yNumber:FB9459 ClaimRepresentative: LITTLE VIN:1XKZDP9X2KJ302489 Insura nceCompany:ACUIITY, A MUTUAL INSURAN CE COMPANY InsuredIsOwner:Y Estimat or:John,Marsh
Photo Location	:
Photo Taken By	: John Marsh
Estimate Indicator	: E01



Claim Reference Id	: TD6217-1-1-486
File Name	: PHOTO33
File Date	: 12/17/2025
Label	: TD6217-1-1-486 Driver Side Back Rear Wheel
Note	: Style:2019,KENW,KENWORTH CONSTRUCTION T880 LossDate:11/26/2025 PolicyNumber:FB9459 ClaimRepresentative:LITTLE VIN:1XKZDP9X2KJ302489 InsuranceCompany:ACUIITY, A MUTUAL INSURANCE COMPANY InsuredIsOwner:Y Estimator:John,Marsh
Photo Location	:
Photo Taken By	: John Marsh
Estimate Indicator	: E01



Claim Reference Id	: TD6217-1-1-486
File Name	: PHOTO34
File Date	: 12/17/2025
Label	: TD6217-1-1-486 Odometer 2025.5429
Note	: Style:2019,KENW,KENWORTH CONSTRUCTION T880 LossDate:11/26/2025 PolicyNumber:FB9459 ClaimRepresentative:LITTLE VIN:1XKZDP9X2KJ302489 InsuranceCompany:ACUITY, A MUTUAL INSURANCE COMPANY InsuredIsOwner:Y Estimator:John,Marsh
Photo Location	:
Photo Taken By	: John Marsh
Estimate Indicator	: E01



Claim Reference Id	: TD6217-1-1-486
File Name	: PHOTO35
File Date	: 12/17/2025
Label	: TD6217-1-1-486 Damage 6 2025.5429
Note	: Style:2019,KENW,KENWORTH CONSTRUCTION T880 LossDate:11/26/2025 PolicyNumber:FB9459 ClaimRepresentative:LITTLE VIN:1XKZDP9X2KJ302489 InsuranceCompany:ACUITY, A MUTUAL INSURANCE COMPANY InsuredIsOwner:Y Estimator:John,Marsh
Photo Location	:
Photo Taken By	: John Marsh
Estimate Indicator	: E01



Claim Reference Id	: TD6217-1-1-486
File Name	: PHOTO36
File Date	: 12/17/2025
Label	: TD6217-1-1-486 Driver Side Interi or Full
Note	: Style:2019,KENW,KENWORTH CONSTRUC TION T880 LossDate:11/26/2025 Polic yNumber:FB9459 ClaimRepresentative: LITTLE VIN:1XKZDP9X2KJ302489 Insura nceCompany:ACUITY, A MUTUAL INSURAN CE COMPANY InsuredIsOwner:Y Estimat or:John,Marsh
Photo Location	:
Photo Taken By	: John Marsh
Estimate Indicator	: E01



Claim Reference Id	: TD6217-1-1-486
File Name	: PHOTO37
File Date	: 12/17/2025
Label	: TD6217-1-1-486 Passenger Side Front Tire
Note	: Style:2019,KENW,KENWORTH CONSTRUCTION T880 LossDate:11/26/2025 PolicyNumber:FB9459 ClaimRepresentative:LITTLE VIN:1XKZDP9X2KJ302489 InsuranceCompany:ACUIITY, A MUTUAL INSURANCE COMPANY InsuredIsOwner:Y Estimator:John,Marsh
Photo Location	:
Photo Taken By	: John Marsh
Estimate Indicator	: E01



Claim Reference Id	: TD6217-1-1-486
File Name	: PHOTO38
File Date	: 12/17/2025
Label	: TD6217-1-1-486 Passenger Side Rear Corner
Note	: Style:2019,KENW,KENWORTH CONSTRUCTION T880 LossDate:11/26/2025 PolicyNumber:FB9459 ClaimRepresentative:LITTLE VIN:1XKZDP9X2KJ302489 InsuranceCompany:ACUIITY, A MUTUAL INSURANCE COMPANY InsuredIsOwner:Y Estimator:John,Marsh
Photo Location	:
Photo Taken By	: John Marsh
Estimate Indicator	: E01



Claim Reference Id	: TD6217-1-1-486
File Name	: PHOTO39
File Date	: 12/17/2025
Label	: TD6217-1-1-486 Damage 3 2025.5429
Note	: Style:2019,KENW,KENWORTH CONSTRUCTION T880 LossDate:11/26/2025 PolicyNumber:FB9459 ClaimRepresentative:LITTLE VIN:1XKZDP9X2KJ302489 InsuranceCompany:ACUITY, A MUTUAL INSURANCE COMPANY InsuredIsOwner:Y Estimator:John,Marsh
Photo Location	:
Photo Taken By	: John Marsh
Estimate Indicator	: E01



Claim Reference Id	: TD6217-1-1-486
File Name	: PHOTO40
File Date	: 12/17/2025
Label	: TD6217-1-1-486 Damage 1 2025.5429
Note	: Style:2019,KENW,KENWORTH CONSTRUCTION T880 LossDate:11/26/2025 PolicyNumber:FB9459 ClaimRepresentative:LITTLE VIN:1XKZDP9X2KJ302489 InsuranceCompany:ACUITY, A MUTUAL INSURANCE COMPANY InsuredIsOwner:Y Estimator:John,Marsh
Photo Location	:
Photo Taken By	: John Marsh
Estimate Indicator	: E01



Claim Reference Id	: TD6217-1-1-486
File Name	: PHOTO41
File Date	: 12/17/2025
Label	: TD6217-1-1-486 Passenger Side Full View
Note	: Style:2019,KENW,KENWORTH CONSTRUCTION T880 LossDate:11/26/2025 PolicyNumber:FB9459 ClaimRepresentative:LITTLE VIN:1XKZDP9X2KJ302489 InsuranceCompany:ACUIITY, A MUTUAL INSURANCE COMPANY InsuredIsOwner:Y Estimator:John,Marsh
Photo Location	:
Photo Taken By	: John Marsh
Estimate Indicator	: E01



Claim Reference Id	: TD6217-1-1-486
File Name	: PHOTO42
File Date	: 12/17/2025
Label	: TD6217-1-1-486 Driver Side Front Corner
Note	: Style:2019,KENW,KENWORTH CONSTRUCTION T880 LossDate:11/26/2025 PolicyNumber:FB9459 ClaimRepresentative:LITTLE VIN:1XKZDP9X2KJ302489 InsuranceCompany:ACUIITY, A MUTUAL INSURANCE COMPANY InsuredIsOwner:Y Estimator:John,Marsh
Photo Location	:
Photo Taken By	: John Marsh
Estimate Indicator	: E01



Claim Reference Id	: TD6217-1-1-486
File Name	: PHOTO43
File Date	: 12/17/2025
Label	: TD6217-1-1-486 Passenger Side Front Wheel
Note	: Style:2019,KENW,KENWORTH CONSTRUCTION T880 LossDate:11/26/2025 PolicyNumber:FB9459 ClaimRepresentative:LITTLE VIN:1XKZDP9X2KJ302489 InsuranceCompany:ACUIITY, A MUTUAL INSURANCE COMPANY InsuredIsOwner:Y Estimator:John,Marsh
Photo Location	:
Photo Taken By	: John Marsh
Estimate Indicator	: E01



Claim Reference Id	: TD6217-1-1-486
File Name	: PHOTO44
File Date	: 12/17/2025
Label	: TD6217-1-1-486 Driver Side Full View 202
Note	: Style:2019,KENW,KENWORTH CONSTRUCTION T880 LossDate:11/26/2025 PolicyNumber:FB9459 ClaimRepresentative:LITTLE VIN:1XKZDP9X2KJ302489 InsuranceCompany:ACUIITY, A MUTUAL INSURANCE COMPANY InsuredIsOwner:Y Estimator:John,Marsh
Photo Location	:
Photo Taken By	: John Marsh
Estimate Indicator	: E01