

Sedgwick
131 Saundersville Road
Hendersonville, TN 37075

Phone: (615) 590-1550 Phone: (615) 000-0000

Address:	15972 County Rd 51	VIN:	JEE0093339
City/State/Zip:	La, Salle, CO 80645	Style:	Wheel Loader
Phone:	- -	Plate/State:	-
Cell Phone:	- -	WMI:	FIN:
Purchase Order:		Odometer:	
Customer Number:	069710001273	Color:	
Claim Contact:	Pierson Chandler	Date Of Loss:	12/16/2025
Contact Title:	Insured	Authorized By:	
Contact Phone:	(970) 590-8615 x	Claim Number:	0AB484307
Contact Email:	pierson.c@humalfa.com	RO:	



Photo of Front



Photo of Front Left



Photo of Left



Photo of Rear Left



Photo of Rear



Photo of Rear Right



Photo of Right

All body panels, engine, electrical, cooling, hydraulic, and intake have been damaged by fire. The only items untouched are the lift arms and front bucket. Equipment is an obvious total loss.

Photo of Front Right



Serial# JEE0093339



Model 821C



Unit 205



Left front tire, damaged by fire



Right front Tire, shows signs of heat damage




Left rear tire, completely damaged



Right rear tire, completely damaged.



Operators station, Complete and total burn



Operators Station

Can has been completely consumed and would need replacing. Due to the age of the machine it is considered obsolete by the manufacture and parts availability is extremely limited. Aftermarket, or used parts would have to be sourced for any type of repairs.



Damage



Damage



electrical compartment under the cab. all electrical harnessed, gauges and sensors have been destroyed.



The cooling system has been destroyed.



Area behind cab. Part of the cooling system, all damaged



rear of the machine where the radiator, charge air cooler, and oil coolers are housed. all damaged.



Air intake system, fuel lines, coolant lines, and wiring all damaged.



Damage



engine is a total burn

Damage



engine damage



wiring damage



More damage to the electrical system



area where the equipment articulates.
All bearings, joints and seals have been damaged




200_10+15972_county_road_51_lasalle_co.jpg




Hydraulics, transmission, and drive train have been subject to fire damage



200_12+15972_county_road_51_lasalle_co.jpg



Hydraulic lines and coolers are all damaged.



more damage to the hydraulic system

Right side of the engine. The injection pump had been subject to excessive heat as well as the hard fuel lines.