



## Transportation Truck & Cargo Adjusters

4500 South 129th East Avenue, Suite 132 East

Tulsa, OK 74134

Phone: (918) 455-3900 Fax: (918) 455-7460

Date: 12/18/2025  
Reference #: 037540014422  
Estimated By: Kendal Berry  
Name: Marlon Guillermo Casado Alcantara

Year: 2006  
Make: FREIGHTLINER  
Model: CST120  
Unit #:

Address:   
City/State/Zip: ,   
Phone: - -   
Inspected Date:   
Claimant:   
Date of Loss: 2/2/2025  
Claim Contact:   
Contact Title:   
Contact Phone: x  
Contact Email:

VIN: 1FUJBBCKX6LX07985  
Style: MDHD: Conventional  
Plate/State: -  
WMI: FIN:   
Odometer:   
Color:   
Date Of Loss: 2/2/2025  
Inspected At:   
Claim Number: 144.384  
File Number: 2700.2679

Operation	Description	Part #	Type	Labor	Paint	-----Parts-----	Misc
----- Cab Exterior Mid and Raised Roof -----							
1	Replace	Raised Roof Cab Assembly	New	46.00	36.00	1 @ \$15,533.89	\$15,533.89
2	* Replace	Freon - 134a	Mtrl's AddPrt			3 @ \$16.74	\$50.22
3		Add for Inside - Raised Roof Cab Assembly	AddPnt		12.00		
4	Replace	Rear Cab Mount (Left)	New	0.30		1 @ \$89.12	\$89.12
5	Replace	Rear Cab Mount (Right)	New	2.00		1 @ \$91.49	\$91.49
6	Replace	Air Spring Front (Left)	New	0.70		1 @ \$68.41	\$68.41
7	Replace	Air Spring Front (Right)	New	0.70		1 @ \$71.69	\$71.69
8	Replace	Cab Shock (Left)	New	0.40		1 @ \$51.53	\$51.53
9	Replace	Cab Shock (Right)	New	0.40		1 @ \$50.71	\$50.71
10	Replace	Decals	New			1 @ \$123.89	\$123.89
----- Cab Extenders -----							
11	Replace	Cab Extender (Left)	New	0.70	1.80	1 @ \$227.72	\$227.72
12		Cab Extender (Left) to Raised Roof Cab Assembly	Adj		-0.40		
13	* Replace	Nut Zert(s)	Mtrl's AddPrt			1 @ \$0.36	\$0.36
14		Add for Inside - Cab Extender (Left)	AddPnt		0.70		
15	Replace	Left Cab Extender Bracket (Each)	New	0.20		1 @ \$49.92	\$49.92
16	Replace	Rubber Edge Extender (Left)	New	0.50		1 @ \$53.31	\$53.31
17	Replace	Upper Rubber Edge (Left)	New	0.30		1 @ \$32.84	\$32.84
18	Replace	Upper Extender (Left)	New	0.50	1.00	1 @ \$201.60	\$201.60
19		Non-Adjacent Overlap	Adj		-0.20		
20		Add for Inside - Upper Extender (Left)	AddPnt		0.60		
21	Replace	Upper Extender Bracket (Left)	New M			1 @ \$37.84	\$37.84
22	Replace	Long Grab Handle (Left)	New	0.70		1 @ \$64.88	\$64.88
----- Frame -----							
23	* Repair	Adjust Front & Rear Alignment		M 3.50			
24	* Repair	Set Up and Measure Frame		F 3.00			





## Transportation Truck & Cargo Adjusters

4500 South 129th East Avenue, Suite 132 East

Tulsa, OK 74134

Phone: (918) 455-3900 Fax: (918) 455-7460

Date:	12/18/2025	Year:	2006
Reference #:	037540014422	Make:	FREIGHTLINER
Estimated By:	Kendal Berry	Model:	CST120
Name:	Marlon Guillermo Casado Alcantara	Unit #:	

Operation	Description	Part #	Type	Labor	Paint	-----Parts-----	Misc
----- Drive Shaft w/o Carrier Bearing -----							
25	R&I	Drive Shaft Assembly		M	1.50		
----- Freight & Delivery -----							
26	Replace	Freight & Delivery Charges	New			1 @ \$363.28	\$363.28
----- Maintenance & Service -----							
27	* Repair	Road Test		M	1.00		
28	* Repair	Tow In		M	1.50		
----- Calculated Values -----							
29	^	Shop Supplies	Mtrl's				\$614.00
30	^	Hazardous Waste					\$15.00
31	^	Two stage paint.			15.00		
32	^	Paint Materials	Mtrl's				\$4,890.00

An '\*' indicates user change of database part and '^' indicates manually entered or custom database rows.

### Estimate Notes:

Summary	Amount	Rate	Disc	Total
Body Labor	53.4	\$125.00	0.00%	\$6,675.00
Paint Labor	66.5	\$125.00	0.00%	\$8,312.50
Mechanical	7.5	\$170.00	0.00%	\$1,275.00
Frame	3.0	\$125.00	0.00%	\$375.00
Misc. Labor	0.0	\$0.00	0.00%	\$0.00
Parts	\$17,162.70		0.00%	\$17,162.70
Misc.				\$5,519.00
Sub-total				\$39,319.20
Sales Tax	State (Parts, Materials) \$22,681.70 @ 8.2500%: \$1,871.24			1,871.24

Total	\$41,190.44
Betterment	\$0.00
Deductible	\$0.00
Grand Total	\$41,190.44





**Transportation Truck & Cargo Adjusters**

**4500 South 129th East Avenue, Suite 132 East  
Tulsa, OK 74134**

**Phone: (918) 455-3900 Fax: (918) 455-7460**

Date:	12/18/2025	Year:	2006
Reference #:	037540014422	Make:	FREIGHTLINER
Estimated By:	Kendal Berry	Model:	CST120
Name:	Marlon Guillermo Casado Alcantara	Unit #:	

---

Repair Facility:

Address:

Phone: '()  
( ) -

Email:

Agreed With:

License 1:

License 2:

Fed Tax ID:

Registration #:

Appraised By: Kendal Berry

License #1:

License #2:

Phone: 918-455-3900

Email: kendal.berry@us.davis-group.com





## Transportation Truck & Cargo Adjusters

4500 South 129th East Avenue, Suite 132 East

Tulsa, OK 74134

Phone: (918) 455-3900 Fax: (918) 455-7460

Date:	12/18/2025	Year:	2006
Reference #:	037540014422	Make:	FREIGHTLINER
Estimated By:	Kendal Berry	Model:	CST120
Name:	Marlon Guillermo Casado Alcantara	Unit #:	

---

### TERMS & CONDITIONS

The above is an estimate based on inspection and does not cover additional parts or labor which may be required after the work has been started. Occasionally worn or damaged parts are discovered which may not have been evident on the first inspection. Because of this, the above prices are not guaranteed. Quotations on parts and labor are current and subject to change.

Signed \_\_\_\_\_ Date \_\_\_\_\_



December 18, 2025

## First Report

c/o Davies Group - Austin  
c/o Davies Claims North America, Inc. 4500 South 129th East Avenue, Suite 132 East  
Tulsa, OK 74134

Re:	Named Insured	:	Marlon Guillermo Casado Alcantara
	Date of Loss	:	12/02/2025
	Company Claim #	:	144.384
	Our File #	:	2700.2679
	Vehicle Description	:	2006 Freightliner Tractor, VIN: LX07985

## COVERAGE

Our assignment notes the involved vehicle as a 2006 Freightliner tractor, VIN: 1FUJBBCKX6LX07985. We note a Stated Limit of \$20,000.00 subject to a deductible of \$1,000.00.0

## DAMAGES

We are in receipt of the photographs provided by your office. The photographs document collision damage to the left rear of the tractor. The scope of the damage includes the cab/sleeper assembly, cab mounts, air springs, shocks, decals, cab extender panel, brackets, upper extender, brackets, grab handle, rubber edge, frame and alignment.

Enclosed is an appraisal for the visible damage in the amount of \$41,190.44. We would anticipate supplemental damage should a tear down inspection be performed. We searched online for comparable tractors and located units with resale values ranging from \$10,000.00 to \$20,000.00. The tractor is a total loss.

## FURTHER WORK

We are closing our file at this time. Thank you for allowing us to be of service. If we can be of any further assistance, please advise.

Sincerely,

***Kendall Berry***

Kendall Berry  
[kendal.berry@us.davies-group.com](mailto:kendal.berry@us.davies-group.com)













ASSED TO:



Hazleton, PA  
T. 3666666  
F. 1269820-C  
GVW.80,000

EXTINGUISHER INSIDE



DRIVER USING  
ELECTRONIC LOGS

KEEP IT QUICKER



KYU 699289

CENTURY  
CLASS 57









KYU 699289











 **Required**  
When Entering & E



**E** **CENTURY**  
**CLASS S/T**













