

## Claim Photo

**Our File Number:** 297-018003  
**Adjuster:** Scott Syner  
**Insured:** Stearns Dumpster Service LLC  
**Date of Loss:** 12/26/2025  
**Customer File Number:** 25AQ1-03890  
**Policy Number:**



### Photo: 1

**Date Taken:**  
12/30/2025

**Taken By:**  
Clifton Bush

**Description:**  
The front of the  
insured vehicle



### Photo: 2

**Date Taken:**  
12/30/2025

**Taken By:**  
Clifton Bush

**Description:**  
The left front

## Claim Photo

**Our File Number:** 297-018003  
**Adjuster:** Scott Syner  
**Insured:** Stearns Dumpster Service LLC  
**Date of Loss:** 12/26/2025  
**Customer File Number:** 25AQ1-03890  
**Policy Number:**



**Photo: 3**

**Date Taken:**  
12/30/2025

**Taken By:**  
Clifton Bush

**Description:**  
The left rear of the insured vehicle



**Photo: 4**

**Date Taken:**  
12/30/2025

**Taken By:**  
Clifton Bush

**Description:**  
The rear of the vehicle



## Claim Photo

**Our File Number:** 297-018003  
**Adjuster:** Scott Syner  
**Insured:** Stearns Dumpster Service LLC  
**Date of Loss:** 12/26/2025  
**Customer File Number:** 25AQ1-03890  
**Policy Number:**




**Photo: 5**

**Date Taken:**  
12/30/2025

**Taken By:**  
Clifton Bush

**Description:**  
The right front of  
the vehicle



**Photo: 6**

**Date Taken:**  
12/30/2025

**Taken By:**  
Clifton Bush

**Description:**  
The emission  
control sticker

Claim Photo

Our File Number: 297-018003  
Adjuster: Scott Syner  
Insured: Stearns Dumpster Service LLC  
Date of Loss: 12/26/2025  
Customer File Number: 25AQ1-03890  
Policy Number:




Photo: 7

Date Taken: 12/30/2025

Taken By: Clifton Bush

Description: The vin plate for the insured vehicle




Photo: 8

Date Taken: 12/30/2025

Taken By: Clifton Bush

Description: The tire chart for the vehicle



## Claim Photo

**Our File Number:** 297-018003  
**Adjuster:** Scott Syner  
**Insured:** Stearns Dumpster Service LLC  
**Date of Loss:** 12/26/2025  
**Customer File Number:** 25AQ1-03890  
**Policy Number:**



**Photo: 9**

**Date Taken:**  
12/30/2025

**Taken By:**  
Clifton Bush

**Description:**  
The truck number



**Photo: 10**

**Date Taken:**  
12/30/2025

**Taken By:**  
Clifton Bush

**Description:**  
The US DOT  
number and logo



## Claim Photo

**Our File Number:** 297-018003  
**Adjuster:** Scott Syner  
**Insured:** Stearns Dumpster Service LLC  
**Date of Loss:** 12/26/2025  
**Customer File Number:** 25AQ1-03890  
**Policy Number:**



**Photo: 11**

**Date Taken:**  
12/30/2025

**Taken By:**  
Clifton Bush

**Description:**  
The tool box on the  
left side of the  
vehicle



**Photo: 12**

**Date Taken:**  
12/30/2025

**Taken By:**  
Clifton Bush

**Description:**  
The right tandem  
tires



## Claim Photo

**Our File Number:** 297-018003  
**Adjuster:** Scott Syner  
**Insured:** Stearns Dumpster Service LLC  
**Date of Loss:** 12/26/2025  
**Customer File Number:** 25AQ1-03890  
**Policy Number:**



**Photo: 13**

**Date Taken:**  
12/30/2025

**Taken By:**  
Clifton Bush

**Description:**  
An overview of the  
right rear tires with  
fire damage



**Photo: 14**

**Date Taken:**  
12/30/2025

**Taken By:**  
Clifton Bush

**Description:**  
The area behind the  
right tandem tires  
with wires burned

## Claim Photo

**Our File Number:** 297-018003  
**Adjuster:** Scott Syner  
**Insured:** Stearns Dumpster Service LLC  
**Date of Loss:** 12/26/2025  
**Customer File Number:** 25AQ1-03890  
**Policy Number:**



**Photo: 15**

**Date Taken:**  
12/30/2025

**Taken By:**  
Clifton Bush

**Description:**  
A view of the right  
tire away from the  
wheel



**Photo: 16**

**Date Taken:**  
12/30/2025

**Taken By:**  
Clifton Bush

**Description:**  
A view of the tire  
and wheel damage  
from the fire



## Claim Photo

**Our File Number:** 297-018003  
**Adjuster:** Scott Syner  
**Insured:** Stearns Dumpster Service LLC  
**Date of Loss:** 12/26/2025  
**Customer File Number:** 25AQ1-03890  
**Policy Number:**




**Photo: 17**

**Date Taken:**  
12/30/2025

**Taken By:**  
Clifton Bush

**Description:**  
A view of the right  
tandem tires with  
burn marks



**Photo: 18**

**Date Taken:**  
12/30/2025

**Taken By:**  
Clifton Bush

**Description:**  
A view of the right  
frame

## Claim Photo

**Our File Number:** 297-018003  
**Adjuster:** Scott Syner  
**Insured:** Stearns Dumpster Service LLC  
**Date of Loss:** 12/26/2025  
**Customer File Number:** 25AQ1-03890  
**Policy Number:**



**Photo: 19**

**Date Taken:**  
12/30/2025

**Taken By:**  
Clifton Bush

**Description:**  
A view of the right  
side tool box



**Photo: 20**

**Date Taken:**  
12/30/2025

**Taken By:**  
Clifton Bush

**Description:**  
Another view of the  
right rear



## Claim Photo

**Our File Number:** 297-018003  
**Adjuster:** Scott Syner  
**Insured:** Stearns Dumpster Service LLC  
**Date of Loss:** 12/26/2025  
**Customer File Number:** 25AQ1-03890  
**Policy Number:**



**Photo: 21**

**Date Taken:**  
12/30/2025

**Taken By:**  
Clifton Bush

**Description:**  
An overview of the  
right rear



**Photo: 22**

**Date Taken:**  
12/30/2025

**Taken By:**  
Clifton Bush

**Description:**  
Another view of the  
damage behind the  
tires



## Claim Photo

**Our File Number:** 297-018003  
**Adjuster:** Scott Syner  
**Insured:** Stearns Dumpster Service LLC  
**Date of Loss:** 12/26/2025  
**Customer File Number:** 25AQ1-03890  
**Policy Number:**



**Photo: 23**

**Date Taken:**  
12/30/2025

**Taken By:**  
Clifton Bush

**Description:**  
A view of the  
burned pump on the  
right rear of the  
vehicle



**Photo: 24**

**Date Taken:**  
12/30/2025

**Taken By:**  
Clifton Bush

**Description:**  
Another view of the  
damaged pump



## Claim Photo

**Our File Number:** 297-018003  
**Adjuster:** Scott Syner  
**Insured:** Stearns Dumpster Service LLC  
**Date of Loss:** 12/26/2025  
**Customer File Number:** 25AQ1-03890  
**Policy Number:**



**Photo: 25**

**Date Taken:**  
12/30/2025

**Taken By:**  
Clifton Bush

**Description:**  
A view of the  
damage to the right  
rear



**Photo: 26**

**Date Taken:**  
12/30/2025

**Taken By:**  
Clifton Bush

**Description:**  
A view of the frame  
and wires



## Claim Photo

**Our File Number:** 297-018003  
**Adjuster:** Scott Syner  
**Insured:** Stearns Dumpster Service LLC  
**Date of Loss:** 12/26/2025  
**Customer File Number:** 25AQ1-03890  
**Policy Number:**



**Photo: 27**

**Date Taken:**  
12/30/2025

**Taken By:**  
Clifton Bush

**Description:**  
A view of the pipe  
behind the toolbox



**Photo: 28**

**Date Taken:**  
12/30/2025

**Taken By:**  
Clifton Bush

**Description:**  
A view of the wires  
in the middle of the  
frame



## Claim Photo

**Our File Number:** 297-018003  
**Adjuster:** Scott Syner  
**Insured:** Stearns Dumpster Service LLC  
**Date of Loss:** 12/26/2025  
**Customer File Number:** 25AQ1-03890  
**Policy Number:**



**Photo: 29**

**Date Taken:**  
12/30/2025

**Taken By:**  
Clifton Bush

**Description:**  
The tire size



**Photo: 30**

**Date Taken:**  
12/30/2025

**Taken By:**  
Clifton Bush

**Description:**  
A view of the  
cables on the rear  
of the cab did not  
appear damaged

## Claim Photo

**Our File Number:** 297-018003  
**Adjuster:** Scott Syner  
**Insured:** Stearns Dumpster Service LLC  
**Date of Loss:** 12/26/2025  
**Customer File Number:** 25AQ1-03890  
**Policy Number:**



**Photo: 31**

**Date Taken:**  
12/30/2025

**Taken By:**  
Clifton Bush

**Description:**  
The make of the  
vehicle



**Photo: 32**

**Date Taken:**  
12/30/2025

**Taken By:**  
Clifton Bush

**Description:**  
The model of the  
insured vehicle



## Claim Photo

**Our File Number:** 297-018003  
**Adjuster:** Scott Syner  
**Insured:** Stearns Dumpster Service LLC  
**Date of Loss:** 12/26/2025  
**Customer File Number:** 25AQ1-03890  
**Policy Number:**



**Photo: 33**

**Date Taken:**  
12/30/2025

**Taken By:**  
Clifton Bush

**Description:**  
The mileage for the  
vehicle