

Photo Sheet

Insured: Jay Ray Wilson
Claim #: CR100053
Policy #: RT-PD-042024-011401



1-IMG_4192

Date Taken: 12/8/2025

Overview



2-IMG_4193

Date Taken: 12/8/2025

Prior damage to front corner

Photo Sheet

Insured: Jay Ray Wilson
Claim #: CR100053
Policy #: RT-PD-042024-011401



3-IMG_4194

Date Taken: 12/8/2025

Overview



4-IMG_4195

Date Taken: 12/8/2025

Overview

Photo Sheet


Insured: Jay Ray Wilson
Claim #: CR100053
Policy #: RT-PD-042024-011401



5-IMG_4200

Date Taken: 12/8/2025

Overview



6-IMG_4196

Date Taken: 12/8/2025


No visible damage to swing arm

Photo Sheet

Insured: Jay Ray Wilson
Claim #: CR100053
Policy #: RT-PD-042024-011401



7-IMG_4197
Date Taken: 12/8/2025
T-65 is the trailer #



8-IMG_4198
Date Taken: 12/8/2025
Make model plaque

Photo Sheet

Insured: Jay Ray Wilson
Claim #: CR100053
Policy #: RT-PD-042024-011401




9-IMG_4199
Date Taken: 12/8/2025
Inspection tag



10-IMG_4201
Date Taken: 12/8/2025
Front section of rear axel

Photo Sheet


Insured: Jay Ray Wilson
Claim #: CR100053
Policy #: RT-PD-042024-011401



11-IMG_4202

Date Taken: 12/8/2025

Overview



12-IMG_4203

Date Taken: 12/8/2025

Sidewall bent

Photo Sheet

Insured: Jay Ray Wilson
Claim #: CR100053
Policy #: RT-PD-042024-011401



13-IMG_4204

Date Taken: 12/8/2025

Overview of trailer bed



14-IMG_4205

Date Taken: 12/8/2025

Bent sidewall

Photo Sheet


Insured: Jay Ray Wilson
Claim #: CR100053
Policy #: RT-PD-042024-011401



15-IMG_4211

Date Taken: 12/8/2025

Sidewall overview




16-IMG_4210

Date Taken: 12/8/2025

Overview of lower rear trailer section

Photo Sheet

Insured: Jay Ray Wilson
Claim #: CR100053
Policy #: RT-PD-042024-011401



17-IMG_4206

Date Taken: 12/8/2025

Bent Framing



18-IMG_4207

Date Taken: 12/8/2025

Bent Framing

Photo Sheet


Insured: Jay Ray Wilson
Claim #: CR100053
Policy #: RT-PD-042024-011401



19-IMG_4208

Date Taken: 12/8/2025

Bent Framing



20-IMG_4212

Date Taken: 12/8/2025

Bent aluminium sidewall where bed
attaches to frame

Photo Sheet

Insured: Jay Ray Wilson
Claim #: CR100053
Policy #: RT-PD-042024-011401



21-IMG_4209

Date Taken: 12/8/2025

Section of rear tire cut from tain



22-IMG_4213

Date Taken: 12/8/2025

Tailgate overview

Photo Sheet

Insured: Jay Ray Wilson
Claim #: CR100053
Policy #: RT-PD-042024-011401



23-IMG_4216

Date Taken: 12/8/2025

Overview



24-IMG_4214

Date Taken: 12/8/2025

Impact damage to tailgate

Photo Sheet

Insured: Jay Ray Wilson
Claim #: CR100053
Policy #: RT-PD-042024-011401



25-IMG_4215

Date Taken: 12/8/2025

Impact damage to tailgate



26-IMG_4217

Date Taken: 12/8/2025

T-65 tailgate matched trailer #