

Claim Photo

Our File Number: 277-065367
Adjuster: Scott Syner
Insured: RODNEY MERRILL 431989
Date of Loss: 12/01/2025
Customer File Number: 000786-091522-AP-01
Policy Number:



Photo: 1

Date Taken:
12/15/2025

Taken By:
Andrew Wurth

Description:
Damaged insured
tractor front.



Photo: 2

Date Taken:
12/15/2025

Taken By:
Andrew Wurth

Description:
Front driver corner.

Claim Photo

Our File Number: 277-065367
Adjuster: Scott Syner
Insured: RODNEY MERRILL 431989
Date of Loss: 12/01/2025
Customer File Number: 000786-091522-AP-01
Policy Number:




Photo: 3

Date Taken:
12/15/2025

Taken By:
Andrew Wurth

Description:
Front driver side.




Photo: 4

Date Taken:
12/15/2025

Taken By:
Andrew Wurth

Description:
Driver side.

Claim Photo

Our File Number: 277-065367
Adjuster: Scott Syner
Insured: RODNEY MERRILL 431989
Date of Loss: 12/01/2025
Customer File Number: 000786-091522-AP-01
Policy Number:



Photo: 5

Date Taken:
12/15/2025

Taken By:
Andrew Wurth

Description:
Driver side door
and mirror.




Photo: 6

Date Taken:
12/15/2025

Taken By:
Andrew Wurth

Description:
Low driver side.

Claim Photo

Our File Number: 277-065367
Adjuster: Scott Syner
Insured: RODNEY MERRILL 431989
Date of Loss: 12/01/2025
Customer File Number: 000786-091522-AP-01
Policy Number:



Photo: 7

Date Taken:
12/15/2025

Taken By:
Andrew Wurth

Description:
Driver side.




Photo: 8

Date Taken:
12/15/2025

Taken By:
Andrew Wurth

Description:
Driver side.

Claim Photo

Our File Number: 277-065367
Adjuster: Scott Syner
Insured: RODNEY MERRILL 431989
Date of Loss: 12/01/2025
Customer File Number: 000786-091522-AP-01
Policy Number:




Photo: 9

Date Taken:
12/15/2025

Taken By:
Andrew Wurth

Description:
Driver side.




Photo: 10

Date Taken:
12/15/2025

Taken By:
Andrew Wurth

Description:
Rear driver side
tires.

Claim Photo

Our File Number: 277-065367
Adjuster: Scott Syner
Insured: RODNEY MERRILL 431989
Date of Loss: 12/01/2025
Customer File Number: 000786-091522-AP-01
Policy Number:



Photo: 11

Date Taken:
12/15/2025

Taken By:
Andrew Wurth

Description:
Low rear passenger
corner.




Photo: 12

Date Taken:
12/15/2025

Taken By:
Andrew Wurth

Description:
Tractor rear.

Claim Photo

Our File Number: 277-065367
Adjuster: Scott Syner
Insured: RODNEY MERRILL 431989
Date of Loss: 12/01/2025
Customer File Number: 000786-091522-AP-01
Policy Number:




Photo: 13

Date Taken:
12/15/2025

Taken By:
Andrew Wurth

Description:
Tractor rear
showing fifth
wheel.




Photo: 14

Date Taken:
12/15/2025

Taken By:
Andrew Wurth

Description:
Low rear passenger
corner.

Claim Photo

Our File Number: 277-065367
Adjuster: Scott Syner
Insured: RODNEY MERRILL 431989
Date of Loss: 12/01/2025
Customer File Number: 000786-091522-AP-01
Policy Number:



Photo: 15

Date Taken:
12/15/2025

Taken By:
Andrew Wurth

Description:
Rear passenger
tires.




Photo: 16

Date Taken:
12/15/2025

Taken By:
Andrew Wurth

Description:
Low rear passenger
corner of tractor
cab.

Claim Photo

Our File Number: 277-065367
Adjuster: Scott Syner
Insured: RODNEY MERRILL 431989
Date of Loss: 12/01/2025
Customer File Number: 000786-091522-AP-01
Policy Number:




Photo: 17

Date Taken:
12/15/2025

Taken By:
Andrew Wurth

Description:
Rear of tractor cab.




Photo: 18

Date Taken:
12/15/2025

Taken By:
Andrew Wurth

Description:
Passenger side.

Claim Photo

Our File Number: 277-065367
Adjuster: Scott Syner
Insured: RODNEY MERRILL 431989
Date of Loss: 12/01/2025
Customer File Number: 000786-091522-AP-01
Policy Number:



Photo: 19

Date Taken:
12/15/2025

Taken By:
Andrew Wurth

Description:
Passenger side.



Photo: 20

Date Taken:
12/15/2025

Taken By:
Andrew Wurth

Description:
Passenger side.

Claim Photo

Our File Number: 277-065367
Adjuster: Scott Syner
Insured: RODNEY MERRILL 431989
Date of Loss: 12/01/2025
Customer File Number: 000786-091522-AP-01
Policy Number:



Photo: 21

Date Taken:
12/15/2025

Taken By:
Andrew Wurth

Description:
Passenger side.



Photo: 22

Date Taken:
12/15/2025

Taken By:
Andrew Wurth

Description:
Passenger side.

Claim Photo

Our File Number: 277-065367
Adjuster: Scott Syner
Insured: RODNEY MERRILL 431989
Date of Loss: 12/01/2025
Customer File Number: 000786-091522-AP-01
Policy Number:



Photo: 23

Date Taken:
12/15/2025

Taken By:
Andrew Wurth

Description:
Front passenger
corner.




Photo: 24

Date Taken:
12/15/2025

Taken By:
Andrew Wurth

Description:
Close-up of
damage to tractor
front.

Claim Photo

Our File Number: 277-065367
Adjuster: Scott Syner
Insured: RODNEY MERRILL 431989
Date of Loss: 12/01/2025
Customer File Number: 000786-091522-AP-01
Policy Number:



Photo: 25

Date Taken:
12/15/2025

Taken By:
Andrew Wurth

Description:
Close-up of
damage to tractor
front.




Photo: 26

Date Taken:
12/15/2025

Taken By:
Andrew Wurth

Description:
Close-up of
damage to tractor
front.

Claim Photo

Our File Number: 277-065367
Adjuster: Scott Syner
Insured: RODNEY MERRILL 431989
Date of Loss: 12/01/2025
Customer File Number: 000786-091522-AP-01
Policy Number:




Photo: 27

Date Taken:
12/15/2025

Taken By:
Andrew Wurth

Description:
Close-up of
damage to tractor
front.




Photo: 28

Date Taken:
12/15/2025

Taken By:
Andrew Wurth

Description:
Tractor interior.

Claim Photo

Our File Number: 277-065367
Adjuster: Scott Syner
Insured: RODNEY MERRILL 431989
Date of Loss: 12/01/2025
Customer File Number: 000786-091522-AP-01
Policy Number:



Photo: 29

Date Taken:
12/15/2025

Taken By:
Andrew Wurth

Description:
Window lock
switch.




Photo: 30

Date Taken:
12/15/2025

Taken By:
Andrew Wurth

Description:
Front dash/steering
wheel.

Claim Photo

Our File Number: 277-065367
Adjuster: Scott Syner
Insured: RODNEY MERRILL 431989
Date of Loss: 12/01/2025
Customer File Number: 000786-091522-AP-01
Policy Number:



Photo: 31

Date Taken:
12/15/2025

Taken By:
Andrew Wurth

Description:
Last 6 of VIN plate
on driver side door
frame.




Photo: 32

Date Taken:
12/15/2025

Taken By:
Andrew Wurth

Description:
Tire tread depth.

Claim Photo

Our File Number: 277-065367
Adjuster: Scott Syner
Insured: RODNEY MERRILL 431989
Date of Loss: 12/01/2025
Customer File Number: 000786-091522-AP-01
Policy Number:




Photo: 33

Date Taken:
12/15/2025

Taken By:
Andrew Wurth

Description:
Tire tread depth.




Photo: 34

Date Taken:
12/15/2025

Taken By:
Andrew Wurth

Description:
Tire tread depth.

Claim Photo

Our File Number: 277-065367
Adjuster: Scott Syner
Insured: RODNEY MERRILL 431989
Date of Loss: 12/01/2025
Customer File Number: 000786-091522-AP-01
Policy Number:




Photo: 35

Date Taken:
12/15/2025

Taken By:
Andrew Wurth

Description:
Tire tread depth.



Photo: 36

Date Taken:
12/15/2025

Taken By:
Andrew Wurth

Description:
Tire tread depth.

Claim Photo

Our File Number: 277-065367
Adjuster: Scott Syner
Insured: RODNEY MERRILL 431989
Date of Loss: 12/01/2025
Customer File Number: 000786-091522-AP-01
Policy Number:




Photo: 37

Date Taken:
12/15/2025

Taken By:
Andrew Wurth

Description:
Tire tread depth.



Photo: 38

Date Taken:
12/15/2025

Taken By:
Andrew Wurth

Description:
Tire tread depth.

Claim Photo

Our File Number: 277-065367
Adjuster: Scott Syner
Insured: RODNEY MERRILL 431989
Date of Loss: 12/01/2025
Customer File Number: 000786-091522-AP-01
Policy Number:




Photo: 39

Date Taken:
12/15/2025

Taken By:
Andrew Wurth

Description:
Tire tread depth.



Photo: 40

Date Taken:
12/15/2025

Taken By:
Andrew Wurth

Description:
Tire tread depth.

Claim Photo

Our File Number: 277-065367
Adjuster: Scott Syner
Insured: RODNEY MERRILL 431989
Date of Loss: 12/01/2025
Customer File Number: 000786-091522-AP-01
Policy Number:



Photo: 41

Date Taken:
12/15/2025

Taken By:
Andrew Wurth

Description:
Tire tread depth.