



**Claim Photo**

**Our File Number:** 277-065073  
**Adjuster:** Scott Syner  
**Insured:** DYCOM INDUSTRIES  
**Date of Loss:** 10/24/2025  
**Customer File Number:** 009080-028639-AD-01  
**Policy Number:**



**Photo: 1**  
**Date Taken:** 11/25/2025  
**Taken By:** Matthew Fuller  
**Description:** VIN and model info.



**Photo: 2**  
**Date Taken:** 11/25/2025  
**Taken By:** Matthew Fuller  
**Description:** Tire info.

**Claim Photo**

**Our File Number:** 277-065073  
**Adjuster:** Scott Syner  
**Insured:** DYCOM INDUSTRIES  
**Date of Loss:** 10/24/2025  
**Customer File Number:** 009080-028639-AD-01  
**Policy Number:**



**Photo: 3**  
**Date Taken:** 11/25/2025  
**Taken By:** Matthew Fuller  
**Description:** Label info.



**Photo: 4**  
**Date Taken:** 11/25/2025  
**Taken By:** Matthew Fuller  
**Description:** Purchase location.

**Claim Photo**

**Our File Number:** 277-065073  
**Adjuster:** Scott Syner  
**Insured:** DYCOM INDUSTRIES  
**Date of Loss:** 10/24/2025  
**Customer File Number:** 009080-028639-AD-01  
**Policy Number:**



**Photo: 5**  
**Date Taken:** 11/25/2025  
**Taken By:** Matthew Fuller  
**Description:** Front view.



**Photo: 6**  
**Date Taken:** 11/25/2025  
**Taken By:** Matthew Fuller  
**Description:** D/S front angle.

**Claim Photo**

**Our File Number:** 277-065073  
**Adjuster:** Scott Syner  
**Insured:** DYCOM INDUSTRIES  
**Date of Loss:** 10/24/2025  
**Customer File Number:** 009080-028639-AD-01  
**Policy Number:**



**Photo: 7**  
**Date Taken:** 11/25/2025  
**Taken By:** Matthew Fuller  
**Description:** D/S landing gear broke.



**Photo: 8**  
**Date Taken:** 11/25/2025  
**Taken By:** Matthew Fuller  
**Description:** Backside view.

## Claim Photo

**Our File Number:** 277-065073  
**Adjuster:** Scott Syner  
**Insured:** DYCOM INDUSTRIES  
**Date of Loss:** 10/24/2025  
**Customer File Number:** 009080-028639-AD-01  
**Policy Number:**



**Photo: 9**

**Date Taken:**  
11/25/2025

**Taken By:**  
Matthew Fuller

**Description:**  
D/S fender bent and damaged.



**Photo: 10**

**Date Taken:**  
11/25/2025

**Taken By:**  
Matthew Fuller

**Description:**  
D/S tandems.

**Claim Photo**

**Our File Number:** 277-065073  
**Adjuster:** Scott Syner  
**Insured:** DYCOM INDUSTRIES  
**Date of Loss:** 10/24/2025  
**Customer File Number:** 009080-028639-AD-01  
**Policy Number:**



**Photo: 11**

**Date Taken:**  
11/25/2025

**Taken By:**  
Matthew Fuller

**Description:**  
D/S rear angle.



**Photo: 12**

**Date Taken:**  
11/25/2025

**Taken By:**  
Matthew Fuller

**Description:**  
Rear view.

## Claim Photo

**Our File Number:** 277-065073  
**Adjuster:** Scott Syner  
**Insured:** DYCOM INDUSTRIES  
**Date of Loss:** 10/24/2025  
**Customer File Number:** 009080-028639-AD-01  
**Policy Number:**



**Photo: 13**

**Date Taken:**  
11/25/2025

**Taken By:**  
Matthew Fuller

**Description:**  
P/S rear angle.



**Photo: 14**

**Date Taken:**  
11/25/2025

**Taken By:**  
Matthew Fuller

**Description:**  
P/S rear angles  
trailer floor warped.

**Claim Photo**

**Our File Number:** 277-065073  
**Adjuster:** Scott Syner  
**Insured:** DYCOM INDUSTRIES  
**Date of Loss:** 10/24/2025  
**Customer File Number:** 009080-028639-AD-01  
**Policy Number:**



**Photo: 15**  
**Date Taken:** 11/25/2025  
**Taken By:** Matthew Fuller  
**Description:** P/S rear angle around side frame.



**Photo: 16**  
**Date Taken:** 11/25/2025  
**Taken By:** Matthew Fuller  
**Description:** P/S damage around marker light:

**Claim Photo**

**Our File Number:** 277-065073  
**Adjuster:** Scott Syner  
**Insured:** DYCOM INDUSTRIES  
**Date of Loss:** 10/24/2025  
**Customer File Number:** 009080-028639-AD-01  
**Policy Number:**




**Photo: 17**

**Date Taken:** 11/25/2025

**Taken By:** Matthew Fuller

**Description:** P/S tandems.



**Photo: 18**

**Date Taken:** 11/25/2025

**Taken By:** Matthew Fuller

**Description:** Wheel torque specs.

**Claim Photo**

**Our File Number:** 277-065073  
**Adjuster:** Scott Syner  
**Insured:** DYCOM INDUSTRIES  
**Date of Loss:** 10/24/2025  
**Customer File Number:** 009080-028639-AD-01  
**Policy Number:**



**Photo: 19**  
**Date Taken:** 11/25/2025  
**Taken By:** Matthew Fuller  
**Description:** Random debris on trailer.




**Photo: 20**  
**Date Taken:** 11/25/2025  
**Taken By:** Matthew Fuller  
**Description:** P/S front angle.

**Claim Photo**

**Our File Number:** 277-065073  
**Adjuster:** Scott Syner  
**Insured:** DYCOM INDUSTRIES  
**Date of Loss:** 10/24/2025  
**Customer File Number:** 009080-028639-AD-01  
**Policy Number:**



**Photo: 21**  
**Date Taken:** 11/25/2025  
**Taken By:** Matthew Fuller  
**Description:** P/S view of axles.



**Photo: 22**  
**Date Taken:** 11/25/2025  
**Taken By:** Matthew Fuller  
**Description:** P/S suspension view.

**Claim Photo**

**Our File Number:** 277-065073  
**Adjuster:** Scott Syner  
**Insured:** DYCOM INDUSTRIES  
**Date of Loss:** 10/24/2025  
**Customer File Number:** 009080-028639-AD-01  
**Policy Number:**




**Photo: 23**

**Date Taken:**  
11/25/2025

**Taken By:**  
Matthew Fuller

**Description:**  
D/S view of axles.



**Photo: 24**

**Date Taken:**  
11/25/2025

**Taken By:**  
Matthew Fuller

**Description:**  
Title.

**Claim Photo**

**Our File Number:** 277-065073  
**Adjuster:** Scott Syner  
**Insured:** DYCOM INDUSTRIES  
**Date of Loss:** 10/24/2025  
**Customer File Number:** 009080-028639-AD-01  
**Policy Number:**



**Photo: 25**

**Date Taken:**  
11/25/2025

**Taken By:**  
Matthew Fuller

**Description:**  
D/S front  
tire/wheel.



**Photo: 26**

**Date Taken:**  
11/25/2025

**Taken By:**  
Matthew Fuller

**Description:**  
Tire size.

**Claim Photo**

**Our File Number:** 277-065073  
**Adjuster:** Scott Syner  
**Insured:** DYCOM INDUSTRIES  
**Date of Loss:** 10/24/2025  
**Customer File Number:** 009080-028639-AD-01  
**Policy Number:**



**Photo: 27**  
**Date Taken:** 11/25/2025  
**Taken By:** Matthew Fuller  
**Description:** D/S front tire.



**Photo: 28**  
**Date Taken:** 11/25/2025  
**Taken By:** Matthew Fuller  
**Description:** D/S rear tire/wheel.

**Claim Photo**

**Our File Number:** 277-065073  
**Adjuster:** Scott Syner  
**Insured:** DYCOM INDUSTRIES  
**Date of Loss:** 10/24/2025  
**Customer File Number:** 009080-028639-AD-01  
**Policy Number:**



**Photo: 29**  
**Date Taken:** 11/25/2025  
**Taken By:** Matthew Fuller  
**Description:** D/S rear tire.



**Photo: 30**  
**Date Taken:** 11/25/2025  
**Taken By:** Matthew Fuller  
**Description:** P/S rear tire/wheel.

**Claim Photo**

**Our File Number:** 277-065073  
**Adjuster:** Scott Syner  
**Insured:** DYCOM INDUSTRIES  
**Date of Loss:** 10/24/2025  
**Customer File Number:** 009080-028639-AD-01  
**Policy Number:**



**Photo: 31**  
**Date Taken:** 11/25/2025  
**Taken By:** Matthew Fuller  
**Description:** P/S rear tire.



**Photo: 32**  
**Date Taken:** 11/25/2025  
**Taken By:** Matthew Fuller  
**Description:** P/S front tire/wheel.

**Claim Photo**

**Our File Number:** 277-065073  
**Adjuster:** Scott Syner  
**Insured:** DYCOM INDUSTRIES  
**Date of Loss:** 10/24/2025  
**Customer File Number:** 009080-028639-AD-01  
**Policy Number:**



**Photo: 33**  
**Date Taken:** 11/25/2025  
**Taken By:** Matthew Fuller  
**Description:** P/S front tire.