

1 1-Front

Date Taken: 2/9/2026

Taken By: Ian Wright

Front



2 2-Front left

Date Taken: 2/9/2026

Taken By: Ian Wright

Front left



3 3-Left side

Date Taken: 2/9/2026

Taken By: Ian Wright

Left side




4 4-Left side

Date Taken: 2/9/2026

Taken By: Ian Wright

Left side



5 5-Left side

Date Taken: 2/9/2026

Taken By: Ian Wright

Left side



6 6-Back left side

Date Taken: 2/9/2026

Taken By: Ian Wright

Back left side



7 7-Back

Date Taken: 2/9/2026

Taken By: Ian Wright

Back



8 8-Back right side

Date Taken: 2/9/2026

Taken By: Ian Wright

Back right side



9 9-Right side

Date Taken: 2/9/2026

Taken By: Ian Wright

Right side



10 10-Right side

Date Taken: 2/9/2026

Taken By: Ian Wright

Right side



11 11-Front right side

Date Taken: 2/9/2026

Taken By: Ian Wright

Front right side




12 12-Damage left front quarter panel

Date Taken: 2/9/2026

Taken By: Ian Wright

Damage left front quarter panel



13 13-Damage steering

Date Taken: 2/9/2026

Taken By: Ian Wright

Damage steering




14 14-Damage windshield

Date Taken: 2/9/2026

Taken By: Ian Wright

Damage windshield




15 15-Damage left side door

Date Taken: 2/9/2026

Taken By: Ian Wright

Damage left side door



16 16-Vin sticker

Date Taken: 2/9/2026

Taken By: Ian Wright

Vin sticker



17 17-Interior

Date Taken: 2/9/2026

Taken By: Ian Wright

Interior




18 18-Interior

Date Taken: 2/9/2026

Taken By: Ian Wright

Interior




19 19-Interior

Date Taken: 2/9/2026

Taken By: Ian Wright

Interior



20 20-Damage back right side door

Date Taken: 2/9/2026

Taken By: Ian Wright

Damage back right side door



21 21-Damage back left side door

Date Taken: 2/9/2026

Taken By: Ian Wright

Damage back left side door




22 22-Interior

Date Taken: 2/9/2026

Taken By: Ian Wright

Interior



23 23-Damaged dashboard

Date Taken: 2/9/2026

Taken By: Ian Wright

Damaged dashboard



24 24-Left side door damage

Date Taken: 2/9/2026

Taken By: Ian Wright

Left side door damage



25 25-No odometer reading

Date Taken: 2/9/2026

Taken By: Ian Wright

No odometer reading




26 26-Left side damages

Date Taken: 2/9/2026

Taken By: Ian Wright

Left side damages



27 27-Left side bed damage

Date Taken: 2/9/2026

Taken By: Ian Wright

Left side bed damage




28 28-Fender well damages

Date Taken: 2/9/2026

Taken By: Ian Wright

Fender well damages



29 29-Tires and wheels

Date Taken: 2/9/2026

Taken By: Ian Wright

Tires and wheels



30 30-Damage bed

Date Taken: 2/9/2026

Taken By: Ian Wright

Damage bed




31 31-Damage rear bumper

Date Taken: 2/9/2026

Taken By: Ian Wright

Damage rear bumper



32 32-Damage rear bumper

Date Taken: 2/9/2026

Taken By: Ian Wright

Damage rear bumper



33 33-Damage rear bumper

Date Taken: 2/9/2026

Taken By: Ian Wright

Damage rear bump




34 34-Underneath the vehicle

Date Taken: 2/9/2026

Taken By: Ian Wright

Underneath the vehicle



35 35-Tires and wheels

Date Taken: 2/9/2026

Taken By: Ian Wright

Tires and wheels



36 36-Damage leaf springs

Date Taken: 2/9/2026

Taken By: Ian Wright

Damage leaf springs



37 38-right side front steering

Date Taken: 2/9/2026

Taken By: Ian Wright

right side front steering



38 39-Under front of vehicle

Date Taken: 2/9/2026

Taken By: Ian Wright

Under front of vehicle



39 40-Damage frame

Date Taken: 2/9/2026

Taken By: Ian Wright

Damage frame



40 41-Damage cab

Date Taken: 2/9/2026

Taken By: Ian Wright

Damage cab



41 37-Damage leaf springs

Date Taken: 2/9/2026

Taken By: Ian Wright

Damage leaf springs



42 42-Damage back windshield

Date Taken: 2/9/2026

Taken By: Ian Wright

Damage back windshield



43 43-Damage back windshield and cab

Date Taken: 2/9/2026

Taken By: Ian Wright

Damage back windshield and cab



44 44-Damage door frame

Date Taken: 2/9/2026

Taken By: Ian Wright

Damage door frame



45 45-Damage windshield

Date Taken: 2/9/2026

Taken By: Ian Wright

Damage windshield



46 46-Damage hood

Date Taken: 2/9/2026

Taken By: Ian Wright

Damage hood

