



Due upon receipt

INVOICE

INVOICE NUMBER	INVOICE DATE
046-0034584	02/09/2026

BILL TO

Attn: Victor Hernandez
LITTLETON GROUP
PO Box PO BOX 163627
AUSTIN TX 78716-3627

CLIENT CODE

LIT400003

BUSINESS LINE / LOSS TYPE

HE - Heavy Truck and Tractor

FOR INQUIRIES:

Bakersfield, CA (Corp) #046
Property Damage Appraisers, LLC
bakersfield@alacritysas.com
(866) 289-2029

SUBMIT PAYMENT TO:

Property Damage Ap
47-2172761
Dept #161, P.O. Box 1000
Memphis, TN 38148-0161

Please reference the invoice number and enclose a copy of the invoice on all payments.

INSURED	CLAIMANT	ASSIGNMENT DATE	ALACRITY ASSIGNMENT #
Jag Carrier		02/05/2026	046-602-0007
CLAIM #	POLICY #	LOSS DATE	REFERENCE #
118.1607	CUS062007037		

T&E: 4.80 hours @ \$139.00 \$ 667.20
Mileage: (9.00 miles) @ \$1.32 \$ 11.88



ACH Payment Info:

Bank: First Horizon Bank ABA
(US): 084000026 Bank
Account: 220002525824
Email Remit Information to:
achbackup@alacritysas.com

[Click here to pay your invoice at the client portal](#)

Same-Day Service. Guaranteed. Alacrity now offers expedited service for standard auto claims in select markets.

****WE HAVE CHANGED OUR BANK REMITTANCE INFORMATION AS NOTED ABOVE
PLEASE UTILIZE OUR PORTAL FOR ALL OTHER ELECTRONIC PAYMENTS.****

*A fuel surcharge of \$0.05/mile is included in the total invoice amount.
Terms: Professional fees due upon receipt. Interest accrues at 1% per
month. Please include the invoice number on all payments.*

TOTAL CHARGES:	679.08
	:
INVOICE TOTAL:	\$ 679.08



TIME AND EXPENSE FORM

DATE OF LOSS	CLAIM NUMBER	CLIENT	CLIENT CONTACT NAME		PDA FILE NUMBER
DATE	INSPECTION ACTIVITY	ADDITIONAL INFORMATION	TIME	TOTAL MILES TRAVELED	EXPENSE
Administrative Activity					
2/9/2026	Create / Setup New File		0.10		
2/9/2026	Acknowledge File Diary		0.10		
2/9/2026	Status Client		0.10		
2/9/2026	Prepare File for Upload to Client		0.20		
2/9/2026	Invoice File		0.10		
Appraiser Activity					
2/5/2026	Status Client - Appraisal		0.10		
2/9/2026	Prepare Appraisal		1.00		
2/9/2026	Inspect Damaged Vehicle or Unit / Item		0.70		
2/9/2026	Drive Time		0.40	9.00	
2/9/2026	Identify / Label Digital Photographs		0.30		
2/9/2026	Parts Search		0.50		
2/5/2026	Contact Storage Facility		0.10		
2/9/2026	Complete Appraiser's Report	Condition and Caption Reports	0.60		
2/9/2026	Other Appraisal Activity	Mitchell WCTL pending	0.50		
TOTALS			4.80	9.00	\$0.00

Alacrity Solutions, Bakersfield, CA
<https://supplements.alacritystatus.com/>
P. O. Box 471909
Fort Worth, TX 76147
Phone: (866) 289-2029 Fax: (800) 866-4732



2/9/2026

To: Victor Hernandez
Littleton Group 1250 S Capital of Texas Hwy
Austin, TX 7854

Report: FIRST & FINAL

RE: Insured: Jag Carrier
Claimant:
Claim #: 118.1607
Policy #: CUS062007037
Our File #: 046-602-0007
Loss Date: 1/1/1900
Risk: 2018 / Great dane trailers / Great Dane Trailers / Not Applicable
Serial #: 1GRAA0620JW113719

ENCLOSURES

Appraisal
Equipment & Condition Report

ASSIGNMENT INFORMATION

This Assignment was received on 2/9/2026. The loss was assigned to David Weldin as Physical Damage

INSURED

The named insured is Jag Carrier They are located at 5306 Pomerado Way , Bakersfield, CA 93313 Their phone number is (661) 343-8845

INSPECTION

The unit was inspected on 2/9/2026 at Commercial Towing - Texas Street, 2609 Texas St Bakersfield, CA 93307. The trailer has sustained major damage. Damage is to both radius panels, both upper caps, left side panels, right side panel, left upper rail, right upper rail, left lower rail, roof, roof bows, liners, left side posts, crossmembers and both rear door skins. Possible supplement for hidden damage to the floor, additional rivets and parts price increases. Supplement could exceed \$8000.

UNIT

The unit is a 2018 Great dane trailers Great Dane Trailers Not Applicable bearing the serial number 1GRAA0620JW113719. As part of our standard procedure, I analyzed the serial number and verified that it is a valid VIN. The overall condition of the unit is Good.

ACTUAL CASH VALUE

Mitchell WCTL pending additional research. Once WCTL is completed we will forward to the adjuster.

SALVAGE

Salvage on this loss has scrap value only. The cost of transporting the items to a recycling center would be greater than the money received for the parts.

RECOMMENDATIONS OR REQUEST FOR AUTHORIZATION

We recommend the unit is a total loss. Gross Loss \$90,249.02 Deductible (\$2,500.00) Net Loss \$87,749.02

CLOSING

We appreciate you giving us the opportunity to serve you.

SIGNATURE BLOCK

Sincerely,

David Weldin

Alacrity Solutions, Bakersfield, CA
<https://supplements.alacritystatus.com/>
P. O. Box 471909
Fort Worth, TX 76147
Phone: (866) 289-2029 Fax: (800) 866-4732

Equipment & Condition Report

Owner:	Jag Carrier	File #:	046-602-0007
Claim #:	118.1607		
Date Of Loss:	1/1/1900		
Vehicle:	2018 / Great dane trailers /		

Identification & Hours

Serial #:	1GRAA0620JW113719	Color:	White
Plate/State:	4WK5180/CA	Trailer Type:	Reefer
Hours:	14363		
HazMat Spec:			

Condition

Paint Condition:	Good
Interior Condition:	Good
Overall Condition:	Good

Trailer Dimensions

Length:	53ft	Width:	102in	Height:	13ft
---------	------	--------	-------	---------	------

Trailer Construction

Make:	Thermo King	Hours:	14363
Model:	S-600	Fuel:	Diesel
HP:			

Frame Type:	Frameless
Frame Construction:	
Outer Body:	Aluminum
Outer Body Sides:	Corrugated
Doors Rear:	Double
Interior Construction:	Plywood
Interior Insulation:	Styrofoam
Floor Construction:	Aluminum Rail

Additional Items

Tarps:	No	Binders:	
Chains:		Tool Boxes:	False

Wheels

Front Wheels:	Aluminum
Rear Wheels:	Aluminum
Suspension:	Air Ride

Suspension & Tires

Location	Tire Size	Recap	Tread Depth
1st Rear L/S Outer	295/75R22.5	False	3
1st Rear L/S Inner	295/75R22.5	False	3
1st Rear R/S Outer	295/75R22.5	False	7
1st Rear R/S Inner	295/75R22.5	False	6
2nd Rear L/S Outer	295/75R22.5	False	4
2nd Rear L/S Inner	295/75R22.5	False	4
2nd Rear R/S Outer	295/75R22.5	False	1
2nd Rear R/S Inner	295/75R22.5	False	

Note:



Date:	2/9/2026	Year:	2018
Reference #:	040870000541SUPP1	Make:	Great dane trailers
Estimated By:	David Weldin	Model:	Great Dane Trailers
Name:	Jag Carrier	Unit #:	
Address:	5306 Pomerado Way	VIN:	1GRAA0620JW113719
City/State/Zip:	Bakersfield, CA 93313	Style:	Not Applicable
Phone:	661-343-8845	Plate/State:	4WK5180 - CA
Inspected Date:	2/9/2026	WMI:	FIN:
Claimant:		Odometer:	
Date of Loss:	1/1/1900	Color:	White
Claim Contact:	Victor Hernandez	Date Of Loss:	1/1/1900
Contact Title:	Adjuster	Inspected At:	Commercial Towing - Texas
Contact Phone:	(210) 634-1509 x	Claim Number:	118.1607
Contact Email:	jagcarrierinc@gmail.com	File Number:	046-602-0007

Total Loss

Operation	Description	Part #	Type	Labor	Paint	-----Parts-----	Misc
----- Front Panel -----							
1	Replace	Stainless Radius Panel (Left)	New	12.00		1 @ \$239.78	\$239.78
2	Replace	Stainless Radius Panel (Right)	New	12.00		1 @ \$239.78	\$239.78
3	Replace	Corner Cap (Left)	New	2.00		1 @ \$96.84	\$96.84
4	Replace	Corner Cap (Right)	New	2.00		1 @ \$96.84	\$96.84
----- Refrigeration -----							
5	R&I	Refrigeration Unit (Nose Mount)	M	6.00			
----- Side Panels -----							
6	Replace	Aluminum Side Panel - Initial (Left)	New	9.00		1 @ \$201.28	\$201.28
7 *	Replace	Aluminum Side Panel - Additional (Left)	New	96.00		12 @ \$200.60	\$2,407.20
8	Replace	Aluminum Side Panel - Initial (Right)	New	9.00		1 @ \$203.73	\$203.73
9 *	Replace	Aluminum Side Panel - Additional (Right)	New	24.00		3 @ \$194.43	\$583.29
10 *	Replace	Inner Post (Left)	New	66.00		22 @ \$61.36	\$1,349.92
11 *	Replace	Foam Insulation	New	10.00		2 @ \$1,003.05	\$2,006.10
----- Upper Rail -----							
12	Replace	Upper Rail 53' (Left)	New	35.50		1 @ \$1,182.68	\$1,182.68
13	Replace	Upper Rail 53' (Right)	New	35.50		1 @ \$1,131.07	\$1,131.07
----- Lower Rail -----							
14	Replace	Bottom Rail 53' (Left)	New	45.80		1 @ \$1,177.92	\$1,177.92
----- Roof -----							
15	Replace	Roof Panel 53'	New	31.80		1 @ \$1,093.97	\$1,093.97
16 *	Replace	Roof Bow (Each)	New	15.00		10 @ \$67.06	\$670.60
17 *	Replace	Foam Insulation	New	10.00		2 @ \$1,003.05	\$2,006.10
----- Interior Walls -----							
18 *	Replace	Inner Side Wall (Right)	New	5.00		1 @ \$817.32	\$817.32

Alacrity Solutions, Bakersfield, CA
<https://supplements.alacritystatus.com/>
P. O. Box 471909
Fort Worth, TX 76147
Phone: (866) 289-2029 Fax: (800) 866-4732
Email: bakersfield@alacritysas.com
Carrier: Littleton Group - 1250 S Capital of Texas Hwy, Austin, TX 37854


Date: 2/9/2026 Year: 2018
 Reference #: 040870000541SUPP1 Make: Great dane trailers
 Estimated By: David Weldin Model: Great Dane Trailers
 Name: Jag Carrier Unit #:

Operation	Description	Part #	Type	Labor	Paint	Parts	Misc
19	Replace Plastic Liner (53')		New	4.50		1 @ \$903.18	\$903.18
----- Rear Door Swing (Left) -----							
20	Replace Stainless Door Skin (Left)		New	7.50		1 @ \$594.45	\$594.45
----- Rear Door Swing (Right) -----							
21	Replace Stainless Door Skin (Right)		New	7.50		1 @ \$582.09	\$582.09
----- Frame -----							
22 *	Replace Crossmember		New	M 10.50		3 @ \$150.36	\$451.08
----- Misc -----							
23 ^	Replace Rivets		New			1 @ \$750.00	\$750.00
----- Calculated Values -----							
24 ^	Shop Supplies		Mtrls				\$3,424.50

An '*' indicates user change of database part and '^' indicates manually entered or custom database rows.

Estimate Notes:

Summary	Amount	Rate	Disc	Total
Body Labor	440.1	\$145.00	0.00%	\$63,814.50
Paint Labor	0.0	\$145.00	0.00%	\$0.00
Mechanical	16.5	\$145.00	0.00%	\$2,392.50
Frame	0.0	\$145.00	0.00%	\$0.00
Misc. Labor	0.0	\$145.00	0.00%	\$0.00
Parts	\$18,785.22		0.00%	\$18,785.22
Misc.				\$3,424.50
Sub-total				\$88,416.72
Sales Tax	City (Parts, Materials) \$22,209.72 @ 8.2500%: \$1,832.30			

Total	\$90,249.02
Betterment	\$0.00
Deductible	\$(2,500.00)
Grand Total	\$87,749.02

Alacrity Solutions, Bakersfield, CA**<https://supplements.alacritystatus.com/>****P. O. Box 471909****Fort Worth, TX 76147****Phone: (866) 289-2029 Fax: (800) 866-4732****Email: bakersfield@alacritysas.com****Carrier: Littleton Group - 1250 S Capital of Texas Hwy, Austin, TX 37854**

Date:	2/9/2026	Year:	2018
Reference #:	040870000541SUPP1	Make:	Great dane trailers
Estimated By:	David Weldon	Model:	Great Dane Trailers
Name:	Jag Carrier	Unit #:	

Repair Facility:

Address:

Phone: () -

Email:

Agreed With:

License 1:

License 2:

Fed Tax ID:

Registration #:

Appraised By: David Weldon

License #1:

License #2:

Phone: 661-805-7592

Email: dweldon@alacritysolutions.com

Alacrity Solutions, Bakersfield, CA

<https://supplements.alacritystatus.com/>

P. O. Box 471909

Fort Worth, TX 76147

Phone: (866) 289-2029 Fax: (800) 866-4732

Email: bakersfield@alacritysas.com

Carrier: Littleton Group - 1250 S Capital of Texas Hwy, Austin, TX 78754



Date:	2/9/2026	Year:	2018
Reference #:	040870000541SUPP1	Make:	Great dane trailers
Estimated By:	David Weldin	Model:	Great Dane Trailers
Name:	Jag Carrier	Unit #:	

Supplement Summary

Supplement Estimate

No Data Found.

Summary	Amount	Rate	Discount	Total
Body Labor	0.0	\$145.00	0.00%	\$0.00
Paint Labor	0.0	\$145.00	0.00%	\$0.00
Mechanical	0.0	\$145.00	0.00%	\$0.00
Frame Labor	0.0	\$145.00	0.00%	\$0.00
Misc. Labor	0.0	\$145.00	0.00%	\$0.00
Parts	\$0.00		0.00%	\$0.00
Misc.				\$0.00
Sub-Total				\$0.00
Sales Tax	City (Parts, Materials)			0.00

Supplement Changes Total:	\$0.00
Betterment:	\$0.00
Supplement Changes Grand Total:	\$0.00

Alacrity Solutions, Bakersfield, CA**<https://supplements.alacritystatus.com/>****P. O. Box 471909****Fort Worth, TX 76147****Phone: (866) 289-2029 Fax: (800) 866-4732****Email: bakersfield@alacritysas.com****Carrier: Littleton Group - 1250 S Capital of Texas Hwy, Austin, TX 78854**

Date:	2/9/2026	Year:	2018
Reference #:	040870000541SUPP1	Make:	Great dane trailers
Estimated By:	David Weldin	Model:	Great Dane Trailers
Name:	Jag Carrier	Unit #:	

TERMS & CONDITIONS

Alacrity Solutions, Bakersfield, CA**<https://supplements.alacritystatus.com/>****P. O. Box 471909****Fort Worth, TX 76147****Phone: (866) 289-2029 Fax: (800) 866-4732****Email: bakersfield@alacritysas.com****Carrier: Littleton Group - 1250 S Capital of Texas Hwy, Austin, TX 37854**

Date:	2/9/2026	Year:	2018
Reference #:	040870000541SUPP1	Make:	Great dane trailers
Estimated By:	David Weldin	Model:	Great Dane Trailers
Name:	Jag Carrier	Unit #:	

Notice - THIS ESTIMATE HAS BEEN PREPARED BASED ON THE USE OF CRASH PARTS SUPPLIED BY A SOURCE OTHER THAN THE MANUFACTURER OF YOUR MOTOR VEHICLE. ANY WARRANTIES APPLICABLE TO THESE REPLACEMENT PARTS ARE PROVIDED BY THE MANUFACTURER OR DISTRIBUTOR OF THE PARTS, RATHER THAN BY THE ORIGINAL MANUFACTURER OF YOUR VEHICLE.

Pursuant to California Code of Regulations, Title 10, Chapter 5, Subchapter 7.5, Section 2695.8 the insurer warrants that any Non-original Equipment Manufacturer parts specified in this estimate are at least equal to the Original Equipment Manufacturer parts in terms of kind, quality, safety, fit and performance.

If you believe that all or part of your claim was wrongfully denied, you may have your claim reviewed by the California Department of Insurance. This department can be reached at California Department of Insurance, Customer Services Division, 300 South Spring Street, Los Angeles, CA 90013, by phone at (800) 927-HELP or (213) 897-8921 or over the internet at www.insurance.ca.gov

Notice - This is not an authorization for repair. All costs of repairs are the sole responsibility of the vehicle owner, who must authorize all repairs. Failure to deliver a copy of this appraisal to the repair shop by the vehicle owner may result in out of pocket expense to the vehicle owner. Providing a copy of this appraisal is not an acceptance of coverage or liability and all issues of coverage or liability are to be determined by the insurance carrier.

Notice - Deductibles may or may not be addressed or included in this appraisal. If applicable, the repairer should collect the deductible from the vehicle owner prior to the release of the repaired vehicle.

Supplement Procedure Notice - It is the repairer's responsibility to send notification of the supplement via fax or email including a statement whether repairs have been halted on the vehicle. Alacrity Solutions will respond to your request within 24 hours. Please allow 48 hour to complete supplement processing from the date of request to ensure timely release of the vehicle.

Notice - This appraisal is subject to the complete review and approval by the assigning insurance company to assure accuracy, cost effectiveness, and that accepted industry repair standards are met. The insurance company listed has the right to accept or reject any part or all of this appraisal or make any changes they feel necessary.

Fraud Disclaimer - For your protection California law requires the following statement to appear on this form. Any person who knowingly presents false or fraudulent claim for the payment of a loss is guilty of a crime and may be subject to fines and confinement in state prison.

Profile ID: Bakersfield California Default

Alacrity Solutions, Bakersfield, CA**<https://supplements.alacritystatus.com/>****P. O. Box 471909****Fort Worth, TX 76147****Phone: (866) 289-2029 Fax: (800) 866-4732****Email: bakersfield@alacritysas.com****Carrier: Littleton Group - 1250 S Capital of Texas Hwy, Austin, TX 78754**

Date:	2/9/2026	Year:	2018
Reference #:	040870000541SUPP1	Make:	Great dane trailers
Estimated By:	David Weldin	Model:	Great Dane Trailers
Name:	Jag Carrier	Unit #:	

Signed _____ Date _____



Document Name: Crossmembers.jpg

Remarks:



Document Name: DOOR.jpg

Remarks:



Document Name: FUEL TANK.jpg

Remarks:



Document Name: INTERIOR.jpg

Remarks:



Document Name: Kemlite.jpg

Remarks:



Document Name: Left corner radius and cap.jpg

Remarks:



Document Name: LEFT FRONT.jpg

Remarks:




Document Name: Left front inner tire.jpg

Remarks:



Document Name: Left front outer tire.jpg

Remarks:



Document Name: Left lower rail.jpg

Remarks:



Document Name: Left posts.jpg

Remarks:



Document Name: LEFT REAR.jpg

Remarks:



Document Name: Left rear inner tire.jpg

Remarks:



Document Name: Left rear outer tire.jpg

Remarks:




Document Name: Left skid plate.jpg

Remarks:



Document Name: LICENSE.jpg

Remarks:



Document Name: Reefer hours.jpg

Remarks:



Document Name: Right corner radius and cap.jpg

Remarks:

2/9/2026 9:56:33 AM



Document Name: RIGHT FRONT.jpg

Remarks:



Document Name: Right front inner tire.jpg

Remarks:



Document Name: Right front outer tire.jpg

Remarks:



Document Name: RIGHT REAR.jpg

Remarks:



Document Name: Right rear door one tire.jpg

Remarks:



Document Name: Right rear outer tire.jpg

Remarks:



Document Name: Right side panels.jpg

Remarks:



Document Name: Right upper rail.jpg

Remarks:

2/9/2026 9:56:11 AM



Document Name: ROOF.jpg

Remarks:

2/9/2026 9:54:58 AM

IBER



Document Name: VIN.jpg

Remarks: