

Claim Photo

Our File Number:

277-066197

Adjuster:

Devon Karnitz

Insured:

Frizell Trucking LLC

Date of Loss:

12/15/2025

Customer File Number:

2025035639

Policy Number:

cia
CUSTARD
INSURANCE ADJUSTERS



Photo: 1

Date Taken:
01/20/2026

Taken By:
Antonio Padgett

Description:
Front



Photo: 2

Date Taken:
01/20/2026

Taken By:
Antonio Padgett

Description:
Front LT side

Claim Photo

Our File Number: 277-066197
Adjuster: Devon Karnitz
Insured: Frizell Trucking LLC
Date of Loss: 12/15/2025
Customer File Number: 2025035639
Policy Number:



Photo: 3

Date Taken:
01/20/2026

Taken By:
Antonio Padgett

Description:
Left Side



Photo: 4

Date Taken:
01/20/2026

Taken By:
Antonio Padgett

Description:
Left side rear

Claim Photo

Our File Number: 277-066197
Adjuster: Devon Karnitz
Insured: Frizell Trucking LLC
Date of Loss: 12/15/2025
Customer File Number: 2025035639
Policy Number:

cia
CUSTARD
INSURANCE ADJUSTERS



Photo: 5

Date Taken:
01/20/2026

Taken By:
Antonio Padgett

Description:
Rear



Photo: 6

Date Taken:
01/20/2026

Taken By:
Antonio Padgett

Description:
Right rear side

Claim Photo

Our File Number: 277-066197
Adjuster: Devon Karnitz
Insured: Frizell Trucking LLC
Date of Loss: 12/15/2025
Customer File Number: 2025035639
Policy Number:

cia
CUSTARD
INSURANCE ADJUSTERS



Photo: 7

Date Taken:
01/20/2026

Taken By:
Antonio Padgett

Description:
Right side



Photo: 8

Date Taken:
01/20/2026

Taken By:
Antonio Padgett

Description:
Rt front side

Claim Photo

Our File Number: 277-066197
Adjuster: Devon Karnitz
Insured: Frizell Trucking LLC
Date of Loss: 12/15/2025
Customer File Number: 2025035639
Policy Number:



Photo: 9

Date Taken:
01/20/2026

Taken By:
Antonio Padgett

Description:
Tag



Photo: 10

Date Taken:
01/20/2026

Taken By:
Antonio Padgett

Description:
Left side

Claim Photo

Our File Number: 277-066197
Adjuster: Devon Karnitz
Insured: Frizell Trucking LLC
Date of Loss: 12/15/2025
Customer File Number: 2025035639
Policy Number:

cia
CUSTARD
INSURANCE ADJUSTERS



Photo: 11

Date Taken:
01/20/2026

Taken By:
Antonio Padgett

Description:
Left door damage




Photo: 12

Date Taken:
01/20/2026

Taken By:
Antonio Padgett

Description:
Left side door damage

Claim Photo

Our File Number: 277-066197
Adjuster: Devon Karnitz
Insured: Frizell Trucking LLC
Date of Loss: 12/15/2025
Customer File Number: 2025035639
Policy Number:



Photo: 13

Date Taken:
01/20/2026

Taken By:
Antonio Padgett

Description:
Console



Photo: 14

Date Taken:
01/20/2026

Taken By:
Antonio Padgett

Description:
Left side interior

Claim Photo

Our File Number: 277-066197
Adjuster: Devon Karnitz
Insured: Frizell Trucking LLC
Date of Loss: 12/15/2025
Customer File Number: 2025035639
Policy Number:

cia
CUSTARD
INSURANCE ADJUSTERS



Photo: 15

Date Taken:
01/20/2026

Taken By:
Antonio Padgett

Description:
Roof damage-
access limited due
to door damage



Photo: 16

Date Taken:
01/20/2026

Taken By:
Antonio Padgett

Description:
Left door pillar
damage

Claim Photo

Our File Number: 277-066197
Adjuster: Devon Karnitz
Insured: Frizell Trucking LLC
Date of Loss: 12/15/2025
Customer File Number: 2025035639
Policy Number:

cia
CUSTARD
INSURANCE ADJUSTERS




Photo: 17

Date Taken:
01/20/2026

Taken By:
Antonio Padgett

Description:
Left corner pillar
damage



Photo: 18

Date Taken:
01/20/2026

Taken By:
Antonio Padgett

Description:
Left side cab
damage

Claim Photo

Our File Number: 277-066197

Adjuster: Devon Karnitz

Insured: Frizell Trucking LLC

Date of Loss: 12/15/2025

Customer File Number: 2025035639

Policy Number:

cia
CUSTARD
INSURANCE ADJUSTERS




Photo: 19

Date Taken:
01/20/2026

Taken By:
Antonio Padgett

Description:
Left side view-
damage



Photo: 20

Date Taken:
01/20/2026

Taken By:
Antonio Padgett

Description:
Informational
Decals

Claim Photo

Our File Number: 277-066197
Adjuster: Devon Karnitz
Insured: Frizell Trucking LLC
Date of Loss: 12/15/2025
Customer File Number: 2025035639
Policy Number:

cia
CUSTARD
INSURANCE ADJUSTERS




Photo: 21

Date Taken:
01/20/2026

Taken By:
Antonio Padgett

Description:
Left side damage view



Photo: 22

Date Taken:
01/20/2026

Taken By:
Antonio Padgett

Description:
Left side door damage

Claim Photo

Our File Number: 277-066197
Adjuster: Devon Karnitz
Insured: Frizell Trucking LLC
Date of Loss: 12/15/2025
Customer File Number: 2025035639
Policy Number:



Photo: 23

Date Taken:
01/20/2026

Taken By:
Antonio Padgett

Description:
Left front side
damage



Photo: 24

Date Taken:
01/20/2026

Taken By:
Antonio Padgett

Description:
Left front side

Claim Photo

Our File Number: 277-066197
Adjuster: Devon Karnitz
Insured: Frizell Trucking LLC
Date of Loss: 12/15/2025
Customer File Number: 2025035639
Policy Number:

cia
CUSTARD
INSURANCE ADJUSTERS




Photo: 25

Date Taken:
01/20/2026

Taken By:
Antonio Padgett

Description:
Right side bumper damage



Photo: 26

Date Taken:
01/20/2026

Taken By:
Antonio Padgett

Description:
Right side door damage

Claim Photo

Our File Number: 277-066197
Adjuster: Devon Karnitz
Insured: Frizell Trucking LLC
Date of Loss: 12/15/2025
Customer File Number: 2025035639
Policy Number:

cia
CUSTARD
INSURANCE ADJUSTERS



Photo: 27

Date Taken:
01/20/2026

Taken By:
Antonio Padgett

Description:
Right side door damage- access limited due to damage.



Photo: 28

Date Taken:
01/20/2026

Taken By:
Antonio Padgett

Description:
Right rear side

Claim Photo

Our File Number: 277-066197
Adjuster: Devon Karnitz
Insured: Frizell Trucking LLC
Date of Loss: 12/15/2025
Customer File Number: 2025035639
Policy Number:



Photo: 29

Date Taken:
01/20/2026

Taken By:
Antonio Padgett

Description:
Rear (tractor)



Photo: 30

Date Taken:
01/20/2026

Taken By:
Antonio Padgett

Description:
Rear

Claim Photo

Our File Number: 277-066197
Adjuster: Devon Karnitz
Insured: Frizell Trucking LLC
Date of Loss: 12/15/2025
Customer File Number: 2025035639
Policy Number:

cia
CUSTARD
INSURANCE ADJUSTERS



Photo: 31

Date Taken:
01/20/2026

Taken By:
Antonio Padgett

Description:
Left rear side



Photo: 32

Date Taken:
01/20/2026

Taken By:
Antonio Padgett

Description:
Right side front tire
- measurement

Claim Photo

Our File Number: 277-066197

Adjuster: Devon Karnitz

Insured: Frizell Trucking LLC

Date of Loss: 12/15/2025

Customer File Number: 2025035639

Policy Number:




Photo: 33

Date Taken:
01/20/2026

Taken By:
Antonio Padgett

Description:
Right side thread depth



Photo: 34

Date Taken:
01/20/2026

Taken By:
Antonio Padgett

Description:
Left rear tire thread depth

Claim Photo

Our File Number: 277-066197
Adjuster: Devon Karnitz
Insured: Frizell Trucking LLC
Date of Loss: 12/15/2025
Customer File Number: 2025035639
Policy Number:



Photo: 35

Date Taken:
01/20/2026

Taken By:
Antonio Padgett

Description:
Repair facility
(Smith
International)



Photo: 36

Date Taken:
01/20/2026

Taken By:
Antonio Padgett

Description:
Repair facility
(Smith
International)

Claim Photo

Our File Number: 277-066197
Adjuster: Devon Karnitz
Insured: Frizell Trucking LLC
Date of Loss: 12/15/2025
Customer File Number: 2025035639
Policy Number:




Photo: 37

Date Taken:
01/21/2026

Taken By:
Antonio Padgett

Description:
Repair Facility -
Repair facility
(Smith
International)