


VIN of 2006 Mack Dump truck VIN: 1M1AG11Y86M039186.




License plate of 2006 Mack Dump truck VIN: 1M1AG11Y86M039186.



Odometer of 2006 Mack Dump truck VIN: 1M1AG11Y86M039186.



Identification tags of make and model of the unit of 2006 Mack Dump truck VIN: 1M1AG11Y86M039186.



Truck company name lettering-unit numbers of 2006 Mack Dump truck VIN: 1M1AG11Y86M039186.



Driver side of vehicle of 2006 Mack Dump truck VIN: 1M1AG11Y86M039186.



Driver side of vehicle of 2006 Mack Dump truck VIN: 1M1AG11Y86M039186.



Driver side of vehicle of 2006 Mack Dump truck VIN: 1M1AG11Y86M039186.



Passenger side of vehicle of 2006 Mack Dump truck VIN: 1M1AG11Y86M039186.



Passenger side of vehicle of 2006 Mack Dump truck VIN: 1M1AG11Y86M039186.



Passenger side of vehicle of 2006 Mack Dump truck VIN: 1M1AG11Y86M039186.



Front of vehicle of 2006 Mack Dump truck VIN: 1M1AG11Y86M039186.



Rear of vehicle of 2006 Mack Dump truck VIN: 1M1AG11Y86M039186.



Damage noted to driver side of vehicle of 2006 Mack Dump truck VIN: 1M1AG11Y86M039186.



Damage noted to passenger side of vehicle of 2006 Mack Dump truck VIN: 1M1AG11Y86M039186.



Damage noted to passenger side of vehicle of 2006 Mack Dump truck VIN: 1M1AG11Y86M039186.




Damage noted to passenger side of vehicle of 2006 Mack Dump truck VIN: 1M1AG11Y86M039186.



Damage noted to passenger side of vehicle of 2006 Mack Dump truck VIN: 1M1AG11Y86M039186.



Damage noted to passenger side of vehicle of 2006 Mack Dump truck VIN: 1M1AG11Y86M039186.



Damage noted to passenger side of vehicle of 2006 Mack Dump truck VIN: 1M1AG11Y86M039186.



Damage noted to passenger side of vehicle of 2006 Mack Dump truck VIN: 1M1AG11Y86M039186.



Damage noted to the rear of the 2006 Mack Dump truck VIN: 1M1AG11Y86M039186. (The rear tailgate doesn't close; it's unbalanced as a result of the rollover.




Damage noted to the rear of the 2006 Mack Dump truck VIN: 1M1AG11Y86M039186. (The rear tailgate doesn't close; it's unbalanced as a result of the rollover.



Damage noted to the rear of the 2006 Mack Dump truck VIN: 1M1AG11Y86M039186. (The rear tailgate doesn't close; it's unbalanced as a result of the rollover.



Truck interior.



Truck interior.




Truck interior.



Truck interior.



(Engine compartment)



(Engine compartment)



(Engine compartment)



(Engine compartment)



(Engine compartment)



(Engine compartment)



(Engine compartment)



(Engine compartment)



(Engine compartment)



(Engine compartment)



(Engine compartment)



(Engine compartment)



Report:

- * The vehicle was towed to the lot. Therefore, they cannot tell us if the vehicle is running perfectly.
- * The truck appears unbalanced (see rear photo) as a result of the rollover.
- * No suspension damage was identified, according to what Mr. Al Pastor told us. (They should have this checked by their mechanic, as they mentioned).
- * The tailgate does not close; it is misaligned as a result of the rollover.
- * No labels were visible on the body mount, nor were there any serial numbers on the engine.
- * They are not required to provide us with a garage payment report, since the truck is in their lot.