

Claim Photo

Our File Number: 277-065974
Adjuster: Curtis Murphy
Insured: Churchill Casualty LTD.
Date of Loss: 12/09/2025
Customer File Number: 000696-282366-AP-01
Policy Number:



Photo: 1
Date Taken: 01/07/2026
Taken By: Curtis Murphy
Description: 2022 Peterbilt 337, VIN: 2NP2HM6X11NM 772006. Unit information label.




Photo: 2
Date Taken: 01/07/2026
Taken By: Curtis Murphy
Description: VIN verification.

Claim Photo

Our File Number: 277-065974
Adjuster: Curtis Murphy
Insured: Churchill Casualty LTD.
Date of Loss: 12/09/2025
Customer File Number: 000696-282366-AP-01
Policy Number:




Photo: 3

Date Taken:
01/07/2026

Taken By:
Curtis Murphy

Description:
Additional unit information.



Photo: 4

Date Taken:
01/07/2026

Taken By:
Curtis Murphy

Description:
Second VIN tag.

Claim Photo

Our File Number: 277-065974
Adjuster: Curtis Murphy
Insured: Churchill Casualty LTD.
Date of Loss: 12/09/2025
Customer File Number: 000696-282366-AP-01
Policy Number:




Photo: 5

Date Taken:
01/07/2026

Taken By:
Curtis Murphy

Description:
Approximate
mileage, mileage
later confirmed via
GPS as: 152036.



Photo: 6

Date Taken:
01/07/2026

Taken By:
Curtis Murphy

Description:
Dash, battery no
longer operational.

Claim Photo

Our File Number: 277-065974
Adjuster: Curtis Murphy
Insured: Churchill Casualty LTD.
Date of Loss: 12/09/2025
Customer File Number: 000696-282366-AP-01
Policy Number:




Photo: 7

Date Taken:
01/07/2026

Taken By:
Curtis Murphy

Description:
View of interior.



Photo: 8

Date Taken:
01/07/2026

Taken By:
Curtis Murphy

Description:
Dash view.

Claim Photo

Our File Number: 277-065974
Adjuster: Curtis Murphy
Insured: Churchill Casualty LTD.
Date of Loss: 12/09/2025
Customer File Number: 000696-282366-AP-01
Policy Number:




Photo: 9

Date Taken:
01/07/2026

Taken By:
Curtis Murphy

Description:
Interior view 2.



Photo: 10

Date Taken:
01/07/2026

Taken By:
Curtis Murphy

Description:
Interior view 3.

Claim Photo

Our File Number: 277-065974
Adjuster: Curtis Murphy
Insured: Churchill Casualty LTD.
Date of Loss: 12/09/2025
Customer File Number: 000696-282366-AP-01
Policy Number:



Photo: 11

Date Taken:
01/07/2026

Taken By:
Curtis Murphy

Description:
Unit #: 110251.



Photo: 12

Date Taken:
01/07/2026

Taken By:
Curtis Murphy

Description:
Company and DOT
information.

Claim Photo

Our File Number: 277-065974
Adjuster: Curtis Murphy
Insured: Churchill Casualty LTD.
Date of Loss: 12/09/2025
Customer File Number: 000696-282366-AP-01
Policy Number:



Photo: 13

Date Taken:
01/07/2026

Taken By:
Curtis Murphy

Description:
License plate.
Missouri 32J 0GM.



Photo: 14

Date Taken:
01/07/2026

Taken By:
Curtis Murphy

Description:
Front driver side
view.

Claim Photo

Our File Number: 277-065974
Adjuster: Curtis Murphy
Insured: Churchill Casualty LTD.
Date of Loss: 12/09/2025
Customer File Number: 000696-282366-AP-01
Policy Number:



Photo: 15

Date Taken:
01/07/2026

Taken By:
Curtis Murphy

Description:
Rear driver side
view.



Photo: 16

Date Taken:
01/07/2026

Taken By:
Curtis Murphy

Description:
Rear passenger side
view.

Claim Photo

Our File Number: 277-065974
Adjuster: Curtis Murphy
Insured: Churchill Casualty LTD.
Date of Loss: 12/09/2025
Customer File Number: 000696-282366-AP-01
Policy Number:



Photo: 17

Date Taken:
01/07/2026

Taken By:
Curtis Murphy

Description:
Front passenger
side view.



Photo: 18

Date Taken:
01/07/2026

Taken By:
Curtis Murphy

Description:
Damages, front
driver side bumper,
headlight, and
hood.

Claim Photo

Our File Number: 277-065974
Adjuster: Curtis Murphy
Insured: Churchill Casualty LTD.
Date of Loss: 12/09/2025
Customer File Number: 000696-282366-AP-01
Policy Number:



Photo: 19

Date Taken:
01/07/2026

Taken By:
Curtis Murphy

Description:
Bumper bent
backwards behind
steer tire.



Photo: 20

Date Taken:
01/07/2026

Taken By:
Curtis Murphy

Description:
Broken axle
component.

Claim Photo

Our File Number: 277-065974
Adjuster: Curtis Murphy
Insured: Churchill Casualty LTD.
Date of Loss: 12/09/2025
Customer File Number: 000696-282366-AP-01
Policy Number:



Photo: 21

Date Taken:
01/07/2026

Taken By:
Curtis Murphy

Description:
Missing headlights.



Photo: 22

Date Taken:
01/07/2026

Taken By:
Curtis Murphy

Description:
Hood damages 1,
cracked over wheel.

Claim Photo

Our File Number: 277-065974
Adjuster: Curtis Murphy
Insured: Churchill Casualty LTD.
Date of Loss: 12/09/2025
Customer File Number: 000696-282366-AP-01
Policy Number:



Photo: 23

Date Taken:
01/07/2026

Taken By:
Curtis Murphy

Description:
Tire pulled from
wheel, damages to
hub cap and hex
covers.



Photo: 24

Date Taken:
01/07/2026

Taken By:
Curtis Murphy

Description:
View of hex
damages.

Claim Photo

Our File Number: 277-065974
Adjuster: Curtis Murphy
Insured: Churchill Casualty LTD.
Date of Loss: 12/09/2025
Customer File Number: 000696-282366-AP-01
Policy Number:



Photo: 25

Date Taken:
01/07/2026

Taken By:
Curtis Murphy

Description:
View of axle
behind wheel.



Photo: 26

Date Taken:
01/07/2026

Taken By:
Curtis Murphy

Description:
View 2.

Claim Photo

Our File Number: 277-065974
Adjuster: Curtis Murphy
Insured: Churchill Casualty LTD.
Date of Loss: 12/09/2025
Customer File Number: 000696-282366-AP-01
Policy Number:



Photo: 27

Date Taken:
01/07/2026

Taken By:
Curtis Murphy

Description:
Step damages,
frame of steps
shifted.



Photo: 28

Date Taken:
01/07/2026

Taken By:
Curtis Murphy

Description:
Front of tank
dented.

Claim Photo

Our File Number: 277-065974
Adjuster: Curtis Murphy
Insured: Churchill Casualty LTD.
Date of Loss: 12/09/2025
Customer File Number: 000696-282366-AP-01
Policy Number:



Photo: 29

Date Taken:
01/07/2026

Taken By:
Curtis Murphy

Description:
Damages to driver
side door.



Photo: 30

Date Taken:
01/07/2026

Taken By:
Curtis Murphy

Description:
Missing cargo door.

Claim Photo

Our File Number: 277-065974
Adjuster: Curtis Murphy
Insured: Churchill Casualty LTD.
Date of Loss: 12/09/2025
Customer File Number: 000696-282366-AP-01
Policy Number:



Photo: 31

Date Taken:
01/07/2026

Taken By:
Curtis Murphy

Description:
Shift of box frame.



Photo: 32

Date Taken:
01/07/2026

Taken By:
Curtis Murphy

Description:
Shift of tool box.

Claim Photo

Our File Number: 277-065974
Adjuster: Curtis Murphy
Insured: Churchill Casualty LTD.
Date of Loss: 12/09/2025
Customer File Number: 000696-282366-AP-01
Policy Number:



Photo: 33

Date Taken:
01/07/2026

Taken By:
Curtis Murphy

Description:
Upper corner of
frame, bent.



Photo: 34

Date Taken:
01/07/2026

Taken By:
Curtis Murphy

Description:
Lower frame
bending.

Claim Photo

Our File Number: 277-065974
Adjuster: Curtis Murphy
Insured: Churchill Casualty LTD.
Date of Loss: 12/09/2025
Customer File Number: 000696-282366-AP-01
Policy Number:



Photo: 35

Date Taken:
01/07/2026

Taken By:
Curtis Murphy

Description:
Dent and shift of
lower frame.



Photo: 36

Date Taken:
01/07/2026

Taken By:
Curtis Murphy

Description:
Steering column
damages.

Claim Photo

Our File Number: 277-065974
Adjuster: Curtis Murphy
Insured: Churchill Casualty LTD.
Date of Loss: 12/09/2025
Customer File Number: 000696-282366-AP-01
Policy Number:



Photo: 37

Date Taken:
01/07/2026

Taken By:
Curtis Murphy

Description:
Bumper and removed door in back of unit.



Photo: 38

Date Taken:
01/07/2026

Taken By:
Curtis Murphy

Description:
Damaged door.

Claim Photo

Our File Number: 277-065974
Adjuster: Curtis Murphy
Insured: Churchill Casualty LTD.
Date of Loss: 12/09/2025
Customer File Number: 000696-282366-AP-01
Policy Number:




Photo: 39

Date Taken:
01/07/2026

Taken By:
Curtis Murphy

Description:
View 2.



Photo: 40

Date Taken:
01/07/2026

Taken By:
Curtis Murphy

Description:
Passenger side
bumper shift and
cracked quarter
panel.

Claim Photo

Our File Number: 277-065974
Adjuster: Curtis Murphy
Insured: Churchill Casualty LTD.
Date of Loss: 12/09/2025
Customer File Number: 000696-282366-AP-01
Policy Number:



Photo: 41

Date Taken:
01/07/2026

Taken By:
Curtis Murphy

Description:
Close up, quarter
panel damages.




Photo: 42

Date Taken:
01/07/2026

Taken By:
Curtis Murphy

Description:
Undercarriage 1.

Claim Photo

Our File Number: 277-065974
Adjuster: Curtis Murphy
Insured: Churchill Casualty LTD.
Date of Loss: 12/09/2025
Customer File Number: 000696-282366-AP-01
Policy Number:



Photo: 43

Date Taken:
01/07/2026

Taken By:
Curtis Murphy

Description:
Undercarriage 2.



Photo: 44

Date Taken:
01/07/2026

Taken By:
Curtis Murphy

Description:
Undercarriage 3,
behind driver side
steer, damages.

Claim Photo

Our File Number: 277-065974
Adjuster: Curtis Murphy
Insured: Churchill Casualty LTD.
Date of Loss: 12/09/2025
Customer File Number: 000696-282366-AP-01
Policy Number:



Photo: 45

Date Taken:
01/07/2026

Taken By:
Curtis Murphy

Description:
Broken
components.



Photo: 46

Date Taken:
01/07/2026

Taken By:
Curtis Murphy

Description:
Close up of axle
damages.

Claim Photo

Our File Number: 277-065974
Adjuster: Curtis Murphy
Insured: Churchill Casualty LTD.
Date of Loss: 12/09/2025
Customer File Number: 000696-282366-AP-01
Policy Number:



Photo: 47

Date Taken:
01/07/2026

Taken By:
Curtis Murphy

Description:
View 2.




Photo: 48

Date Taken:
01/07/2026

Taken By:
Curtis Murphy

Description:
View under
suspension.

Claim Photo

Our File Number: 277-065974
Adjuster: Curtis Murphy
Insured: Churchill Casualty LTD.
Date of Loss: 12/09/2025
Customer File Number: 000696-282366-AP-01
Policy Number:




Photo: 49

Date Taken:
01/07/2026

Taken By:
Curtis Murphy

Description:
Components above
suspension.



Photo: 50

Date Taken:
01/07/2026

Taken By:
Curtis Murphy

Description:
Bumper pushed
against steer tire.

Claim Photo

Our File Number: 277-065974
Adjuster: Curtis Murphy
Insured: Churchill Casualty LTD.
Date of Loss: 12/09/2025
Customer File Number: 000696-282366-AP-01
Policy Number:



Photo: 51

Date Taken:
01/07/2026

Taken By:
Curtis Murphy

Description:
Additional
displaced
components.



Photo: 52

Date Taken:
01/07/2026

Taken By:
Curtis Murphy

Description:
View behind steer
tire.

Claim Photo

Our File Number: 277-065974
Adjuster: Curtis Murphy
Insured: Churchill Casualty LTD.
Date of Loss: 12/09/2025
Customer File Number: 000696-282366-AP-01
Policy Number:



Photo: 53

Date Taken:
01/07/2026

Taken By:
Curtis Murphy

Description:
Suspension shift.



Photo: 54

Date Taken:
01/07/2026

Taken By:
Curtis Murphy

Description:
Undercarriage
continued.

Claim Photo

Our File Number: 277-065974
Adjuster: Curtis Murphy
Insured: Churchill Casualty LTD.
Date of Loss: 12/09/2025
Customer File Number: 000696-282366-AP-01
Policy Number:



Photo: 55

Date Taken:
01/07/2026

Taken By:
Curtis Murphy

Description:
Damages to
column, front and
rear.




Photo: 56

Date Taken:
01/07/2026

Taken By:
Curtis Murphy

Description:
Showing steering
column shift.

Claim Photo

Our File Number: 277-065974
Adjuster: Curtis Murphy
Insured: Churchill Casualty LTD.
Date of Loss: 12/09/2025
Customer File Number: 000696-282366-AP-01
Policy Number:



Photo: 57

Date Taken:
01/07/2026

Taken By:
Curtis Murphy

Description:
View 2.




Photo: 58

Date Taken:
01/07/2026

Taken By:
Curtis Murphy

Description:
View 3.

Claim Photo

Our File Number: 277-065974
Adjuster: Curtis Murphy
Insured: Churchill Casualty LTD.
Date of Loss: 12/09/2025
Customer File Number: 000696-282366-AP-01
Policy Number:



Photo: 59

Date Taken:
01/07/2026

Taken By:
Curtis Murphy

Description:
Disconnect point.



Photo: 60

Date Taken:
01/07/2026

Taken By:
Curtis Murphy

Description:
Close up of
disconnect.

Claim Photo

Our File Number: 277-065974
Adjuster: Curtis Murphy
Insured: Churchill Casualty LTD.
Date of Loss: 12/09/2025
Customer File Number: 000696-282366-AP-01
Policy Number:



Photo: 61

Date Taken:
01/07/2026

Taken By:
Curtis Murphy

Description:
Undercarriage of
rear.



Photo: 62

Date Taken:
01/07/2026

Taken By:
Curtis Murphy

Description:
Undercarriage
continued.

Claim Photo

Our File Number: 277-065974
Adjuster: Curtis Murphy
Insured: Churchill Casualty LTD.
Date of Loss: 12/09/2025
Customer File Number: 000696-282366-AP-01
Policy Number:



Photo: 63

Date Taken:
01/07/2026

Taken By:
Curtis Murphy

Description:
Front connection
point, possible
shift.




Photo: 64

Date Taken:
01/07/2026

Taken By:
Curtis Murphy

Description:
Engine view,
Passenger side
engine view.

Claim Photo

Our File Number: 277-065974
Adjuster: Curtis Murphy
Insured: Churchill Casualty LTD.
Date of Loss: 12/09/2025
Customer File Number: 000696-282366-AP-01
Policy Number:




Photo: 65
Date Taken:
01/07/2026
Taken By:
Curtis Murphy
Description:
Upper view of the engine.



Photo: 66
Date Taken:
01/07/2026
Taken By:
Curtis Murphy
Description:
Engine information.

Claim Photo

Our File Number: 277-065974
Adjuster: Curtis Murphy
Insured: Churchill Casualty LTD.
Date of Loss: 12/09/2025
Customer File Number: 000696-282366-AP-01
Policy Number:



Photo: 67

Date Taken:
01/07/2026

Taken By:
Curtis Murphy

Description:
Additional engine tags.



Photo: 68

Date Taken:
01/07/2026

Taken By:
Curtis Murphy

Description:
Engine brand information.

Claim Photo

Our File Number: 277-065974
Adjuster: Curtis Murphy
Insured: Churchill Casualty LTD.
Date of Loss: 12/09/2025
Customer File Number: 000696-282366-AP-01
Policy Number:



Photo: 69

Date Taken:
01/07/2026

Taken By:
Curtis Murphy

Description:
Driver side engine
view.




Photo: 70

Date Taken:
01/07/2026

Taken By:
Curtis Murphy

Description:
Upper view, driver
side.

Claim Photo

Our File Number: 277-065974
Adjuster: Curtis Murphy
Insured: Churchill Casualty LTD.
Date of Loss: 12/09/2025
Customer File Number: 000696-282366-AP-01
Policy Number:



Photo: 71

Date Taken:
01/07/2026

Taken By:
Curtis Murphy

Description:
Front of grill view



Photo: 72

Date Taken:
01/07/2026

Taken By:
Curtis Murphy

Description:
View of bumper
damages from
above.

Claim Photo

Our File Number: 277-065974
Adjuster: Curtis Murphy
Insured: Churchill Casualty LTD.
Date of Loss: 12/09/2025
Customer File Number: 000696-282366-AP-01
Policy Number:



Photo: 73

Date Taken:
01/07/2026

Taken By:
Curtis Murphy

Description:
Close up.




Photo: 74

Date Taken:
01/07/2026

Taken By:
Curtis Murphy

Description:
View of suspension
and axle from
above.

Claim Photo

Our File Number: 277-065974
Adjuster: Curtis Murphy
Insured: Churchill Casualty LTD.
Date of Loss: 12/09/2025
Customer File Number: 000696-282366-AP-01
Policy Number:




Photo: 75

Date Taken:
01/07/2026

Taken By:
Curtis Murphy

Description:
View behind steer
tire.




Photo: 76

Date Taken:
01/07/2026

Taken By:
Curtis Murphy

Description:
Steer tire
information.

Claim Photo

Our File Number: 277-065974
Adjuster: Curtis Murphy
Insured: Churchill Casualty LTD.
Date of Loss: 12/09/2025
Customer File Number: 000696-282366-AP-01
Policy Number:



Photo: 77

Date Taken:
01/07/2026

Taken By:
Curtis Murphy

Description:
Continued.




Photo: 78

Date Taken:
01/07/2026

Taken By:
Curtis Murphy

Description:
Driver side steer
tread.

Claim Photo

Our File Number: 277-065974
Adjuster: Curtis Murphy
Insured: Churchill Casualty LTD.
Date of Loss: 12/09/2025
Customer File Number: 000696-282366-AP-01
Policy Number:



Photo: 79

Date Taken:
01/07/2026

Taken By:
Curtis Murphy

Description:
Drive tire
information.



Photo: 80

Date Taken:
01/07/2026

Taken By:
Curtis Murphy

Description:
Exterior driver side
drive.

Claim Photo

Our File Number: 277-065974
Adjuster: Curtis Murphy
Insured: Churchill Casualty LTD.
Date of Loss: 12/09/2025
Customer File Number: 000696-282366-AP-01
Policy Number:



Photo: 81

Date Taken:
01/07/2026

Taken By:
Curtis Murphy

Description:
Interior driver side
drive.



Photo: 82

Date Taken:
01/07/2026

Taken By:
Curtis Murphy

Description:
Exterior passenger
side drive.

Claim Photo

Our File Number: 277-065974
Adjuster: Curtis Murphy
Insured: Churchill Casualty LTD.
Date of Loss: 12/09/2025
Customer File Number: 000696-282366-AP-01
Policy Number:



Photo: 83

Date Taken:
01/07/2026

Taken By:
Curtis Murphy

Description:
Interior passenger
side drive.




Photo: 84

Date Taken:
01/07/2026

Taken By:
Curtis Murphy

Description:
Box and arm
assembly model
and serial.
Model #: 12000-30
K478444.
Serial #:
12000201015
Manufacture Date:
2/17/2020

Claim Photo

Our File Number: 277-065974
Adjuster: Curtis Murphy
Insured: Churchill Casualty LTD.
Date of Loss: 12/09/2025
Customer File Number: 000696-282366-AP-01
Policy Number:



Photo: 85

Date Taken:
01/07/2026

Taken By:
Curtis Murphy

Description:
Arm chart.



Photo: 86

Date Taken:
01/07/2026

Taken By:
Curtis Murphy

Description:
Electrical components.

Claim Photo

Our File Number: 277-065974
Adjuster: Curtis Murphy
Insured: Churchill Casualty LTD.
Date of Loss: 12/09/2025
Customer File Number: 000696-282366-AP-01
Policy Number:



Photo: 87

Date Taken:
01/07/2026

Taken By:
Curtis Murphy

Description:
Company and arm
information.



Photo: 88

Date Taken:
01/07/2026

Taken By:
Curtis Murphy

Description:
Damaged door
view 2.

Claim Photo

Our File Number: 277-065974
Adjuster: Curtis Murphy
Insured: Churchill Casualty LTD.
Date of Loss: 12/09/2025
Customer File Number: 000696-282366-AP-01
Policy Number:



Photo: 89

Date Taken:
01/07/2026

Taken By:
Curtis Murphy

Description:
Bumper remains.



Photo: 90

Date Taken:
01/07/2026

Taken By:
Curtis Murphy

Description:
Electrical
component
information.

Claim Photo

Our File Number: 277-065974
Adjuster: Curtis Murphy
Insured: Churchill Casualty LTD.
Date of Loss: 12/09/2025
Customer File Number: 000696-282366-AP-01
Policy Number:




Photo: 91

Date Taken:
01/07/2026

Taken By:
Curtis Murphy

Description:
Component chart.



Photo: 92

Date Taken:
01/07/2026

Taken By:
Curtis Murphy

Description:
Damaged tool box
section.

Claim Photo

Our File Number: 277-065974
Adjuster: Curtis Murphy
Insured: Churchill Casualty LTD.
Date of Loss: 12/09/2025
Customer File Number: 000696-282366-AP-01
Policy Number:




Photo: 93

Date Taken:
01/07/2026

Taken By:
Curtis Murphy

Description:
Tool Box frame
model, serial, and
manufacture.
Model #: D0M3S3
K478443
Serial #:
D0M3S3201029
Manufacture:
2/12/2020




Photo: 94

Date Taken:
01/07/2026

Taken By:
Curtis Murphy

Description:
Additional
manufacture
information.

Claim Photo

Our File Number: 277-065974
Adjuster: Curtis Murphy
Insured: Churchill Casualty LTD.
Date of Loss: 12/09/2025
Customer File Number: 000696-282366-AP-01
Policy Number:




Photo: 95

Date Taken:
01/07/2026

Taken By:
Curtis Murphy

Description:
Behind steer tire,
brake shot.




Photo: 96

Date Taken:
01/07/2026

Taken By:
Curtis Murphy

Description:
Between drive tires.

Claim Photo

Our File Number: 277-065974
Adjuster: Curtis Murphy
Insured: Churchill Casualty LTD.
Date of Loss: 12/09/2025
Customer File Number: 000696-282366-AP-01
Policy Number:



Photo: 97

Date Taken:
01/07/2026

Taken By:
Curtis Murphy

Description:
Behind drive tire,
brake shot.