

vin



info tag



miles



dash



left front



left view



left side sleeper damage



right rear



right side



fuel tank crushed, tool box damaged



left rear



rear



rear view



engine




right rear fender torn



right rear wheels



size



tread



brackets bent



left rear wheels damaged



aluminum rims damaged



left rear wheels/tires




left fender torn off



suspension damaged




air bag damaged




suspension damages



rim/tire damages



tread




tread



u bolt damage



rear suspension/axles



rear suspension damages



damaged air bag



left side damages



bracket damage



cab body panel torn



damage height



damage height



damage height





height



engine label



interior



sleeper



seats



interior view



side window broken



frame ok



under cab ok