

Claim Photo

Our File Number: 277-065888
Adjuster: Mike Hogan
Insured: Sysco Eastern Wisconsin
Date of Loss: 12/27/2025
Customer File Number: 1276-AV-26-0308126-001
Policy Number:




Photo: 1

Date Taken:
01/05/2026

Taken By:
William Orban

Description:
vin#




Photo: 2

Date Taken:
01/05/2026

Taken By:
William Orban

Description:
VIN#

Claim Photo

Our File Number: 277-065888
Adjuster: Mike Hogan
Insured: Sysco Eastern Wisconsin
Date of Loss: 12/27/2025
Customer File Number: 1276-AV-26-0308126-001
Policy Number:

cia
CUSTARD
INSURANCE ADJUSTERS



Photo: 3

Date Taken:
01/04/2026

Taken By:
William Orban

Description:
right front no
damage



Photo: 4

Date Taken:
01/04/2026

Taken By:
William Orban

Description:
left front

Claim Photo

Our File Number: 277-065888
Adjuster: Mike Hogan
Insured: Sysco Eastern Wisconsin
Date of Loss: 12/27/2025
Customer File Number: 1276-AV-26-0308126-001
Policy Number:



Photo: 5

Date Taken:
01/04/2026

Taken By:
William Orban

Description:
truck#



Photo: 6

Date Taken:
01/04/2026

Taken By:
William Orban

Description:
refer. no damage.
hours worked
unknown

Claim Photo

Our File Number: 277-065888
Adjuster: Mike Hogan
Insured: Sysco Eastern Wisconsin
Date of Loss: 12/27/2025
Customer File Number: 1276-AV-26-0308126-001
Policy Number:



Photo: 7

Date Taken:
01/05/2026

Taken By:
William Orban

Description:
right rear outer tire



Photo: 8

Date Taken:
01/05/2026

Taken By:
William Orban

Description:
right rear inner tire

Claim Photo

Our File Number: 277-065888
Adjuster: Mike Hogan
Insured: Sysco Eastern Wisconsin
Date of Loss: 12/27/2025
Customer File Number: 1276-AV-26-0308126-001
Policy Number:

cia
CUSTARD
INSURANCE ADJUSTERS



Photo: 9

Date Taken:
01/04/2026

Taken By:
William Orban

Description:
right front




Photo: 10

Date Taken:
01/05/2026

Taken By:
William Orban

Description:

Claim Photo

Our File Number: 277-065888
Adjuster: Mike Hogan
Insured: Sysco Eastern Wisconsin
Date of Loss: 12/27/2025
Customer File Number: 1276-AV-26-0308126-001
Policy Number:

cia[®]
CUSTARD
INSURANCE ADJUSTERS



Photo: 11

Date Taken:
01/04/2026

Taken By:
William Orban

Description:
right rear



Photo: 12

Date Taken:
01/04/2026

Taken By:
William Orban

Description:
right rear

Claim Photo

Our File Number: 277-065888
Adjuster: Mike Hogan
Insured: Sysco Eastern Wisconsin
Date of Loss: 12/27/2025
Customer File Number: 1276-AV-26-0308126-001
Policy Number:



Photo: 13

Date Taken:
01/04/2026

Taken By:
William Orban

Description:
top of the rear end



Photo: 14

Date Taken:
01/04/2026

Taken By:
William Orban

Description:
bottom of the rear end

Claim Photo

Our File Number: 277-065888
Adjuster: Mike Hogan
Insured: Sysco Eastern Wisconsin
Date of Loss: 12/27/2025
Customer File Number: 1276-AV-26-0308126-001
Policy Number:



Photo: 15

Date Taken:
01/04/2026

Taken By:
William Orban

Description:
left rear corner




Photo: 16

Date Taken:
01/04/2026

Taken By:
William Orban

Description:
left rear panel

Claim Photo

Our File Number: 277-065888
Adjuster: Mike Hogan
Insured: Sysco Eastern Wisconsin
Date of Loss: 12/27/2025
Customer File Number: 1276-AV-26-0308126-001
Policy Number:

cia
CUSTARD
INSURANCE ADJUSTERS



Photo: 17

Date Taken:
01/04/2026

Taken By:
William Orban

Description:
left rear corner



Photo: 18

Date Taken:
01/04/2026

Taken By:
William Orban

Description:
undercarriage
behind left rear
wheels

Claim Photo

Our File Number: 277-065888
Adjuster: Mike Hogan
Insured: Sysco Eastern Wisconsin
Date of Loss: 12/27/2025
Customer File Number: 1276-AV-26-0308126-001
Policy Number:



Photo: 19

Date Taken:
01/04/2026

Taken By:
William Orban

Description:
left rear wheels



Photo: 20

Date Taken:
01/04/2026

Taken By:
William Orban

Description:
undercarriage
behind the left rear
wheels

Claim Photo

Our File Number: 277-065888
Adjuster: Mike Hogan
Insured: Sysco Eastern Wisconsin
Date of Loss: 12/27/2025
Customer File Number: 1276-AV-26-0308126-001
Policy Number:

cia
CUSTARD
INSURANCE ADJUSTERS



Photo: 21

Date Taken:
01/04/2026

Taken By:
William Orban

Description:
damage to the rear left side



Photo: 22

Date Taken:
01/04/2026

Taken By:
William Orban

Description:
undercarriage on the left rear

Claim Photo

Our File Number: 277-065888
Adjuster: Mike Hogan
Insured: Sysco Eastern Wisconsin
Date of Loss: 12/27/2025
Customer File Number: 1276-AV-26-0308126-001
Policy Number:




2026/01/04

Photo: 23

Date Taken:
01/04/2026

Taken By:
William Orban

Description:
bottom rail below
the interior floor



2026/01/05

Photo: 24

Date Taken:
01/05/2026

Taken By:
William Orban

Description:
inside left rear. no
evidence of damage

Claim Photo

Our File Number: 277-065888
Adjuster: Mike Hogan
Insured: Sysco Eastern Wisconsin
Date of Loss: 12/27/2025
Customer File Number: 1276-AV-26-0308126-001
Policy Number:



Photo: 25

Date Taken:
01/05/2026

Taken By:
William Orban

Description:
interior right rear side. no damage



Photo: 26

Date Taken:
01/05/2026

Taken By:
William Orban

Description:
both left rear wheels damaged

Claim Photo

Our File Number: 277-065888
Adjuster: Mike Hogan
Insured: Sysco Eastern Wisconsin
Date of Loss: 12/27/2025
Customer File Number: 1276-AV-26-0308126-001
Policy Number:



Photo: 27

Date Taken:
01/05/2026

Taken By:
William Orban

Description:
damaged wheels