



Copart sticker VIN #



License plate number



Rear end



Rear end



Front end



Front end



4 section was damaged on the passenger's side



Front end damage



Roof damage



Roof damage



Front end was cut off



3 section was damaged on the driver's side



Driver's side



Undercarriage



Driver's side damage



Tires 30%



Rear end



Rear end damage



Passenger's side



4 sections was damaged on the passenger's side



Front end, floor damage



Undercarriage



Front undercarriage damage