

Fullerton Appraisal Services, Inc

2150 E FM 487

Jarrell, TX 76537

Phone: (512) 746-2500 Fax: (512) 531-7592

fullertonappraisal.net

Est ID: 770

File # 90453

Date Of Loss 11/7/2025

Insp Date: 2/16/2026

Written by: Robert Cox - 512-746-2500
Owner: DETMAR LOGISTICS - Insured
Contact Address

SAN ANTONIO TX 78258-3494

Phone Cell or email

Ins Company AUTO CLUB ENTERPRISES

Claim Rep JENNIFER STAGNER

Policy #

Claim # 017490641-C-304

Vehicle Information

2015 BEALL BAPS-105-2 10907K Trailer

VIN 10BDA7233FP002856

License Plate: 072B432 TX

Unit #

Color SILVER

Mileage 0

Hours 0

Repair Days

Line	Damage Description	Qty	Operation	Price	MU	Ext Price	BMT	BT	Labor	Paint	Sublet
1	QUARTER FENDER LT	1	Replace OEM	352.45		352.45			4.5	*	
2	QUARTER FENDER RT	1	Replace OEM	352.42		352.42			4.5	*	
3	CROSSMEMBER	1	Replace OEM	215.63		215.63			4.0		
4	FRAME RAIL LT		Repair Op						4.5		2.5
5	FRAME RAIL RT	1	Replace OEM	2,244.14		2,244.14			41.5	*	7.0
6	LANDING GEAR ASSEMBLY	1	Replace OEM	1,642.00		1,642.00			5.0		
7	BRACE, FLOOR SUPT	1	Replace OEM	154.54		154.54			0.5		
# 8	LOWER PIPE COUPLING LT SI	1	Replace OEM	342.85		342.85			3.2		
# 9	D.O.T. TAPE	1	Replace AM	52.00		52.00			1.0		
# 10	PIPE ASSEMBLY, CURBSIDE HOSE TUBE	1	Replace OEM	489.87		489.87			2.8		
# 11	10'HOSE CENTER	2	Replace OEM	312.22		624.44			2.0		
# 12	6'HOSE CENTER	1	Replace OEM	319.22		319.22			1.0		
# 13	HOSE COUPLER- ALUMINUM	2	Replace OEM	328.57		657.14			6.0		
# 14	BOTTOM TUB	1	Replace OEM	612.22		612.22			16.0		
# 15	PRESSURE TESTING		Labor Op						2.0		

Indicates Manual Entry Sup= Supplement Item F= Frame Labor M= Mechanical Labor BT= Betterment Type BX= Truck Box Item

BMT= Percentage of Betterment applies to Parts and/or Labor as indicated plus applicable sales tax. Line totals shown above do not include taxes.

* User selected to override TruckWriter labor and disable automated overlap protection.

Labor Detail Subtotals

Body Hrs	98.5 @ 175.00	17,237.50	Parts Total	-----	8,058.92
Paint Hrs	9.5 @ 175.00	1,662.50	Labor Total	-----	18,900.00
Mech Hrs	0.0 @ 175.00	0.00	Sublet	-----	0.00
Frame Hrs	0.0 @ 175.00	0.00	Towing	-----	0.00

Parts Detail Subtotals

OEM Parts:	8,006.92		Paint Materials	9.5 Hrs @ Rate 55.00	522.50
Plus 0% Markup = Net OEM Parts	8,006.92		Shop Materials	98.5 Hrs @ Rate 0.00	0.00
Non-OEM:	0.00	w/Mark Ups = 52.00	Taxes		
			Sales Tax	8,581.42 @ Rate 8.250%	707.97

Line	Damage Description	Qty	Operation	Price	MU	Ext Price	BMT	BT	Labor	Paint	Sublet
Sublet Sales Tax: 0.00 (Not Taxable)				Labor Tax		18,900.00 @	Rate	0.000%			0.00

BT= Betterment Type

- 1= Part Only
- 2= Part and Labor

Adjustments		
	Estimate Grand Total	\$ 28,189.39
	Less Deductible	\$ 0.00
	Less Betterment Inc Tax	\$ 0.00
	Net Estimate Amt	\$ 28,189.39

Estimate Remarks

Estimate is valid for 30 days from date written.

Damage Status:

This is not an authorization to repair or a guarantee of payment. The repair facility using this estimate must obtain authorization directly from the vehicle owner for repairs. This is only an estimate based on a visual inspection and further damage is possible due to unforeseen or hidden damage. No supplements will be considered unless prior approval is obtained from the estimator listed on this estimate. Parts listed as salvaged parts require replacement of damaged part with recycled salvaged parts of equal or better condition. TWE is not affiliated with any supplier depicted in this estimate and the end user has the right to chose whether or not to utilize their parts.

Repairer _____ *Contact*

,

Fax _____

e-mail _____

The above named repairer agrees to repair vehicle as per the contents of this estimate. Repairer also agrees to notify the appraiser if hidden or unforeseen damages are discovered during the repair process for prior approval.

Est agreed by: _____ Date _____