

## Claim Photo

**Our File Number:** 297-017926  
**Adjuster:** Scott Syner  
**Insured:** Juan Green Bull Transport LLC  
**Date of Loss:**  
**Customer File Number:** 25AQ1-03845  
**Policy Number:**



### Photo: 1

**Date Taken:**  
12/22/2025

**Taken By:**  
Dennis Thomson

**Description:**  
1322555 miles on  
the odometer



### Photo: 2

**Date Taken:**  
12/22/2025

**Taken By:**  
Dennis Thomson

**Description:**  
id/VIn on tractor 27



## Claim Photo

**Our File Number:** 297-017926  
**Adjuster:** Scott Syner  
**Insured:** Juan Green Bull Transport LLC  
**Date of Loss:**  
**Customer File Number:** 25AQ1-03845  
**Policy Number:**




**Photo: 3**

**Date Taken:**  
12/22/2025

**Taken By:**  
Dennis Thomson

**Description:**  
another ID on  
driver door f unit  
27



**Photo: 4**

**Date Taken:**  
12/22/2025

**Taken By:**  
Dennis Thomson

**Description:**  
component info on  
glove box area



## Claim Photo

**Our File Number:** 297-017926  
**Adjuster:** Scott Syner  
**Insured:** Juan Green Bull Transport LLC  
**Date of Loss:**  
**Customer File Number:** 25AQ1-03845  
**Policy Number:**




**Photo: 5**

**Date Taken:**  
12/22/2025

**Taken By:**  
Dennis Thomson

**Description:**  
unit 27; 2000  
freightliner



**Photo: 6**

**Date Taken:**  
12/22/2025

**Taken By:**  
Dennis Thomson

**Description:**  
passenger front to  
rear view unit 27



## Claim Photo

**Our File Number:** 297-017926  
**Adjuster:** Scott Syner  
**Insured:** Juan Green Bull Transport LLC  
**Date of Loss:**  
**Customer File Number:** 25AQ1-03845  
**Policy Number:**



**Photo: 7**

**Date Taken:**  
12/22/2025

**Taken By:**  
Dennis Thomson

**Description:**  
driver front to rear  
view unit 27



**Photo: 8**

**Date Taken:**  
12/22/2025

**Taken By:**  
Dennis Thomson

**Description:**  
drivers rear to front  
view



## Claim Photo

**Our File Number:** 297-017926  
**Adjuster:** Scott Syner  
**Insured:** Juan Green Bull Transport LLC  
**Date of Loss:**  
**Customer File Number:** 25AQ1-03845  
**Policy Number:**



**Photo: 9**

**Date Taken:**  
12/22/2025

**Taken By:**  
Dennis Thomson

**Description:**  
rear view unit 27



**Photo: 10**

**Date Taken:**  
12/22/2025


**Taken By:**  
Dennis Thomson

**Description:**  
area of  
impact/damage:  
lower right front



## Claim Photo

**Our File Number:** 297-017926  
**Adjuster:** Scott Syner  
**Insured:** Juan Green Bull Transport LLC  
**Date of Loss:**  
**Customer File Number:** 25AQ1-03845  
**Policy Number:**



**Photo: 11**

**Date Taken:**  
12/22/2025

**Taken By:**  
Dennis Thomson

**Description:**  
left side drives



**Photo: 12**

**Date Taken:**  
12/22/2025

**Taken By:**  
Dennis Thomson

**Description:**  
right side drives



## Claim Photo

**Our File Number:** 297-017926  
**Adjuster:** Scott Syner  
**Insured:** Juan Green Bull Transport LLC  
**Date of Loss:**  
**Customer File Number:** 25AQ1-03845  
**Policy Number:**



**Photo: 13**

**Date Taken:**  
12/22/2025

**Taken By:**  
Dennis Thomson

**Description:**  
prior damage to  
headache rack



**Photo: 14**

**Date Taken:**  
12/22/2025

**Taken By:**  
Dennis Thomson

**Description:**  
lower right side  
view-no step  
damage



## Claim Photo

**Our File Number:** 297-017926  
**Adjuster:** Scott Syner  
**Insured:** Juan Green Bull Transport LLC  
**Date of Loss:**  
**Customer File Number:** 25AQ1-03845  
**Policy Number:**



**Photo: 15**

**Date Taken:**  
12/22/2025

**Taken By:**  
Dennis Thomson

**Description:**  
no engine damage



**Photo: 16**

**Date Taken:**  
12/22/2025

**Taken By:**  
Dennis Thomson

**Description:**  
right front steer



## Claim Photo

**Our File Number:** 297-017926  
**Adjuster:** Scott Syner  
**Insured:** Juan Green Bull Transport LLC  
**Date of Loss:**  
**Customer File Number:** 25AQ1-03845  
**Policy Number:**



**Photo: 17**

**Date Taken:**  
12/22/2025

**Taken By:**  
Dennis Thomson

**Description:**  
looking across front  
at hood mounts  
right to left



**Photo: 18**

**Date Taken:**  
12/22/2025


**Taken By:**  
Dennis Thomson

**Description:**  
tire marks on lower  
front bumper right  
side



## Claim Photo

**Our File Number:** 297-017926  
**Adjuster:** Scott Syner  
**Insured:** Juan Green Bull Transport LLC  
**Date of Loss:**  
**Customer File Number:** 25AQ1-03845  
**Policy Number:**



**Photo: 19**

**Date Taken:**  
12/22/2025

**Taken By:**  
Dennis Thomson

**Description:**  
looking across front  
left to right at hood  
mounts



**Photo: 20**

**Date Taken:**  
12/22/2025

**Taken By:**  
Dennis Thomson

**Description:**  
sleeper



## Claim Photo

**Our File Number:** 297-017926  
**Adjuster:** Scott Syner  
**Insured:** Juan Green Bull Transport LLC  
**Date of Loss:**  
**Customer File Number:** 25AQ1-03845  
**Policy Number:**



**Photo: 21**

**Date Taken:**  
12/22/2025

**Taken By:**  
Dennis Thomson

**Description:**  
sitting on sleeper  
looking at dash and  
interior



**Photo: 22**

**Date Taken:**  
12/22/2025

**Taken By:**  
Dennis Thomson

**Description:**  
dash



## Claim Photo

**Our File Number:** 297-017926  
**Adjuster:** Scott Syner  
**Insured:** Juan Green Bull Transport LLC  
**Date of Loss:**  
**Customer File Number:** 25AQ1-03845  
**Policy Number:**



**Photo: 23**

**Date Taken:**  
12/22/2025

**Taken By:**  
Dennis Thomson

**Description:**  
eaton 18 speed



**Photo: 24**

**Date Taken:**  
12/22/2025

**Taken By:**  
Dennis Thomson

**Description:**  
sleeper bed good  
shape



## Claim Photo

**Our File Number:** 297-017926  
**Adjuster:** Scott Syner  
**Insured:** Juan Green Bull Transport LLC  
**Date of Loss:**  
**Customer File Number:** 25AQ1-03845  
**Policy Number:**



**Photo: 25**

**Date Taken:**  
12/22/2025

**Taken By:**  
Dennis Thomson

**Description:**  
sleeper  
compartment  
interior-right side



**Photo: 26**

**Date Taken:**  
12/22/2025

**Taken By:**  
Dennis Thomson

**Description:**  
left side sleeper  
interior



## Claim Photo

**Our File Number:** 297-017926  
**Adjuster:** Scott Syner  
**Insured:** Juan Green Bull Transport LLC  
**Date of Loss:**  
**Customer File Number:** 25AQ1-03845  
**Policy Number:**



**Photo: 27**

**Date Taken:**  
12/22/2025

**Taken By:**  
Dennis Thomson

**Description:**  
looking down on  
driver seat



**Photo: 28**



**Date Taken:**  
12/22/2025

**Taken By:**  
Dennis Thomson

**Description:**  
lower right side  
behind hood



**Our File Number:** 297-017926  
**Adjuster:** Scott Syner  
**Insured:** Juan Green Bull Transport LLC  
**Date of Loss:**  
**Customer File Number:** 25AQ1-03845  
**Policy Number:**

**Description:****Description:**



Claim Photo

Our File Number: 297-017926  
Adjuster: Scott Syner  
Insured: Juan Green Bull Transport LLC  
Date of Loss:  
Customer File Number: 25AQ1-03845  
Policy Number:



Photo: 31

Date Taken:  
12/22/2025

Taken By:  
Page 2

Description:

[External] QEO - Message (HTML) (Read-Only)

File Message Help

Ignore Delete Archive Reply Reply Forward IM Meeting All Apps Move Send to OneNote Mark Unread Categorize Follow Up Find Related Select Read Aloud Immersive Reader Translate Zoom

[External] QEO

Dthomson <dthsm@yahoo.com>  
To: Thomson, Dennis

Options / Equipment

☐ Auxiliary Power Unit ☐ PTO Wet Line Kit ☐ Cruise Control ☐ AM ☐ FM ☐ Type ☐ CD ☐ CB

☐ AC ☐ TR Wheel ☐ Telescopic Wheel ☐ Air Ride Seat ☐ Air Ride Cab ☐ Air Bag

☐ PS ☐ Elec Windows ☐ Heated Mirror ☐ Engine Braking System

☐ Owner/Operator Package

☐ Liftgate Manufacturer

☐ Roof Rack Unit (Straight Truck) Roof Rack Model # \_\_\_\_\_ Rating \_\_\_\_\_ Serial # \_\_\_\_\_

☐ Special Paint/Trim ☐ Other: \_\_\_\_\_

CONDITION: (1 = Excellent, 2 = Above Average, 3 = Average, 4 = Below Average, 5 = Poor)

	TRUCK	TIRES
PAINT:	<input type="checkbox"/> 1 <input type="checkbox"/> 2 <input type="checkbox"/> 3 <input type="checkbox"/> 4 <input type="checkbox"/> 5	Front Tires: Make: <u>7DVP</u> Size: <u>295-75R22.5</u>
INTERIOR:	<input type="checkbox"/> 1 <input type="checkbox"/> 2 <input type="checkbox"/> 3 <input type="checkbox"/> 4 <input type="checkbox"/> 5	Rear Tires: Make: <u>6R11</u> Size: <u>295-75R22.5</u>
EXTERIOR:	<input type="checkbox"/> 1 <input type="checkbox"/> 2 <input type="checkbox"/> 3 <input type="checkbox"/> 4 <input type="checkbox"/> 5	Chromes/Demolished Trim
MECHANICAL:	<input type="checkbox"/> 1 <input type="checkbox"/> 2 <input type="checkbox"/> 3 <input type="checkbox"/> 4 <input type="checkbox"/> 5	Tread Wear: L1 <u>1.5</u> R2 RF <u>1.5</u> R2
OVERALL:	<input type="checkbox"/> 1 <input type="checkbox"/> 2 <input type="checkbox"/> 3 <input type="checkbox"/> 4 <input type="checkbox"/> 5	

NADA OR TRUCK BLUE BOOK RETAIL VALUE:

☐ This unit has a current NADA or Truck Blue Book retail value of: \$ \_\_\_\_\_  
(Please see the attached book value report for details.)

☐ NADA or Truck Blue Book values are not available for this unit.

MARKET SURVEY OF DEALER QUOTES:

	Dealer Name	Phone	Contact	Dealer quote
1.				\$
2.				\$
3.				\$
4.				\$

Truck Specification/Valuation Sheet 1 Rev. 04/13/17