

Claim Photo

Our File Number: 277-065691
Adjuster: Michael Cameron
Insured: FEDEX CORPORATION-EXPRESS, FREIGHT, OFFICE, LOGISTICS
Date of Loss: 12/09/2025
Customer File Number: 015558-605065-AD-01
Policy Number:



Photo: 1

Date Taken:
12/22/2025

Taken By:
Alvaro Canarte

Description:
VIN



Photo: 2

Date Taken:
12/22/2025

Taken By:
Alvaro Canarte

Description:
VIN

Claim Photo

Our File Number: 277-065691
Adjuster: Michael Cameron
Insured: FEDEX CORPORATION-EXPRESS, FREIGHT, OFFICE, LOGISTICS
Date of Loss: 12/09/2025
Customer File Number: 015558-605065-AD-01
Policy Number:



Photo: 3

Date Taken:
12/22/2025

Taken By:
Alvaro Canarte

Description:
Label on trailer



Photo: 4

Date Taken:
12/22/2025

Taken By:
Alvaro Canarte

Description:
Overview

Claim Photo

Our File Number: 277-065691
Adjuster: Michael Cameron
Insured: FEDEX CORPORATION-EXPRESS, FREIGHT, OFFICE, LOGISTICS
Date of Loss: 12/09/2025
Customer File Number: 015558-605065-AD-01
Policy Number:



Photo: 5

Date Taken:
12/22/2025

Taken By:
Alvaro Canarte

Description:
Overview



Photo: 6

Date Taken:
12/22/2025

Taken By:
Alvaro Canarte

Description:
Overview

Claim Photo

Our File Number: 277-065691
Adjuster: Michael Cameron
Insured: FEDEX CORPORATION-EXPRESS, FREIGHT, OFFICE, LOGISTICS
Date of Loss: 12/09/2025
Customer File Number: 015558-605065-AD-01
Policy Number:



Photo: 7

Date Taken:
12/22/2025

Taken By:
Alvaro Canarte

Description:
Overview



Photo: 8

Date Taken:
12/22/2025

Taken By:
Alvaro Canarte

Description:
License plate

Claim Photo

Our File Number: 277-065691
Adjuster: Michael Cameron
Insured: FEDEX CORPORATION-EXPRESS, FREI GHT, OFFICE, LOGISTICS
Date of Loss: 12/09/2025
Customer File Number: 015558-605065-AD-01
Policy Number:



Photo: 9

Date Taken:
12/22/2025

Taken By:
Alvaro Canarte

Description:
Overview of
damaged area
driver side




Photo: 10

Date Taken:
12/22/2025

Taken By:
Alvaro Canarte

Description:
Driver side:
damaged to corner
frame

Claim Photo

Our File Number: 277-065691
Adjuster: Michael Cameron
Insured: FEDEX CORPORATION-EXPRESS, FREI GHT, OFFICE, LOGISTICS
Date of Loss: 12/09/2025
Customer File Number: 015558-605065-AD-01
Policy Number:



Photo: 11

Date Taken:
12/22/2025

Taken By:
Alvaro Canarte

Description:
Driver side:
damaged to corner
frame



Photo: 12

Date Taken:
12/22/2025

Taken By:
Alvaro Canarte

Description:
Driver side:
damaged to corner
frame

Claim Photo

Our File Number: 277-065691
Adjuster: Michael Cameron
Insured: FEDEX CORPORATION-EXPRESS, FREI GHT, OFFICE, LOGISTICS
Date of Loss: 12/09/2025
Customer File Number: 015558-605065-AD-01
Policy Number:



Photo: 13

Date Taken:
12/22/2025

Taken By:
Alvaro Canarte

Description:
Driver side:
damaged to corner
frame, wiring



Photo: 14

Date Taken:
12/22/2025

Taken By:
Alvaro Canarte

Description:
Driver side:
damaged to corner
frame

Claim Photo

Our File Number: 277-065691
Adjuster: Michael Cameron
Insured: FEDEX CORPORATION-EXPRESS, FREIGHT, OFFICE, LOGISTICS
Date of Loss: 12/09/2025
Customer File Number: 015558-605065-AD-01
Policy Number:



Photo: 15

Date Taken:
12/22/2025

Taken By:
Alvaro Canarte

Description:
Driver side: bottom
area damaged



Photo: 16

Date Taken:
12/22/2025

Taken By:
Alvaro Canarte

Description:
Driver side:
damaged to corner
frame

Claim Photo

Our File Number: 277-065691
Adjuster: Michael Cameron
Insured: FEDEX CORPORATION-EXPRESS, FREI GHT, OFFICE, LOGISTICS
Date of Loss: 12/09/2025
Customer File Number: 015558-605065-AD-01
Policy Number:



Photo: 17

Date Taken:
12/22/2025

Taken By:
Alvaro Canarte

Description:
Driver side:
damaged to corner
frame



Photo: 18

Date Taken:
12/22/2025

Taken By:
Alvaro Canarte

Description:
Passenger side:
damaged to corner
frame and light

Claim Photo

Our File Number: 277-065691
Adjuster: Michael Cameron
Insured: FEDEX CORPORATION-EXPRESS, FREI GHT, OFFICE, LOGISTICS
Date of Loss: 12/09/2025
Customer File Number: 015558-605065-AD-01
Policy Number:



Photo: 19

Date Taken:
12/22/2025

Taken By:
Alvaro Canarte

Description:
Passenger side:
damaged to corner
frame and light



Photo: 20

Date Taken:
12/22/2025

Taken By:
Alvaro Canarte

Description:
Passenger side:
damaged to corner
frame and light

Claim Photo

Our File Number: 277-065691
Adjuster: Michael Cameron
Insured: FEDEX CORPORATION-EXPRESS, FREI GHT, OFFICE, LOGISTICS
Date of Loss: 12/09/2025
Customer File Number: 015558-605065-AD-01
Policy Number:



Photo: 21

Date Taken:
12/22/2025

Taken By:
Alvaro Canarte

Description:
Passenger side:
damaged to corner
frame and light



Photo: 22

Date Taken:
12/22/2025

Taken By:
Alvaro Canarte

Description:
Overview of
damaged area

Claim Photo

Our File Number: 277-065691
Adjuster: Michael Cameron
Insured: FEDEX CORPORATION-EXPRESS, FREI GHT, OFFICE, LOGISTICS
Date of Loss: 12/09/2025
Customer File Number: 015558-605065-AD-01
Policy Number:



Photo: 23

Date Taken:
12/22/2025

Taken By:
Alvaro Canarte

Description:
Overview of
damaged area



Photo: 24

Date Taken:
12/22/2025

Taken By:
Alvaro Canarte

Description:
Overview of
damaged area

Claim Photo

Our File Number: 277-065691
Adjuster: Michael Cameron
Insured: FEDEX CORPORATION-EXPRESS, FREIGHT, OFFICE, LOGISTICS
Date of Loss: 12/09/2025
Customer File Number: 015558-605065-AD-01
Policy Number:



Photo: 25

Date Taken:
12/22/2025

Taken By:
Alvaro Canarte

Description:
Overview of
damaged area



Photo: 26

Date Taken:
12/22/2025

Taken By:
Alvaro Canarte

Description:
Overview of
damaged area

Claim Photo

Our File Number: 277-065691
Adjuster: Michael Cameron
Insured: FEDEX CORPORATION-EXPRESS, FREI GHT, OFFICE, LOGISTICS
Date of Loss: 12/09/2025
Customer File Number: 015558-605065-AD-01
Policy Number:



Photo: 27

Date Taken:
12/22/2025

Taken By:
Alvaro Canarte

Description:
Inside of trailer



Photo: 28

Date Taken:
12/22/2025

Taken By:
Alvaro Canarte

Description:
Inside of trailer

Claim Photo

Our File Number: 277-065691
Adjuster: Michael Cameron
Insured: FEDEX CORPORATION-EXPRESS, FREI GHT, OFFICE, LOGISTICS
Date of Loss: 12/09/2025
Customer File Number: 015558-605065-AD-01
Policy Number:



Photo: 29

Date Taken:
12/22/2025

Taken By:
Alvaro Canarte

Description:
Inside of trailer,
whole on drive side
top corner




Photo: 30

Date Taken:
12/22/2025

Taken By:
Alvaro Canarte

Description:
Inside of trailer,
whole on drive side
top corner

Claim Photo

Our File Number: 277-065691
Adjuster: Michael Cameron
Insured: FEDEX CORPORATION-EXPRESS, FREI GHT, OFFICE, LOGISTICS
Date of Loss: 12/09/2025
Customer File Number: 015558-605065-AD-01
Policy Number:



Photo: 31

Date Taken:
12/22/2025

Taken By:
Alvaro Canarte

Description:
Inside of trailer,
whole on drive side
top corner




Photo: 32

Date Taken:
12/22/2025

Taken By:
Alvaro Canarte

Description:
Inside of trailer,
whole on drive side
top corner

Claim Photo

Our File Number: 277-065691
Adjuster: Michael Cameron
Insured: FEDEX CORPORATION-EXPRESS, FREIGHT, OFFICE, LOGISTICS
Date of Loss: 12/09/2025
Customer File Number: 015558-605065-AD-01
Policy Number:



Photo: 33

Date Taken:
12/22/2025

Taken By:
Alvaro Canarte

Description:
Inside of trailer,
whole on drive side
top corner




Photo: 34

Date Taken:
12/22/2025

Taken By:
Alvaro Canarte

Description:
Damaged plywood
and inside frame

Claim Photo

Our File Number: 277-065691
Adjuster: Michael Cameron
Insured: FEDEX CORPORATION-EXPRESS, FREIGHT, OFFICE, LOGISTICS
Date of Loss: 12/09/2025
Customer File Number: 015558-605065-AD-01
Policy Number:



Photo: 35

Date Taken:
12/22/2025

Taken By:
Alvaro Canarte

Description:
Damaged plywood
and inside frame



Photo: 36

Date Taken:
12/22/2025

Taken By:
Alvaro Canarte

Description:
Damaged plywood
and inside frame

Claim Photo

Our File Number: 277-065691
Adjuster: Michael Cameron
Insured: FEDEX CORPORATION-EXPRESS, FREI GHT, OFFICE, LOGISTICS
Date of Loss: 12/09/2025
Customer File Number: 015558-605065-AD-01
Policy Number:



Photo: 37
Date Taken: 12/22/2025
Taken By: Alvaro Canarte
Description: Damaged plywood and inside frame