



Outside of building



LF



01/20/2026 12:28

LR



01/20/2026 12:30

RF



RR




Homeless camp behind building



01/20/2026 12:28

Engine Compartment



01/20/2026 12:29

Engine Door



Dealer Tag



Melted plastic on hydraulic line



Upper Cab & melted Roof



Lower Cab



Hood & Back of Cab



Engine