



all front end damaged



99 gal tank



all front end damaged



clmt logo



clmt loss



coolers against motor



dayton hubs



has roll back box



interior worn



auto shift



interior view



rt interior view



all front end damaged



ok here



odometer view



tag number



steering broken glass damage



steer wheel



steel dayton



drive tires worn



faded vin tag