

Claim Photo

Our File Number: 277-065585
Adjuster: Michael Cameron
Insured: AMCON DISTRIBUTING COMPANY
Date of Loss: 12/10/2025
Customer File Number: 011260-189171-AP-02
Policy Number:




Photo: 1

Date Taken:
01/02/2026

Taken By:
Curtis Murphy

Description:
2016 Utility Trailer,
VIN:
1UYVS128XGU72
8003. VIN tag.




Photo: 2

Date Taken:
01/02/2026

Taken By:
Curtis Murphy

Description:
VIN verification.

Claim Photo

Our File Number: 277-065585
Adjuster: Michael Cameron
Insured: AMCON DISTRIBUTING COMPANY
Date of Loss: 12/10/2025
Customer File Number: 011260-189171-AP-02
Policy Number:



Photo: 3

Date Taken:
01/02/2026

Taken By:
Curtis Murphy

Description:
Unit tags.



Photo: 4

Date Taken:
01/02/2026

Taken By:
Curtis Murphy

Description:
Reefer unit, pulled free and inside remaining trailer.

Claim Photo

Our File Number: 277-065585
Adjuster: Michael Cameron
Insured: AMCON DISTRIBUTING COMPANY
Date of Loss: 12/10/2025
Customer File Number: 011260-189171-AP-02
Policy Number:




Photo: 5

Date Taken:
01/02/2026

Taken By:
Curtis Murphy

Description:
Reefer unit.




Photo: 6

Date Taken:
01/02/2026

Taken By:
Curtis Murphy

Description:
Copart lot number:
97030455.

Claim Photo

Our File Number: 277-065585
Adjuster: Michael Cameron
Insured: AMCON DISTRIBUTING COMPANY
Date of Loss: 12/10/2025
Customer File Number: 011260-189171-AP-02
Policy Number:



Photo: 7

Date Taken:
01/02/2026

Taken By:
Curtis Murphy

Description:
Front driver side.



Photo: 8

Date Taken:
01/02/2026

Taken By:
Curtis Murphy

Description:
Rear driver side.

Claim Photo

Our File Number: 277-065585
Adjuster: Michael Cameron
Insured: AMCON DISTRIBUTING COMPANY
Date of Loss: 12/10/2025
Customer File Number: 011260-189171-AP-02
Policy Number:



Photo: 9

Date Taken:
01/02/2026

Taken By:
Curtis Murphy

Description:
Rear passenger
side.



Photo: 10

Date Taken:
01/02/2026

Taken By:
Curtis Murphy

Description:
Front passenger
side.

Claim Photo

Our File Number: 277-065585
Adjuster: Michael Cameron
Insured: AMCON DISTRIBUTING COMPANY
Date of Loss: 12/10/2025
Customer File Number: 011260-189171-AP-02
Policy Number:



Photo: 11

Date Taken:
01/02/2026

Taken By:
Curtis Murphy

Description:
Damages, front
passenger side.



Photo: 12

Date Taken:
01/02/2026

Taken By:
Curtis Murphy

Description:
Roof damages.

Claim Photo

Our File Number: 277-065585
Adjuster: Michael Cameron
Insured: AMCON DISTRIBUTING COMPANY
Date of Loss: 12/10/2025
Customer File Number: 011260-189171-AP-02
Policy Number:



Photo: 13

Date Taken:
01/02/2026

Taken By:
Curtis Murphy

Description:
Front driver side.



Photo: 14

Date Taken:
01/02/2026

Taken By:
Curtis Murphy

Description:
Upper view, roof
damages.

Claim Photo

Our File Number: 277-065585
Adjuster: Michael Cameron
Insured: AMCON DISTRIBUTING COMPANY
Date of Loss: 12/10/2025
Customer File Number: 011260-189171-AP-02
Policy Number:



Photo: 15

Date Taken:
01/02/2026

Taken By:
Curtis Murphy

Description:
Driver side panel
damages.



Photo: 16

Date Taken:
01/02/2026

Taken By:
Curtis Murphy

Description:
Upper panel view,
damages.

Claim Photo

Our File Number: 277-065585
Adjuster: Michael Cameron
Insured: AMCON DISTRIBUTING COMPANY
Date of Loss: 12/10/2025
Customer File Number: 011260-189171-AP-02
Policy Number:



Photo: 17

Date Taken:
01/02/2026

Taken By:
Curtis Murphy

Description:
Lower rail missing.




Photo: 18

Date Taken:
01/02/2026

Taken By:
Curtis Murphy

Description:
Scrapes along
driver side,
consistent.

Claim Photo

Our File Number: 277-065585
Adjuster: Michael Cameron
Insured: AMCON DISTRIBUTING COMPANY
Date of Loss: 12/10/2025
Customer File Number: 011260-189171-AP-02
Policy Number:



Photo: 19

Date Taken:
01/02/2026

Taken By:
Curtis Murphy

Description:
Upper wall view.



Photo: 20

Date Taken:
01/02/2026

Taken By:
Curtis Murphy

Description:
Breaks within the
lower rail.

Claim Photo

Our File Number: 277-065585
Adjuster: Michael Cameron
Insured: AMCON DISTRIBUTING COMPANY
Date of Loss: 12/10/2025
Customer File Number: 011260-189171-AP-02
Policy Number:



Photo: 21

Date Taken:
01/02/2026

Taken By:
Curtis Murphy

Description:
Close up, rail
damages.



Photo: 22

Date Taken:
01/02/2026

Taken By:
Curtis Murphy

Description:
Impact to lower
rail, additional
damages.

Claim Photo

Our File Number: 277-065585
Adjuster: Michael Cameron
Insured: AMCON DISTRIBUTING COMPANY
Date of Loss: 12/10/2025
Customer File Number: 011260-189171-AP-02
Policy Number:



Photo: 23

Date Taken:
01/02/2026

Taken By:
Curtis Murphy

Description:
Lower impact view.




Photo: 24

Date Taken:
01/02/2026

Taken By:
Curtis Murphy

Description:
Rear driver side
corner. Bumper
shift.

Claim Photo

Our File Number: 277-065585
Adjuster: Michael Cameron
Insured: AMCON DISTRIBUTING COMPANY
Date of Loss: 12/10/2025
Customer File Number: 011260-189171-AP-02
Policy Number:



Photo: 25

Date Taken:
01/02/2026

Taken By:
Curtis Murphy

Description:
Rear driver side
corner, dents to
corner rail.



Photo: 26

Date Taken:
01/02/2026

Taken By:
Curtis Murphy

Description:
Scrapes and dents
to corner.

Claim Photo

Our File Number: 277-065585
Adjuster: Michael Cameron
Insured: AMCON DISTRIBUTING COMPANY
Date of Loss: 12/10/2025
Customer File Number: 011260-189171-AP-02
Policy Number:



Photo: 27

Date Taken:
01/02/2026

Taken By:
Curtis Murphy

Description:
Dent in rear driver
side cargo door.




Photo: 28

Date Taken:
01/02/2026

Taken By:
Curtis Murphy

Description:
Upper door view.

Claim Photo

Our File Number: 277-065585
Adjuster: Michael Cameron
Insured: AMCON DISTRIBUTING COMPANY
Date of Loss: 12/10/2025
Customer File Number: 011260-189171-AP-02
Policy Number:



Photo: 29

Date Taken:
01/02/2026

Taken By:
Curtis Murphy

Description:
Full rear view of
trailer.



Photo: 30

Date Taken:
01/02/2026

Taken By:
Curtis Murphy

Description:
Upper doors, shift
to driver side door.

Claim Photo

Our File Number: 277-065585
Adjuster: Michael Cameron
Insured: AMCON DISTRIBUTING COMPANY
Date of Loss: 12/10/2025
Customer File Number: 011260-189171-AP-02
Policy Number:



Photo: 31

Date Taken:
01/02/2026

Taken By:
Curtis Murphy

Description:
Close up, shift to door.




Photo: 32

Date Taken:
01/02/2026

Taken By:
Curtis Murphy

Description:
Passenger side trailer.

Claim Photo

Our File Number: 277-065585
Adjuster: Michael Cameron
Insured: AMCON DISTRIBUTING COMPANY
Date of Loss: 12/10/2025
Customer File Number: 011260-189171-AP-02
Policy Number:



Photo: 33

Date Taken:
01/02/2026

Taken By:
Curtis Murphy

Description:
Panels damages
along passenger
side.




Photo: 34

Date Taken:
01/02/2026

Taken By:
Curtis Murphy

Description:
Upper rail
damages.

Claim Photo

Our File Number: 277-065585
Adjuster: Michael Cameron
Insured: AMCON DISTRIBUTING COMPANY
Date of Loss: 12/10/2025
Customer File Number: 011260-189171-AP-02
Policy Number:



Photo: 35

Date Taken:
01/02/2026

Taken By:
Curtis Murphy

Description:
Decking and panel
damages, passenger
side.



Photo: 36

Date Taken:
01/02/2026

Taken By:
Curtis Murphy

Description:
Upper panel view.

Claim Photo

Our File Number: 277-065585
Adjuster: Michael Cameron
Insured: AMCON DISTRIBUTING COMPANY
Date of Loss: 12/10/2025
Customer File Number: 011260-189171-AP-02
Policy Number:



Photo: 37

Date Taken:
01/02/2026

Taken By:
Curtis Murphy

Description:
Front passenger
side corner
damages, decking.



Photo: 38

Date Taken:
01/02/2026

Taken By:
Curtis Murphy

Description:
Front of trailer
damages.

Claim Photo

Our File Number: 277-065585
Adjuster: Michael Cameron
Insured: AMCON DISTRIBUTING COMPANY
Date of Loss: 12/10/2025
Customer File Number: 011260-189171-AP-02
Policy Number:



Photo: 39

Date Taken:
01/02/2026

Taken By:
Curtis Murphy

Description:
Roofing hanging on interior.



Photo: 40

Date Taken:
01/02/2026

Taken By:
Curtis Murphy

Description:
Upper roof view.

Claim Photo

Our File Number: 277-065585
Adjuster: Michael Cameron
Insured: AMCON DISTRIBUTING COMPANY
Date of Loss: 12/10/2025
Customer File Number: 011260-189171-AP-02
Policy Number:



Photo: 41

Date Taken:
01/02/2026

Taken By:
Curtis Murphy

Description:
Passenger side
interior damages.



Photo: 42

Date Taken:
01/02/2026

Taken By:
Curtis Murphy

Description:
View of reefer unit.

Claim Photo

Our File Number: 277-065585
Adjuster: Michael Cameron
Insured: AMCON DISTRIBUTING COMPANY
Date of Loss: 12/10/2025
Customer File Number: 011260-189171-AP-02
Policy Number:



Photo: 43

Date Taken:
01/02/2026

Taken By:
Curtis Murphy

Description:
View of interior
near cargo doors.



Photo: 44

Date Taken:
01/02/2026

Taken By:
Curtis Murphy

Description:
Top view, showing
gap above driver
side cargo door.

Claim Photo

Our File Number: 277-065585
Adjuster: Michael Cameron
Insured: AMCON DISTRIBUTING COMPANY
Date of Loss: 12/10/2025
Customer File Number: 011260-189171-AP-02
Policy Number:



Photo: 45

Date Taken:
01/02/2026

Taken By:
Curtis Murphy

Description:
View 2 of reefer unit.



Photo: 46

Date Taken:
01/02/2026

Taken By:
Curtis Murphy

Description:
Bending of
passenger side wall.

Claim Photo

Our File Number: 277-065585
Adjuster: Michael Cameron
Insured: AMCON DISTRIBUTING COMPANY
Date of Loss: 12/10/2025
Customer File Number: 011260-189171-AP-02
Policy Number:



Photo: 47

Date Taken:
01/02/2026

Taken By:
Curtis Murphy

Description:
Upper roof.



Photo: 48

Date Taken:
01/02/2026

Taken By:
Curtis Murphy

Description:
Lower exterior rail,
preparing for
undercarriage view.

Claim Photo

Our File Number: 277-065585
Adjuster: Michael Cameron
Insured: AMCON DISTRIBUTING COMPANY
Date of Loss: 12/10/2025
Customer File Number: 011260-189171-AP-02
Policy Number:



Photo: 49

Date Taken:
01/02/2026

Taken By:
Curtis Murphy

Description:
Undercarriage view
1. Substantial frame
damages.



Photo: 50

Date Taken:
01/02/2026

Taken By:
Curtis Murphy

Description:
View 2.

Claim Photo

Our File Number: 277-065585
Adjuster: Michael Cameron
Insured: AMCON DISTRIBUTING COMPANY
Date of Loss: 12/10/2025
Customer File Number: 011260-189171-AP-02
Policy Number:



Photo: 51

Date Taken:
01/02/2026

Taken By:
Curtis Murphy

Description:
View 3.



Photo: 52

Date Taken:
01/02/2026

Taken By:
Curtis Murphy

Description:
View of landing gear.

Claim Photo

Our File Number: 277-065585
Adjuster: Michael Cameron
Insured: AMCON DISTRIBUTING COMPANY
Date of Loss: 12/10/2025
Customer File Number: 011260-189171-AP-02
Policy Number:



Photo: 53

Date Taken:
01/02/2026

Taken By:
Curtis Murphy

Description:
Landing gear bent
up.



Photo: 54

Date Taken:
01/02/2026

Taken By:
Curtis Murphy

Description:
Top view of
landing gear,
displaced.

Claim Photo

Our File Number: 277-065585
Adjuster: Michael Cameron
Insured: AMCON DISTRIBUTING COMPANY
Date of Loss: 12/10/2025
Customer File Number: 011260-189171-AP-02
Policy Number:



Photo: 55

Date Taken:
01/02/2026

Taken By:
Curtis Murphy

Description:
Lower landing gear
damages.



Photo: 56

Date Taken:
01/02/2026

Taken By:
Curtis Murphy

Description:
Additional
undercarriage view,
slight frame
damages.

Claim Photo

Our File Number: 277-065585
Adjuster: Michael Cameron
Insured: AMCON DISTRIBUTING COMPANY
Date of Loss: 12/10/2025
Customer File Number: 011260-189171-AP-02
Policy Number:



Photo: 57

Date Taken:
01/02/2026

Taken By:
Curtis Murphy

Description:
Undercarriage
view.



Photo: 58

Date Taken:
01/02/2026

Taken By:
Curtis Murphy

Description:
Tire information.

Claim Photo

Our File Number: 277-065585
Adjuster: Michael Cameron
Insured: AMCON DISTRIBUTING COMPANY
Date of Loss: 12/10/2025
Customer File Number: 011260-189171-AP-02
Policy Number:



Photo: 59

Date Taken:
01/02/2026

Taken By:
Curtis Murphy

Description:
Driver sid exterior.



Photo: 60

Date Taken:
01/02/2026

Taken By:
Curtis Murphy

Description:
Driver side interior.

Claim Photo

Our File Number: 277-065585
Adjuster: Michael Cameron
Insured: AMCON DISTRIBUTING COMPANY
Date of Loss: 12/10/2025
Customer File Number: 011260-189171-AP-02
Policy Number:



Photo: 61

Date Taken:
01/02/2026

Taken By:
Curtis Murphy

Description:
Passenger side
exterior



Photo: 62

Date Taken:
01/02/2026

Taken By:
Curtis Murphy

Description:
Passenger side
interior.

Claim Photo

Our File Number: 277-065585
Adjuster: Michael Cameron
Insured: AMCON DISTRIBUTING COMPANY
Date of Loss: 12/10/2025
Customer File Number: 011260-189171-AP-02
Policy Number:



Photo: 63

Date Taken:
01/02/2026

Taken By:
Curtis Murphy

Description:
Between tires.



Photo: 64

Date Taken:
01/02/2026

Taken By:
Curtis Murphy

Description:
Brake view.