

Claim Photo

Our File Number: 277-065502
Adjuster: David Crans
Insured: AFFINITY INSURANCE, LTD.
Date of Loss: 11/20/2025
Customer File Number: 001960-276027-AP-02
Policy Number:



Photo: 1

Date Taken:
12/11/2025

Taken By:
Edward Mauro

Description:
Vin / Serial tag




Photo: 2

Date Taken:
12/11/2025

Taken By:
Edward Mauro

Description:
Serial number

Claim Photo

Our File Number: 277-065502
Adjuster: David Crans
Insured: AFFINITY INSURANCE, LTD.
Date of Loss: 11/20/2025
Customer File Number: 001960-276027-AP-02
Policy Number:



Photo: 3

Date Taken:
12/11/2025

Taken By:
Edward Mauro

Description:
Registrations
showing serial
number



Photo: 4

Date Taken:
12/11/2025

Taken By:
Edward Mauro

Description:
Front driver corner

Claim Photo

Our File Number: 277-065502
Adjuster: David Crans
Insured: AFFINITY INSURANCE, LTD.
Date of Loss: 11/20/2025
Customer File Number: 001960-276027-AP-02
Policy Number:



Photo: 5

Date Taken:
12/11/2025

Taken By:
Edward Mauro

Description:
Front passenger
corner



Photo: 6

Date Taken:
12/11/2025

Taken By:
Edward Mauro

Description:
Rear passenger
corner

Claim Photo

Our File Number: 277-065502
Adjuster: David Crans
Insured: AFFINITY INSURANCE, LTD.
Date of Loss: 11/20/2025
Customer File Number: 001960-276027-AP-02
Policy Number:



Photo: 7

Date Taken:
12/11/2025

Taken By:
Edward Mauro

Description:
Rear driver corner



Photo: 8

Date Taken:
12/11/2025

Taken By:
Edward Mauro

Description:
Driver front axle
outer tire 12/32

Claim Photo

Our File Number: 277-065502
Adjuster: David Crans
Insured: AFFINITY INSURANCE, LTD.
Date of Loss: 11/20/2025
Customer File Number: 001960-276027-AP-02
Policy Number:



Photo: 9

Date Taken:
12/11/2025

Taken By:
Edward Mauro

Description:
Driver front axle
inner tire 12/32



Photo: 10

Date Taken:
12/11/2025

Taken By:
Edward Mauro

Description:
Driver rear axle
outer tire 10/32

Claim Photo

Our File Number: 277-065502
Adjuster: David Crans
Insured: AFFINITY INSURANCE, LTD.
Date of Loss: 11/20/2025
Customer File Number: 001960-276027-AP-02
Policy Number:



Photo: 11

Date Taken:
12/11/2025

Taken By:
Edward Mauro

Description:
Driver rear axle
inner tire 10/32



Photo: 12

Date Taken:
12/11/2025

Taken By:
Edward Mauro

Description:
Passenger side
front axle outer tire
11/32

Claim Photo

Our File Number: 277-065502
Adjuster: David Crans
Insured: AFFINITY INSURANCE, LTD.
Date of Loss: 11/20/2025
Customer File Number: 001960-276027-AP-02
Policy Number:



Photo: 13

Date Taken:
12/11/2025

Taken By:
Edward Mauro

Description:
Passenger side
front axle inner tire
11/32



Photo: 14

Date Taken:
12/11/2025

Taken By:
Edward Mauro

Description:
Passenger side rear
axle outer tire 7/32

Claim Photo

Our File Number: 277-065502
Adjuster: David Crans
Insured: AFFINITY INSURANCE, LTD.
Date of Loss: 11/20/2025
Customer File Number: 001960-276027-AP-02
Policy Number:



Photo: 15

Date Taken:
12/11/2025

Taken By:
Edward Mauro

Description:
Passenger side axle
inner tire 10/32



Photo: 16

Date Taken:
12/11/2025

Taken By:
Edward Mauro

Description:
Walking around
showing damages,
light bars, all
appear to have been
bent

Claim Photo

Our File Number: 277-065502
Adjuster: David Crans
Insured: AFFINITY INSURANCE, LTD.
Date of Loss: 11/20/2025
Customer File Number: 001960-276027-AP-02
Policy Number:



Photo: 17

Date Taken:
12/11/2025

Taken By:
Edward Mauro

Description:
No obvious damage
to the front



Photo: 18

Date Taken:
12/11/2025

Taken By:
Edward Mauro

Description:
Light bar or bracket
bent

Claim Photo

Our File Number: 277-065502
Adjuster: David Crans
Insured: AFFINITY INSURANCE, LTD.
Date of Loss: 11/20/2025
Customer File Number: 001960-276027-AP-02
Policy Number:



Photo: 19

Date Taken:
12/11/2025

Taken By:
Edward Mauro

Description:
Light bar bent



Photo: 20

Date Taken:
12/11/2025

Taken By:
Edward Mauro

Description:
Light bar bent

Claim Photo

Our File Number: 277-065502
Adjuster: David Crans
Insured: AFFINITY INSURANCE, LTD.
Date of Loss: 11/20/2025
Customer File Number: 001960-276027-AP-02
Policy Number:



Photo: 21

Date Taken:
12/11/2025

Taken By:
Edward Mauro

Description:
Second bar,
passenger side bent



Photo: 22

Date Taken:
12/11/2025

Taken By:
Edward Mauro

Description:
Framework around
hitch front bent

Claim Photo

Our File Number: 277-065502
Adjuster: David Crans
Insured: AFFINITY INSURANCE, LTD.
Date of Loss: 11/20/2025
Customer File Number: 001960-276027-AP-02
Policy Number:



Photo: 23

Date Taken:
12/11/2025

Taken By:
Edward Mauro

Description:
Walking down
passenger side,
showing damage to
landing gear



Photo: 24

Date Taken:
12/11/2025

Taken By:
Edward Mauro

Description:
Passenger side
damage to landing
gear

Claim Photo

Our File Number: 277-065502
Adjuster: David Crans
Insured: AFFINITY INSURANCE, LTD.
Date of Loss: 11/20/2025
Customer File Number: 001960-276027-AP-02
Policy Number:



Photo: 25

Date Taken:
12/11/2025

Taken By:
Edward Mauro

Description:
Passenger side
damage to landing
gear



Photo: 26

Date Taken:
12/11/2025

Taken By:
Edward Mauro

Description:
Mudflap on
passenger side
damaged

Claim Photo

Our File Number: 277-065502
Adjuster: David Crans
Insured: AFFINITY INSURANCE, LTD.
Date of Loss: 11/20/2025
Customer File Number: 001960-276027-AP-02
Policy Number:



Photo: 27

Date Taken:
12/11/2025

Taken By:
Edward Mauro

Description:
Framework
between the
landing gear post
damaged



Photo: 28

Date Taken:
12/11/2025

Taken By:
Edward Mauro

Description:
Damage to landing
gear shows frame
ripped from the
welding pad that's
welded to the tank

Claim Photo

Our File Number: 277-065502
Adjuster: David Crans
Insured: AFFINITY INSURANCE, LTD.
Date of Loss: 11/20/2025
Customer File Number: 001960-276027-AP-02
Policy Number:



Photo: 29

Date Taken:
12/11/2025

Taken By:
Edward Mauro

Description:
Shows landing gear
ripped from tank



Photo: 30

Date Taken:
12/11/2025

Taken By:
Edward Mauro

Description:
Landing gear
ripped from tank

Claim Photo

Our File Number: 277-065502
Adjuster: David Crans
Insured: AFFINITY INSURANCE, LTD.
Date of Loss: 11/20/2025
Customer File Number: 001960-276027-AP-02
Policy Number:



Photo: 31

Date Taken:
12/11/2025

Taken By:
Edward Mauro

Description:
Valve that was
attached to this was
ripped away from
tank



Photo: 32

Date Taken:
12/11/2025

Taken By:
Edward Mauro

Description:
Damage to landing
gear

Claim Photo

Our File Number: 277-065502
Adjuster: David Crans
Insured: AFFINITY INSURANCE, LTD.
Date of Loss: 11/20/2025
Customer File Number: 001960-276027-AP-02
Policy Number:



Photo: 33

Date Taken:
12/11/2025

Taken By:
Edward Mauro

Description:
Framework around
landing gear
damaged



Photo: 34

Date Taken:
12/11/2025

Taken By:
Edward Mauro

Description:
Framework on
landing gear
damaged

Claim Photo

Our File Number: 277-065502
Adjuster: David Crans
Insured: AFFINITY INSURANCE, LTD.
Date of Loss: 11/20/2025
Customer File Number: 001960-276027-AP-02
Policy Number:



Photo: 35

Date Taken:
12/11/2025

Taken By:
Edward Mauro

Description:
Framework on
landing gear
damaged



Photo: 36

Date Taken:
12/11/2025

Taken By:
Edward Mauro

Description:
Framework on
landing gear
damaged

Claim Photo

Our File Number: 277-065502
Adjuster: David Crans
Insured: AFFINITY INSURANCE, LTD.
Date of Loss: 11/20/2025
Customer File Number: 001960-276027-AP-02
Policy Number:



Photo: 37

Date Taken:
12/11/2025

Taken By:
Edward Mauro

Description:
Framework around
landing gear
damaged



Photo: 38

Date Taken:
12/11/2025

Taken By:
Edward Mauro

Description:
Framework behind
landing gear
damaged

Claim Photo

Our File Number: 277-065502
Adjuster: David Crans
Insured: AFFINITY INSURANCE, LTD.
Date of Loss: 11/20/2025
Customer File Number: 001960-276027-AP-02
Policy Number:



Photo: 39

Date Taken:
12/11/2025

Taken By:
Edward Mauro

Description:
Framework around
landing gear
damaged panels on
the bottom are the
mudflaps that are
also damaged



Photo: 40

Date Taken:
12/11/2025

Taken By:
Edward Mauro

Description:
Damage to
framework behind
landing gear to
protect the valve on
the bottom

Claim Photo

Our File Number: 277-065502
Adjuster: David Crans
Insured: AFFINITY INSURANCE, LTD.
Date of Loss: 11/20/2025
Customer File Number: 001960-276027-AP-02
Policy Number:



Photo: 41

Date Taken:
12/11/2025

Taken By:
Edward Mauro

Description:
Damaged to
framework behind
landing gear



Photo: 42

Date Taken:
12/11/2025

Taken By:
Edward Mauro

Description:

Claim Photo

Our File Number: 277-065502
Adjuster: David Crans
Insured: AFFINITY INSURANCE, LTD.
Date of Loss: 11/20/2025
Customer File Number: 001960-276027-AP-02
Policy Number:



Photo: 43

Date Taken:
12/11/2025

Taken By:
Edward Mauro

Description:
Damage to
framework behind
landing gear



Photo: 44

Date Taken:
12/11/2025

Taken By:
Edward Mauro

Description:
Damage to
framework behind
the gear, also shows
the mudflaps

Claim Photo

Our File Number: 277-065502
Adjuster: David Crans
Insured: AFFINITY INSURANCE, LTD.
Date of Loss: 11/20/2025
Customer File Number: 001960-276027-AP-02
Policy Number:



Photo: 45

Date Taken:
12/11/2025

Taken By:
Edward Mauro

Description:
Valves that were
attached
underneath.



Photo: 46

Date Taken:
12/11/2025

Taken By:
Edward Mauro

Description:
Damage to
mudflaps

Claim Photo

Our File Number: 277-065502
Adjuster: David Crans
Insured: AFFINITY INSURANCE, LTD.
Date of Loss: 11/20/2025
Customer File Number: 001960-276027-AP-02
Policy Number:



Photo: 47

Date Taken:
12/11/2025

Taken By:
Edward Mauro

Description:
Shaz mudflaps
under trailer that
were damaged



Photo: 48

Date Taken:
12/11/2025

Taken By:
Edward Mauro

Description:
Damage to mud
flaps

Claim Photo

Our File Number: 277-065502
Adjuster: David Crans
Insured: AFFINITY INSURANCE, LTD.
Date of Loss: 11/20/2025
Customer File Number: 001960-276027-AP-02
Policy Number:



Photo: 49

Date Taken:
12/11/2025

Taken By:
Edward Mauro

Description:
Frame in front of
rear axles damaged



Photo: 50

Date Taken:
12/11/2025

Taken By:
Edward Mauro

Description:
Show Ben
framework in front
of the rear axles

Claim Photo

Our File Number: 277-065502
Adjuster: David Crans
Insured: AFFINITY INSURANCE, LTD.
Date of Loss: 11/20/2025
Customer File Number: 001960-276027-AP-02
Policy Number:



Photo: 51

Date Taken:
12/11/2025

Taken By:
Edward Mauro

Description:
Damage to
framework around
where axles impact
from the driver side



Photo: 52

Date Taken:
12/11/2025

Taken By:
Edward Mauro

Description:
Show Ben
framework

Claim Photo

Our File Number: 277-065502
Adjuster: David Crans
Insured: AFFINITY INSURANCE, LTD.
Date of Loss: 11/20/2025
Customer File Number: 001960-276027-AP-02
Policy Number:



Photo: 53

Date Taken:
12/11/2025

Taken By:
Edward Mauro

Description:
Broken framework



Photo: 54

Date Taken:
12/11/2025

Taken By:
Edward Mauro

Description:
Passenger side
appears to be in
place frame bent
and broke around it

Claim Photo

Our File Number: 277-065502
Adjuster: David Crans
Insured: AFFINITY INSURANCE, LTD.
Date of Loss: 11/20/2025
Customer File Number: 001960-276027-AP-02
Policy Number:



Photo: 55

Date Taken:
12/11/2025

Taken By:
Edward Mauro

Description:
Walking down
passenger side rear
no obvious damage



Photo: 56

Date Taken:
12/11/2025

Taken By:
Edward Mauro

Description:
No obvious damage

Claim Photo

Our File Number: 277-065502
Adjuster: David Crans
Insured: AFFINITY INSURANCE, LTD.
Date of Loss: 11/20/2025
Customer File Number: 001960-276027-AP-02
Policy Number:



Photo: 57

Date Taken:
12/11/2025

Taken By:
Edward Mauro

Description:
No obvious damage



Photo: 58

Date Taken:
12/11/2025

Taken By:
Edward Mauro

Description:
Damage to the tube
on top of the
fenders that holds a
drain tube.

Claim Photo

Our File Number: 277-065502
Adjuster: David Crans
Insured: AFFINITY INSURANCE, LTD.
Date of Loss: 11/20/2025
Customer File Number: 001960-276027-AP-02
Policy Number:



Photo: 59

Date Taken:
12/11/2025

Taken By:
Edward Mauro

Description:
Damage to the tube
on top of the
defender



Photo: 60

Date Taken:
12/11/2025

Taken By:
Edward Mauro

Description:
Walking down
driver side damage
to be tube on top of
the fender

Claim Photo

Our File Number: 277-065502
Adjuster: David Crans
Insured: AFFINITY INSURANCE, LTD.
Date of Loss: 11/20/2025
Customer File Number: 001960-276027-AP-02
Policy Number:



Photo: 61

Date Taken:
12/11/2025

Taken By:
Edward Mauro

Description:
Damage to tube and
bracket below



Photo: 62

Date Taken:
12/11/2025

Taken By:
Edward Mauro

Description:
Damage to tube and
bracket below

Claim Photo

Our File Number: 277-065502
Adjuster: David Crans
Insured: AFFINITY INSURANCE, LTD.
Date of Loss: 11/20/2025
Customer File Number: 001960-276027-AP-02
Policy Number:



Photo: 63

Date Taken:
12/11/2025

Taken By:
Edward Mauro

Description:
Damage to bracket
no obvious damage
to the axles



Photo: 64

Date Taken:
12/11/2025

Taken By:
Edward Mauro

Description:
Damage to bracket

Claim Photo

Our File Number: 277-065502
Adjuster: David Crans
Insured: AFFINITY INSURANCE, LTD.
Date of Loss: 11/20/2025
Customer File Number: 001960-276027-AP-02
Policy Number:



Photo: 65

Date Taken:
12/11/2025

Taken By:
Edward Mauro

Description:
Damage bracket



Photo: 66

Date Taken:
12/11/2025

Taken By:
Edward Mauro

Description:
Damage to bracket

Claim Photo

Our File Number: 277-065502
Adjuster: David Crans
Insured: AFFINITY INSURANCE, LTD.
Date of Loss: 11/20/2025
Customer File Number: 001960-276027-AP-02
Policy Number:



Photo: 67

Date Taken:
12/11/2025

Taken By:
Edward Mauro

Description:
Damaged to
bracket and tube



Photo: 68

Date Taken:
12/11/2025

Taken By:
Edward Mauro

Description:
Damage to tube no
obvious damage to
the tank

Claim Photo

Our File Number: 277-065502
Adjuster: David Crans
Insured: AFFINITY INSURANCE, LTD.
Date of Loss: 11/20/2025
Customer File Number: 001960-276027-AP-02
Policy Number:



Photo: 69

Date Taken:
12/11/2025

Taken By:
Edward Mauro

Description:
Damaged to tube
no obvious damage
to the tank



Photo: 70

Date Taken:
12/11/2025

Taken By:
Edward Mauro

Description:
Damage to tube
no obvious damage
to the tank

Claim Photo

Our File Number: 277-065502
Adjuster: David Crans
Insured: AFFINITY INSURANCE, LTD.
Date of Loss: 11/20/2025
Customer File Number: 001960-276027-AP-02
Policy Number:



Photo: 71

Date Taken:
12/11/2025

Taken By:
Edward Mauro

Description:
Damage two
fenders



Photo: 72

Date Taken:
12/11/2025

Taken By:
Edward Mauro

Description:
Damage to the
fenders

Claim Photo

Our File Number: 277-065502
Adjuster: David Crans
Insured: AFFINITY INSURANCE, LTD.
Date of Loss: 11/20/2025
Customer File Number: 001960-276027-AP-02
Policy Number:



Photo: 73

Date Taken:
12/11/2025

Taken By:
Edward Mauro

Description:
Damage to the
bottom fenders



Photo: 74

Date Taken:
12/11/2025

Taken By:
Edward Mauro

Description:
Damage to tube no
obvious damages to
the tank

Claim Photo

Our File Number: 277-065502
Adjuster: David Crans
Insured: AFFINITY INSURANCE, LTD.
Date of Loss: 11/20/2025
Customer File Number: 001960-276027-AP-02
Policy Number:



Photo: 75

Date Taken:
12/11/2025

Taken By:
Edward Mauro

Description:
Damage to tub no
obvious damage to
the tank



Photo: 76

Date Taken:
12/11/2025

Taken By:
Edward Mauro

Description:
Damage to the
fenders as well as
bracket

Claim Photo

Our File Number: 277-065502
Adjuster: David Crans
Insured: AFFINITY INSURANCE, LTD.
Date of Loss: 11/20/2025
Customer File Number: 001960-276027-AP-02
Policy Number:



Photo: 77

Date Taken:
12/11/2025

Taken By:
Edward Mauro

Description:
This was the
assembly
underneath with the
avail attached



Photo: 78

Date Taken:
12/11/2025

Taken By:
Edward Mauro

Description:
Damage to the
valve area. Frame
was all broken.

Claim Photo

Our File Number: 277-065502
Adjuster: David Crans
Insured: AFFINITY INSURANCE, LTD.
Date of Loss: 11/20/2025
Customer File Number: 001960-276027-AP-02
Policy Number:



Photo: 79

Date Taken:
12/11/2025

Taken By:
Edward Mauro

Description:
Landing gear
framework,
damaged, landing
gear, bent, torn
from the welding
pad on the tank



Photo: 80

Date Taken:
12/11/2025

Taken By:
Edward Mauro

Description:
Shows damage to
landing gear

Claim Photo

Our File Number: 277-065502
Adjuster: David Crans
Insured: AFFINITY INSURANCE, LTD.
Date of Loss: 11/20/2025
Customer File Number: 001960-276027-AP-02
Policy Number:



Photo: 81

Date Taken:
12/11/2025

Taken By:
Edward Mauro

Description:
Damage to landing
gear



Photo: 82

Date Taken:
12/11/2025

Taken By:
Edward Mauro

Description:
Damage to landing
gear

Claim Photo

Our File Number: 277-065502
Adjuster: David Crans
Insured: AFFINITY INSURANCE, LTD.
Date of Loss: 11/20/2025
Customer File Number: 001960-276027-AP-02
Policy Number:



Photo: 83

Date Taken:
12/11/2025

Taken By:
Edward Mauro

Description:
Damage to landing gear there is a welding pad. It is attached to between the tank and the landing gear



Photo: 84

Date Taken:
12/11/2025

Taken By:
Edward Mauro

Description:
Shows broken weld on driver side, landing gear. This landing gear is attached to a welding pad that is attached to the tank.

Claim Photo

Our File Number: 277-065502
Adjuster: David Crans
Insured: AFFINITY INSURANCE, LTD.
Date of Loss: 11/20/2025
Customer File Number: 001960-276027-AP-02
Policy Number:



Photo: 85

Date Taken:
12/11/2025

Taken By:
Edward Mauro

Description:
Landing gear



Photo: 86

Date Taken:
12/11/2025

Taken By:
Edward Mauro

Description:
Landing gear
damaged

Claim Photo

Our File Number: 277-065502
Adjuster: David Crans
Insured: AFFINITY INSURANCE, LTD.
Date of Loss: 11/20/2025
Customer File Number: 001960-276027-AP-02
Policy Number:



Photo: 87

Date Taken:
12/11/2025

Taken By:
Edward Mauro

Description:
Landing gear
damaged



Photo: 88

Date Taken:
12/11/2025

Taken By:
Edward Mauro

Description:
Landing gear
damaged

Claim Photo

Our File Number: 277-065502
Adjuster: David Crans
Insured: AFFINITY INSURANCE, LTD.
Date of Loss: 11/20/2025
Customer File Number: 001960-276027-AP-02
Policy Number:



Photo: 89

Date Taken:
12/11/2025

Taken By:
Edward Mauro

Description:
Blue paint and scratches cause
caused by tractor
when it jackknifed



Photo: 90

Date Taken:
12/11/2025

Taken By:
Edward Mauro

Description:
Damage in this area
caused by the
tractor

Claim Photo

Our File Number: 277-065502
Adjuster: David Crans
Insured: AFFINITY INSURANCE, LTD.
Date of Loss: 11/20/2025
Customer File Number: 001960-276027-AP-02
Policy Number:



Photo: 91

Date Taken:
12/11/2025

Taken By:
Edward Mauro

Description:
Framework damage
damaged



Photo: 92

Date Taken:
12/11/2025

Taken By:
Edward Mauro

Description:
Walking down tank
on front driver
corner

Claim Photo

Our File Number: 277-065502
Adjuster: David Crans
Insured: AFFINITY INSURANCE, LTD.
Date of Loss: 11/20/2025
Customer File Number: 001960-276027-AP-02
Policy Number:



Photo: 93

Date Taken:
12/11/2025

Taken By:
Edward Mauro

Description:
Tank front driver
corner bars for
ligars are bent



Photo: 94

Date Taken:
12/11/2025

Taken By:
Edward Mauro

Description:
King Pin looks to
be in place

Claim Photo

Our File Number: 277-065502
Adjuster: David Crans
Insured: AFFINITY INSURANCE, LTD.
Date of Loss: 11/20/2025
Customer File Number: 001960-276027-AP-02
Policy Number:



Photo: 95

Date Taken:
12/11/2025

Taken By:
Edward Mauro

Description:
Bar on driver side
bent



Photo: 96

Date Taken:
12/11/2025

Taken By:
Edward Mauro

Description:
More paint damage

Claim Photo

Our File Number: 277-065502
Adjuster: David Crans
Insured: AFFINITY INSURANCE, LTD.
Date of Loss: 11/20/2025
Customer File Number: 001960-276027-AP-02
Policy Number:



Photo: 97

Date Taken:
12/11/2025

Taken By:
Edward Mauro

Description:
Paint damage
driver side



Photo: 98

Date Taken:
12/11/2025

Taken By:
Edward Mauro

Description:
Paint damage
driver side

Claim Photo

Our File Number: 277-065502
Adjuster: David Crans
Insured: AFFINITY INSURANCE, LTD.
Date of Loss: 11/20/2025
Customer File Number: 001960-276027-AP-02
Policy Number:



Photo: 99

Date Taken:
12/11/2025

Taken By:
Edward Mauro

Description:
Paint damage
driver side



Photo: 100

Date Taken:
12/11/2025

Taken By:
Edward Mauro

Description:
Under front

Claim Photo

Our File Number: 277-065502
Adjuster: David Crans
Insured: AFFINITY INSURANCE, LTD.
Date of Loss: 11/20/2025
Customer File Number: 001960-276027-AP-02
Policy Number:



Photo: 101

Date Taken:
12/11/2025

Taken By:
Edward Mauro

Description:
Under rear