

Claim Photo

Our File Number: 277-065703
Adjuster: David Crans
Insured: Hogan Truck Leasing
Date of Loss: 11/09/2025
Customer File Number: 011260-187698-AP-01
Policy Number:



Photo: 1
Date Taken: 12/19/2025
Taken By: Josefina Cruz
Description: VIN: 3AKJHLD8RSVJ 4548



Photo: 2
Date Taken: 12/19/2025
Taken By: Josefina Cruz
Description: manufacture information

Claim Photo

Our File Number: 277-065703
Adjuster: David Crans
Insured: Hogan Truck Leasing
Date of Loss: 11/09/2025
Customer File Number: 011260-187698-AP-01
Policy Number:



Photo: 3

Date Taken:
12/19/2025

Taken By:
Josefina Cruz

Description:
front



Photo: 4

Date Taken:
12/19/2025

Taken By:
Josefina Cruz

Description:
front right corner

Claim Photo

Our File Number: 277-065703
Adjuster: David Crans
Insured: Hogan Truck Leasing
Date of Loss: 11/09/2025
Customer File Number: 011260-187698-AP-01
Policy Number:



Photo: 5

Date Taken:
12/19/2025

Taken By:
Josefina Cruz

Description:
front left corner



Photo: 6

Date Taken:
12/19/2025

Taken By:
Josefina Cruz

Description:
rear

Claim Photo

Our File Number: 277-065703
Adjuster: David Crans
Insured: Hogan Truck Leasing
Date of Loss: 11/09/2025
Customer File Number: 011260-187698-AP-01
Policy Number:



Photo: 7

Date Taken:
12/19/2025

Taken By:
Josefina Cruz

Description:
rear right corner



Photo: 8

Date Taken:
12/19/2025

Taken By:
Josefina Cruz

Description:
rear left corner

Claim Photo

Our File Number: 277-065703
Adjuster: David Crans
Insured: Hogan Truck Leasing
Date of Loss: 11/09/2025
Customer File Number: 011260-187698-AP-01
Policy Number:



Photo: 9

Date Taken:
12/19/2025

Taken By:
Josefina Cruz

Description:
interior photos



Photo: 10

Date Taken:
12/19/2025

Taken By:
Josefina Cruz

Description:
interior photos
driver seat warn

Claim Photo

Our File Number: 277-065703
Adjuster: David Crans
Insured: Hogan Truck Leasing
Date of Loss: 11/09/2025
Customer File Number: 011260-187698-AP-01
Policy Number:



Photo: 11

Date Taken:
12/19/2025

Taken By:
Josefina Cruz

Description:
interior photo



Photo: 12

Date Taken:
12/19/2025

Taken By:
Josefina Cruz

Description:
interior damage

Claim Photo

Our File Number: 277-065703
Adjuster: David Crans
Insured: Hogan Truck Leasing
Date of Loss: 11/09/2025
Customer File Number: 011260-187698-AP-01
Policy Number:



Photo: 13

Date Taken:
12/19/2025

Taken By:
Josefina Cruz

Description:
front right mirror
damage



Photo: 14

Date Taken:
12/19/2025

Taken By:
Josefina Cruz

Description:
damage to exhaust,
running board,
catalytic converter
shield, right side
rear cab bent

Claim Photo

Our File Number: 277-065703
Adjuster: David Crans
Insured: Hogan Truck Leasing
Date of Loss: 11/09/2025
Customer File Number: 011260-187698-AP-01
Policy Number:




Photo: 15

Date Taken:
12/19/2025

Taken By:
Josefina Cruz

Description:
damage deck plate,
bent chassis



Photo: 16

Date Taken:
12/19/2025

Taken By:
Josefina Cruz

Description:
damage mud flap

Claim Photo

Our File Number: 277-065703
Adjuster: David Crans
Insured: Hogan Truck Leasing
Date of Loss: 11/09/2025
Customer File Number: 011260-187698-AP-01
Policy Number:



Photo: 17

Date Taken:
12/19/2025

Taken By:
Josefina Cruz

Description:
damage rear left air
spring



Photo: 18

Date Taken:
12/19/2025

Taken By:
Josefina Cruz

Description:
damage rear axle

Claim Photo

Our File Number: 277-065703
Adjuster: David Crans
Insured: Hogan Truck Leasing
Date of Loss: 11/09/2025
Customer File Number: 011260-187698-AP-01
Policy Number:



Photo: 19

Date Taken:
12/19/2025

Taken By:
Josefina Cruz

Description:
damage rear left
dual tire and
suspension system



Photo: 20

Date Taken:
12/19/2025

Taken By:
Josefina Cruz

Description:
damage left rear
stainless steel axle
fender

Claim Photo

Our File Number: 277-065703
Adjuster: David Crans
Insured: Hogan Truck Leasing
Date of Loss: 11/09/2025
Customer File Number: 011260-187698-AP-01
Policy Number:



Photo: 21

Date Taken:
12/19/2025

Taken By:
Josefina Cruz

Description:
damage left gas
tank and step kit



Photo: 22

Date Taken:
12/19/2025

Taken By:
Josefina Cruz

Description:
close up of damage
step left side

Claim Photo

Our File Number: 277-065703
Adjuster: David Crans
Insured: Hogan Truck Leasing
Date of Loss: 11/09/2025
Customer File Number: 011260-187698-AP-01
Policy Number:



Photo: 23

Date Taken:
12/19/2025

Taken By:
Josefina Cruz

Description:
rear side view
showing rear bent



Photo: 24

Date Taken:
12/19/2025

Taken By:
Josefina Cruz

Description:
damage left mirror,
windshield, extended
mirror

Claim Photo

Our File Number: 277-065703
Adjuster: David Crans
Insured: Hogan Truck Leasing
Date of Loss: 11/09/2025
Customer File Number: 011260-187698-AP-01
Policy Number:



Photo: 25

Date Taken:
12/19/2025

Taken By:
Josefina Cruz

Description:
damage to fender,
hood, door



Photo: 26

Date Taken:
12/19/2025

Taken By:
Josefina Cruz

Description:
damage steps

Claim Photo

Our File Number: 277-065703
Adjuster: David Crans
Insured: Hogan Truck Leasing
Date of Loss: 11/09/2025
Customer File Number: 011260-187698-AP-01
Policy Number:



Photo: 27

Date Taken:
12/19/2025

Taken By:
Josefina Cruz

Description:
damage to sunvisor,
window



Photo: 28

Date Taken:
12/19/2025

Taken By:
Josefina Cruz

Description:
damage to entire
left side

Claim Photo

Our File Number: 277-065703
Adjuster: David Crans
Insured: Hogan Truck Leasing
Date of Loss: 11/09/2025
Customer File Number: 011260-187698-AP-01
Policy Number:



Photo: 29

Date Taken:
12/19/2025

Taken By:
Josefina Cruz

Description:
damage top right
side of gas tank



Photo: 30

Date Taken:
12/19/2025

Taken By:
Josefina Cruz

Description:
close up of damage

Claim Photo

Our File Number: 277-065703
Adjuster: David Crans
Insured: Hogan Truck Leasing
Date of Loss: 11/09/2025
Customer File Number: 011260-187698-AP-01
Policy Number:



Photo: 31

Date Taken:
12/19/2025

Taken By:
Josefina Cruz

Description:
left side engine



Photo: 32

Date Taken:
12/19/2025

Taken By:
Josefina Cruz

Description:
top left side engine

Claim Photo

Our File Number: 277-065703
Adjuster: David Crans
Insured: Hogan Truck Leasing
Date of Loss: 11/09/2025
Customer File Number: 011260-187698-AP-01
Policy Number:




Photo: 33

Date Taken:
12/19/2025

Taken By:
Josefina Cruz

Description:
right side engine



Photo: 34

Date Taken:
12/19/2025

Taken By:
Josefina Cruz

Description:
top right side
engine

Claim Photo

Our File Number: 277-065703
Adjuster: David Crans
Insured: Hogan Truck Leasing
Date of Loss: 11/09/2025
Customer File Number: 011260-187698-AP-01
Policy Number:



Photo: 35

Date Taken:
12/19/2025

Taken By:
Josefina Cruz

Description:
License plate



Photo: 36

Date Taken:
12/19/2025

Taken By:
Josefina Cruz

Description:
front undercarriage

Claim Photo

Our File Number: 277-065703
Adjuster: David Crans
Insured: Hogan Truck Leasing
Date of Loss: 11/09/2025
Customer File Number: 011260-187698-AP-01
Policy Number:



Photo: 37

Date Taken:
12/19/2025

Taken By:
Josefina Cruz

Description:
damage bent frame



Photo: 38

Date Taken:
12/19/2025

Taken By:
Josefina Cruz

Description:
rear undercarriage

Claim Photo

Our File Number: 277-065703
Adjuster: David Crans
Insured: Hogan Truck Leasing
Date of Loss: 11/09/2025
Customer File Number: 011260-187698-AP-01
Policy Number:



Photo: 39

Date Taken:
12/19/2025

Taken By:
Josefina Cruz

Description:
front left tire



Photo: 40

Date Taken:
12/19/2025

Taken By:
Josefina Cruz

Description:
front left tire tread

Claim Photo

Our File Number: 277-065703
Adjuster: David Crans
Insured: Hogan Truck Leasing
Date of Loss: 11/09/2025
Customer File Number: 011260-187698-AP-01
Policy Number:



Photo: 41

Date Taken:
12/19/2025

Taken By:
Josefina Cruz

Description:
front left tire tread
depth



Photo: 42

Date Taken:
12/19/2025

Taken By:
Josefina Cruz

Description:
rear left tire

Claim Photo

Our File Number: 277-065703
Adjuster: David Crans
Insured: Hogan Truck Leasing
Date of Loss: 11/09/2025
Customer File Number: 011260-187698-AP-01
Policy Number:



Photo: 43

Date Taken:
12/19/2025

Taken By:
Josefina Cruz

Description:
rear left tire tread



Photo: 44

Date Taken:
12/19/2025

Taken By:
Josefina Cruz

Description:
rear left tire tread
depth

Claim Photo

Our File Number: 277-065703
Adjuster: David Crans
Insured: Hogan Truck Leasing
Date of Loss: 11/09/2025
Customer File Number: 011260-187698-AP-01
Policy Number:



Photo: 45

Date Taken:
12/19/2025

Taken By:
Josefina Cruz

Description:
rear left tire tread
depth



Photo: 46

Date Taken:
12/19/2025

Taken By:
Josefina Cruz

Description:
rear left tire

Claim Photo

Our File Number: 277-065703
Adjuster: David Crans
Insured: Hogan Truck Leasing
Date of Loss: 11/09/2025
Customer File Number: 011260-187698-AP-01
Policy Number:



Photo: 47

Date Taken:
12/19/2025

Taken By:
Josefina Cruz

Description:
rear left tire tread



Photo: 48

Date Taken:
12/19/2025

Taken By:
Josefina Cruz

Description:
rear left tire tread
depth

Claim Photo

Our File Number: 277-065703
Adjuster: David Crans
Insured: Hogan Truck Leasing
Date of Loss: 11/09/2025
Customer File Number: 011260-187698-AP-01
Policy Number:



Photo: 49

Date Taken:
12/19/2025

Taken By:
Josefina Cruz

Description:
rear left tire tread
depth



Photo: 50

Date Taken:
12/19/2025

Taken By:
Josefina Cruz

Description:
front right tire

Claim Photo

Our File Number: 277-065703
Adjuster: David Crans
Insured: Hogan Truck Leasing
Date of Loss: 11/09/2025
Customer File Number: 011260-187698-AP-01
Policy Number:



Photo: 51

Date Taken:
12/19/2025

Taken By:
Josefina Cruz

Description:
front right tire
tread



Photo: 52

Date Taken:
12/19/2025

Taken By:
Josefina Cruz

Description:
front right tire tread
depth

Claim Photo

Our File Number: 277-065703
Adjuster: David Crans
Insured: Hogan Truck Leasing
Date of Loss: 11/09/2025
Customer File Number: 011260-187698-AP-01
Policy Number:



Photo: 53

Date Taken:
12/19/2025

Taken By:
Josefina Cruz

Description:
rear right tire



Photo: 54

Date Taken:
12/19/2025

Taken By:
Josefina Cruz

Description:
rear right tire tread

Claim Photo

Our File Number: 277-065703
Adjuster: David Crans
Insured: Hogan Truck Leasing
Date of Loss: 11/09/2025
Customer File Number: 011260-187698-AP-01
Policy Number:



Photo: 55

Date Taken:
12/19/2025

Taken By:
Josefina Cruz

Description:
rear right tire tread
depth



Photo: 56

Date Taken:
12/19/2025

Taken By:
Josefina Cruz

Description:
rear right tire tread
depth

Claim Photo

Our File Number: 277-065703
Adjuster: David Crans
Insured: Hogan Truck Leasing
Date of Loss: 11/09/2025
Customer File Number: 011260-187698-AP-01
Policy Number:



Photo: 57

Date Taken:
12/19/2025

Taken By:
Josefina Cruz

Description:
rear right tire



Photo: 58

Date Taken:
12/19/2025

Taken By:
Josefina Cruz

Description:
rear right tire tread

Claim Photo

Our File Number: 277-065703
Adjuster: David Crans
Insured: Hogan Truck Leasing
Date of Loss: 11/09/2025
Customer File Number: 011260-187698-AP-01
Policy Number:



Photo: 59

Date Taken:
12/19/2025

Taken By:
Josefina Cruz

Description:
rear right tire tread
depth



Photo: 60

Date Taken:
12/19/2025

Taken By:
Josefina Cruz

Description:
rear right tire tread
depth

Claim Photo

Our File Number: 277-065703
Adjuster: David Crans
Insured: Hogan Truck Leasing
Date of Loss: 11/09/2025
Customer File Number: 011260-187698-AP-01
Policy Number:



Photo: 61

Date Taken:
12/19/2025

Taken By:
Josefina Cruz

Description:
damage fender



Photo: 62

Date Taken:
12/19/2025

Taken By:
Josefina Cruz

Description:

Claim Photo

Our File Number: 277-065703
Adjuster: David Crans
Insured: Hogan Truck Leasing
Date of Loss: 11/09/2025
Customer File Number: 011260-187698-AP-01
Policy Number:



Photo: 63

Date Taken:
12/19/2025

Taken By:
Josefina Cruz

Description:



Photo: 64

Date Taken:
12/19/2025

Taken By:
Josefina Cruz

Description:

Claim Photo

Our File Number: 277-065703
Adjuster: David Crans
Insured: Hogan Truck Leasing
Date of Loss: 11/09/2025
Customer File Number: 011260-187698-AP-01
Policy Number:



Photo: 65

Date Taken:
12/19/2025

Taken By:
Josefina Cruz

Description:



Photo: 66

Date Taken:
12/19/2025

Taken By:
Josefina Cruz

Description:

Claim Photo

Our File Number: 277-065703
Adjuster: David Crans
Insured: Hogan Truck Leasing
Date of Loss: 11/09/2025
Customer File Number: 011260-187698-AP-01
Policy Number:



	A close-up photograph of a dark, textured metal surface. In the upper left, there is a hexagonal bolt head. Below it, several sets of numbers and letters are stamped into the metal. The first line reads "15 31347 030". The second line reads "3 311 3". The third line reads "120 KSI". To the right of these lines, there is a single letter "G". The metal surface appears slightly worn and has some discoloration.		<p>Photo: 67</p> <p>Date Taken: 12/19/2025</p> <p>Taken By: Josefina Cruz</p> <p>Description:</p>
--	--	--	---