



MANUFACTURED BY: DAIMLER VEH. COMERC. MEXICO
DATE OF MFR: 04/17
GVWR/PNBV.KG: 23,587
GVWR/PNBV.LBS: 52,000
THIS VEHICLE COMPLEES WITH ALL
APPLICABLE FEDERAL MOTOR VEHICLE
SAFETY STANDARDS IN EFFECT AT THE DATE
OF MANUFACTURE SHOWN ABOVE
VEHICLE ID NO: 3AKJGDR8SHF3880
TYPE: TRUCK/TRACTOR TT/CT
COUNTRY OF ORIGIN: MEXICO

	GVWR/PNBE KGS	GVWR/PNBE LBS	TIRES	PIMS	KPA COLD	PSI COLD	"S"
FRONT AXLE:	5,670	12,500	295/75R22.5(H)	22.5X8.25	827	120	S
1ST INT AXLE:	9,072	20,000	295/75R22.5(G)	22.5X8.25	758	110	D
2ND INT AXLE:							
3RD INT AXLE:							
4TH INT AXLE:							
5TH INT AXLE:							
6TH INT AXLE:							
REAR AXLE:	9,072	20,000	295/75R22.5(G)	22.5X8.25	758	110	D



















