

## Claim Photo

**Our File Number:** 277-066272  
**Adjuster:** Jason Baka  
**Insured:** ARCHWAY INSURANCE LTD  
**Date of Loss:** 01/13/2026  
**Customer File Number:** 011260-190600-AP-01  
**Policy Number:**



### Photo: 1

**Date Taken:**  
01/29/2026

**Taken By:**  
Daniel Bednarek

**Description:**  
Left front 2023  
International Cab:  
3HSDZAPR8PN20  
8332



### Photo: 2

**Date Taken:**  
01/29/2026

**Taken By:**  
Daniel Bednarek

**Description:**  
Front view note  
twist in cattle guard  
specifically at the  
right front with  
damage to lower  
hood.



## Claim Photo

**Our File Number:** 277-066272  
**Adjuster:** Jason Baka  
**Insured:** ARCHWAY INSURANCE LTD  
**Date of Loss:** 01/13/2026  
**Customer File Number:** 011260-190600-AP-01  
**Policy Number:**



### Photo: 3

**Date Taken:**  
01/29/2026

**Taken By:**  
Daniel Bednarek

**Description:**  
Right front view.  
Cattle guard  
damage, right front  
hood damage  
below lamp.



### Photo: 4

**Date Taken:**  
01/29/2026

**Taken By:**  
Daniel Bednarek

**Description:**  
Right side. Note  
damage to right  
fuel tank.



## Claim Photo

**Our File Number:** 277-066272  
**Adjuster:** Jason Baka  
**Insured:** ARCHWAY INSURANCE LTD  
**Date of Loss:** 01/13/2026  
**Customer File Number:** 011260-190600-AP-01  
**Policy Number:**



**Photo: 5**

**Date Taken:**  
01/29/2026

**Taken By:**  
Daniel Bednarek

**Description:**  
Right tank damage.



**Photo: 6**

**Date Taken:**  
01/29/2026

**Taken By:**  
Daniel Bednarek

**Description:**  
Impact on top of  
frame rails.



## Claim Photo

**Our File Number:** 277-066272  
**Adjuster:** Jason Baka  
**Insured:** ARCHWAY INSURANCE LTD  
**Date of Loss:** 01/13/2026  
**Customer File Number:** 011260-190600-AP-01  
**Policy Number:**



**Photo: 7**

**Date Taken:**  
01/29/2026

**Taken By:**  
Daniel Bednarek

**Description:**  
Frame rail damage.



**Photo: 8**

**Date Taken:**  
01/29/2026

**Taken By:**  
Daniel Bednarek

**Description:**  
Right rear.



## Claim Photo

**Our File Number:** 277-066272  
**Adjuster:** Jason Baka  
**Insured:** ARCHWAY INSURANCE LTD  
**Date of Loss:** 01/13/2026  
**Customer File Number:** 011260-190600-AP-01  
**Policy Number:**



**Photo: 9**

**Date Taken:**  
01/29/2026

**Taken By:**  
Daniel Bednarek

**Description:**  
Rear view.



**Photo: 10**

**Date Taken:**  
01/29/2026

**Taken By:**  
Daniel Bednarek

**Description:**  
5th wheel plate.  
Potentially twisted.



## Claim Photo

**Our File Number:** 277-066272  
**Adjuster:** Jason Baka  
**Insured:** ARCHWAY INSURANCE LTD  
**Date of Loss:** 01/13/2026  
**Customer File Number:** 011260-190600-AP-01  
**Policy Number:**



**Photo: 11**

**Date Taken:**  
01/29/2026

**Taken By:**  
Daniel Bednarek

**Description:**  
Left rear.



**Photo: 12**

**Date Taken:**  
01/29/2026

**Taken By:**  
Daniel Bednarek

**Description:**  
Close-up of 5th  
wheel



## Claim Photo

**Our File Number:** 277-066272  
**Adjuster:** Jason Baka  
**Insured:** ARCHWAY INSURANCE LTD  
**Date of Loss:** 01/13/2026  
**Customer File Number:** 011260-190600-AP-01  
**Policy Number:**



**Photo: 13**

**Date Taken:**  
01/29/2026

**Taken By:**  
Daniel Bednarek

**Description:**  
Impact to frame



**Photo: 14**

**Date Taken:**  
01/29/2026

**Taken By:**  
Daniel Bednarek

**Description:**  
Left tank, left cab  
deflector/valance  
damage.



## Claim Photo

**Our File Number:** 277-066272  
**Adjuster:** Jason Baka  
**Insured:** ARCHWAY INSURANCE LTD  
**Date of Loss:** 01/13/2026  
**Customer File Number:** 011260-190600-AP-01  
**Policy Number:**



**Photo: 15**

**Date Taken:**  
01/29/2026

**Taken By:**  
Daniel Bednarek

**Description:**  
Left cab and tank damage.



**Photo: 16**

**Date Taken:**  
01/29/2026

**Taken By:**  
Daniel Bednarek

**Description:**  
Close-up of cab  
deflector damage at  
bottom left.



## Claim Photo

**Our File Number:** 277-066272  
**Adjuster:** Jason Baka  
**Insured:** ARCHWAY INSURANCE LTD  
**Date of Loss:** 01/13/2026  
**Customer File Number:** 011260-190600-AP-01  
**Policy Number:**




**Photo: 17**

**Date Taken:**  
01/29/2026

**Taken By:**  
Daniel Bednarek

**Description:**  
Alignment of upper  
deflector.



**Photo: 18**

**Date Taken:**  
01/29/2026


**Taken By:**  
Daniel Bednarek

**Description:**  
Interior view of  
deflectors at left  
cab.



## Claim Photo

**Our File Number:** 277-066272  
**Adjuster:** Jason Baka  
**Insured:** ARCHWAY INSURANCE LTD  
**Date of Loss:** 01/13/2026  
**Customer File Number:** 011260-190600-AP-01  
**Policy Number:**



**Photo: 19**

**Date Taken:**  
01/29/2026

**Taken By:**  
Daniel Bednarek

**Description:**  
Tank Damage close  
-up



**Photo: 20**

**Date Taken:**  
01/29/2026

**Taken By:**  
Daniel Bednarek

**Description:**  
Left front wheel



## Claim Photo

**Our File Number:** 277-066272  
**Adjuster:** Jason Baka  
**Insured:** ARCHWAY INSURANCE LTD  
**Date of Loss:** 01/13/2026  
**Customer File Number:** 011260-190600-AP-01  
**Policy Number:**



**Photo: 21**

**Date Taken:**  
01/29/2026

**Taken By:**  
Daniel Bednarek

**Description:**  
Left front



**Photo: 22**

**Date Taken:**  
01/29/2026

**Taken By:**  
Daniel Bednarek

**Description:**  
Left rear front.



## Claim Photo

**Our File Number:** 277-066272  
**Adjuster:** Jason Baka  
**Insured:** ARCHWAY INSURANCE LTD  
**Date of Loss:** 01/13/2026  
**Customer File Number:** 011260-190600-AP-01  
**Policy Number:**




**Photo: 23**

**Date Taken:**  
01/29/2026

**Taken By:**  
Daniel Bednarek

**Description:**  
Left rear front  
outer.



**Photo: 24**

**Date Taken:**  
01/29/2026

**Taken By:**  
Daniel Bednarek

**Description:**  
Left rear front  
inner.



## Claim Photo

**Our File Number:** 277-066272  
**Adjuster:** Jason Baka  
**Insured:** ARCHWAY INSURANCE LTD  
**Date of Loss:** 01/13/2026  
**Customer File Number:** 011260-190600-AP-01  
**Policy Number:**



**Photo: 25**

**Date Taken:**  
01/29/2026

**Taken By:**  
Daniel Bednarek

**Description:**  
Left rear rear outer.



**Photo: 26**

**Date Taken:**  
01/29/2026

**Taken By:**  
Daniel Bednarek

**Description:**  
Left rear rear inner.



## Claim Photo

**Our File Number:** 277-066272  
**Adjuster:** Jason Baka  
**Insured:** ARCHWAY INSURANCE LTD  
**Date of Loss:** 01/13/2026  
**Customer File Number:** 011260-190600-AP-01  
**Policy Number:**



**Photo: 27**

**Date Taken:**  
01/29/2026

**Taken By:**  
Daniel Bednarek

**Description:**  
Rear differential  
view.



**Photo: 28**

**Date Taken:**  
01/29/2026

**Taken By:**  
Daniel Bednarek

**Description:**  
Rear wheel inner  
view.



## Claim Photo

**Our File Number:** 277-066272  
**Adjuster:** Jason Baka  
**Insured:** ARCHWAY INSURANCE LTD  
**Date of Loss:** 01/13/2026  
**Customer File Number:** 011260-190600-AP-01  
**Policy Number:**



**Photo: 29**

**Date Taken:**  
01/29/2026

**Taken By:**  
Daniel Bednarek

**Description:**  
Left rear wheel.



**Photo: 30**

**Date Taken:**  
01/29/2026

**Taken By:**  
Daniel Bednarek

**Description:**  
Right rear rear  
outer.



## Claim Photo

**Our File Number:** 277-066272  
**Adjuster:** Jason Baka  
**Insured:** ARCHWAY INSURANCE LTD  
**Date of Loss:** 01/13/2026  
**Customer File Number:** 011260-190600-AP-01  
**Policy Number:**




**Photo: 31**

**Date Taken:**  
01/29/2026

**Taken By:**  
Daniel Bednarek

**Description:**  
Right rear rear  
inner.



**Photo: 32**

**Date Taken:**  
01/29/2026

**Taken By:**  
Daniel Bednarek

**Description:**  
Right rear front  
inner. .



## Claim Photo

**Our File Number:** 277-066272  
**Adjuster:** Jason Baka  
**Insured:** ARCHWAY INSURANCE LTD  
**Date of Loss:** 01/13/2026  
**Customer File Number:** 011260-190600-AP-01  
**Policy Number:**



**Photo: 33**

**Date Taken:**  
01/29/2026

**Taken By:**  
Daniel Bednarek

**Description:**  
Right tank damage  
close-up



**Photo: 34**

**Date Taken:**  
01/29/2026

**Taken By:**  
Daniel Bednarek

**Description:**  
Right front.



## Claim Photo

**Our File Number:** 277-066272  
**Adjuster:** Jason Baka  
**Insured:** ARCHWAY INSURANCE LTD  
**Date of Loss:** 01/13/2026  
**Customer File Number:** 011260-190600-AP-01  
**Policy Number:**



**Photo: 35**

**Date Taken:**  
01/29/2026

**Taken By:**  
Daniel Bednarek

**Description:**  
Cattle guard close-up Twisted. Also fog lamp missing.



**Photo: 36**

**Date Taken:**  
01/29/2026

**Taken By:**  
Daniel Bednarek

**Description:**  
Distant view right front cattle guard.



## Claim Photo

**Our File Number:** 277-066272  
**Adjuster:** Jason Baka  
**Insured:** ARCHWAY INSURANCE LTD  
**Date of Loss:** 01/13/2026  
**Customer File Number:** 011260-190600-AP-01  
**Policy Number:**



**Photo: 37**

**Date Taken:**  
01/29/2026

**Taken By:**  
Daniel Bednarek

**Description:**  
Shows lower hood  
damage below  
lamp.



**Photo: 38**

**Date Taken:**  
01/29/2026

**Taken By:**  
Daniel Bednarek

**Description:**  
Right lower hood  
damage below  
lamp. Note  
closeness of the  
cattle guard.



## Claim Photo

**Our File Number:** 277-066272  
**Adjuster:** Jason Baka  
**Insured:** ARCHWAY INSURANCE LTD  
**Date of Loss:** 01/13/2026  
**Customer File Number:** 011260-190600-AP-01  
**Policy Number:**



**Photo: 39**

**Date Taken:**  
01/29/2026

**Taken By:**  
Daniel Bednarek

**Description:**  
Cattle guard twist.



**Photo: 40**

**Date Taken:**  
01/29/2026

**Taken By:**  
Daniel Bednarek

**Description:**  
Cattle guard twist  
at right side.



## Claim Photo

**Our File Number:** 277-066272  
**Adjuster:** Jason Baka  
**Insured:** ARCHWAY INSURANCE LTD  
**Date of Loss:** 01/13/2026  
**Customer File Number:** 011260-190600-AP-01  
**Policy Number:**



**Photo: 41**

**Date Taken:**  
01/29/2026

**Taken By:**  
Daniel Bednarek

**Description:**  
Left side cattle  
guard view. Note  
additional distance.



**Photo: 42**

**Date Taken:**  
01/29/2026

**Taken By:**  
Daniel Bednarek

**Description:**  
Underside view of  
cattle guard hinge.



## Claim Photo

**Our File Number:** 277-066272  
**Adjuster:** Jason Baka  
**Insured:** ARCHWAY INSURANCE LTD  
**Date of Loss:** 01/13/2026  
**Customer File Number:** 011260-190600-AP-01  
**Policy Number:**




**Photo: 43**

**Date Taken:**  
01/29/2026

**Taken By:**  
Daniel Bednarek

**Description:**  
Underside view of  
cattle guard hinge.



**Photo: 44**

**Date Taken:**  
01/29/2026

**Taken By:**  
Daniel Bednarek

**Description:**  
View shows only  
damage to hood at  
right front under  
lamp.



## Claim Photo

**Our File Number:** 277-066272  
**Adjuster:** Jason Baka  
**Insured:** ARCHWAY INSURANCE LTD  
**Date of Loss:** 01/13/2026  
**Customer File Number:** 011260-190600-AP-01  
**Policy Number:**



**Photo: 45**

**Date Taken:**  
01/29/2026

**Taken By:**  
Daniel Bednarek

**Description:**  
Engine  
compartment  
overview.



**Photo: 46**

**Date Taken:**  
01/29/2026

**Taken By:**  
Daniel Bednarek

**Description:**  
Engine tag.



## Claim Photo

**Our File Number:** 277-066272  
**Adjuster:** Jason Baka  
**Insured:** ARCHWAY INSURANCE LTD  
**Date of Loss:** 01/13/2026  
**Customer File Number:** 011260-190600-AP-01  
**Policy Number:**



**Photo: 47**

**Date Taken:**  
01/29/2026

**Taken By:**  
Daniel Bednarek

**Description:**  
Underside of hoof  
at right side.



**Photo: 48**

**Date Taken:**  
01/29/2026


**Taken By:**  
Daniel Bednarek

**Description:**  
Front wheel shows  
disk brake.



## Claim Photo

**Our File Number:** 277-066272  
**Adjuster:** Jason Baka  
**Insured:** ARCHWAY INSURANCE LTD  
**Date of Loss:** 01/13/2026  
**Customer File Number:** 011260-190600-AP-01  
**Policy Number:**



**Photo: 49**

**Date Taken:**  
01/29/2026

**Taken By:**  
Daniel Bednarek

**Description:**  
Close-up of left cab  
deflector damage.



**Photo: 50**

**Date Taken:**  
01/29/2026

**Taken By:**  
Daniel Bednarek

**Description:**  
Left cab deflector  
damage.



## Claim Photo

**Our File Number:** 277-066272  
**Adjuster:** Jason Baka  
**Insured:** ARCHWAY INSURANCE LTD  
**Date of Loss:** 01/13/2026  
**Customer File Number:** 011260-190600-AP-01  
**Policy Number:**



**Photo: 51**

**Date Taken:**  
01/29/2026

**Taken By:**  
Daniel Bednarek

**Description:**  
Interior view seat options.



**Photo: 52**

**Date Taken:**  
01/29/2026

**Taken By:**  
Daniel Bednarek

**Description:**  
VIN TAG.



## Claim Photo

**Our File Number:** 277-066272  
**Adjuster:** Jason Baka  
**Insured:** ARCHWAY INSURANCE LTD  
**Date of Loss:** 01/13/2026  
**Customer File Number:** 011260-190600-AP-01  
**Policy Number:**



**Photo: 53**

**Date Taken:**  
01/29/2026

**Taken By:**  
Daniel Bednarek

**Description:**  
Miles



**Photo: 54**

**Date Taken:**  
01/29/2026

**Taken By:**  
Daniel Bednarek

**Description:**  
Hours



## Claim Photo

**Our File Number:** 277-066272  
**Adjuster:** Jason Baka  
**Insured:** ARCHWAY INSURANCE LTD  
**Date of Loss:** 01/13/2026  
**Customer File Number:** 011260-190600-AP-01  
**Policy Number:**



**Photo: 55**

**Date Taken:**  
01/29/2026

**Taken By:**  
Daniel Bednarek

**Description:**  
Dash overview.



**Photo: 56**

**Date Taken:**  
01/29/2026

**Taken By:**  
Daniel Bednarek

**Description:**  
Window/mirror options.



## Claim Photo

**Our File Number:** 277-066272  
**Adjuster:** Jason Baka  
**Insured:** ARCHWAY INSURANCE LTD  
**Date of Loss:** 01/13/2026  
**Customer File Number:** 011260-190600-AP-01  
**Policy Number:**



**Photo: 57**

**Date Taken:**  
01/29/2026

**Taken By:**  
Daniel Bednarek

**Description:**  
Options.



**Photo: 58**

**Date Taken:**  
01/29/2026

**Taken By:**  
Daniel Bednarek

**Description:**  
Transmission.



## Claim Photo

**Our File Number:** 277-066272  
**Adjuster:** Jason Baka  
**Insured:** ARCHWAY INSURANCE LTD  
**Date of Loss:** 01/13/2026  
**Customer File Number:** 011260-190600-AP-01  
**Policy Number:**



**Photo: 59**

**Date Taken:**  
01/29/2026

**Taken By:**  
Daniel Bednarek

**Description:**  
Emissions tag;



**Photo: 60**

**Date Taken:**  
01/29/2026

**Taken By:**  
Daniel Bednarek

**Description:**  
Emissions tag.