

## Claim Photo

**Our File Number:** 277-066371  
**Adjuster:** Mike Hogan  
**Insured:** 2Twenty Logistics LLC  
**Date of Loss:** 01/08/2026  
**Customer File Number:** DEL26001084  
**Policy Number:** ZACAT9783303




### Photo: 1

**Date Taken:**  
01/22/2026

**Taken By:**  
Adrianne Adame

**Description:**  
Copart lot #



### Photo: 2


**Date Taken:**  
01/22/2026

**Taken By:**  
Adrianne Adame

**Description:**  
VIN

## Claim Photo

**Our File Number:** 277-066371  
**Adjuster:** Mike Hogan  
**Insured:** 2Twenty Logistics LLC  
**Date of Loss:** 01/08/2026  
**Customer File Number:** DEL26001084  
**Policy Number:** ZACAT9783303



### Photo: 3

**Date Taken:**  
01/22/2026

**Taken By:**  
Adrianne Adame

**Description:**  
Additional van labels



### Photo: 4


**Date Taken:**  
01/22/2026

**Taken By:**  
Adrianne Adame

**Description:**  
Additional van labels

## Claim Photo

**Our File Number:** 277-066371  
**Adjuster:** Mike Hogan  
**Insured:** 2Twenty Logistics LLC  
**Date of Loss:** 01/08/2026  
**Customer File Number:** DEL26001084  
**Policy Number:** ZACAT9783303




### Photo: 5

**Date Taken:**  
01/22/2026

**Taken By:**  
Adrianne Adame

**Description:**  
Additional van labels



### Photo: 6


**Date Taken:**  
01/22/2026

**Taken By:**  
Adrianne Adame

**Description:**  
Van Control panel

## Claim Photo

**Our File Number:** 277-066371  
**Adjuster:** Mike Hogan  
**Insured:** Twenty Logistics LLC  
**Date of Loss:** 01/08/2026  
**Customer File Number:** DEL26001084  
**Policy Number:** ZACAT9783303



**Photo: 7**

**Date Taken:**  
01/22/2026

**Taken By:**  
Adrianne Adame

**Description:**  
Odometer reading



**Photo: 8**


**Date Taken:**  
01/22/2026

**Taken By:**  
Adrianne Adame

**Description:**  
Make

## Claim Photo

**Our File Number:** 277-066371  
**Adjuster:** Mike Hogan  
**Insured:** 2Twenty Logistics LLC  
**Date of Loss:** 01/08/2026  
**Customer File Number:** DEL26001084  
**Policy Number:** ZACAT9783303



**Photo: 9**

**Date Taken:**  
01/22/2026

**Taken By:**  
Adrianne Adame

**Description:**  
Model



**Photo: 10**

**Date Taken:**  
01/22/2026

**Taken By:**  
Adrianne Adame

**Description:**  
Company Name

## Claim Photo

**Our File Number:** 277-066371  
**Adjuster:** Mike Hogan  
**Insured:** 2Twenty Logistics LLC  
**Date of Loss:** 01/08/2026  
**Customer File Number:** DEL26001084  
**Policy Number:** ZACAT9783303




**Photo: 11**

**Date Taken:**  
01/22/2026

**Taken By:**  
Adrianne Adame

**Description:**  
Van unit # 618310



**Photo: 12**

**Date Taken:**  
01/22/2026

**Taken By:**  
Adrianne Adame

**Description:**  
Notification:  
Bulkhead door  
closed

## Claim Photo

**Our File Number:** 277-066371  
**Adjuster:** Mike Hogan  
**Insured:** 2Twenty Logistics LLC  
**Date of Loss:** 01/08/2026  
**Customer File Number:** DEL26001084  
**Policy Number:** ZACAT9783303



**Photo: 13**

**Date Taken:**  
01/22/2026

**Taken By:**  
Adrianne Adame

**Description:**  
View of driver-side front charging port



**Photo: 14**


**Date Taken:**  
01/22/2026

**Taken By:**  
Adrianne Adame

**Description:**  
View of driver-side jump port

## Claim Photo

**Our File Number:** 277-066371  
**Adjuster:** Mike Hogan  
**Insured:** Twenty Logistics LLC  
**Date of Loss:** 01/08/2026  
**Customer File Number:** DEL26001084  
**Policy Number:** ZACAT9783303



**Photo: 15**

**Date Taken:**  
01/22/2026

**Taken By:**  
Adrianne Adame

**Description:**  
Close-up view of  
driver-side jump  
port



**Photo: 16**

**Date Taken:**  
01/22/2026

**Taken By:**  
Adrianne Adame

**Description:**  
Van key

## Claim Photo

**Our File Number:** 277-066371  
**Adjuster:** Mike Hogan  
**Insured:** 2Twenty Logistics LLC  
**Date of Loss:** 01/08/2026  
**Customer File Number:** DEL26001084  
**Policy Number:** ZACAT9783303



**Photo: 17**

**Date Taken:**  
01/22/2026

**Taken By:**  
Adrienne Adame

**Description:**  
Additional view of van key



**Photo: 18**

**Date Taken:**  
01/22/2026

**Taken By:**  
Adrienne Adame

**Description:**  
Front view

## Claim Photo

**Our File Number:** 277-066371  
**Adjuster:** Mike Hogan  
**Insured:** Twenty Logistics LLC  
**Date of Loss:** 01/08/2026  
**Customer File Number:** DEL26001084  
**Policy Number:** ZACAT9783303



**Photo: 19**

**Date Taken:**  
01/22/2026

**Taken By:**  
Adrianne Adame

**Description:**  
Driver-side front



**Photo: 20**

**Date Taken:**  
01/22/2026

**Taken By:**  
Adrianne Adame

**Description:**  
Driver-side rear

## Claim Photo

**Our File Number:** 277-066371  
**Adjuster:** Mike Hogan  
**Insured:** 2Twenty Logistics LLC  
**Date of Loss:** 01/08/2026  
**Customer File Number:** DEL26001084  
**Policy Number:** ZACAT9783303



**Photo: 21**

**Date Taken:**  
01/22/2026

**Taken By:**  
Adrienne Adame

**Description:**  
Passenger-side  
front



**Photo: 22**

**Date Taken:**  
01/22/2026

**Taken By:**  
Adrienne Adame

**Description:**  
Driver-side rear

## Claim Photo

**Our File Number:** 277-066371  
**Adjuster:** Mike Hogan  
**Insured:** 2Twenty Logistics LLC  
**Date of Loss:** 01/08/2026  
**Customer File Number:** DEL26001084  
**Policy Number:** ZACAT9783303



**Photo:** 23

**Date Taken:**  
01/22/2026

**Taken By:**  
Adrianne Adame

**Description:**  
Rear



**Photo:** 24

**Date Taken:**  
01/22/2026


**Taken By:**  
Adrianne Adame

**Description:**  
Driver-side front corner damage

## Claim Photo

**Our File Number:** 277-066371  
**Adjuster:** Mike Hogan  
**Insured:** 2Twenty Logistics LLC  
**Date of Loss:** 01/08/2026  
**Customer File Number:** DEL26001084  
**Policy Number:** ZACAT9783303

**cia**  
CUSTARD  
INSURANCE ADJUSTERS



**Photo: 25**

**Date Taken:**  
01/22/2026

**Taken By:**  
Adrianne Adame

**Description:**  
Additional view of  
driver-side front  
corner damage



**Photo: 26**


**Date Taken:**  
01/22/2026

**Taken By:**  
Adrianne Adame

**Description:**  
Additional view of  
driver-side front  
corner damage

## Claim Photo

**Our File Number:** 277-066371  
**Adjuster:** Mike Hogan  
**Insured:** 2Twenty Logistics LLC  
**Date of Loss:** 01/08/2026  
**Customer File Number:** DEL26001084  
**Policy Number:** ZACAT9783303




**Photo: 27**

**Date Taken:**  
01/22/2026

**Taken By:**  
Adrianne Adame

**Description:**  
Additional view of  
driver-side front  
corner damage



**Photo: 28**


**Date Taken:**  
01/22/2026

**Taken By:**  
Adrianne Adame

**Description:**  
Driver-side front  
damage

## Claim Photo

**Our File Number:** 277-066371  
**Adjuster:** Mike Hogan  
**Insured:** 2Twenty Logistics LLC  
**Date of Loss:** 01/08/2026  
**Customer File Number:** DEL26001084  
**Policy Number:** ZACAT9783303




**Photo: 29**

**Date Taken:**  
01/22/2026

**Taken By:**  
Adrianne Adame

**Description:**  
Additional driver-side front damage



**Photo: 30**


**Date Taken:**  
01/22/2026

**Taken By:**  
Adrianne Adame

**Description:**  
Additional driver-side front damage

## Claim Photo

**Our File Number:** 277-066371  
**Adjuster:** Mike Hogan  
**Insured:** 2Twenty Logistics LLC  
**Date of Loss:** 01/08/2026  
**Customer File Number:** DEL26001084  
**Policy Number:** ZACAT9783303




**Photo: 31**

**Date Taken:**  
01/22/2026

**Taken By:**  
Adrianne Adame

**Description:**  
Additional driver-side front damage



**Photo: 32**


**Date Taken:**  
01/22/2026

**Taken By:**  
Adrianne Adame

**Description:**  
View of front-end damage

## Claim Photo

**Our File Number:** 277-066371  
**Adjuster:** Mike Hogan  
**Insured:** 2Twenty Logistics LLC  
**Date of Loss:** 01/08/2026  
**Customer File Number:** DEL26001084  
**Policy Number:** ZACAT9783303




**Photo: 33**

**Date Taken:**  
01/22/2026

**Taken By:**  
Adrianne Adame

**Description:**  
Additional view of front-end damage



**Photo: 34**


**Date Taken:**  
01/22/2026

**Taken By:**  
Adrianne Adame

**Description:**  
Additional view of front-end damage

## Claim Photo

**Our File Number:** 277-066371  
**Adjuster:** Mike Hogan  
**Insured:** 2Twenty Logistics LLC  
**Date of Loss:** 01/08/2026  
**Customer File Number:** DEL26001084  
**Policy Number:** ZACAT9783303




**Photo: 35**

**Date Taken:**  
01/22/2026

**Taken By:**  
Adrianne Adame

**Description:**  
Additional view of front-end damage



**Photo: 36**


**Date Taken:**  
01/22/2026

**Taken By:**  
Adrianne Adame

**Description:**  
Passenger-side front damage

## Claim Photo

**Our File Number:** 277-066371  
**Adjuster:** Mike Hogan  
**Insured:** 2Twenty Logistics LLC  
**Date of Loss:** 01/08/2026  
**Customer File Number:** DEL26001084  
**Policy Number:** ZACAT9783303




**Photo: 37**

**Date Taken:**  
01/22/2026

**Taken By:**  
Adrianne Adame

**Description:**  
Additional view of  
passenger-side  
front damage



**Photo: 38**

**Date Taken:**  
01/22/2026

**Taken By:**  
Adrianne Adame

**Description:**  
Passenger-side  
front corner  
damage

## Claim Photo

**Our File Number:** 277-066371  
**Adjuster:** Mike Hogan  
**Insured:** 2Twenty Logistics LLC  
**Date of Loss:** 01/08/2026  
**Customer File Number:** DEL26001084  
**Policy Number:** ZACAT9783303

**cia**  
**CUSTARD**  
**INSURANCE ADJUSTERS**



**Photo: 39**

**Date Taken:**  
01/22/2026

**Taken By:**  
Adrienne Adame

**Description:**  
Additional view of  
passenger-side  
front corner  
damage



**Photo: 40**


**Date Taken:**  
01/22/2026

**Taken By:**  
Adrienne Adame

**Description:**  
Additional view of  
passenger-side  
front corner  
damage

## Claim Photo

**Our File Number:** 277-066371  
**Adjuster:** Mike Hogan  
**Insured:** 2Twenty Logistics LLC  
**Date of Loss:** 01/08/2026  
**Customer File Number:** DEL26001084  
**Policy Number:** ZACAT9783303



**Photo: 41**

**Date Taken:**  
01/22/2026

**Taken By:**  
Adrianne Adame

**Description:**  
Additional view of  
passenger-side  
front corner  
damage



**Photo: 42**

**Date Taken:**  
01/22/2026

**Taken By:**  
Adrianne Adame

**Description:**  
Passenger-side  
front damage

## Claim Photo

**Our File Number:** 277-066371  
**Adjuster:** Mike Hogan  
**Insured:** 2Twenty Logistics LLC  
**Date of Loss:** 01/08/2026  
**Customer File Number:** DEL26001084  
**Policy Number:** ZACAT9783303



**Photo: 43**

**Date Taken:**  
01/22/2026

**Taken By:**  
Adrianne Adame

**Description:**  
Additional view of  
passenger-side  
front damage



**Photo: 44**

**Date Taken:**  
01/22/2026

**Taken By:**  
Adrianne Adame

**Description:**  
Hood damage

## Claim Photo

**Our File Number:** 277-066371  
**Adjuster:** Mike Hogan  
**Insured:** 2Twenty Logistics LLC  
**Date of Loss:** 01/08/2026  
**Customer File Number:** DEL26001084  
**Policy Number:** ZACAT9783303



**Photo: 45**

**Date Taken:**  
01/22/2026

**Taken By:**  
Adrianne Adame

**Description:**  
Additional view of  
hood damage



**Photo: 46**

**Date Taken:**  
01/22/2026

**Taken By:**  
Adrianne Adame

**Description:**  
Additional view of  
hood damage

## Claim Photo

**Our File Number:** 277-066371  
**Adjuster:** Mike Hogan  
**Insured:** 2Twenty Logistics LLC  
**Date of Loss:** 01/08/2026  
**Customer File Number:** DEL26001084  
**Policy Number:** ZACAT9783303




**Photo: 47**

**Date Taken:**  
01/22/2026

**Taken By:**  
Adrianne Adame

**Description:**  
View of interior  
(driver-side)



**Photo: 48**


**Date Taken:**  
01/22/2026

**Taken By:**  
Adrianne Adame

**Description:**  
View of interior  
(passenger-side)

## Claim Photo

**Our File Number:** 277-066371  
**Adjuster:** Mike Hogan  
**Insured:** 2Twenty Logistics LLC  
**Date of Loss:** 01/08/2026  
**Customer File Number:** DEL26001084  
**Policy Number:** ZACAT9783303




**Photo: 49**

**Date Taken:**  
01/22/2026

**Taken By:**  
Adrianne Adame

**Description:**  
Instrument panel



**Photo: 50**

**Date Taken:**  
01/22/2026

**Taken By:**  
Adrianne Adame

**Description:**  
Shifter (automatic)

## Claim Photo

**Our File Number:** 277-066371  
**Adjuster:** Mike Hogan  
**Insured:** 2Twenty Logistics LLC  
**Date of Loss:** 01/08/2026  
**Customer File Number:** DEL26001084  
**Policy Number:** ZACAT9783303



**Photo: 51**

**Date Taken:**  
01/22/2026

**Taken By:**  
Adrianne Adame

**Description:**  
View of interior floor



**Photo: 52**

**Date Taken:**  
01/22/2026

**Taken By:**  
Adrianne Adame

**Description:**  
Under carriage

## Claim Photo

**Our File Number:** 277-066371  
**Adjuster:** Mike Hogan  
**Insured:** 2Twenty Logistics LLC  
**Date of Loss:** 01/08/2026  
**Customer File Number:** DEL26001084  
**Policy Number:** ZACAT9783303



**Photo: 53**

**Date Taken:**  
01/22/2026

**Taken By:**  
Adrianne Adame

**Description:**  
Driver-side front tire



**Photo: 54**

**Date Taken:**  
01/22/2026

**Taken By:**  
Adrianne Adame

**Description:**  
Close-up view of  
driver-side front  
tire

## Claim Photo

**Our File Number:** 277-066371  
**Adjuster:** Mike Hogan  
**Insured:** Twenty Logistics LLC  
**Date of Loss:** 01/08/2026  
**Customer File Number:** DEL26001084  
**Policy Number:** ZACAT9783303



**Photo:** 55

**Date Taken:**  
01/22/2026

**Taken By:**  
Adrianne Adame

**Description:**  
Driver-side front  
tire - Tread depth  
measurement:  
05/32



**Photo:** 56

**Date Taken:**  
01/22/2026

**Taken By:**  
Adrianne Adame

**Description:**  
Driver-side rear tire

## Claim Photo

**Our File Number:** 277-066371  
**Adjuster:** Mike Hogan  
**Insured:** 2Twenty Logistics LLC  
**Date of Loss:** 01/08/2026  
**Customer File Number:** DEL26001084  
**Policy Number:** ZACAT9783303



**Photo: 57**

**Date Taken:**  
01/22/2026

**Taken By:**  
Adrianne Adame

**Description:**  
Close-up view of  
driver-side rear tire



**Photo: 58**

**Date Taken:**  
01/22/2026

**Taken By:**  
Adrianne Adame

**Description:**  
Driver-side rear tire  
- Tread depth  
measurement:  
13/32

## Claim Photo

**Our File Number:** 277-066371  
**Adjuster:** Mike Hogan  
**Insured:** 2Twenty Logistics LLC  
**Date of Loss:** 01/08/2026  
**Customer File Number:** DEL26001084  
**Policy Number:** ZACAT9783303



**Photo: 59**

**Date Taken:**  
01/22/2026

**Taken By:**  
Adrianne Adame

**Description:**  
Passenger-side  
front tire



**Photo: 60**


**Date Taken:**  
01/22/2026

**Taken By:**  
Adrianne Adame

**Description:**  
Close-up view of  
passenger-side  
front tire

## Claim Photo

**Our File Number:** 277-066371  
**Adjuster:** Mike Hogan  
**Insured:** 2Twenty Logistics LLC  
**Date of Loss:** 01/08/2026  
**Customer File Number:** DEL26001084  
**Policy Number:** ZACAT9783303



**Photo: 61**

**Date Taken:**  
01/22/2026

**Taken By:**  
Adrianne Adame

**Description:**  
Passenger-side  
front tire - Tread  
depth  
measurement:  
13/32



**Photo: 62**

**Date Taken:**  
01/22/2026

**Taken By:**  
Adrianne Adame

**Description:**  
Passenger-side rear  
tire

## Claim Photo

**Our File Number:** 277-066371  
**Adjuster:** Mike Hogan  
**Insured:** Twenty Logistics LLC  
**Date of Loss:** 01/08/2026  
**Customer File Number:** DEL26001084  
**Policy Number:** ZACAT9783303



**Photo: 63**

**Date Taken:**  
01/22/2026

**Taken By:**  
Adrianne Adame

**Description:**  
Close-up view of passenger-side rear tire



**Photo: 64**

**Date Taken:**  
01/22/2026

**Taken By:**  
Adrianne Adame

**Description:**  
Passenger-side rear tire - Tread depth measurement:  
12/32

## Claim Photo

**Our File Number:** 277-066371  
**Adjuster:** Mike Hogan  
**Insured:** 2Twenty Logistics LLC  
**Date of Loss:** 01/08/2026  
**Customer File Number:** DEL26001084  
**Policy Number:** ZACAT9783303



**Photo: 65**

**Date Taken:**  
01/22/2026

**Taken By:**  
Adrianne Adame

**Description:**  
Driver-side front disc brakes



**Photo: 66**


**Date Taken:**  
01/22/2026

**Taken By:**  
Adrianne Adame

**Description:**  
Passenger-side rear disc brakes

## Claim Photo

**Our File Number:** 277-066371  
**Adjuster:** Mike Hogan  
**Insured:** 2Twenty Logistics LLC  
**Date of Loss:** 01/08/2026  
**Customer File Number:** DEL26001084  
**Policy Number:** ZACAT9783303



**Photo:** 67

**Date Taken:**  
01/22/2026

**Taken By:**  
Adrianne Adame

**Description:**  
Driver-side seat  
damage (PRIOR)



**Photo:** 68

**Date Taken:**  
01/22/2026

**Taken By:**  
Adrianne Adame

**Description:**  
Additional view of  
driver-side seat  
damage (PRIOR)

## Claim Photo

**Our File Number:** 277-066371  
**Adjuster:** Mike Hogan  
**Insured:** 2Twenty Logistics LLC  
**Date of Loss:** 01/08/2026  
**Customer File Number:** DEL26001084  
**Policy Number:** ZACAT9783303




**Photo: 69**

**Date Taken:**  
01/22/2026

**Taken By:**  
Adrianne Adame

**Description:**  
Driver-side damage  
(PRIOR)



**Photo: 70**


**Date Taken:**  
01/22/2026

**Taken By:**  
Adrianne Adame

**Description:**  
Additional driver-  
side damage  
(PRIOR)

## Claim Photo

**Our File Number:** 277-066371  
**Adjuster:** Mike Hogan  
**Insured:** Twenty Logistics LLC  
**Date of Loss:** 01/08/2026  
**Customer File Number:** DEL26001084  
**Policy Number:** ZACAT9783303



**Photo: 71**

**Date Taken:**  
01/22/2026

**Taken By:**  
Adrianne Adame

**Description:**  
Additional driver-side damage (PRIOR)



**Photo: 72**

**Date Taken:**  
01/22/2026

**Taken By:**  
Adrianne Adame

**Description:**  
Additional driver-side damage (PRIOR)

## Claim Photo

**Our File Number:** 277-066371  
**Adjuster:** Mike Hogan  
**Insured:** 2Twenty Logistics LLC  
**Date of Loss:** 01/08/2026  
**Customer File Number:** DEL26001084  
**Policy Number:** ZACAT9783303




**Photo:** 73

**Date Taken:**  
01/22/2026

**Taken By:**  
Adrianne Adame

**Description:**  
Additional driver-side damage  
(PRIOR)



**Photo:** 74

**Date Taken:**  
01/22/2026

**Taken By:**  
Adrianne Adame

**Description:**  
Additional driver-side damage  
(PRIOR)

## Claim Photo

**Our File Number:** 277-066371  
**Adjuster:** Mike Hogan  
**Insured:** 2Twenty Logistics LLC  
**Date of Loss:** 01/08/2026  
**Customer File Number:** DEL26001084  
**Policy Number:** ZACAT9783303



**Photo:** 75

**Date Taken:**  
01/22/2026

**Taken By:**  
Adrianne Adame

**Description:**  
Passenger-side  
damage (PRIOR)



**Photo:** 76

**Date Taken:**  
01/22/2026

**Taken By:**  
Adrianne Adame

**Description:**  
Additional view of  
passenger-side  
damage (PRIOR)

## Claim Photo

**Our File Number:** 277-066371  
**Adjuster:** Mike Hogan  
**Insured:** 2Twenty Logistics LLC  
**Date of Loss:** 01/08/2026  
**Customer File Number:** DEL26001084  
**Policy Number:** ZACAT9783303




**Photo:** 77

**Date Taken:**  
01/22/2026

**Taken By:**  
Adrianne Adame

**Description:**  
Additional view of  
passenger-side  
damage (PRIOR)



**Photo:** 78


**Date Taken:**  
01/22/2026

**Taken By:**  
Adrianne Adame

**Description:**  
Additional view of  
passenger-side  
damage (PRIOR)

## Claim Photo

**Our File Number:** 277-066371  
**Adjuster:** Mike Hogan  
**Insured:** 2Twenty Logistics LLC  
**Date of Loss:** 01/08/2026  
**Customer File Number:** DEL26001084  
**Policy Number:** ZACAT9783303




**Photo: 79**

**Date Taken:**  
01/22/2026

**Taken By:**  
Adrienne Adame

**Description:**  
Additional view of passenger-side damage (PRIOR)



**Photo: 80**

**Date Taken:**  
01/22/2026

**Taken By:**  
Adrienne Adame

**Description:**  
Additional view of passenger-side damage (PRIOR)