



Option Form

Truck/Tractor
Daycab/Non-Sleeper Heavy Duty
- Class 7/8

Claim Information

| Customer Claim Number | Reference Number | Loss Date | Type of Loss | Prior Damage/Other Ded. |
|-----------------------|------------------|------------|--------------|-------------------------|
| 31007 | | 11/21/2025 | Collision | \$0 |

Claim Rep

| Company | Southern States Insurance Exchange | Claim Rep Name | Cindi Hodges |
|---------|------------------------------------|----------------|--------------|
|---------|------------------------------------|----------------|--------------|

Owner /Insured

| Owner Name | Insured Name | Owner Phone | Owner Email |
|---------------|----------------------|--------------|-------------------|
| AFC Feed, LLC | | 256-560-2845 | waltb@alafarm.com |
| Owner Address | 121 Somerville Rd NE | | |
| Owner City | Owner State | Owner Zip | Sales Tax Rate % |
| Decatur | Alabama | 25609 | 10 |

Vehicle / Asset

| VIN | Year | Make | Model | Mileage | |
|-------------------|-----------------|--------------------|--------------------|------------------|-----------|
| 365797 | 2011 | International | LF627 | Original 321,656 | |
| Overall Condition | Drive Line Type | Body Type | Axle Configuration | GVW | Fuel Type |
| Average | 4WD | feed trailer-truck | tri | 52000 | Diesel |

Powertrain

| Engine | Make / Model | | Type | | HP | | Engine Condition | |
|--------------|----------------|------|----------|------|------------|-----------------|------------------------|------|
| | INTERNATIONAL | | MAXFORCE | | | | Average | |
| | Rebuilt Engine | Type | Date | Cost | Miles | Turbo | Date | Cost |
| No | | | | | | | | |
| Transmission | Make / Model | | Type | | # of Gears | | Transmission Condition | |
| | EATON FULLER | | Manual | | 10 | | Average | |
| | Rebuilt Trans | Type | Date | Cost | Miles | Suspension Type | | |
| No | | | | | | | | |

Tires/Axles

| | Wheel Type | Tire Size | Qty | Tire Tread Remaining | Axle Rating |
|-----------------|------------|-----------|-----|----------------------|-------------|
| Front | Steel | 20.5R25 | 2 | 90% | 12 |
| Rear | Steel | 20.5R25 | 4 | 90% | 20 |
| Tag | Steel | 20.5R25 | 4 | 80% | 20 |
| # of Rear Axles | Tri | | | | |

Truck/Trailer Body Options

| Truck Body Type | Year/Make/Model of Body | | Composition | Length | Capacity |
|---------------------|-------------------------|------|-------------|-----------------|----------------------------|
| | 2024 CIRCLE A | | Alum | 30 | 5 TANK |
| Truck Body Features | Repainted | Date | Cost | Paint Condition | Windshield/Glass Condition |
| | | | | Average | Average |

Exterior Features

| | | | | | | | |
|-------------------|-------------|----------------------|--|-------------|------------|-----------|------|
| Truck Accessories | | Aerodynamics | | Tool Boxes | Qty / Size | Date | Cost |
| | | | | | | | |
| 5th Wheel | Tarp System | Air Cleaner/Breather | | Fuel Tanks | Qty | Capacity | |
| | | | | Alum | 2 | 90 | |

Interior Features


| | | | | |
|-----------------|--------------------|--------------|------|------------------------|
| Trim Type | Interior Condition | Sleeper Type | Size | Truck Options Interior |
| Standard | Average | | | |

Electronics/Power Accessories

| | | |
|---|-------------------------|----------------------|
| Sound System | Truck Power Accessories | Backup Camera System |
| AM Radio, FM Radio and CD Player | | |

Comments/Additional Info

THR TRUCK HAS A CIRCLE A 5 BIN FEED BODY ATTACHED



VIN



LF



INTERIOR



DOOR CONTROLS



FLOOR



SEAT



INTERIOR



VIN



December 01, 2025

VIN



December 01, 2025

ODOMETER




STEERING WHEEL



HEADLINER



DASH



CONTROLS



December 01, 2025

TRANSMISSION



December 01, 2025

RF



BODY TAG



BATTERY BOX



LF TANKS



EMBLEM



MEASUREMENT



LR




FT



LOGO



FUEL TANK



INTERIOR



LT SIDE



REAR



RR



RT SIDE TANK



RRI TIRE



LRO TIRE



WHEEL



LF TIRE



RRO TIRE



RRI TIRE



RRO TIRE



LF TIRE



RF TIRE



ENGINE



SUSPENSION



LRO TIRE



LR I TIRE



LR O TIRE



December 01, 2025

LRI TIRE



December 01, 2025

AXLE



AIRBAG



DAMAGED PLATE



BODY DAMAGE



BODY DAMAGE