

Date: 1/5/2024 06:44 AM
Estimate ID: SR0022
Estimate Version: 0
Preliminary
Profile ID: * BASIC

Casualty & Property Resolutions (CPR)

600 E John Carpenter Fwy. Ste. 365 , Irving, TX 75062
(855) 215-6439

ALL SUPPLEMENT REQUEST MUST BE E-MAILED TO SUPPLEMENT@CPRINS.COM

Damage Assessed By: CPR APPRAISER
Classification: Field

Appraised For: Michael Toth

*****NOTICE*****
THIS IS A DAMAGE ASSESSMENT ONLY, WHICH IS BASED ON DAMAGE VISIBLE OR CERTAIN AT THE TIME IT WAS WRITTEN. THIS IS NOT AN AUTHORIZATION TO REPAIR, NOR AN ADMISSION OF LIABILITY! ALL COST OF REPAIRS ARE THE SOLE RESPONSIBILITY OF THE VEHICLE OWNER, WHO ULTIMATELY MUST AUTHORIZE ALL WORK TO BE PERFORMED. THE VEHICLE OWNER MAINTAINS THE RIGHT TO REPAIR THE VEHICLE AT A REPAIR FACILITY OF THEIR CHOICE.

CPR SPECIFIES THAT ALL REPAIRS AND/OR PARTS REPLACEMENTS LISTED HEREIN, BE MADE IN STRICT ACCORDANCE WITH ALL MANUFACTURER'S SPECIFICATIONS AND GUIDELINES.

Condition Code: Fair
Deductible: UNKNOWN
Claim Number: SR0022

Insured: SCOTT VAHL TRUCKING LLC
Owner: SCOTT VAHL TRUCKING LLC

Mitchell Service: 917867

Description: 2006 Freightliner Columbia
Type/Component: Truck
VIN: 1FUJA6CVX6LV97444
OEM/ALT: A
Color: PEWTER

Drive Train:
Search Code: B1004299

Line Item	Entry Number	Labor Type	Operation	Line Item Description	Part Type/ Part Number	Dollar Amount	Labor Units
<u>Front Lamps</u>							
1	700791	BDY	CHECK/ADJUST	Headlamps			0.5
<u>Hood</u>							
2	700039	REF	REFINISH	Hood Outside			C 8.9
3	702183	BDY	REPAIR	Hood Panel	Existing		6.5* #
<u>Fuel Tank</u>							
4	700601	MCH	REMOVE/REPLACE	R Fuel System Tank -M	Qual Recycled Part	750.00 *	1.5 #r
5				INCLS STEPS			
6				VANDER HAAGS PH# (888) 930-3050			
7				Line Markup %25.00		187.50	
<u>Front Axle & Suspension</u>							

ESTIMATE RECALL NUMBER: 01/05/2024 06:32:08 SR0022

Mitchell Data Version: OEM: JUL_23_V

MAPP: JUL_23_V

Software Version:

7.1.243

Copyright (C) 1994 - 2023 Mitchell International
All Rights Reserved

Date: 1/ 5/2024 06:44 AM
Estimate ID: SR0022
Estimate Version: 0
Preliminary
Profile ID: * BASIC

8	701115	MCH	ALIGN	Add To Adjust Front Suspension	-M			2.0
				<u>Engine</u>				
9	841152	MCH	REMOVE/INSTALL	Oil Pan	-M			3.1 #
10	843671	MCH	REMOVE/REPLACE	Engine Oil Pan	-M	** QUAL REPL PART	131.89 *	2.8 #
				<u>Additional Costs & Materials</u>				
11	936003		ADD'L COST	Coolant			100.00 *	
				<u>Exhaust</u>				
12	700664	BDY	REMOVE/REPLACE	Exhaust Tailpipe		** QUAL REPL PART	189.99 *	0.5
13	700667	BDY	REMOVE/REPLACE	Otr Exhaust Heat Shield		New	467.45 *	0.5
14	700668	BDY	REMOVE/REPLACE	Exhaust Muffler		** QUAL REPL PART	489.19 *	1.0
15	700672	BDY	REMOVE/REPLACE	Frnt Exhaust Pipe		** QUAL REPL PART	287.12 *	1.0
16	700674	BDY	REMOVE/REPLACE	Lwr Exhaust Pipe		** QUAL REPL PART	238.17 *	1.0
				<u>Cab Assy</u>				
17	700232	REF	REFINISH	Cab Assy				C 32.0
18	701638	REF	REFINISH	Add For Inside				C 12.8
19	701550	BDY	REMOVE/REPLACE	Cab Shell Assy		Qual Recycled Part	5,500.00 *	39.0 r
20				VANDER HAAGS PH# (888) 930-3050				
21				Line Markup %25.00			1,375.00	
				<u>Front Door</u>				
22	702858	BDY	REMOVE/REPLACE	R Frnt Door Mirror Assy		Qual Recycled Part	250.00 *	1.3 #r
23				VANDER HAAGS PH# (888) 930-3050				
24				Line Markup %25.00			62.50	
				<u>Rear Suspension</u>				
25	843015	MCH	CHECK/ADJUST	Rear Axle Alignment	-M			2.3
				<u>Fifth Wheel</u>				
26	843388	MCH	REMOVE/REPLACE	Fifth Wheel	-M	** QUAL REPL PART	3,278.95 *	4.0
				<u>Additional Costs & Materials</u>				
27	936004		ADD'L COST	Shipping			1,250.00 *	
28				TRUCK FREIGHT REQUIRED				
29	936005		ADD'L COST	Lubricants			125.00 *	
30	936012		ADD'L COST	Hazardous Waste Disposal			10.00 *	
				<u>Additional Operations</u>				
31		REF	ADD'L OPR	Clear Coat				5.1
				<u>Additional Costs & Materials</u>				
32			ADD'L COST	Paint/Materials			4,116.00 *	
				<u>Special/Manual Entry</u>				
33	900500	FRM *	REPAIR	Setup and Measure		Existing		4.5*
34	900500	FRM *	REPAIR	L Rail		Existing		8.0*
35				CORRECT TWIST				
36	900500	FRM *	REPAIR	R Rail		Existing		8.0*
37				CORRECT TWIST				
38	900500	MCH *	ADD'L LABOR OP	Check Rods and Mains		Existing		10.0*
39				POSS INTERNAL ENGINE DAMAGE DUE				
40				TO OIL STARVATION THAT COULD HAVE				
41				OCCURED AT THE TIME OF THE LOSS				
42	900500	MCH *	ADD'L LABOR OP	Service Unit		Existing		6.0*
43	900500	MCH *	REMOVE/REPLACE	Misc Filters (FOR SERVICE)		** QUAL REPL PART	225.00 *	INC*
44	900500	MCH *	ADD'L LABOR OP	Check/Inspect Cooling Pack		Existing		3.0*
45				INCLS PRESSURE TEST				
46	900500	BDY *	ADD'L LABOR OP	Decaling		Sublet	450.00 *	INC*

* - Judgment Item
- Labor Note Applies
C - Included in Clear Coat Calc
r - CEG R&R Time Used For This Labor Operation

ESTIMATE RECALL NUMBER: 01/05/2024 06:32:08 SR0022

Mitchell Data Version: OEM: JUL_23_V

MAPP:JUL_23_V

Software Version:

7.1.243

Copyright (C) 1994 - 2023 Mitchell International
All Rights Reserved

Date: 1/5/2024 06:44 AM
Estimate ID: SR0022
Estimate Version: 0
Preliminary
Profile ID: * BASIC

AND THE NAMED ESTIMATOR IN THE SUBJECT LINE OF THE E-MAIL.

RENTAL CAR PROVISIONS:

The need for a rental vehicle and/or extension, will be determined and authorized by the handling adjuster ONLY. If a rental is deemed necessary, the length and duration of the rental will be calculated in accordance with the total estimated labor hours noted on the original estimate of record. If there is a need to extend the rental past this allotted time PRIOR approval must be granted by the handling adjuster.

NOTICE: Vehicles constructed of special metals may require the use of specialized welding and bonding equipment. Proper measuring and structural repair systems are a requirement on today's vehicles in order to accurately accomplish necessary repairs.

ALTERNATE PARTS DISCLAIMER:

IF A QUALITY REPLACEMENT PART (A/M, LKQ, RECOND OR OPT OEM) APPEARS ON THIS ESTIMATE, IT INDICATES THAT THE ESTIMATE HAS BEEN PREPARED BASED ON THE USE OF ONE OR MORE CRASH PARTS SUPPLIED BY A SOURCE OTHER THAN THE ORIGINAL MANUFACTURER OF YOUR MOTOR VEHICLE. WARRANTIES, IF ANY, APPLICABLE TO THESE REPLACEMENT CRASH PARTS ARE PROVIDED BY THE PART MANUFACTURER OR DISCTIBUTOR, RATHER THAN THE MANUFACTURER OF THE VEHICLE.



Phone 800-875-2217 Fax 913-825-4801

Heavy Truck Total Loss

Date Requested: 12/05/2024

Autobid Request No	Company Name ACUITY		Adjuster Name MICHAEL TOTH		Adjuster Phone No (800) 242-7666 Ext 3207	Loss Date 11/14/2024	
Claim No SR0022	File #	Insured Name SCOTT VAHL TRUCKING LLC.		Insured Phone No (715) 478-2587	Loss Type ROLLOVER		
Market Area (City/Zip) CRANDON, WI 54520		Claimant Name N/A		Claimant Phone No N/A			
Adjuster eMail address mtoth@acuity.com		Appraiser Name CPR		Appraiser eMail Address mwilson@cprins.com		Appraiser Phone No (817) 694-6691	
VIN 1FUJA6CVX6LV97444	Year 2006	Make FREIGHTLINER		Model COLUMBIA			
Style CONVENTIONAL	Engine MERCEDES	Transmission AUTO		Engine Hours			
Interior Condition	<input type="checkbox"/> Above Average <input type="checkbox"/> Average <input checked="" type="checkbox"/> Below Average			Prior Damage		\$	
Exterior Condition	<input type="checkbox"/> Above Average <input type="checkbox"/> Average <input checked="" type="checkbox"/> Below Average			Remarks on Condition FAIR CONDITION EXTERIOR POOR CONDITION INTERIOR WITH HEAVY WEAR AND TEAR			
Tire Condition	<input type="checkbox"/> Above Average <input checked="" type="checkbox"/> Average <input type="checkbox"/> Below Average			Tire Size	# of Tires		
Engine	Make	MERCEDES	Model	Serial #	HP	450	
Transmission	Make		Model	AUTO	Type	AUTO	Speeds
	Serial		Axle Power		Single Axle	Tandem	Pusher/tag Axle
Bed	Main Length		Bedroom Length		Windows #	EA	
Tank	Capacity		Total #		Gallons		
Suspension	Front	12K SPRING	Rear	40K AIR			

Equipment

Interior		Radio / Alarm		Exterior		Paint/Trim/Glass	
<input type="checkbox"/>	Premium Level Interior	<input type="checkbox"/>	AM Radio	<input type="checkbox"/>	New Bumper	<input type="checkbox"/>	New Paint
<input type="checkbox"/>	New Interior in Sleeper	<input type="checkbox"/>	AM/FM Stereo	<input type="checkbox"/>	Dual Chrome Exhaust	<input type="checkbox"/>	2 Tone Paint
<input type="checkbox"/>	Dual Painted Air Cleaners	<input type="checkbox"/>	AM/FM Tape	<input type="checkbox"/>	Liftgate	<input type="checkbox"/>	Custom Paint
<input type="checkbox"/>	Truck Warranty	<input checked="" type="checkbox"/>	AM/FM Tape/CD	<input type="checkbox"/>	Side Fairings Only	<input type="checkbox"/>	Custom Graphics
<input type="checkbox"/>	Accessory Warranties	<input type="checkbox"/>	CD Player	<input type="checkbox"/>	Aero Pkg (Roof, Sides, and Full Chassis)	<input type="checkbox"/>	Tinted Glass (OEM)
<input type="checkbox"/>	Wet Kit	<input type="checkbox"/>	CD Changer	<input type="checkbox"/>	Roof Fairing Only	<input type="checkbox"/>	Tinted Glass (AM)
<input type="checkbox"/>	Dual Stainless/Chrome Air Cleaners	<input type="checkbox"/>	Equalizer	<input type="checkbox"/>	Stainless 1/4 Fender	<input type="checkbox"/>	Privacy Glass
<input type="checkbox"/>	New Clutch	<input checked="" type="checkbox"/>	CB	<input type="checkbox"/>	4 New Batteries	<input type="checkbox"/>	Front Spoiler
<input type="checkbox"/>	New Interior	<input type="checkbox"/>	Alarm System			Wheels/Tires	
<input checked="" type="checkbox"/>	Sun Visor	<input type="checkbox"/>	GPS Navigation			<input type="checkbox"/>	2 New Front Tires
						<input checked="" type="checkbox"/>	2 Front Aluminum Wheels
						<input checked="" type="checkbox"/>	4-8 Rear Alum Wheels
						<input type="checkbox"/>	8 New Rear Re-Cap Tires
						<input type="checkbox"/>	8 New Rear Tires

Additional Equipment and Comments

PLEASE RUN MILEAGE AS AVERAGE FOR YEAR. EXTERIOR IN FAIR CONDITION WITH INTERIOR BEING IN POOR CONDITION.

























