

Claim Photo

Our File Number:

Adjuster:

Insured:

Date of Loss:

Customer File Number:

Policy Number:



Photo: 1

Date Taken:
12/02/2025

Taken By:
Lazette Hoglund-
Hall

Description:
Front trailer



Photo: 2

Date Taken:
12/02/2025

Taken By:
Lazette Hoglund-
Hall

Description:
Front left overview

Claim Photo

Our File Number:

Adjuster:

Insured:

Date of Loss:

Customer File Number:

Policy Number:



Photo: 3

Date Taken:
12/02/2025

Taken By:
Lazette Hoglund-
Hall

Description:
VIN
P12581ID170W20
49



Photo: 4

Date Taken:
12/02/2025

Taken By:
Lazette Hoglund-
Hall

Description:
Right overview

Claim Photo

Our File Number:

Adjuster:

Insured:

Date of Loss:

Customer File Number:

Policy Number:



Photo: 5

Date Taken:
12/02/2025

Taken By:
Lazette Hoglund-
Hall

Description:
Rear left overview



Photo: 6

Date Taken:
12/02/2025

Taken By:
Lazette Hoglund-
Hall

Description:
Rear right overview

Claim Photo

Our File Number:

Adjuster:

Insured:

Date of Loss:

Customer File Number:

Policy Number:



Photo: 7

Date Taken:
12/02/2025

Taken By:
Lazette Hoglund-
Hall

Description:
Right side was
where trailer came
to rest at scene



Photo: 8

Date Taken:
12/02/2025

Taken By:
Lazette Hoglund-
Hall

Description:
Right side near
front damage

Claim Photo

Our File Number:

Adjuster:

Insured:

Date of Loss:

Customer File Number:

Policy Number:



Photo: 9

Date Taken:
12/02/2025

Taken By:
Lazette Hoglund-Hall

Description:
Observed some bending to the frame



Photo: 10

Date Taken:
12/02/2025

Taken By:
Lazette Hoglund-Hall

Description:
Star cool system