

Claim Photo
Our File Number:
Adjuster:
Insured:
Date of Loss:
Customer File Number:
Policy Number:




Photo: 1
Date Taken: 12/04/2025
Taken By: Jeremy Garcia-Baez
Description: Impound invoice




Photo: 2
Date Taken: 12/03/2025
Taken By: Jeremy Garcia-Baez
Description: VIN

Claim Photo

Our File Number:

Adjuster:

Insured:

Date of Loss:

Customer File Number:

Policy Number:



Photo: 3

Date Taken:
12/03/2025

Taken By:
Jeremy Garcia-
Baez

Description:
License Plate



Photo: 4

Date Taken:
12/03/2025

Taken By:
Jeremy Garcia-
Baez

Description:
Left front

Claim Photo

Our File Number:

Adjuster:

Insured:

Date of Loss:

Customer File Number:

Policy Number:



Photo: 5

Date Taken:
12/03/2025

Taken By:
Jeremy Garcia-
Baez

Description:
Right front



Photo: 6

Date Taken:
12/03/2025

Taken By:
Jeremy Garcia-
Baez

Description:
Right rear

Claim Photo

Our File Number:

Adjuster:

Insured:

Date of Loss:

Customer File Number:

Policy Number:



Photo: 7

Date Taken:
12/03/2025

Taken By:
Jeremy Garcia-
Baez

Description:
Left rear



Photo: 8

Date Taken:
12/03/2025

Taken By:
Jeremy Garcia-
Baez

Description:
Front end damage

Claim Photo

Our File Number:
Adjuster:
Insured:
Date of Loss:
Customer File Number:
Policy Number:



Photo: 9
Date Taken:
12/03/2025
Taken By:
Jeremy Garcia-
Baez
Description:
Left front tire
damage



Photo: 10
Date Taken:
12/03/2025
Taken By:
Jeremy Garcia-
Baez
Description:
Left front axle
dame

Claim Photo

Our File Number:

Adjuster:

Insured:

Date of Loss:

Customer File Number:

Policy Number:



Photo: 11

Date Taken:
12/03/2025

Taken By:
Jeremy Garcia-
Baez

Description:
Left front control
arm damage



Photo: 12

Date Taken:
12/03/2025

Taken By:
Jeremy Garcia-
Baez

Description:
Left front headlight

Claim Photo

Our File Number:

Adjuster:

Insured:

Date of Loss:

Customer File Number:

Policy Number:



Photo: 13

Date Taken:
12/03/2025

Taken By:
Jeremy Garcia-
Baez

Description:
Front
bumper/component
s damage



Photo: 14

Date Taken:
12/03/2025

Taken By:
Jeremy Garcia-
Baez

Description:
Radiator/support/co
ndenser damage

Claim Photo

Our File Number:

Adjuster:

Insured:

Date of Loss:

Customer File Number:

Policy Number:



Photo: 15

Date Taken:
12/03/2025

Taken By:
Jeremy Garcia-
Baez

Description:
Right side damage
view



Photo: 16

Date Taken:
12/03/2025

Taken By:
Jeremy Garcia-
Baez

Description:
Right front axle
damage

Claim Photo

Our File Number:

Adjuster:

Insured:

Date of Loss:

Customer File Number:

Policy Number:



Photo: 17

Date Taken:
12/03/2025

Taken By:
Jeremy Garcia-
Baez

Description:
right front damage



Photo: 18

Date Taken:
12/03/2025

Taken By:
Jeremy Garcia-
Baez

Description:
impact bar/ radiator
support

Claim Photo

Our File Number:

Adjuster:

Insured:

Date of Loss:

Customer File Number:

Policy Number:



Photo: 19

Date Taken:
12/03/2025

Taken By:
Jeremy Garcia-
Baez

Description:
right uniside
damage



Photo: 20

Date Taken:
12/03/2025

Taken By:
Jeremy Garcia-
Baez

Description:
Damaged right side
service/utility body

Claim Photo

Our File Number:

Adjuster:

Insured:

Date of Loss:

Customer File Number:

Policy Number:



Photo: 21

Date Taken:
12/03/2025

Taken By:
Jeremy Garcia-
Baez

Description:
Damaged right side
service/utility body



Photo: 22

Date Taken:
12/03/2025

Taken By:
Jeremy Garcia-
Baez

Description:
Damaged right side
service/utility body

Claim Photo

Our File Number:

Adjuster:

Insured:

Date of Loss:

Customer File Number:

Policy Number:



Photo: 23

Date Taken:
12/03/2025

Taken By:
Jeremy Garcia-
Baez

Description:
Damaged right side
service/utility body



Photo: 24

Date Taken:
12/03/2025

Taken By:
Jeremy Garcia-
Baez

Description:
right uniside/roof
damage

Claim Photo

Our File Number:

Adjuster:

Insured:

Date of Loss:

Customer File Number:

Policy Number:



Photo: 25

Date Taken:
12/03/2025

Taken By:
Jeremy Garcia-
Baez

Description:
right side damage
angle view



Photo: 26

Date Taken:
12/03/2025

Taken By:
Jeremy Garcia-
Baez

Description:
Right passenger
airbag

Claim Photo

Our File Number:
Adjuster:
Insured:
Date of Loss:
Customer File Number:
Policy Number:



Photo: 27
Date Taken:
12/03/2025
Taken By:
Jeremy Garcia-
Baez
Description:
Right passenger
seat airbag



Photo: 28
Date Taken:
12/03/2025
Taken By:
Jeremy Garcia-
Baez
Description:
Drivers side airbag

Claim Photo

Our File Number:
Adjuster:
Insured:
Date of Loss:
Customer File Number:
Policy Number:



Photo: 29
Date Taken:
12/03/2025
Taken By:
Jeremy Garcia-
Baez
Description:
Drivers door trim



Photo: 30
Date Taken:
12/03/2025
Taken By:
Jeremy Garcia-
Baez
Description:
Drivers seat/airbag

Claim Photo

Our File Number:

Adjuster:

Insured:

Date of Loss:

Customer File Number:

Policy Number:



Photo: 31

Date Taken:
12/03/2025

Taken By:
Jeremy Garcia-
Baez

Description:
Drivers under
carpet



Photo: 32

Date Taken:
12/03/2025

Taken By:
Jeremy Garcia-
Baez

Description:
Dash

Claim Photo

Our File Number:
Adjuster:
Insured:
Date of Loss:
Customer File Number:
Policy Number:



Photo: 33
Date Taken:
12/03/2025
Taken By:
Jeremy Garcia-
Baez
Description:
Headliner



Photo: 34
Date Taken:
12/03/2025
Taken By:
Jeremy Garcia-
Baez
Description:
roof

Claim Photo

Our File Number:

Adjuster:

Insured:

Date of Loss:

Customer File Number:

Policy Number:



Photo: 35

Date Taken:
12/03/2025

Taken By:
Jeremy Garcia-
Baez

Description:
Passenger seat



Photo: 36

Date Taken:
12/03/2025

Taken By:
Jeremy Garcia-
Baez

Description:
Left front tire

Claim Photo

Our File Number:

Adjuster:

Insured:

Date of Loss:

Customer File Number:

Policy Number:



Photo: 37

Date Taken:
12/03/2025

Taken By:
Jeremy Garcia-
Baez

Description:
Right front tire



Photo: 38

Date Taken:
12/03/2025

Taken By:
Jeremy Garcia-
Baez

Description:
Right rear tire

Claim Photo

Our File Number:

Adjuster:

Insured:

Date of Loss:

Customer File Number:

Policy Number:



Photo: 39

Date Taken:
12/03/2025

Taken By:
Jeremy Garcia-
Baez

Description:
Left rear tire



Photo: 40

Date Taken:
12/03/2025

Taken By:
Jeremy Garcia-
Baez

Description:
Diesel gas

Claim Photo

Our File Number:

Adjuster:

Insured:

Date of Loss:

Customer File Number:

Policy Number:



Photo: 41

Date Taken:
12/03/2025

Taken By:
Jeremy Garcia-
Baez

Description:
Altec part



Photo: 42

Date Taken:
12/03/2025

Taken By:
Jeremy Garcia-
Baez

Description:
Hitch capacity

Claim Photo

Our File Number:

Adjuster:

Insured:

Date of Loss:

Customer File Number:

Policy Number:



Photo: 43

Date Taken:
12/03/2025

Taken By:
Jeremy Garcia-
Baez

Description:
lift options



Photo: 44

Date Taken:
12/03/2025

Taken By:
Jeremy Garcia-
Baez

Description:
truck information
paper

Claim Photo

Our File Number:
Adjuster:
Insured:
Date of Loss:
Customer File Number:
Policy Number:



Photo: 45

Date Taken:
12/03/2025

Taken By:
Jeremy Garcia-
Baez

Description:
V8 turbocharged
diesel engine



Photo: 46

Date Taken:
12/03/2025

Taken By:
Jeremy Garcia-
Baez

Description:
Engine

Claim Photo

Our File Number:
Adjuster:
Insured:
Date of Loss:
Customer File Number:
Policy Number:



Photo: 47

Date Taken:
12/03/2025

Taken By:
Jeremy Garcia-
Baez

Description:
Clean idle