

Claim Photo

Our File Number: 277-066336
Adjuster: Jason Gomez
Insured: Anderson Trucking Service
Date of Loss:
Customer File Number: 2026-01-000103
Policy Number:



Photo: 1

Date Taken:
01/28/2026

Taken By:
Jason Gomez

Description:
Overview of crates.



Photo: 2

Date Taken:
01/28/2026

Taken By:
Jason Gomez

Description:
Serial # 24-1819
marked on crate.

Claim Photo

Our File Number: 277-066336

Adjuster: Jason Gomez

Insured: Anderson Trucking Service

Date of Loss:

Customer File Number: 2026-01-000103

Policy Number:

cia
CUSTARD
INSURANCE ADJUSTERS




Photo: 3

Date Taken:
01/28/2026

Taken By:
Jason Gomez

Description:
Serial # 24-1819
marked on crate.



Photo: 4

Date Taken:
01/28/2026

Taken By:
Jason Gomez

Description:
Overview of
damage to crate and
V-Cone 14" 24-
1419.

Claim Photo

Our File Number: 277-066336

Adjuster: Jason Gomez

Insured: Anderson Trucking Service

Date of Loss:

Customer File Number: 2026-01-000103

Policy Number:

cia
CUSTARD
INSURANCE ADJUSTERS



Photo: 5

Date Taken:
01/28/2026

Taken By:
Jason Gomez

Description:
Overview of
damage to crate and
V-Cone 14" 24-
1419.



Photo: 6

Date Taken:
01/28/2026

Taken By:
Jason Gomez

Description:
Overview of
damage to crate and
V-Cone 14" 24-
1419.

Claim Photo

Our File Number: 277-066336

Adjuster: Jason Gomez

Insured: Anderson Trucking Service

Date of Loss:

Customer File Number: 2026-01-000103

Policy Number:

cia
CUSTARD
INSURANCE ADJUSTERS



Photo: 7

Date Taken:
01/28/2026

Taken By:
Jason Gomez

Description:
Overview of
damage to crate and
V-Cone 14" 24-
1419.



Photo: 8

Date Taken:
01/28/2026

Taken By:
Jason Gomez

Description:
Overview of
damage to the V-
Cone 14" 24-1419.

Claim Photo

Our File Number: 277-066336
Adjuster: Jason Gomez
Insured: Anderson Trucking Service
Date of Loss:
Customer File Number: 2026-01-000103
Policy Number:



Photo: 9

Date Taken:
01/28/2026

Taken By:
Jason Gomez

Description:
Identification Plate
for V-Cone 14" 24-
1419.



Photo: 10

Date Taken:
01/28/2026

Taken By:
Jason Gomez

Description:
Identification Plate
for V-Cone 14" 24-
1419.

Claim Photo

Our File Number: 277-066336
Adjuster: Jason Gomez
Insured: Anderson Trucking Service
Date of Loss:
Customer File Number: 2026-01-000103
Policy Number:



Photo: 11

Date Taken:
01/28/2026

Taken By:
Jason Gomez

Description:
Identification Plate
for V-Cone 14" 24-
1419.



Photo: 12

Date Taken:
01/28/2026

Taken By:
Jason Gomez

Description:
Identification Plate
for V-Cone 14" 24-
1419.

Claim Photo

Our File Number: 277-066336
Adjuster: Jason Gomez
Insured: Anderson Trucking Service
Date of Loss:
Customer File Number: 2026-01-000103
Policy Number:



Photo: 13

Date Taken:
01/28/2026

Taken By:
Jason Gomez

Description:
Identification Plate
for V-Cone 14" 24-
1419.



Photo: 14

Date Taken:
01/28/2026

Taken By:
Jason Gomez

Description:
Identification Plate
for V-Cone 14" 24-
1419.

Claim Photo

Our File Number: 277-066336
Adjuster: Jason Gomez
Insured: Anderson Trucking Service
Date of Loss:
Customer File Number: 2026-01-000103
Policy Number:



Photo: 15

Date Taken:
01/28/2026

Taken By:
Jason Gomez

Description:
Identification Plate
for V-Cone 14" 24-
1419.



Photo: 16

Date Taken:
01/28/2026

Taken By:
Jason Gomez

Description:
Identification Plate
for V-Cone 14" 24-
1419.

Claim Photo

Our File Number:

277-066336

Adjuster:

Jason Gomez

Insured:

Anderson Trucking Service

Date of Loss:

Customer File Number: 2026-01-000103

Policy Number:



Photo: 17

Date Taken:
01/28/2026

Taken By:
Jason Gomez

Description:
Identification Plate
for V-Cone 14" 24-
1419.



Photo: 18

Date Taken:
01/28/2026

Taken By:
Jason Gomez

Description:
Identification Plate
for V-Cone 14" 24-
1419.

Claim Photo

Our File Number: 277-066336
Adjuster: Jason Gomez
Insured: Anderson Trucking Service
Date of Loss:
Customer File Number: 2026-01-000103
Policy Number:



Photo: 19

Date Taken:
01/28/2026

Taken By:
Jason Gomez

Description:
Identification Plate
for V-Cone 14" 24-
1419.



Photo: 20

Date Taken:
01/28/2026

Taken By:
Jason Gomez

Description:
Identification Plate
for V-Cone 14" 24-
1419.

Claim Photo

Our File Number: 277-066336
Adjuster: Jason Gomez
Insured: Anderson Trucking Service
Date of Loss:
Customer File Number: 2026-01-000103
Policy Number:



Photo: 21

Date Taken:
01/28/2026

Taken By:
Jason Gomez

Description:
Identification Plate
for V-Cone 14" 24-
1419.



Photo: 22

Date Taken:
01/28/2026

Taken By:
Jason Gomez

Description:
Overview of
damage to the V-
Cone 14" 24-1419.

Claim Photo

Our File Number: 277-066336
Adjuster: Jason Gomez
Insured: Anderson Trucking Service
Date of Loss:
Customer File Number: 2026-01-000103
Policy Number:



Photo: 23

Date Taken:
01/28/2026

Taken By:
Jason Gomez

Description:
Overview of
damage to the V-
Cone 14" 24-1419.



Photo: 24

Date Taken:
01/28/2026

Taken By:
Jason Gomez

Description:
Overview of
damage to the V-
Cone 14" 24-1419.

Claim Photo

Our File Number: 277-066336
Adjuster: Jason Gomez
Insured: Anderson Trucking Service
Date of Loss:
Customer File Number: 2026-01-000103
Policy Number:



Photo: 25

Date Taken:
01/28/2026

Taken By:
Jason Gomez

Description:
Overview of
damage to the V-
Cone 14" 24-1419.



Photo: 26

Date Taken:
01/28/2026

Taken By:
Jason Gomez

Description:
Overview of
damage to the V-
Cone 14" 24-1419.

Claim Photo

Our File Number: 277-066336
Adjuster: Jason Gomez
Insured: Anderson Trucking Service
Date of Loss:
Customer File Number: 2026-01-000103
Policy Number:



Photo: 27

Date Taken:
01/28/2026

Taken By:
Jason Gomez

Description:
Overview of
damage to the V-
Cone 14" 24-1419.



Photo: 28

Date Taken:
01/28/2026

Taken By:
Jason Gomez

Description:
Overview of
damage to the V-
Cone 14" 24-1419.

Claim Photo

Our File Number: 277-066336
Adjuster: Jason Gomez
Insured: Anderson Trucking Service
Date of Loss:
Customer File Number: 2026-01-000103
Policy Number:



Photo: 29

Date Taken:
01/28/2026

Taken By:
Jason Gomez

Description:
Overview of
damage to the V-
Cone 14" 24-1419.



Photo: 30

Date Taken:
01/28/2026

Taken By:
Jason Gomez

Description:
Overview of
damage to the V-
Cone 14" 24-1419.

Claim Photo

Our File Number: 277-066336

Adjuster: Jason Gomez

Insured: Anderson Trucking Service

Date of Loss:

Customer File Number: 2026-01-000103

Policy Number:

cia
CUSTARD
INSURANCE ADJUSTERS




Photo: 31

Date Taken:
01/28/2026

Taken By:
Jason Gomez

Description:
Overview of
damage to the V-
Cone 14" 24-1419.



Photo: 32

Date Taken:
01/28/2026

Taken By:
Jason Gomez

Description:
Overview of
damage to the V-
Cone 14" 24-1419.

Claim Photo

Our File Number: 277-066336
Adjuster: Jason Gomez
Insured: Anderson Trucking Service
Date of Loss:
Customer File Number: 2026-01-000103
Policy Number:



Photo: 33

Date Taken:
01/28/2026

Taken By:
Jason Gomez

Description:
Overview of
damage to the V-
Cone 14" 24-1419.



Photo: 34

Date Taken:
01/28/2026

Taken By:
Jason Gomez

Description:
After the
completion of the
joint inspection, all
cargo was left in
the yard. E-Z
Towing staff
informed us that all
cargo will be
moved indoors for
storage.