

Photo Sheet



Iron Insurance Adjusters
7600 Crescent Lake Ct.
Fort Worth TX 76137
8177794970
Claims@ironadjusters.com

INSURED & INSPECTION ADDRESS

American Landscaping Partners, LLC
101 Progress Lane
Canonsburg, PA 15317

Project/Claim: Iron Adjusters File Number: 25-00248 | Claim Number: 714108
Date of Origin: 12/02/2025
Type of Inspection: Heavy Equipment

2018 PUSH-N-PULL Western Snow
Plow | SN: 18091910089385900

Date taken: 12/16/2025

Taken by: Garrett Cox

Front View



2018 PUSH-N-PULL Western Snow
Plow | SN: 18091910089385900

Date taken: 12/16/2025

Taken by: Garrett Cox

Front View



Photo Sheet

Iron Insurance Adjusters

7600 Crescent Lake Ct.

Fort Worth TX 76137

8177794970

Claims@ironadjusters.com



INSURED & INSPECTION ADDRESS

American Landscaping Partners, LLC

101 Progress Lane

Canonsburg, PA 15317

Project/Claim: Iron Adjusters File Number: 25-00248 | Claim Number: 714108

Date of Origin: 12/02/2025

Type of Inspection: Heavy Equipment

2018 PUSH-N-PULL Western Snow
Plow | SN: 18091910089385900

Date taken: 12/16/2025

Taken by: Garrett Cox

Front Left Corner



2018 PUSH-N-PULL Western Snow
Plow | SN: 18091910089385900

Date taken: 12/16/2025

Taken by: Garrett Cox

Left Side View



Photo Sheet

Iron Insurance Adjusters

7600 Crescent Lake Ct.

Fort Worth TX 76137

8177794970

Claims@ironadjusters.com



INSURED & INSPECTION ADDRESS

American Landscaping Partners, LLC

101 Progress Lane

Canonsburg, PA 15317

Project/Claim: Iron Adjusters File Number: 25-00248 | Claim Number: 714108

Date of Origin: 12/02/2025

Type of Inspection: Heavy Equipment

2018 PUSH-N-PULL Western Snow
Plow | SN: 18091910089385900

Date taken: 12/16/2025

Taken by: Garrett Cox

Rear Left Corner



2018 PUSH-N-PULL Western Snow
Plow | SN: 18091910089385900

Date taken: 12/16/2025

Taken by: Garrett Cox

Rear View



Photo Sheet



Iron Insurance Adjusters
7600 Crescent Lake Ct.
Fort Worth TX 76137
8177794970
Claims@ironadjusters.com

INSURED & INSPECTION ADDRESS

American Landscaping Partners, LLC
101 Progress Lane
Canonsburg, PA 15317

Project/Claim: Iron Adjusters File Number: 25-00248 | Claim Number: 714108
Date of Origin: 12/02/2025
Type of Inspection: Heavy Equipment

2018 PUSH-N-PULL Western Snow
Plow | SN: 18091910089385900

Date taken: 12/16/2025

Taken by: Garrett Cox

Rear View



2018 PUSH-N-PULL Western Snow
Plow | SN: 18091910089385900

Date taken: 12/16/2025

Taken by: Garrett Cox

Right Side View



Photo Sheet



Iron Insurance Adjusters
7600 Crescent Lake Ct.
Fort Worth TX 76137
8177794970
Claims@ironadjusters.com

INSURED & INSPECTION ADDRESS
American Landscaping Partners, LLC
101 Progress Lane
Canonsburg, PA 15317
Project/Claim: Iron Adjusters File Number: 25-00248 | Claim Number: 714108
Date of Origin: 12/02/2025
Type of Inspection: Heavy Equipment

2018 PUSH-N-PULL Western Snow
Plow | SN: 18091910089385900

Date taken: 12/16/2025

Taken by: Garrett Cox

Front Right Corner



2018 PUSH-N-PULL Western Snow
Plow | SN: 18091910089385900

Date taken: 12/16/2025

Taken by: Garrett Cox

Front View



Photo Sheet

Iron Insurance Adjusters

7600 Crescent Lake Ct.

Fort Worth TX 76137

8177794970

Claims@ironadjusters.com



INSURED & INSPECTION ADDRESS

American Landscaping Partners, LLC

101 Progress Lane

Canonsburg, PA 15317

Project/Claim: Iron Adjusters File Number: 25-00248 | Claim Number: 714108

Date of Origin: 12/02/2025

Type of Inspection: Heavy Equipment

2018 PUSH-N-PULL Western Snow
Plow | SN: 18091910089385900

Date taken: 12/16/2025

Taken by: Garrett Cox

Serial Number Tag For Big Box

Assembly | S/N:

18091910089385900



2018 PUSH-N-PULL Western Snow
Plow | SN: 18091910089385900

Date taken: 12/16/2025

Taken by: Garrett Cox

Location Of S/N Tag




Photo Sheet



Iron Insurance Adjusters
7600 Crescent Lake Ct.
Fort Worth TX 76137
8177794970
Claims@ironadjusters.com

INSURED & INSPECTION ADDRESS

American Landscaping Partners, LLC
101 Progress Lane
Canonsburg, PA 15317

Project/Claim: Iron Adjusters File Number: 25-00248 | Claim Number: 714108
Date of Origin: 12/02/2025
Type of Inspection: Heavy Equipment

2018 PUSH-N-PULL Western Snow
Plow | SN: 18091910089385900

Date taken: 12/16/2025

Taken by: Garrett Cox

Plow Wide Out Blade Assembly
Serial Number Is Coming Off &
Can't Rear | S/N:
8110720840885810



2018 PUSH-N-PULL Western Snow
Plow | SN: 18091910089385900

Date taken: 12/16/2025

Taken by: Garrett Cox

Plow Information



Photo Sheet

Iron Insurance Adjusters

7600 Crescent Lake Ct.

Fort Worth TX 76137

8177794970

Claims@ironadjusters.com



INSURED & INSPECTION ADDRESS

American Landscaping Partners, LLC

101 Progress Lane

Canonsburg, PA 15317

Project/Claim: Iron Adjusters File Number: 25-00248 | Claim Number: 714108

Date of Origin: 12/02/2025

Type of Inspection: Heavy Equipment

2018 PUSH-N-PULL Western Snow
Plow | SN: 18091910089385900

Date taken: 12/16/2025

Taken by: Garrett Cox

Overview Of Damage



2018 PUSH-N-PULL Western Snow
Plow | SN: 18091910089385900

Date taken: 12/16/2025

Taken by: Garrett Cox

Overview Of Damaged Connection



Photo Sheet

Iron Insurance Adjusters

7600 Crescent Lake Ct.

Fort Worth TX 76137

8177794970

Claims@ironadjusters.com



INSURED & INSPECTION ADDRESS

American Landscaping Partners, LLC

101 Progress Lane

Canonsburg, PA 15317

Project/Claim: Iron Adjusters File Number: 25-00248 | Claim Number: 714108

Date of Origin: 12/02/2025

Type of Inspection: Heavy Equipment

2018 PUSH-N-PULL Western Snow
Plow | SN: 18091910089385900

Date taken: 12/16/2025

Taken by: Garrett Cox

Back Hookup & Connection Is
Damaged



2018 PUSH-N-PULL Western Snow
Plow | SN: 18091910089385900

Date taken: 12/16/2025

Taken by: Garrett Cox

Back Hookup & Connection Is
Damaged



Photo Sheet



Iron Insurance Adjusters
7600 Crescent Lake Ct.
Fort Worth TX 76137
8177794970
Claims@ironadjusters.com

INSURED & INSPECTION ADDRESS
American Landscaping Partners, LLC
101 Progress Lane
Canonsburg, PA 15317
Project/Claim: Iron Adjusters File Number: 25-00248 | Claim Number: 714108
Date of Origin: 12/02/2025
Type of Inspection: Heavy Equipment

2018 PUSH-N-PULL Western Snow
Plow | SN: 18091910089385900

Date taken: 12/16/2025

Taken by: Garrett Cox

Back Hookup & Connection Is
Damaged



2018 PUSH-N-PULL Western Snow
Plow | SN: 18091910089385900

Date taken: 12/16/2025

Taken by: Garrett Cox

Back Hookup & Connection Is
Damaged




Photo Sheet

Iron Insurance Adjusters

7600 Crescent Lake Ct.

Fort Worth TX 76137

8177794970

Claims@ironadjusters.com



INSURED & INSPECTION ADDRESS

American Landscaping Partners, LLC

101 Progress Lane

Canonsburg, PA 15317

Project/Claim: Iron Adjusters File Number: 25-00248 | Claim Number: 714108

Date of Origin: 12/02/2025

Type of Inspection: Heavy Equipment

2018 PUSH-N-PULL Western Snow
Plow | SN: 18091910089385900

Date taken: 12/16/2025

Taken by: Garrett Cox

Back Hookup & Connection Is
Damaged



2018 PUSH-N-PULL Western Snow
Plow | SN: 18091910089385900

Date taken: 12/16/2025

Taken by: Garrett Cox

Back Hookup & Connection Is
Damaged



Photo Sheet

Iron Insurance Adjusters

7600 Crescent Lake Ct.

Fort Worth TX 76137

8177794970

Claims@ironadjusters.com



INSURED & INSPECTION ADDRESS

American Landscaping Partners, LLC

101 Progress Lane

Canonsburg, PA 15317

Project/Claim: Iron Adjusters File Number: 25-00248 | Claim Number: 714108

Date of Origin: 12/02/2025

Type of Inspection: Heavy Equipment

2018 PUSH-N-PULL Western Snow
Plow | SN: 18091910089385900

Date taken: 12/16/2025

Taken by: Garrett Cox

Hookup Is Bent



2018 PUSH-N-PULL Western Snow
Plow | SN: 18091910089385900

Date taken: 12/16/2025

Taken by: Garrett Cox

Overview Before Cleaning Snow Off



Photo Sheet



Iron Insurance Adjusters
7600 Crescent Lake Ct.
Fort Worth TX 76137
8177794970
Claims@ironadjusters.com

INSURED & INSPECTION ADDRESS

American Landscaping Partners, LLC
101 Progress Lane
Canonsburg, PA 15317

Project/Claim: Iron Adjusters File Number: 25-00248 | Claim Number: 714108
Date of Origin: 12/02/2025
Type of Inspection: Heavy Equipment

2018 PUSH-N-PULL Western Snow
Plow | SN: 18091910089385900

Date taken: 12/16/2025

Taken by: Garrett Cox

Back Hookup & Connection Is
Damaged



2018 PUSH-N-PULL Western Snow
Plow | SN: 18091910089385900

Date taken: 12/16/2025

Taken by: Garrett Cox

Back Hookup & Connection Is
Damaged



Photo Sheet



Iron Insurance Adjusters
7600 Crescent Lake Ct.
Fort Worth TX 76137
8177794970
Claims@ironadjusters.com

INSURED & INSPECTION ADDRESS

American Landscaping Partners, LLC
101 Progress Lane
Canonsburg, PA 15317

Project/Claim: Iron Adjusters File Number: 25-00248 | Claim Number: 714108
Date of Origin: 12/02/2025
Type of Inspection: Heavy Equipment

2018 PUSH-N-PULL Western Snow
Plow | SN: 18091910089385900

Date taken: 12/16/2025

Taken by: Garrett Cox

Back Hookup & Connection Is
Damaged



2018 PUSH-N-PULL Western Snow
Plow | SN: 18091910089385900

Date taken: 12/16/2025

Taken by: Garrett Cox

Showing Bent Hookup In The Back




Photo Sheet



Iron Insurance Adjusters
7600 Crescent Lake Ct.
Fort Worth TX 76137
8177794970
Claims@ironadjusters.com

INSURED & INSPECTION ADDRESS
American Landscaping Partners, LLC
101 Progress Lane
Canonsburg, PA 15317
Project/Claim: Iron Adjusters File Number: 25-00248 | Claim Number: 714108
Date of Origin: 12/02/2025
Type of Inspection: Heavy Equipment

2018 PUSH-N-PULL Western Snow Plow | SN: 18091910089385900

Date taken: 12/16/2025

Taken by: Garrett Cox

Showing Bent Hookup In The Back



2018 PUSH-N-PULL Western Snow Plow | SN: 18091910089385900

Date taken: 12/16/2025

Taken by: Garrett Cox

This Is NOT The Damaged Plow -
Showing What An Undamaged
Plow Looks Like



Photo Sheet



Iron Insurance Adjusters
7600 Crescent Lake Ct.
Fort Worth TX 76137
8177794970
Claims@ironadjusters.com

INSURED & INSPECTION ADDRESS

American Landscaping Partners, LLC
101 Progress Lane
Canonsburg, PA 15317

Project/Claim: Iron Adjusters File Number: 25-00248 | Claim Number: 714108
Date of Origin: 12/02/2025
Type of Inspection: Heavy Equipment

2018 PUSH-N-PULL Western Snow
Plow | SN: 18091910089385900

Date taken: 12/03/2025

Taken by: Garrett Cox

Photo Provided By The Insured



2018 PUSH-N-PULL Western Snow
Plow | SN: 18091910089385900

Date taken: 12/03/2025

Taken by: Garrett Cox

Photo Provided By The Insured



Photo Sheet

Iron Insurance Adjusters

7600 Crescent Lake Ct.

Fort Worth TX 76137

8177794970

Claims@ironadjusters.com



INSURED & INSPECTION ADDRESS

American Landscaping Partners, LLC

101 Progress Lane

Canonsburg, PA 15317

Project/Claim: Iron Adjusters File Number: 25-00248 | Claim Number: 714108

Date of Origin: 12/02/2025

Type of Inspection: Heavy Equipment

2018 PUSH-N-PULL Western Snow
Plow | SN: 18091910089385900

Date taken: 12/03/2025

Taken by: Garrett Cox

Photo Provided By The Insured



2018 PUSH-N-PULL Western Snow
Plow | SN: 18091910089385900

Date taken: 12/03/2025

Taken by: Garrett Cox

Photo Provided By The Insured



Photo Sheet



Iron Insurance Adjusters
7600 Crescent Lake Ct.
Fort Worth TX 76137
8177794970
Claims@ironadjusters.com

INSURED & INSPECTION ADDRESS

American Landscaping Partners, LLC
101 Progress Lane
Canonsburg, PA 15317

Project/Claim: Iron Adjusters File Number: 25-00248 | Claim Number: 714108
Date of Origin: 12/02/2025
Type of Inspection: Heavy Equipment

2018 PUSH-N-PULL Western Snow
Plow | SN: 18091910089385900

Date taken: 12/03/2025

Taken by: Garrett Cox

Photo Provided By The Insured



2018 PUSH-N-PULL Western Snow
Plow | SN: 18091910089385900

Date taken: 12/11/2025

Taken by: Garrett Cox

Photo Provided By The Insured



Photo Sheet



Iron Insurance Adjusters
7600 Crescent Lake Ct.
Fort Worth TX 76137
8177794970
Claims@ironadjusters.com

INSURED & INSPECTION ADDRESS

American Landscaping Partners, LLC
101 Progress Lane
Canonsburg, PA 15317

Project/Claim: Iron Adjusters File Number: 25-00248 | Claim Number: 714108
Date of Origin: 12/02/2025
Type of Inspection: Heavy Equipment

2018 PUSH-N-PULL Western Snow
Plow | SN: 18091910089385900

Date taken: 12/03/2025

Taken by: Garrett Cox

Photo Provided By The Insured



2018 PUSH-N-PULL Western Snow
Plow | SN: 18091910089385900

Date taken: 12/16/2025

Taken by: Garrett Cox

Photo Provided By The Insured

