

Attachments:

60410.jpg; 200_33+24309_riverside_drive_channahon_il_60410.jpg; 200_34+24309_riverside_drive_channahon_il_60410.jpg; 200_35+24309_riverside_drive_channahon_il_60410.jpg; 200_36+24309_riverside_drive_channahon_il_60410.jpg; 200_37+24309_riverside_drive_channahon_il_60410.jpg; 200_38+24309_riverside_drive_channahon_il_60410.jpg; 200_39+24309_riverside_drive_channahon_il_60410.jpg; 200_40+24309_riverside_drive_channahon_il_60410.jpg; 200_41+24309_riverside_drive_channahon_il_60410.jpg; 200_42+24309_riverside_drive_channahon_il_60410.jpg; 200_43+24309_riverside_drive_channahon_il_60410.jpg; 200_44+24309_riverside_drive_channahon_il_60410.jpg; 200_45+24309_riverside_drive_channahon_il_60410.jpg; 200_46+24309_riverside_drive_channahon_il_60410.jpg; 200_47+24309_riverside_drive_channahon_il_60410.jpg; 200_48+24309_riverside_drive_channahon_il_60410.jpg; 200_49+24309_riverside_drive_channahon_il_60410.jpg; 200_50+24309_riverside_drive_channahon_il_60410.jpg; 200_51+24309_riverside_drive_channahon_il_60410.jpg; 200_52+24309_riverside_drive_channahon_il_60410.jpg; 200_53+24309_riverside_drive_channahon_il_60410.jpg; 200_54+24309_riverside_drive_channahon_il_60410.jpg; 200_55+24309_riverside_drive_channahon_il_60410.jpg; Photo Inspection Report-CHI25119030.pdf

Good afternoon Caroline,

We have inspected the above captioned tractor and forwarding pdf and mounting of photos. Due to the extent of the damage and possible additional, I am going to run an VVSI for ACV and solicit salvage bids to verify value over repairs.

Please diary your file for an additional 5 days for further reporting.

Best,

Nancy

Nancy Greenidge – Executive General Adjuster AIC CELL 503-577-8541 | EMAIL : Nancy.Greenidge@Sedgwick.com

Executive Administrative Assistant – Heather Reddell CELL 479.212.6872 | EMAIL : Heather.Reddell@Sedgwick.com
www.sedgwick.com | Caring counts®