Our File Number: 277-065360 Adjuster: Jason Baka

Insured: AFFINITY INSURANCE, LTD.

Date of Loss: 07/10/2025

Customer File Number: 001960-268840-AD-01

Policy Number:

12/30/2025 10:47:27 AM *





Photo: 1

12/18/2025

Taken By:

Kevin Thomas

Description: Claimant vehicle.

VIN label.

Date Taken:

Photo: 2

Date Taken:

12/18/2025

Taken By:

Kevin Thomas

Description:

Claimant vehicle. VIN label.



Our File Number: 277-065360 Adjuster: Jason Baka

Insured: AFFINITY INSURANCE, LTD.

Date of Loss: 07/10/2025

Customer File Number: 001960-268840-AD-01

Policy Number:





Photo: 3

Date Taken: 12/18/2025

Taken By: Kevin Thomas

Description: Claimant vehicle. Front left corner.



Photo: 4

Date Taken: 12/18/2025

Taken By:Kevin Thomas

Description: Claimant vehicle. Front right corner.

Our File Number: 277-065360 Adjuster: Jason Baka

Insured: AFFINITY INSURANCE, LTD.

Date of Loss: 07/10/2025

Customer File Number: 001960-268840-AD-01

Policy Number:





Photo: 5

Date Taken: 12/18/2025

Taken By: Kevin Thomas

Description:Claimant vehicle.
Rear right corner.



Photo: 6

Date Taken: 12/18/2025

Taken By:Kevin Thomas

Description: Claimant vehicle. Rear left corner.

Our File Number: 277-065360 Adjuster: Jason Baka

Insured: AFFINITY INSURANCE, LTD.

Date of Loss: 07/10/2025

Customer File Number: 001960-268840-AD-01

Policy Number:





Photo: 7

Date Taken: 12/18/2025

Taken By: Kevin Thomas

Description:Claimant vehicle.
Registration plate.



Photo: 8

Date Taken:

12/18/2025

Taken By: Kevin Thomas

Our File Number: 277-065360 Adjuster: Jason Baka

Insured: AFFINITY INSURANCE, LTD.

Date of Loss: 07/10/2025

Customer File Number: 001960-268840-AD-01

Policy Number:





Photo: 9

Date Taken: 12/18/2025

Taken By: Kevin Thomas

Description:Claimant vehicle.
DAMAGE AREA.



Photo: 10

Date Taken:

12/18/2025

Taken By:

Kevin Thomas

Our File Number: 277-065360 Adjuster: Jason Baka

Insured: AFFINITY INSURANCE, LTD.

Date of Loss: 07/10/2025

Customer File Number: 001960-268840-AD-01

Policy Number:





Photo: 11

Date Taken: 12/18/2025

Taken By: Kevin Thomas

Description:Claimant vehicle.
DAMAGE AREA.



Photo: 12

Date Taken:

12/18/2025

Taken By:

Kevin Thomas

Our File Number: 277-065360 Adjuster: Jason Baka

Insured: AFFINITY INSURANCE, LTD.

Date of Loss: 07/10/2025

Customer File Number: 001960-268840-AD-01

Policy Number:





Photo: 13

Date Taken: 12/18/2025

Taken By: Kevin Thomas

Description: Claimant vehicle.
DAMAGE AREA.



Photo: 14

Date Taken:

12/18/2025

Taken By:

Kevin Thomas

Our File Number: 277-065360 Adjuster: Jason Baka

Insured: AFFINITY INSURANCE, LTD.

Date of Loss: 07/10/2025

Customer File Number: 001960-268840-AD-01

Policy Number:





Photo: 15

Date Taken: 12/18/2025

Taken By: Kevin Thomas

Description:Claimant vehicle.
DAMAGE AREA.



Photo: 16

Date Taken:

12/18/2025

Taken By:

Kevin Thomas

Our File Number: 277-065360 Adjuster: Jason Baka

Insured: AFFINITY INSURANCE, LTD.

Date of Loss: 07/10/2025

Customer File Number: 001960-268840-AD-01

Policy Number:





Photo: 17

Date Taken: 12/18/2025

Taken By: Kevin Thomas

Description: Claimant vehicle.
DAMAGE AREA.




Photo: 18

Date Taken:

12/18/2025

Taken By:

Kevin Thomas

Description: Inadvertent photo

Our File Number: 277-065360 Adjuster: Jason Baka

Insured: AFFINITY INSURANCE, LTD.

Date of Loss: 07/10/2025

Customer File Number: 001960-268840-AD-01

Policy Number:





Photo: 19

Date Taken: 12/18/2025

Taken By: Kevin Thomas

Description: Claimant vehicle. DAMAGE AREA. Undercarriage rear looking forward.



Photo: 20

Date Taken: 12/18/2025

Taken By: Kevin Thomas

Description:Claimant vehicle.
DAMAGE AREA.

DAMAGE AREA. Undercarriage between wheels looking rearward.

Our File Number: 277-065360 Adjuster: Jason Baka

Insured: AFFINITY INSURANCE, LTD.

Date of Loss: 07/10/2025

Customer File Number: 001960-268840-AD-01

Policy Number:





Photo: 21

Date Taken: 12/18/2025

Taken By: Kevin Thomas

Description: Claimant vehicle.
DAMAGE AREA. Undercarriage between wheels looking forward.



Photo: 22

Date Taken: 12/18/2025

Taken By: Kevin Thomas

Description:Claimant vehicle.
DAMAGE AREA. Undercarriage in front of wheels looking rearward.