

Claim Photo

Our File Number: 277-066759
Adjuster: David Crans
Insured: CHURCHILL CASUALTY LTD
Date of Loss: 01/29/2026
Customer File Number: 000696-284439-AD-01
Policy Number:



Photo: 1
Date Taken: 02/03/2026
Taken By: Keith Shipley
Description:
Vin
1GDJG31K491107
055




Photo: 2
Date Taken: 02/03/2026
Taken By: Keith Shipley
Description:
Vin
1GDJG31K491107
055

Claim Photo

Our File Number: 277-066759
Adjuster: David Crans
Insured: CHURCHILL CASUALTY LTD
Date of Loss: 01/29/2026
Customer File Number: 000696-284439-AD-01
Policy Number:



Photo: 3
Date Taken: 02/03/2026
Taken By: Keith Shipley
Description: Mileage 374160. Claimant states major mechanical work completed recently



Photo: 4
Date Taken: 02/03/2026
Taken By: Keith Shipley
Description: Front - driver corner view. Note metal bolt in bumper. Bumper damaged from accident

Claim Photo

Our File Number: 277-066759
Adjuster: David Crans
Insured: CHURCHILL CASUALTY LTD
Date of Loss: 01/29/2026
Customer File Number: 000696-284439-AD-01
Policy Number:



Photo: 5

Date Taken:
02/03/2026

Taken By:
Keith Shipley

Description:
Front - passenger view. Note bolt in bumper. Bumper caved in as struck a cemented post due to accident causing buckling to front cab framing to buckle



Photo: 6

Date Taken:
02/03/2026

Taken By:
Keith Shipley

Description:
Passenger side view. No visible or reported damage to this exterior. Frame at cab end metal tie loosened

Claim Photo

Our File Number: 277-066759
Adjuster: David Crans
Insured: CHURCHILL CASUALTY LTD
Date of Loss: 01/29/2026
Customer File Number: 000696-284439-AD-01
Policy Number:



Photo: 7
Date Taken: 02/03/2026
Taken By: Keith Shipley
Description: Driver side front tire tread



Photo: 8
Date Taken: 02/03/2026
Taken By: Keith Shipley
Description: Drivers side rear wheels tread

Claim Photo

Our File Number: 277-066759
Adjuster: David Crans
Insured: CHURCHILL CASUALTY LTD
Date of Loss: 01/29/2026
Customer File Number: 000696-284439-AD-01
Policy Number:



Photo: 9
Date Taken: 02/03/2026
Taken By: Keith Shipley
Description: Drivers side outer rear wheel tread same as inner wheel



Photo: 10
Date Taken: 02/03/2026
Taken By: Keith Shipley
Description: Drivers side rear. No reported damage to exterior box. Gas fill cap area had gas leak at time of accident

Claim Photo

Our File Number: 277-066759
Adjuster: David Crans
Insured: CHURCHILL CASUALTY LTD
Date of Loss: 01/29/2026
Customer File Number: 000696-284439-AD-01
Policy Number:



Photo: 11
Date Taken: 02/03/2026
Taken By: Keith Shipley
Description: Passenger side view. Next photo is front tire tread



Photo: 12
Date Taken: 02/03/2026
Taken By: Keith Shipley
Description: Front passenger tire tread depth

Claim Photo

Our File Number: 277-066759
Adjuster: David Crans
Insured: CHURCHILL CASUALTY LTD
Date of Loss: 01/29/2026
Customer File Number: 000696-284439-AD-01
Policy Number:



Photo: 13
Date Taken: 02/03/2026
Taken By: Keith Shipley
Description: Passenger side view



Photo: 14
Date Taken: 02/03/2026
Taken By: Keith Shipley
Description: Rear wheel passenger tire tread depth next view

Claim Photo

Our File Number: 277-066759
Adjuster: David Crans
Insured: CHURCHILL CASUALTY LTD
Date of Loss: 01/29/2026
Customer File Number: 000696-284439-AD-01
Policy Number:



Photo: 15

Date Taken:
02/03/2026

Taken By:
Keith Shipley

Description:
Rear passenger tire
tread typical both
tires



Photo: 16

Date Taken:
02/03/2026

Taken By:
Keith Shipley

Description:
Rear passenger side
corner view. Truck
struck from rear

Claim Photo

Our File Number: 277-066759
Adjuster: David Crans
Insured: CHURCHILL CASUALTY LTD
Date of Loss: 01/29/2026
Customer File Number: 000696-284439-AD-01
Policy Number:



Photo: 17

Date Taken:
02/03/2026

Taken By:
Keith Shipley

Description:
Rear view.
Bumper, bed frame
and doors damaged
from impact



Photo: 18

Date Taken:
02/03/2026

Taken By:
Keith Shipley

Description:
Rear view.
Bumper, framing
and doors damaged
from impact

Claim Photo

Our File Number: 277-066759
Adjuster: David Crans
Insured: CHURCHILL CASUALTY LTD
Date of Loss: 01/29/2026
Customer File Number: 000696-284439-AD-01
Policy Number:



Photo: 19

Date Taken:
02/03/2026

Taken By:
Keith Shipley

Description:
Rear Bumper frame
and door damage.
SC 508812



Photo: 20

Date Taken:
02/03/2026

Taken By:
Keith Shipley

Description:
Rear driver side
view

Claim Photo

Our File Number: 277-066759
Adjuster: David Crans
Insured: CHURCHILL CASUALTY LTD
Date of Loss: 01/29/2026
Customer File Number: 000696-284439-AD-01
Policy Number:



Photo: 21

Date Taken:
02/03/2026

Taken By:
Keith Shipley

Description:
Metal tube frame
pushed in, bumper
detached and doors
directly hit



Photo: 22

Date Taken:
02/03/2026

Taken By:
Keith Shipley

Description:
Note door damage.
Claimant states
new doors. Frame
below pushed in

Claim Photo

Our File Number: 277-066759
Adjuster: David Crans
Insured: CHURCHILL CASUALTY LTD
Date of Loss: 01/29/2026
Customer File Number: 000696-284439-AD-01
Policy Number:



Photo: 23

Date Taken:
02/03/2026

Taken By:
Keith Shipley

Description:
Passenger side cab
pushed in to box.
Gap at top and
flush at bottom



Photo: 24

Date Taken:
02/03/2026

Taken By:
Keith Shipley

Description:
Passenger side gap
at top cab to box

Claim Photo

Our File Number: 277-066759
Adjuster: David Crans
Insured: CHURCHILL CASUALTY LTD
Date of Loss: 01/29/2026
Customer File Number: 000696-284439-AD-01
Policy Number:



Photo: 25

Date Taken:
02/03/2026

Taken By:
Keith Shipley

Description:
Close up front bumper. Fence gate through bolt embedded in front bumper. Possible frame damage front end



Photo: 26

Date Taken:
02/03/2026

Taken By:
Keith Shipley

Description:
Possible buckle at top of box passenger side

Claim Photo

Our File Number: 277-066759
Adjuster: David Crans
Insured: CHURCHILL CASUALTY LTD
Date of Loss: 01/29/2026
Customer File Number: 000696-284439-AD-01
Policy Number:



Photo: 27

Date Taken:
02/03/2026

Taken By:
Keith Shipley

Description:
Roof top reference
previous photo



Photo: 28

Date Taken:
02/03/2026

Taken By:
Keith Shipley

Description:
Interior box at /
below previous
photo. Passenger
side front box roof

Claim Photo

Our File Number: 277-066759
Adjuster: David Crans
Insured: CHURCHILL CASUALTY LTD
Date of Loss: 01/29/2026
Customer File Number: 000696-284439-AD-01
Policy Number:



Photo: 29

Date Taken:
02/03/2026

Taken By:
Keith Shipley

Description:
Interior box



Photo: 30

Date Taken:
02/03/2026

Taken By:
Keith Shipley

Description:
Interior rear box
doors damaged
from impact as per
claimant

Claim Photo

Our File Number: 277-066759
Adjuster: David Crans
Insured: CHURCHILL CASUALTY LTD
Date of Loss: 01/29/2026
Customer File Number: 000696-284439-AD-01
Policy Number:



Photo: 31

Date Taken:
02/03/2026

Taken By:
Keith Shipley

Description:
Box interior rear



Photo: 32

Date Taken:
02/03/2026

Taken By:
Keith Shipley

Description:
Driver side rear.
Gas leaked at time
of accident this area

Claim Photo

Our File Number: 277-066759
Adjuster: David Crans
Insured: CHURCHILL CASUALTY LTD
Date of Loss: 01/29/2026
Customer File Number: 000696-284439-AD-01
Policy Number:



Photo: 33
Date Taken: 02/03/2026
Taken By: Keith Shipley
Description: Under frame previous photo. Gas tube intact. Metal tie from truck frame to box is loose



Photo: 34
Date Taken: 02/03/2026
Taken By: Keith Shipley
Description: Same as previous photo

Claim Photo

Our File Number: 277-066759
Adjuster: David Crans
Insured: CHURCHILL CASUALTY LTD
Date of Loss: 01/29/2026
Customer File Number: 000696-284439-AD-01
Policy Number:



Photo: 35

Date Taken:
02/03/2026

Taken By:
Keith Shipley

Description:
Frame under at rear driver side



Photo: 36

Date Taken:
02/03/2026

Taken By:
Keith Shipley

Description:
Under rear drivers side

Claim Photo

Our File Number: 277-066759
Adjuster: David Crans
Insured: CHURCHILL CASUALTY LTD
Date of Loss: 01/29/2026
Customer File Number: 000696-284439-AD-01
Policy Number:



Photo: 37
Date Taken: 02/03/2026
Taken By: Keith Shipley
Description: Tax receipt in lieu of Registration. Claimant looking for registration



Photo: 38
Date Taken: 02/03/2026
Taken By: Keith Shipley
Description: Passenger side front U bracket tying box frame to chassis frame loose

Claim Photo

Our File Number: 277-066759
Adjuster: David Crans
Insured: CHURCHILL CASUALTY LTD
Date of Loss: 01/29/2026
Customer File Number: 000696-284439-AD-01
Policy Number:



Photo: 39
Date Taken: 02/04/2026
Taken By: Keith Shipley
Description: Registration