

## Claim Photo

Our File Number:


Adjuster:

Insured:

Date of Loss:

Customer File Number:

Policy Number:




**Photo: 1**

**Date Taken:**  
12/15/2025

**Taken By:**  
Maria Hill-Dudley

**Description:**  
Insured vehicle's  
front.



**Photo: 2**

**Date Taken:**  
12/15/2025

**Taken By:**  
Maria Hill-Dudley

**Description:**  
Insured vehicle's  
passenger side.

## Claim Photo

Our File Number:


Adjuster:

Insured:

Date of Loss:

Customer File Number:

Policy Number:



**Photo: 3**

**Date Taken:**  
12/15/2025

**Taken By:**  
Maria Hill-Dudley

**Description:**  
Insured vehicle's  
driver side.



**Photo: 4**

**Date Taken:**  
12/15/2025

**Taken By:**  
Maria Hill-Dudley

**Description:**  
Insured trailer's  
rear.



## Claim Photo

Our File Number:


Adjuster:

Insured:

Date of Loss:

Customer File Number:

Policy Number:



**Photo: 5**

**Date Taken:**  
12/15/2025

**Taken By:**  
Maria Hill-Dudley

**Description:**  
Photograph of the  
insured trailer's  
seal.



**Photo: 6**

**Date Taken:**  
12/15/2025

**Taken By:**  
Maria Hill-Dudley

**Description:**  
Photograph of the  
insured trailer's  
seal.

## Claim Photo

Our File Number:

Adjuster:

Insured:

Date of Loss:

Customer File Number:

Policy Number:



**Photo: 7**

**Date Taken:**  
12/15/2025

**Taken By:**  
Maria Hill-Dudley

**Description:**  
Photograph of the  
insured trailer's  
seal.



**Photo: 8**

**Date Taken:**  
12/15/2025

**Taken By:**  
Maria Hull-Dudley

**Description:**  
Photograph of the  
insured trailer's  
license plate



## Claim Photo

Our File Number:

Adjuster:

Insured:

Date of Loss:

Customer File Number:

Policy Number:



**Photo: 9**

**Date Taken:**  
12/15/2025

**Taken By:**  
Maria Hill-Dudley

**Description:**  
Photograph of the  
insured tractors  
USDOT.#




**Photo: 10**

**Date Taken:**  
12/15/2025

**Taken By:**  
Maria Hill-Dudley

**Description:**  
Photograph of the  
insured tractor's  
VIN.

Claim Photo  
Our File Number:  
Adjuster:  
Insured:  
Date of Loss:  
Customer File Number:  
Policy Number:



**Photo: 11**  
**Date Taken:**  
12/15/2025  
**Taken By:**  
Maria Hill-Dudley  
**Description:**  
Photograph of the insured tractor's VIN.



**Photo: 12**  
**Date Taken:**  
12/15/2025  
**Taken By:**  
Maria Hill-Dudley  
**Description:**  
Photograph of the insured tractor's VIN.



## Claim Photo

Our File Number:


Adjuster:

Insured:

Date of Loss:

Customer File Number:

Policy Number:



**Photo: 13**

**Date Taken:**  
12/15/2025

**Taken By:**  
Maria Hill-Dudley

**Description:**  
Photograph of the  
insured tractor's  
interior.



**Photo: 14**

**Date Taken:**  
12/15/2025

**Taken By:**  
Maria Hill-Dudley

**Description:**  
Photograph of the  
insured tractor's  
windshield.

## Claim Photo

Our File Number:


Adjuster:

Insured:

Date of Loss:

Customer File Number:

Policy Number:



**Photo: 15**

**Date Taken:**  
12/15/2025

**Taken By:**  
Maria Hill-Dudley

**Description:**  
Photograph of the  
insured tractor's  
interior.



**Photo: 16**

**Date Taken:**  
12/15/2025

**Taken By:**  
Maria Hill-Dudley

**Description:**  
Photograph of the  
insured tractor's  
interior rear cabin.



**Claim Photo**

**Our File Number:**  
**Adjuster:**  
**Insured:**  
**Date of Loss:**  
**Customer File Number:**  
**Policy Number:**



**Photo: 17**

**Date Taken:**  
12/15/2025

**Taken By:**  
Maria Hill-Dudley

**Description:**  
Photograph of the insured tractor's interior rear cabin.



**Photo: 18**

**Date Taken:**  
12/15/2025

**Taken By:**  
Maria Hill-Dudley

**Description:**  
Photograph of the insured tractor's windshield.

## Claim Photo

Our File Number:

Adjuster:

Insured:

Date of Loss:

Customer File Number:

Policy Number:



**Photo: 19**

**Date Taken:**  
12/15/2025

**Taken By:**  
Maria Hill-Dudley

**Description:**  
Photograph of the insured tractor's interior passenger side window.



**Photo: 20**

**Date Taken:**  
12/15/2025

**Taken By:**  
Maria Hill-Dudley

**Description:**  
Photograph of the insured tractor's windshield.



## Claim Photo

Our File Number:

Adjuster:

Insured:

Date of Loss:

Customer File Number:

Policy Number:




**Photo: 21**

**Date Taken:**  
12/15/2025

**Taken By:**  
Maria Hill-Dudley

**Description:**  
Photograph of the  
insured tractor's  
odometer.



**Photo: 22**

**Date Taken:**  
12/15/2025

**Taken By:**  
Maria Hill-Dudley

**Description:**  
Photograph of the  
insured tractor's  
windshield.

## Claim Photo

Our File Number:

Adjuster:

Insured:

Date of Loss:

Customer File Number:

Policy Number:



**Photo: 23**

**Date Taken:**  
12/15/2025

**Taken By:**  
Maria Hill-Dudley

**Description:**  
Photograph of the insured tractor's interior driver's side.



**Photo: 24**

**Date Taken:**  
12/15/2025

**Taken By:**  
Maria Hill-Dudley

**Description:**  
Photograph of the insured tractor's windshield.



## Claim Photo

Our File Number:

Adjuster:

Insured:

Date of Loss:

Customer File Number:

Policy Number:




**Photo: 25**

**Date Taken:**  
12/15/2025

**Taken By:**  
Maria Hill-Dudley

**Description:**  
Photograph of the insured tractor's passenger side.



**Photo: 26**

**Date Taken:**  
12/15/2025

**Taken By:**  
Maria Hill-Dudley

**Description:**  
Photograph of the insured tractor's windshield.

Claim Photo

Our File Number:  
Adjuster:  
Insured:  
Date of Loss:  
Customer File Number:  
Policy Number:




**Photo: 27**

**Date Taken:**  
12/15/2025

**Taken By:**  
Maria Hill-Dudley

**Description:**  
Photograph of the insured tractor's windshield.



**Photo: 28**

**Date Taken:**  
12/15/2025

**Taken By:**  
Maria Hill-Dudley

**Description:**  
Photograph of the insured trailer's passenger side.



## Claim Photo

Our File Number:

Adjuster:

Insured:

Date of Loss:

Customer File Number:

Policy Number:




**Photo: 29**

**Date Taken:**  
12/15/2025

**Taken By:**  
Maria Hill-Dudley

**Description:**  
Photograph of the  
insured vehicle's  
passenger side.



**Photo: 30**

**Date Taken:**  
12/15/2025

**Taken By:**  
Maria Hill-Dudley

**Description:**  
Photograph of the  
insured vehicle's  
passenger side.

## Claim Photo

Our File Number:


Adjuster:

Insured:

Date of Loss:

Customer File Number:

Policy Number:



**Photo: 31**

**Date Taken:**  
12/15/2025

**Taken By:**  
Maria Hill-Dudley

**Description:**  
Photograph of the insured vehicle's passenger side.



**Photo: 32**

**Date Taken:**  
12/15/2025

**Taken By:**  
Maria Hill-Dudley

**Description:**  
Photograph of the insured vehicle's passenger side.



## Claim Photo

Our File Number:


Adjuster:

Insured:

Date of Loss:

Customer File Number:

Policy Number:



**Photo: 33**

**Date Taken:**  
12/15/2025

**Taken By:**  
Maria Hill-Dudley

**Description:**  
Photograph of the insured vehicle's passenger side.



**Photo: 34**

**Date Taken:**  
12/15/2025

**Taken By:**  
Maria Hill-Dudley

**Description:**  
Photograph of the insured vehicle's passenger side.

## Claim Photo

Our File Number:

Adjuster:

Insured:

Date of Loss:

Customer File Number:

Policy Number:




**Photo: 35**

**Date Taken:**  
12/15/2025

**Taken By:**  
Maria Hill-Dudley

**Description:**  
Photograph of the  
insured vehicle's  
passenger side.



**Photo: 36**

**Date Taken:**  
12/15/2025

**Taken By:**  
Maria Hill-Dudley

**Description:**  
Photograph of the  
insured vehicle's  
passenger side.



## Claim Photo

Our File Number:

Adjuster:

Insured:

Date of Loss:

Customer File Number:

Policy Number:



**Photo: 37**

**Date Taken:**  
12/15/2025

**Taken By:**  
Maria Hill-Dudley

**Description:**  
Photograph of the insured vehicle's passenger side.



**Photo: 38**

**Date Taken:**  
12/15/2025

**Taken By:**  
Maria Hill-Dudley

**Description:**  
Photograph of the insured vehicle's passenger side.

## Claim Photo

Our File Number:


Adjuster:

Insured:

Date of Loss:

Customer File Number:

Policy Number:




**Photo: 39**

**Date Taken:**  
12/15/2025

**Taken By:**  
Maria Hill-Dudley

**Description:**  
Photograph of the  
insured vehicle's  
passenger side.



**Photo: 40**

**Date Taken:**  
12/15/2025

**Taken By:**  
Maria Hill-Dudley

**Description:**  
Photograph of the  
insured vehicle's  
passenger side.



## Claim Photo

Our File Number:


Adjuster:

Insured:

Date of Loss:

Customer File Number:

Policy Number:




**Photo: 41**

**Date Taken:**  
12/15/2025

**Taken By:**  
Maria Hill-Dudley

**Description:**  
Photograph of the  
insured vehicle's  
front end.



**Photo: 42**

**Date Taken:**  
12/15/2025

**Taken By:**  
Maria Hill-Dudley

**Description:**  
Photograph of the  
insured vehicle's  
front.

## Claim Photo

Our File Number:


Adjuster:

Insured:

Date of Loss:

Customer File Number:

Policy Number:




**Photo: 43**

**Date Taken:**  
12/15/2025

**Taken By:**  
Maria Hill-Dudley

**Description:**  
Photograph of the  
insured vehicle's  
front.



**Photo: 44**

**Date Taken:**  
12/15/2025

**Taken By:**  
Maria Hill-Dudley

**Description:**  
Photograph of the  
insured vehicle's  
front.



## Claim Photo

Our File Number:

Adjuster:

Insured:

Date of Loss:

Customer File Number:

Policy Number:




**Photo: 45**

**Date Taken:**  
12/15/2025

**Taken By:**  
Maria Hill-Dudley

**Description:**  
Photograph of the  
insured vehicle's  
front.



**Photo: 46**

**Date Taken:**  
12/15/2025

**Taken By:**  
Maria Hill-Dudley

**Description:**  
Photograph of the  
insured vehicle's  
front driver's side.

## Claim Photo

Our File Number:


Adjuster:

Insured:

Date of Loss:

Customer File Number:

Policy Number:



**Photo: 47**

**Date Taken:**  
12/15/2025

**Taken By:**  
Maria Hill-Dudley

**Description:**  
Photograph of the insured vehicle's front driver's side.



**Photo: 48**

**Date Taken:**  
12/15/2025

**Taken By:**  
Maria Hill-Dudley

**Description:**  
Photograph of the insured vehicle's front driver's side.



## Claim Photo

Our File Number:


Adjuster:

Insured:

Date of Loss:

Customer File Number:

Policy Number:



**Photo: 49**

**Date Taken:**  
12/15/2025

**Taken By:**  
Maria Hill-Dudley

**Description:**  
Photograph of the  
insured vehicle's  
front driver's side.



**Photo: 50**

**Date Taken:**  
12/15/2025

**Taken By:**  
Maria Hill-Dudley

**Description:**  
Photograph of the  
insured vehicle's  
front driver's side.

## Claim Photo

Our File Number:

Adjuster:

Insured:

Date of Loss:

Customer File Number:

Policy Number:



**Photo: 51**

**Date Taken:**  
12/15/2025

**Taken By:**  
Maria Hill-Dudley

**Description:**  
Photograph of the  
insured vehicle's  
front driver's side.



**Photo: 52**

**Date Taken:**  
12/15/2025

**Taken By:**  
Maria Hill-Dudley

**Description:**  
Photograph of the  
insured vehicle's  
front driver's side.



## Claim Photo

Our File Number:

Adjuster:

Insured:

Date of Loss:

Customer File Number:

Policy Number:



**Photo: 53**

**Date Taken:**  
12/15/2025

**Taken By:**  
Maria Hill-Dudley

**Description:**  
Photograph of the insured vehicle's front driver's side door.



**Photo: 54**

**Date Taken:**  
12/15/2025

**Taken By:**  
Maria Hill-Dudley

**Description:**  
Photograph of the insured vehicle's front driver's side door.

## Claim Photo

Our File Number:

Adjuster:

Insured:

Date of Loss:

Customer File Number:

Policy Number:



**Photo: 55**

**Date Taken:**  
12/15/2025

**Taken By:**  
Maria Himl-Dudley

**Description:**  
Photograph of the insured vehicle's front driver's side door.



**Photo: 56**

**Date Taken:**  
12/15/2025

**Taken By:**  
Maria Hill-Dudley

**Description:**  
Photograph of the insured vehicle's front driver's side.



## Claim Photo

Our File Number:

Adjuster:

Insured:

Date of Loss:

Customer File Number:

Policy Number:




**Photo: 57**

**Date Taken:**  
12/15/2025

**Taken By:**  
Maria Hill-Dudley

**Description:**  
Photograph of the insured vehicle's front driver's side.



**Photo: 58**

**Date Taken:**  
12/15/2025

**Taken By:**  
Maria Hill-Dudley

**Description:**  
Photograph of the insured vehicle's front driver's side.

## Claim Photo

Our File Number:

Adjuster:

Insured:

Date of Loss:

Customer File Number:

Policy Number:



**Photo: 59**

**Date Taken:**  
12/15/2025

**Taken By:**  
Maria Hill-Dudley

**Description:**  
Photograph of the insured vehicle's front driver's side.



**Photo: 60**

**Date Taken:**  
12/15/2025

**Taken By:**  
Maria Hill-Dudley

**Description:**  
Photograph of the insured vehicle's front driver's side.



## Claim Photo

Our File Number:

Adjuster:

Insured:

Date of Loss:

Customer File Number:

Policy Number:




**Photo: 61**

**Date Taken:**  
12/15/2025

**Taken By:**  
Maria Hill-Dudley

**Description:**  
Photograph of the  
insured vehicle's  
front driver's side.



**Photo: 62**

**Date Taken:**  
12/15/2025

**Taken By:**  
Maria Hill-Dudley

**Description:**  
Photograph of the  
insured vehicle's  
front driver's side.

## Claim Photo

Our File Number:


Adjuster:

Insured:

Date of Loss:

Customer File Number:

Policy Number:




**Photo: 63**

**Date Taken:**  
12/15/2025

**Taken By:**  
Maria Hill-Dudley

**Description:**  
Photograph of the insured vehicle's front driver's side undercarriage.



**Photo: 64**

**Date Taken:**  
12/15/2025

**Taken By:**  
Maria Hill-Dudley

**Description:**  
Photograph of the insured vehicle's front driver's side undercarriage.



## Claim Photo

Our File Number:


Adjuster:

Insured:

Date of Loss:

Customer File Number:

Policy Number:



**Photo: 65**

**Date Taken:**  
12/15/2025

**Taken By:**  
Maria Hill-Dudley

**Description:**  
Photograph of the  
insured vehicle's  
front driver's side  
undercarriage.



**Photo: 66**

**Date Taken:**  
12/15/2025

**Taken By:**  
Maria Hill-Dudley

**Description:**  
Photograph of the  
insured vehicle's  
front driver's side  
undercarriage

## Claim Photo

Our File Number:


Adjuster:

Insured:

Date of Loss:

Customer File Number:

Policy Number:



**Photo: 67**

**Date Taken:**  
12/15/2025

**Taken By:**  
Maria Hill-Dudley

**Description:**  
Photograph of the insured vehicle's front driver's side.



**Photo: 68**

**Date Taken:**  
12/15/2025

**Taken By:**  
Maria Hill-Dudley

**Description:**  
Photograph of the insured vehicle's front driver's side.



## Claim Photo

Our File Number:

Adjuster:

Insured:

Date of Loss:

Customer File Number:

Policy Number:




**Photo: 69**

**Date Taken:**  
12/15/2025

**Taken By:**  
Maria Hill-Dudley

**Description:**  
Photograph of the insured vehicle's front driver's side.



**Photo: 70**

**Date Taken:**  
12/15/2025

**Taken By:**  
Maria Hill-Dudley

**Description:**  
Photograph of the insured vehicle's front driver's side undercarriage.

## Claim Photo

Our File Number:


Adjuster:

Insured:

Date of Loss:

Customer File Number:

Policy Number:




**Photo: 71**

**Date Taken:**  
12/15/2025

**Taken By:**  
Maria Hill-Dudley

**Description:**  
Photograph of the  
insured vehicle's  
front driver's side  
undercarriage.



**Photo: 72**

**Date Taken:**  
12/15/2025

**Taken By:**  
Maria Hill-Dudley

**Description:**  
Photograph of the  
insured vehicle's  
front driver's side  
undercarriage.



## Claim Photo

Our File Number:


Adjuster:

Insured:

Date of Loss:

Customer File Number:

Policy Number:




**Photo: 73**

**Date Taken:**  
12/15/2025

**Taken By:**  
Maria Hill-Dudley

**Description:**  
Photograph of the insured vehicle's front driver's side undercarriage.



**Photo: 74**

**Date Taken:**  
12/15/2025

**Taken By:**  
Maria Hill-Dudley

**Description:**  
Photograph of the insured vehicle's front driver's side undercarriage.

## Claim Photo

Our File Number:


Adjuster:

Insured:

Date of Loss:

Customer File Number:

Policy Number:



**Photo: 75**

**Date Taken:**  
12/15/2025

**Taken By:**  
Maria Hill-Dudley

**Description:**  
Photograph of the insured vehicle's front driver's side.



**Photo: 76**

**Date Taken:**  
12/15/2025

**Taken By:**  
Maria Hill-Dudley

**Description:**  
Photograph of the insured vehicle's front.



## Claim Photo

Our File Number:


Adjuster:

Insured:

Date of Loss:

Customer File Number:

Policy Number:




**Photo: 77**

**Date Taken:**  
12/15/2025

**Taken By:**  
Maria Hill-Dudley

**Description:**  
Photograph of the insured vehicle's front passenger's side.



**Photo: 78**

**Date Taken:**  
12/15/2025

**Taken By:**  
Maria Hill-Dudley

**Description:**  
Photograph of the insured vehicle's front passenger's side undercarriage.

## Claim Photo

Our File Number:


Adjuster:

Insured:

Date of Loss:

Customer File Number:

Policy Number:



**Photo: 79**

**Date Taken:**  
12/15/2025

**Taken By:**  
Maria Hill-Dudley

**Description:**  
Photograph of the insured vehicle's front passenger's side.



**Photo: 80**

**Date Taken:**  
12/15/2025

**Taken By:**  
Maria Hill-Dudley

**Description:**  
Photograph of the insured vehicle's front passenger's side.



## Claim Photo

Our File Number:

Adjuster:

Insured:

Date of Loss:

Customer File Number:

Policy Number:




**Photo: 81**

**Date Taken:**  
12/15/2025

**Taken By:**  
Maria Hill-Dudley

**Description:**  
Photograph of the insured vehicle's front passenger's side.



**Photo: 82**

**Date Taken:**  
12/15/2025

**Taken By:**  
Maria Hill-Dudley

**Description:**  
Photograph of the insured vehicle's front passenger's side.