

Photo Sheet

Iron Insurance Adjusters

7600 Crescent Lake Ct.

Fort Worth TX 76137

8177794970

Claims@ironadjusters.com



INSURED & INSPECTION ADDRESS

Tracy & Brenda Carman

109083 N3700 Road

Okemah, OK 74859

Project/Claim: Iron Adjusters File Number: 26-00256 | Claim Number: 3688

Policy: EQR357416322

Date of Origin: 01/18/2026

Type of Inspection: Heavy Equipment

2019 Takeuchi TB250-2 Mini
Excavator | SN: 125100533

Date taken: 01/22/2026

Taken by: Garrett Cox

Front Right Corner



2019 Takeuchi TB250-2 Mini
Excavator | SN: 125100533

Date taken: 01/22/2026

Taken by: Garrett Cox

Front Left Corner




Photo Sheet



Iron Insurance Adjusters
7600 Crescent Lake Ct.
Fort Worth TX 76137
8177794970
Claims@ironadjusters.com

INSURED & INSPECTION ADDRESS

Tracy & Brenda Carman
109083 N3700 Road
Okemah, OK 74859

Project/Claim: Iron Adjusters File Number: 26-00256 | Claim Number: 3688
Policy: EQR357416322
Date of Origin: 01/18/2026
Type of Inspection: Heavy Equipment

2019 Takeuchi TB250-2 Mini
Excavator | SN: 125100533

Date taken: 01/22/2026

Taken by: Garrett Cox

Left Side View



2019 Takeuchi TB250-2 Mini
Excavator | SN: 125100533

Date taken: 01/22/2026

Taken by: Garrett Cox

Rear Left Corner



Photo Sheet

Iron Insurance Adjusters

7600 Crescent Lake Ct.

Fort Worth TX 76137

8177794970

Claims@ironadjusters.com



INSURED & INSPECTION ADDRESS

Tracy & Brenda Carman

109083 N3700 Road

Okemah, OK 74859

Project/Claim: Iron Adjusters File Number: 26-00256 | Claim Number: 3688

Policy: EQR357416322

Date of Origin: 01/18/2026

Type of Inspection: Heavy Equipment

2019 Takeuchi TB250-2 Mini
Excavator | SN: 125100533

Date taken: 01/22/2026

Taken by: Garrett Cox

Rear Right Corner



2019 Takeuchi TB250-2 Mini
Excavator | SN: 125100533

Date taken: 01/22/2026

Taken by: Garrett Cox

Right Side View



Photo Sheet



Iron Insurance Adjusters
7600 Crescent Lake Ct.
Fort Worth TX 76137
8177794970
Claims@ironadjusters.com

INSURED & INSPECTION ADDRESS

Tracy & Brenda Carman
109083 N3700 Road
Okemah, OK 74859

Project/Claim: Iron Adjusters File Number: 26-00256 | Claim Number: 3688
Policy: EQR357416322
Date of Origin: 01/18/2026
Type of Inspection: Heavy Equipment

2019 Takeuchi TB250-2 Mini
Excavator | SN: 125100533

Date taken: 01/22/2026

Taken by: Garrett Cox

Front View



2019 Takeuchi TB250-2 Mini
Excavator | SN: 125100533

Date taken: 01/22/2026

Taken by: Garrett Cox

Front View




Photo Sheet



Iron Insurance Adjusters
7600 Crescent Lake Ct.
Fort Worth TX 76137
8177794970
Claims@ironadjusters.com

INSURED & INSPECTION ADDRESS

Tracy & Brenda Carman
109083 N3700 Road
Okemah, OK 74859

Project/Claim: Iron Adjusters File Number: 26-00256 | Claim Number: 3688
Policy: EQR357416322
Date of Origin: 01/18/2026
Type of Inspection: Heavy Equipment

2019 Takeuchi TB250-2 Mini
Excavator | SN: 125100533

Date taken: 01/22/2026

Taken by: Garrett Cox

Serial Number Tag | S/N:
125100533



2019 Takeuchi TB250-2 Mini
Excavator | SN: 125100533

Date taken: 01/22/2026

Taken by: Garrett Cox

Serial Number Tag | S/N:
125100533



Photo Sheet



Iron Insurance Adjusters
7600 Crescent Lake Ct.
Fort Worth TX 76137
8177794970
Claims@ironadjusters.com

INSURED & INSPECTION ADDRESS

Tracy & Brenda Carman
109083 N3700 Road
Okemah, OK 74859

Project/Claim: Iron Adjusters File Number: 26-00256 | Claim Number: 3688
Policy: EQR357416322
Date of Origin: 01/18/2026
Type of Inspection: Heavy Equipment

2019 Takeuchi TB250-2 Mini
Excavator | SN: 125100533

Date taken: 01/22/2026

Taken by: Garrett Cox

Hours: 2,534



2019 Takeuchi TB250-2 Mini
Excavator | SN: 125100533

Date taken: 01/22/2026

Taken by: Garrett Cox

Hours: 2,534



Photo Sheet



Iron Insurance Adjusters
7600 Crescent Lake Ct.
Fort Worth TX 76137
8177794970
Claims@ironadjusters.com

INSURED & INSPECTION ADDRESS

Tracy & Brenda Carman
109083 N3700 Road
Okemah, OK 74859

Project/Claim: Iron Adjusters File Number: 26-00256 | Claim Number: 3688
Policy: EQR357416322
Date of Origin: 01/18/2026
Type of Inspection: Heavy Equipment

2019 Takeuchi TB250-2 Mini
Excavator | SN: 125100533

Date taken: 01/22/2026

Taken by: Garrett Cox

Hours: 2,534



2019 Takeuchi TB250-2 Mini
Excavator | SN: 125100533

Date taken: 01/22/2026

Taken by: Garrett Cox

Bucket & Lower Boom Is Twisted



Photo Sheet



Iron Insurance Adjusters
7600 Crescent Lake Ct.
Fort Worth TX 76137
8177794970
Claims@ironadjusters.com

INSURED & INSPECTION ADDRESS

Tracy & Brenda Carman
109083 N3700 Road
Okemah, OK 74859

Project/Claim: Iron Adjusters File Number: 26-00256 | Claim Number: 3688
Policy: EQR357416322
Date of Origin: 01/18/2026
Type of Inspection: Heavy Equipment

2019 Takeuchi TB250-2 Mini
Excavator | SN: 125100533

Date taken: 01/22/2026

Taken by: Garrett Cox

Bucket & Lower Boom Is Twisted



2019 Takeuchi TB250-2 Mini
Excavator | SN: 125100533

Date taken: 01/22/2026

Taken by: Garrett Cox

Bucket & Lower Boom Is Twisted



Photo Sheet



Iron Insurance Adjusters
7600 Crescent Lake Ct.
Fort Worth TX 76137
8177794970
Claims@ironadjusters.com

INSURED & INSPECTION ADDRESS

Tracy & Brenda Carman
109083 N3700 Road
Okemah, OK 74859

Project/Claim: Iron Adjusters File Number: 26-00256 | Claim Number: 3688
Policy: EQR357416322
Date of Origin: 01/18/2026
Type of Inspection: Heavy Equipment

2019 Takeuchi TB250-2 Mini
Excavator | SN: 125100533

Date taken: 01/22/2026

Taken by: Garrett Cox

Excavator Is Equiped With Thumb



2019 Takeuchi TB250-2 Mini
Excavator | SN: 125100533

Date taken: 01/22/2026

Taken by: Garrett Cox

Thumb Cylinder



Photo Sheet



Iron Insurance Adjusters
7600 Crescent Lake Ct.
Fort Worth TX 76137
8177794970
Claims@ironadjusters.com

INSURED & INSPECTION ADDRESS

Tracy & Brenda Carman
109083 N3700 Road
Okemah, OK 74859

Project/Claim: Iron Adjusters File Number: 26-00256 | Claim Number: 3688
Policy: EQR357416322
Date of Origin: 01/18/2026
Type of Inspection: Heavy Equipment

2019 Takeuchi TB250-2 Mini
Excavator | SN: 125100533

Date taken: 01/22/2026

Taken by: Garrett Cox

Hyd Block, Hose, & Fitting Is
Damaged



2019 Takeuchi TB250-2 Mini
Excavator | SN: 125100533

Date taken: 01/22/2026

Taken by: Garrett Cox

Hyd Block, Hose, & Fitting Is
Damaged



Photo Sheet

Iron Insurance Adjusters

7600 Crescent Lake Ct.

Fort Worth TX 76137

8177794970

Claims@ironadjusters.com



INSURED & INSPECTION ADDRESS

Tracy & Brenda Carman

109083 N3700 Road

Okemah, OK 74859

Project/Claim: Iron Adjusters File Number: 26-00256 | Claim Number: 3688

Policy: EQR357416322

Date of Origin: 01/18/2026

Type of Inspection: Heavy Equipment

2019 Takeuchi TB250-2 Mini
Excavator | SN: 125100533

Date taken: 01/22/2026

Taken by: Garrett Cox

Hyd Block, Hose, & Fitting Is
Damaged



2019 Takeuchi TB250-2 Mini
Excavator | SN: 125100533

Date taken: 01/22/2026

Taken by: Garrett Cox

Hyd Block, Hose, & Fitting Is
Damaged



Photo Sheet



Iron Insurance Adjusters
7600 Crescent Lake Ct.
Fort Worth TX 76137
8177794970
Claims@ironadjusters.com

INSURED & INSPECTION ADDRESS

Tracy & Brenda Carman
109083 N3700 Road
Okemah, OK 74859

Project/Claim: Iron Adjusters File Number: 26-00256 | Claim Number: 3688
Policy: EQR357416322
Date of Origin: 01/18/2026
Type of Inspection: Heavy Equipment

2019 Takeuchi TB250-2 Mini
Excavator | SN: 125100533

Date taken: 01/22/2026

Taken by: Garrett Cox

Hyd Block, Hose, & Fitting Is
Damaged



2019 Takeuchi TB250-2 Mini
Excavator | SN: 125100533

Date taken: 01/22/2026

Taken by: Garrett Cox

Hyd Block, Hose, & Fitting Is
Damaged



Photo Sheet



Iron Insurance Adjusters
7600 Crescent Lake Ct.
Fort Worth TX 76137
8177794970
Claims@ironadjusters.com

INSURED & INSPECTION ADDRESS

Tracy & Brenda Carman
109083 N3700 Road
Okemah, OK 74859

Project/Claim: Iron Adjusters File Number: 26-00256 | Claim Number: 3688
Policy: EQR357416322
Date of Origin: 01/18/2026
Type of Inspection: Heavy Equipment

2019 Takeuchi TB250-2 Mini
Excavator | SN: 125100533

Date taken: 01/22/2026

Taken by: Garrett Cox

Hyd Block, Hose, & Fitting Is
Damaged



2019 Takeuchi TB250-2 Mini
Excavator | SN: 125100533

Date taken: 01/22/2026

Taken by: Garrett Cox

Bottom Of Upper Boom Is
Damaged



Photo Sheet



Iron Insurance Adjusters
7600 Crescent Lake Ct.
Fort Worth TX 76137
8177794970
Claims@ironadjusters.com

INSURED & INSPECTION ADDRESS

Tracy & Brenda Carman
109083 N3700 Road
Okemah, OK 74859

Project/Claim: Iron Adjusters File Number: 26-00256 | Claim Number: 3688
Policy: EQR357416322
Date of Origin: 01/18/2026
Type of Inspection: Heavy Equipment

2019 Takeuchi TB250-2 Mini
Excavator | SN: 125100533

Date taken: 01/22/2026

Taken by: Garrett Cox

Bottom Of Upper Boom Is
Damaged



2019 Takeuchi TB250-2 Mini
Excavator | SN: 125100533

Date taken: 01/22/2026

Taken by: Garrett Cox

Bottom Of Upper Boom Is
Damaged



Photo Sheet



Iron Insurance Adjusters
7600 Crescent Lake Ct.
Fort Worth TX 76137
8177794970
Claims@ironadjusters.com

INSURED & INSPECTION ADDRESS

Tracy & Brenda Carman
109083 N3700 Road
Okemah, OK 74859

Project/Claim: Iron Adjusters File Number: 26-00256 | Claim Number: 3688
Policy: EQR357416322
Date of Origin: 01/18/2026
Type of Inspection: Heavy Equipment

2019 Takeuchi TB250-2 Mini
Excavator | SN: 125100533

Date taken: 01/22/2026

Taken by: Garrett Cox

Front Blade Has A Twist To It



2019 Takeuchi TB250-2 Mini
Excavator | SN: 125100533

Date taken: 01/22/2026

Taken by: Garrett Cox

Front Blade Has A Twist To It



Photo Sheet



Iron Insurance Adjusters
7600 Crescent Lake Ct.
Fort Worth TX 76137
8177794970
Claims@ironadjusters.com

INSURED & INSPECTION ADDRESS

Tracy & Brenda Carman
109083 N3700 Road
Okemah, OK 74859

Project/Claim: Iron Adjusters File Number: 26-00256 | Claim Number: 3688
Policy: EQR357416322
Date of Origin: 01/18/2026
Type of Inspection: Heavy Equipment

2019 Takeuchi TB250-2 Mini
Excavator | SN: 125100533

Date taken: 01/22/2026

Taken by: Garrett Cox

Front Blade Has A Twist To It



2019 Takeuchi TB250-2 Mini
Excavator | SN: 125100533

Date taken: 01/22/2026

Taken by: Garrett Cox

Front Blade Has A Twist To It



Photo Sheet

Iron Insurance Adjusters

7600 Crescent Lake Ct.

Fort Worth TX 76137

8177794970

Claims@ironadjusters.com



INSURED & INSPECTION ADDRESS

Tracy & Brenda Carman

109083 N3700 Road

Okemah, OK 74859

Project/Claim: Iron Adjusters File Number: 26-00256 | Claim Number: 3688

Policy: EQR357416322

Date of Origin: 01/18/2026

Type of Inspection: Heavy Equipment

2019 Takeuchi TB250-2 Mini
Excavator | SN: 125100533

Date taken: 01/22/2026

Taken by: Garrett Cox

Boom Pivot Needs Cleaned



2019 Takeuchi TB250-2 Mini
Excavator | SN: 125100533

Date taken: 01/22/2026

Taken by: Garrett Cox

Air Filter Look Clean & Dry




Photo Sheet



Iron Insurance Adjusters
7600 Crescent Lake Ct.
Fort Worth TX 76137
8177794970
Claims@ironadjusters.com

INSURED & INSPECTION ADDRESS

Tracy & Brenda Carman
109083 N3700 Road
Okemah, OK 74859

Project/Claim: Iron Adjusters File Number: 26-00256 | Claim Number: 3688
Policy: EQR357416322
Date of Origin: 01/18/2026
Type of Inspection: Heavy Equipment

2019 Takeuchi TB250-2 Mini
Excavator | SN: 125100533

Date taken: 01/22/2026

Taken by: Garrett Cox

Air Filter Look Clean & Dry



2019 Takeuchi TB250-2 Mini
Excavator | SN: 125100533

Date taken: 01/22/2026

Taken by: Garrett Cox

Oil Level Look Good



Photo Sheet



Iron Insurance Adjusters
7600 Crescent Lake Ct.
Fort Worth TX 76137
8177794970
Claims@ironadjusters.com

INSURED & INSPECTION ADDRESS

Tracy & Brenda Carman
109083 N3700 Road
Okemah, OK 74859

Project/Claim: Iron Adjusters File Number: 26-00256 | Claim Number: 3688
Policy: EQR357416322
Date of Origin: 01/18/2026
Type of Inspection: Heavy Equipment

2019 Takeuchi TB250-2 Mini
Excavator | SN: 125100533

Date taken: 01/22/2026

Taken by: Garrett Cox

Mud Packed Into The Exhaust



2019 Takeuchi TB250-2 Mini
Excavator | SN: 125100533

Date taken: 01/22/2026

Taken by: Garrett Cox

Mud Packed Into The Exhaust



Photo Sheet



Iron Insurance Adjusters
7600 Crescent Lake Ct.
Fort Worth TX 76137
8177794970
Claims@ironadjusters.com

INSURED & INSPECTION ADDRESS

Tracy & Brenda Carman
109083 N3700 Road
Okemah, OK 74859

Project/Claim: Iron Adjusters File Number: 26-00256 | Claim Number: 3688
Policy: EQR357416322
Date of Origin: 01/18/2026
Type of Inspection: Heavy Equipment

2019 Takeuchi TB250-2 Mini
Excavator | SN: 125100533

Date taken: 01/22/2026

Taken by: Garrett Cox

Mud Packed Into The Exhaust



2019 Takeuchi TB250-2 Mini
Excavator | SN: 125100533

Date taken: 01/22/2026

Taken by: Garrett Cox

Mud Packed Into The Exhaust




Photo Sheet



Iron Insurance Adjusters
7600 Crescent Lake Ct.
Fort Worth TX 76137
8177794970
Claims@ironadjusters.com

INSURED & INSPECTION ADDRESS

Tracy & Brenda Carman
109083 N3700 Road
Okemah, OK 74859


Project/Claim: Iron Adjusters File Number: 26-00256 | Claim Number: 3688
Policy: EQR357416322
Date of Origin: 01/18/2026
Type of Inspection: Heavy Equipment

2019 Takeuchi TB250-2 Mini
Excavator | SN: 125100533

Date taken: 01/22/2026

Taken by: Garrett Cox

Mud Packed Into The Exhaust



2019 Takeuchi TB250-2 Mini
Excavator | SN: 125100533

Date taken: 01/22/2026

Taken by: Garrett Cox

Mud Packed Into The Exhaust



Photo Sheet



Iron Insurance Adjusters
7600 Crescent Lake Ct.
Fort Worth TX 76137
8177794970
Claims@ironadjusters.com

INSURED & INSPECTION ADDRESS

Tracy & Brenda Carman
109083 N3700 Road
Okemah, OK 74859

Project/Claim: Iron Adjusters File Number: 26-00256 | Claim Number: 3688
Policy: EQR357416322
Date of Origin: 01/18/2026
Type of Inspection: Heavy Equipment

2019 Takeuchi TB250-2 Mini
Excavator | SN: 125100533

Date taken: 01/22/2026

Taken by: Garrett Cox

Model TB250-2



2019 Takeuchi TB250-2 Mini
Excavator | SN: 125100533

Date taken: 01/22/2026

Taken by: Garrett Cox

Right Hood & Light Damage



Photo Sheet

Iron Insurance Adjusters

7600 Crescent Lake Ct.

Fort Worth TX 76137

8177794970

Claims@ironadjusters.com



INSURED & INSPECTION ADDRESS

Tracy & Brenda Carman

109083 N3700 Road

Okemah, OK 74859

Project/Claim: Iron Adjusters File Number: 26-00256 | Claim Number: 3688

Policy: EQR357416322

Date of Origin: 01/18/2026

Type of Inspection: Heavy Equipment

2019 Takeuchi TB250-2 Mini
Excavator | SN: 125100533

Date taken: 01/22/2026

Taken by: Garrett Cox

Right Hood & Light Damage



2019 Takeuchi TB250-2 Mini
Excavator | SN: 125100533

Date taken: 01/22/2026

Taken by: Garrett Cox

Right Hood & Light Damage



Photo Sheet



Iron Insurance Adjusters
7600 Crescent Lake Ct.
Fort Worth TX 76137
8177794970
Claims@ironadjusters.com

INSURED & INSPECTION ADDRESS

Tracy & Brenda Carman
109083 N3700 Road
Okemah, OK 74859


Project/Claim: Iron Adjusters File Number: 26-00256 | Claim Number: 3688
Policy: EQR357416322
Date of Origin: 01/18/2026
Type of Inspection: Heavy Equipment

2019 Takeuchi TB250-2 Mini
Excavator | SN: 125100533

Date taken: 01/22/2026

Taken by: Garrett Cox

View Under Right Hood



2019 Takeuchi TB250-2 Mini
Excavator | SN: 125100533

Date taken: 01/22/2026

Taken by: Garrett Cox

Overview Of Right Track - Tread
Life 50%



Photo Sheet



Iron Insurance Adjusters
7600 Crescent Lake Ct.
Fort Worth TX 76137
8177794970
Claims@ironadjusters.com

INSURED & INSPECTION ADDRESS

Tracy & Brenda Carman
109083 N3700 Road
Okemah, OK 74859

Project/Claim: Iron Adjusters File Number: 26-00256 | Claim Number: 3688
Policy: EQR357416322
Date of Origin: 01/18/2026
Type of Inspection: Heavy Equipment

2019 Takeuchi TB250-2 Mini
Excavator | SN: 125100533

Date taken: 01/22/2026

Taken by: Garrett Cox

Overview Of Right Track - Tread
Life 50%



2019 Takeuchi TB250-2 Mini
Excavator | SN: 125100533

Date taken: 01/22/2026

Taken by: Garrett Cox

Overview Of Right Track - Tread
Life 50%



Photo Sheet

Iron Insurance Adjusters

7600 Crescent Lake Ct.

Fort Worth TX 76137

8177794970

Claims@ironadjusters.com



INSURED & INSPECTION ADDRESS

Tracy & Brenda Carman

109083 N3700 Road

Okemah, OK 74859

Project/Claim: Iron Adjusters File Number: 26-00256 | Claim Number: 3688

Policy: EQR357416322

Date of Origin: 01/18/2026

Type of Inspection: Heavy Equipment

2019 Takeuchi TB250-2 Mini
Excavator | SN: 125100533

Date taken: 01/22/2026

Taken by: Garrett Cox

Overview Of Right Track - Tread
Life 50%



2019 Takeuchi TB250-2 Mini
Excavator | SN: 125100533

Date taken: 01/22/2026

Taken by: Garrett Cox

Mud Packed In Machine



Photo Sheet



Iron Insurance Adjusters
7600 Crescent Lake Ct.
Fort Worth TX 76137
8177794970
Claims@ironadjusters.com

INSURED & INSPECTION ADDRESS

Tracy & Brenda Carman
109083 N3700 Road
Okemah, OK 74859

Project/Claim: Iron Adjusters File Number: 26-00256 | Claim Number: 3688
Policy: EQR357416322
Date of Origin: 01/18/2026
Type of Inspection: Heavy Equipment

2019 Takeuchi TB250-2 Mini
Excavator | SN: 125100533

Date taken: 01/22/2026

Taken by: Garrett Cox

Mud Packed In Machine



2019 Takeuchi TB250-2 Mini
Excavator | SN: 125100533

Date taken: 01/22/2026

Taken by: Garrett Cox

Overview Of Left Track - Tread Life
50%



Photo Sheet



Iron Insurance Adjusters
7600 Crescent Lake Ct.
Fort Worth TX 76137
8177794970
Claims@ironadjusters.com

INSURED & INSPECTION ADDRESS

Tracy & Brenda Carman
109083 N3700 Road
Okemah, OK 74859

Project/Claim: Iron Adjusters File Number: 26-00256 | Claim Number: 3688
Policy: EQR357416322
Date of Origin: 01/18/2026
Type of Inspection: Heavy Equipment

2019 Takeuchi TB250-2 Mini
Excavator | SN: 125100533

Date taken: 01/22/2026

Taken by: Garrett Cox

Overview Of Left Track - Tread Life
50%



2019 Takeuchi TB250-2 Mini
Excavator | SN: 125100533

Date taken: 01/22/2026

Taken by: Garrett Cox

Cab Overview



Photo Sheet



Iron Insurance Adjusters
7600 Crescent Lake Ct.
Fort Worth TX 76137
8177794970
Claims@ironadjusters.com

INSURED & INSPECTION ADDRESS

Tracy & Brenda Carman
109083 N3700 Road
Okemah, OK 74859

Project/Claim: Iron Adjusters File Number: 26-00256 | Claim Number: 3688
Policy: EQR357416322
Date of Origin: 01/18/2026
Type of Inspection: Heavy Equipment

2019 Takeuchi TB250-2 Mini
Excavator | SN: 125100533

Date taken: 01/22/2026

Taken by: Garrett Cox

Cab Overview



2019 Takeuchi TB250-2 Mini
Excavator | SN: 125100533

Date taken: 01/22/2026

Taken by: Garrett Cox

Prior Damage



Photo Sheet



Iron Insurance Adjusters
7600 Crescent Lake Ct.
Fort Worth TX 76137
8177794970
Claims@ironadjusters.com

INSURED & INSPECTION ADDRESS

Tracy & Brenda Carman
109083 N3700 Road
Okemah, OK 74859

Project/Claim: Iron Adjusters File Number: 26-00256 | Claim Number: 3688
Policy: EQR357416322
Date of Origin: 01/18/2026
Type of Inspection: Heavy Equipment

2019 Takeuchi TB250-2 Mini
Excavator | SN: 125100533

Date taken: 01/22/2026

Taken by: Garrett Cox

Prior Damage



2019 Takeuchi TB250-2 Mini
Excavator | SN: 125100533

Date taken: 01/22/2026

Taken by: Garrett Cox

Prior Damage



Photo Sheet



Iron Insurance Adjusters
7600 Crescent Lake Ct.
Fort Worth TX 76137
8177794970
Claims@ironadjusters.com

INSURED & INSPECTION ADDRESS

Tracy & Brenda Carman
109083 N3700 Road
Okemah, OK 74859

Project/Claim: Iron Adjusters File Number: 26-00256 | Claim Number: 3688
Policy: EQR357416322
Date of Origin: 01/18/2026
Type of Inspection: Heavy Equipment

2019 Takeuchi TB250-2 Mini
Excavator | SN: 125100533

Date taken: 01/22/2026

Taken by: Garrett Cox

Mud Line



2019 Takeuchi TB250-2 Mini
Excavator | SN: 125100533

Date taken: 01/22/2026

Taken by: Garrett Cox

Recovery Invoice | \$1,300.00

CITY	
JOB NAME OR LEGAL DESCRIPTION	
DESCRIPTION OF WORK	
DRIVER'S NAME AND TRUCK NO.	
DRIVER'S SIGNATURE	
☐ 10 WHEELER ☐ BELLY DUMP ☐ END DUMP	
QUANT.	DESCRIPTION OF MATERIAL USED
	Track hoe time
	pd
	chk # 395
	pd
	1,300.00
	pd
	Dig Dred
MATERIAL SOLD	
TAX	
TOTAL	
cc: File	
117 W. Court Square, Okemah, OK 74859 Phone: (800) 476-2379 - Fax	

Photo Sheet



Iron Insurance Adjusters
7600 Crescent Lake Ct.
Fort Worth TX 76137
8177794970
Claims@ironadjusters.com

INSURED & INSPECTION ADDRESS

Tracy & Brenda Carman
109083 N3700 Road
Okemah, OK 74859

Project/Claim: Iron Adjusters File Number: 26-00256 | Claim Number: 3688
Policy: EQR357416322
Date of Origin: 01/18/2026
Type of Inspection: Heavy Equipment

2019 Takeuchi TB250-2 Mini
Excavator | SN: 125100533

Date taken: 01/23/2026

Taken by: Insured Provided Photo

Photo Provided By The Insured



2019 Takeuchi TB250-2 Mini
Excavator | SN: 125100533

Date taken: 01/23/2026

Taken by: Insured Provided Photo

Photo Provided By The Insured



Photo Sheet



Iron Insurance Adjusters
7600 Crescent Lake Ct.
Fort Worth TX 76137
8177794970
Claims@ironadjusters.com

INSURED & INSPECTION ADDRESS

Tracy & Brenda Carman
109083 N3700 Road
Okemah, OK 74859

Project/Claim: Iron Adjusters File Number: 26-00256 | Claim Number: 3688
Policy: EQR357416322
Date of Origin: 01/18/2026
Type of Inspection: Heavy Equipment

2019 Takeuchi TB250-2 Mini
Excavator | SN: 125100533

Date taken: 01/23/2026

Taken by: Insured Provided Photo

Photo Provided By The Insured



2019 Takeuchi TB250-2 Mini
Excavator | SN: 125100533

Date taken: 01/23/2026

Taken by: Insured Provided Photo

Photo Provided By The Insured



Photo Sheet



Iron Insurance Adjusters
7600 Crescent Lake Ct.
Fort Worth TX 76137
8177794970
Claims@ironadjusters.com

INSURED & INSPECTION ADDRESS

Tracy & Brenda Carman
109083 N3700 Road
Okemah, OK 74859

Project/Claim: Iron Adjusters File Number: 26-00256 | Claim Number: 3688
Policy: EQR357416322
Date of Origin: 01/18/2026
Type of Inspection: Heavy Equipment

2019 Takeuchi TB250-2 Mini
Excavator | SN: 125100533

Date taken: 01/23/2026

Taken by: Insured Provided Photo

Photo Provided By The Insured



2019 Takeuchi TB250-2 Mini
Excavator | SN: 125100533

Date taken: 01/23/2026

Taken by: Insured Provided Photo

Photo Provided By The Insured



Photo Sheet



Iron Insurance Adjusters
7600 Crescent Lake Ct.
Fort Worth TX 76137
8177794970
Claims@ironadjusters.com

INSURED & INSPECTION ADDRESS

Tracy & Brenda Carman
109083 N3700 Road
Okemah, OK 74859

Project/Claim: Iron Adjusters File Number: 26-00256 | Claim Number: 3688
Policy: EQR357416322
Date of Origin: 01/18/2026
Type of Inspection: Heavy Equipment

2019 Takeuchi TB250-2 Mini
Excavator | SN: 125100533

Date taken: 01/23/2026

Taken by: Insured Provided Photo

Photo Provided By The Insured



2019 Takeuchi TB250-2 Mini
Excavator | SN: 125100533

Date taken: 01/23/2026

Taken by: Insured Provided Photo

Photo Provided By The Insured



Photo Sheet



Iron Insurance Adjusters
7600 Crescent Lake Ct.
Fort Worth TX 76137
8177794970
Claims@ironadjusters.com

INSURED & INSPECTION ADDRESS

Tracy & Brenda Carman
109083 N3700 Road
Okemah, OK 74859

Project/Claim: Iron Adjusters File Number: 26-00256 | Claim Number: 3688
Policy: EQR357416322
Date of Origin: 01/18/2026
Type of Inspection: Heavy Equipment

2019 Takeuchi TB250-2 Mini
Excavator | SN: 125100533

Date taken: 01/23/2026

Taken by: Insured Provided Photo

Photo Provided By The Insured



2019 Takeuchi TB250-2 Mini
Excavator | SN: 125100533

Date taken: 01/23/2026

Taken by: Insured Provided Photo

Photo Provided By The Insured



Photo Sheet

Iron Insurance Adjusters
7600 Crescent Lake Ct.
Fort Worth TX 76137
8177794970
Claims@ironadjusters.com



INSURED & INSPECTION ADDRESS

Tracy & Brenda Carman
109083 N3700 Road
Okemah, OK 74859

Project/Claim: Iron Adjusters File Number: 26-00256 | Claim Number: 3688
Policy: EQR357416322
Date of Origin: 01/18/2026
Type of Inspection: Heavy Equipment

2019 Takeuchi TB250-2 Mini
Excavator | SN: 125100533

Date taken: 01/23/2026

Taken by: Insured Provided Photo

Photo Provided By The Insured



2019 Takeuchi TB250-2 Mini
Excavator | SN: 125100533

Date taken: 01/23/2026

Taken by: Insured Provided Photo

Photo Provided By The Insured

