

Claim Photo

Our File Number: 277-066298
Adjuster: Mike Hogan
Insured: Arctic Express, Inc.
Date of Loss: 01/08/2026
Customer File Number: TRK26001007
Policy Number:




Photo: 1

Date Taken:
01/22/2026

Taken By:
Sheila Allen

Description:
Insured trailer VIN



Photo: 2

Date Taken:
01/22/2026

Taken By:
Sheila Allen

Description:
Insured trailer
reefer

Claim Photo

Our File Number: 277-066298
Adjuster: Mike Hogan
Insured: Arctic Express, Inc.
Date of Loss: 01/08/2026
Customer File Number: TRK26001007
Policy Number:




Photo: 3

Date Taken:
01/22/2026

Taken By:
Sheila Allen

Description:
Insured trailer exterior



Photo: 4

Date Taken:
01/22/2026

Taken By:
Sheila Allen

Description:
Insured trailer exterior

Claim Photo

Our File Number: 277-066298
Adjuster: Mike Hogan
Insured: Arctic Express, Inc.
Date of Loss: 01/08/2026
Customer File Number: TRK26001007
Policy Number:

cia
CUSTARD
INSURANCE ADJUSTERS




Photo: 5

Date Taken:
01/22/2026

Taken By:
Sheila Allen

Description:
Insured trailer exterior



Photo: 6

Date Taken:
01/22/2026

Taken By:
Sheila Allen

Description:
Insured trailer exterior

Claim Photo

Our File Number: 277-066298
Adjuster: Mike Hogan
Insured: Arctic Express, Inc.
Date of Loss: 01/08/2026
Customer File Number: TRK26001007
Policy Number:



Photo: 7

Date Taken:
01/22/2026

Taken By:
Sheila Allen

Description:
Insured trailer exterior



Photo: 8

Date Taken:
01/22/2026

Taken By:
Sheila Allen

Description:
Insured trailer exterior

Claim Photo

Our File Number: 277-066298
Adjuster: Mike Hogan
Insured: Arctic Express, Inc.
Date of Loss: 01/08/2026
Customer File Number: TRK26001007
Policy Number:




Photo: 9

Date Taken:
01/22/2026

Taken By:
Sheila Allen

Description:
Insured trailer
exterior



Photo: 10

Date Taken:
01/22/2026

Taken By:
Sheila Allen

Description:
Insured trailer
damages to the
right side from the
outside.

Claim Photo

Our File Number: 277-066298
Adjuster: Mike Hogan
Insured: Arctic Express, Inc.
Date of Loss: 01/08/2026
Customer File Number: TRK26001007
Policy Number:



Photo: 11

Date Taken:
01/22/2026

Taken By:
Sheila Allen

Description:
Insured trailer damages to the right side from the outside.



Photo: 12

Date Taken:
01/22/2026

Taken By:
Sheila Allen

Description:
Insured trailer damages to the right side from the outside.

Claim Photo

Our File Number: 277-066298
Adjuster: Mike Hogan
Insured: Arctic Express, Inc.
Date of Loss: 01/08/2026
Customer File Number: TRK26001007
Policy Number:



Photo: 13

Date Taken:
01/22/2026

Taken By:
Sheila Allen

Description:
Insured trailer
damages to the
right side from the
outside.



Photo: 14

Date Taken:
01/22/2026

Taken By:
Sheila Allen

Description:
Insured trailer
damages to the
right side from the
outside.

Claim Photo

Our File Number: 277-066298
Adjuster: Mike Hogan
Insured: Arctic Express, Inc.
Date of Loss: 01/08/2026
Customer File Number: TRK26001007
Policy Number:

cia
CUSTARD
INSURANCE ADJUSTERS



Photo: 15

Date Taken:
01/22/2026

Taken By:
Sheila Allen

Description:
Insured trailer
damages on the
right side from the
inside.



Photo: 16

Date Taken:
01/22/2026

Taken By:
Sheila Allen

Description:
Insured trailer
damages on the
right side from the
inside.

Claim Photo

Our File Number: 277-066298
Adjuster: Mike Hogan
Insured: Arctic Express, Inc.
Date of Loss: 01/08/2026
Customer File Number: TRK26001007
Policy Number:

cia
CUSTARD
INSURANCE ADJUSTERS




Photo: 17

Date Taken:
01/22/2026

Taken By:
Sheila Allen

Description:
Insured trailer
damages on the
right side from the
inside.



Photo: 18

Date Taken:
01/22/2026

Taken By:
Sheila Allen

Description:
Insured trailer
damages on the
right side from the
inside.

Claim Photo

Our File Number: 277-066298
Adjuster: Mike Hogan
Insured: Arctic Express, Inc.
Date of Loss: 01/08/2026
Customer File Number: TRK26001007
Policy Number:

cia
CUSTARD
INSURANCE ADJUSTERS



Photo: 19

Date Taken:
01/22/2026

Taken By:
Sheila Allen

Description:
Insured trailer
damages on the
right side from the
inside.



Photo: 20

Date Taken:
01/22/2026

Taken By:
Sheila Allen

Description:
Insured trailer
damages on the
right side from the
inside.