

IC BUS, LLC

MODEL

PB10500

SERIAL NO

595921

CAP.

71

DATE MFG.

08/29/19

PARTS ORDER NO.

Property of Harrison County School District



962777

NAVISTAR,
VEHICLE EMISSIONS COMPLIANCE

THIS VEHICLE COMPLIES WITH CALIFORNIA
U.S. EPA REGULATIONS FOR 2020



445YMB5

LPRR				
------	--	--	--	--

LNXX2VOCVXXB CLASS 6-7 VO

FUEL TYPE: GASOLINE

MFD BY IC-BUS, LLC

DATE 08 MO. 19 YR.

AXLE GAWR SU
TIR

KG LB TIR

FRT 4.536 10.000 265/75R22

REAR 8.981 19.800 10R22.5 G


THIS VEHICLE CONFORMS TO
MOTOR VEHICLE SAFETY STANDARDS
DATE OF MANUFACTURE SHOWN

VIN: 4DRBUPWP2MB596921

ATTENTION

USE CROSS VIEW MIRRORS
WHILE BUS IS STOPPED
MIRRORS TO VIEW TRAILER
IMAGES IN SUCH MIRRORS
SHOW ANOTHER VEHICLE

ROSCO CROSS
90-21 144TH PLACE, J
WWW.ROSCOCROSS.COM



This vehicle is equipped with

ALARM M

WHEN OPERATING THE BUS
FAILURE TO MAINTAIN
DIRECTION OF TRAVEL



419

419



A close-up, side-view photograph of a yellow school bus. The bus is bright yellow with black trim around the windows and along the side. The text "HARRISON COUNTY SCHOOL DISTRICT" is printed in large, bold, black capital letters along the side of the bus. The windows are large and rectangular, reflecting the sky and surrounding environment. The bus is parked on a gravel surface, and the background shows a clear blue sky.

HARRISON COUNTY SCHOOL DISTRICT



SCHOOL BUS

419





SCHOOL BUS

EMERGENCY DOOR

419

G 87861

THIS VEHICLE STOPS AT
ALL RAILROAD CROSSINGS

SCHOOL BUS

74

THIS VEHICLE STOPS AT
ALL RAILROAD CROSSINGS

WILLIS



SCHOOL BUS

EMERGENCY DOOR

419

G 87861
MISSISSIPPI
GOVERNMENT

THIS VEHICLE STOPS AT
ALL INTERSECTION CROSSINGS







SCHOOL DISTRICT

YTW













HARRISON COUN





HARRISON COUNTY SCHOOL DISTRICT

ONLY



























183





FRANK
MADE IN U.S.A.

Do not adjust these brakes until the
brake is fully adjusted. Do not use the





STOP

419





EMERGENCY EXIT

EMERGENCY EXIT

HARRISON COUNTY SCHOOL DISTRICT





NAVISTAR

NO ONE OTHER THAN STUDENTS AND
SCHOOL OFFICIALS ALLOWED ON BUS

WATCH YOUR STEP

419





NOTICE

**STEPS FOR SERVICE
REFILL OF AN EMPTY
COOLANT SYSTEM**

Read instructions in the operator's manual and use proper air conditioning. Use coolant level indicators for normal operation.

1. Close heater return valve BEFORE OR
2. Use thermostat to remove air from heater system. Run engine to 1500 rpm to push coolant through heater.
3. Open heater return valve and run until air is gone.

Always use proper safety devices.



PSI

POWER SOLUTIONS
INTERNATIONAL

PSI- 8.8W



8.8W0001076

08-19-2019

201 Mittel Drive,
Wood Dale, Illinois 60191 USA
TEL: 630-350-9400
TOLL FREE: 800-551-2936
www.psiengines.com









HARRISON

419















EXHAUST FILTER









