

Claim Photo

Our File Number:

Adjuster:

Insured:

Date of Loss:

Customer File Number:

Policy Number:



Photo: 1

Date Taken:
12/29/2025

Taken By:
Anthony Hunter

Description:
Vehicle: 2025
Bitdeer Scissor Lift
SN: 17307796 left
rear



Photo: 2

Date Taken:
12/29/2025

Taken By:
Anthony Hunter

Description:
Vehicle: 2025
Bitdeer Scissor Lift
SN: 17307796 rear

Claim Photo

Our File Number:

Adjuster:

Insured:

Date of Loss:

Customer File Number:

Policy Number:



Photo: 3

Date Taken:
12/29/2025

Taken By:
Anthony Hunter

Description:
Vehicle: 2025
Bitdeer Scissor Lift
SN: 17307796 left
front



Photo: 4

Date Taken:
12/29/2025

Taken By:
Anthony Hunter

Description:
Vehicle: 2025
Bitdeer Scissor Lift
SN: 17307796 left
rear

Claim Photo

Our File Number:

Adjuster:

Insured:

Date of Loss:

Customer File Number:

Policy Number:



Photo: 5

Date Taken:
12/29/2025

Taken By:
Anthony Hunter

Description:
Vehicle: 2025
Bitdeer Scissor Lift
SN: 17307796 rear




Photo: 6

Date Taken:
12/29/2025

Taken By:
Anthony Hunter

Description:
Vehicle: 2025
Bitdeer Scissor Lift
SN: 17307796 rt
rear

Claim Photo

Our File Number:

Adjuster:

Insured:

Date of Loss:

Customer File Number:

Policy Number:




Photo: 7

Date Taken:
12/29/2025

Taken By:
Anthony Hunter

Description:
Vehicle: 2025
Bitdeer Scissor Lift
SN: 17307796 VIN
plate




Photo: 8

Date Taken:
12/29/2025

Taken By:
Anthony Hunter

Description:
Vehicle: 2025
Bitdeer Scissor Lift
SN: 17307796 VIN
plate

Claim Photo

Our File Number:

Adjuster:

Insured:

Date of Loss:

Customer File Number:

Policy Number:



Photo: 9

Date Taken:
12/29/2025

Taken By:
Anthony Hunter

Description:
Vehicle: 2025
Bitdeer Scissor Lift
SN: 17307796 burn
area



Photo: 10

Date Taken:
12/29/2025

Taken By:
Anthony Hunter

Description:
Vehicle: 2025
Bitdeer Scissor Lift
SN: 17307796
burn area

Claim Photo

Our File Number:

Adjuster:

Insured:

Date of Loss:

Customer File Number:

Policy Number:



Photo: 11

Date Taken:
12/29/2025

Taken By:
Anthony Hunter

Description:
Vehicle: 2025
Bitdeer Scissor Lift
SN: 17307796
burn area



Photo: 12

Date Taken:
12/29/2025

Taken By:
Anthony Hunter

Description:
Vehicle: 2025
Bitdeer Scissor Lift
SN: 17307796
hours

Claim Photo

Our File Number:

Adjuster:

Insured:

Date of Loss:

Customer File Number:

Policy Number:



Photo: 13

Date Taken:
12/29/2025

Taken By:
Anthony Hunter

Description:
Vehicle: 2025
Bitdeer Scissor Lift
SN: 17307796 ID



Photo: 14

Date Taken:
12/29/2025

Taken By:
Anthony Hunter

Description:
Vehicle: 2025
Bitdeer Scissor Lift
SN: 17307796 burn
area

Claim Photo

Our File Number:

Adjuster:

Insured:

Date of Loss:

Customer File Number:

Policy Number:



Photo: 15

Date Taken:
12/29/2025

Taken By:
Anthony Hunter

Description:
Vehicle: 2025
Bitdeer Scissor Lift
SN: 17307796




Photo: 16

Date Taken:
12/29/2025

Taken By:
Anthony Hunter

Description:
Vehicle: 2025
Bitdeer Scissor Lift
SN: 17307796
damaged cables

Claim Photo

Our File Number:

Adjuster:

Insured:

Date of Loss:

Customer File Number:

Policy Number:



Photo: 17

Date Taken:
12/29/2025

Taken By:
Anthony Hunter

Description:
Vehicle: 2025
Bitdeer Scissor Lift
SN: 17307796
damaged cables




Photo: 18

Date Taken:
12/29/2025

Taken By:
Anthony Hunter

Description:
Vehicle: 2025
Bitdeer Scissor Lift
SN: 17307796 rt
side rollers

Claim Photo

Our File Number:

Adjuster:

Insured:

Date of Loss:

Customer File Number:

Policy Number:




Photo: 19

Date Taken:
12/29/2025

Taken By:
Anthony Hunter

Description:
Vehicle: 2025
Bitdeer Scissor Lift
SN: 17307796 rt
side rollers and
cables



Photo: 20

Date Taken:
12/29/2025

Taken By:
Anthony Hunter

Description:
Vehicle: 2025
Bitdeer Scissor Lift
SN: 17307796 rt
side

Claim Photo

Our File Number:

Adjuster:

Insured:

Date of Loss:

Customer File Number:

Policy Number:



Photo: 21

Date Taken:
12/29/2025

Taken By:
Anthony Hunter

Description:
Vehicle: 2025
Bitdeer Scissor Lift
SN: 17307796 rt
side



Photo: 22

Date Taken:
12/29/2025

Taken By:
Anthony Hunter

Description:
Vehicle: 2025
Bitdeer Scissor Lift
SN: 17307796
batteries

Claim Photo

Our File Number:
Adjuster:
Insured:
Date of Loss:
Customer File Number:
Policy Number:



Photo: 23

Date Taken:
12/29/2025

Taken By:
Anthony Hunter

Description:
Vehicle: 2025
Bitdeer Scissor Lift
SN: 17307796
batteries