

Claim Photo

Our File Number: 277-066321
Adjuster: Lee Klokow
Insured: Road Master Group
Date of Loss: 01/14/2026
Customer File Number: 001960-278567-AP-02
Policy Number:



Photo: 1

Date Taken:
01/26/2026

Taken By:
Mike Tope

Description:



Photo: 2

Date Taken:
01/26/2026

Taken By:
Mike Tope

Description:

Claim Photo

Our File Number: 277-066321
Adjuster: Lee Klokow
Insured: Road Master Group
Date of Loss: 01/14/2026
Customer File Number: 001960-278567-AP-02
Policy Number:



Photo: 3

Date Taken:
01/26/2026

Taken By:
Mike Tope

Description:



Photo: 4

Date Taken:
01/26/2026

Taken By:
Mike Tope

Description:

Claim Photo

Our File Number: 277-066321
Adjuster: Lee Klokow
Insured: Road Master Group
Date of Loss: 01/14/2026
Customer File Number: 001960-278567-AP-02
Policy Number:



Photo: 5

Date Taken:
01/26/2026

Taken By:
Mike Tope

Description:

NEW MOTOR VEHICLE REGISTRATION RECEIPT

Missouri Department of Revenue

2022184068014DG337000010324

848601

OWNER INFORMATION

ROADMASTER EQUIPMENT LEASING, INC.
8141 E 7TH ST
JOPLIN, MO 64801

COUNTY: JASPER

VEHICLE INFORMATION

MAKE	YEAR	VEHICLE ID NUMBER	KIND OF VEHICLE	BODY STYLE	FUEL TYPE	ODOMETER	HORSEPOWER
HYTR	2022	3H3F482K9NJ069046	TRAILER	SEMI			
TITLE NUMBER		PURCHASE DATE					
		12/31/2021					

REGISTRATION INFORMATION

CURRENT REGISTRATION TYPE: PLATE STANDARD TRAILER REGULAR

CURRENT NUMBER: 03L1TG

EXPIRATION: NON-EXPIRING

ISSUED INVENTORY INFORMATION

INVENTORY TYPE: TRAILER

PERMANENT TRAILER TAB

INVENTORY NUMBER: 1041155P

FEE INFORMATION

DESCRIPTION - CODE

AGENT FEE / AGENT FEE - 0708

REGISTRATION FEE / TRAILER - 0066

TOTAL PAID:

Missouri Department of Revenue may electronically resubmit checks returned for insufficient or uncollected funds. Other restrictions may apply.

Photo: 6

Date Taken:
01/26/2026

Taken By:
Mike Tope

Description:

ANNUAL VEHICLE INSPECTION REPORT

VEHICLE HISTORY RECORD

17589 848601

DATE: 01/26/25

VEHICLE: Tristar Motor Transit

ADDRESS: 8141 E 7th St

CITY, STATE, ZIP CODE: JOPLIN, MO 64801

VEHICLE TYPE: TRAILER

INSPECTOR: Mike Tope

VEHICLE COMPONENTS INSPECTED

ITEM	OK	NOT OK	REMARKS
1. BRAKE SYSTEM			
a. Service Brakes			
b. Parking Brake System			
c. Brake Drums or Rotors			
d. Brake Hoses			
e. Brake Tubing			
f. Low Pressure Warning Device			
g. Trailer Protection Valve			
h. Air Compressor			
i. Electric Brakes			
j. Hydraulic Brakes			
k. Vacuum Systems			
l. Antilock Brake System			
m. Automatic Brake Actuators			
2. COUPLING DEVICES			
a. Fifth Wheels			
b. Pintle Hooks			
c. Drawbar/Towbar Eye			
d. Drawbar/Towbar Tongue			
e. Safety Devices			
f. Saddle Mounts			
3. EXHAUST SYSTEM			
a. No leaks forward of directly below the driver's compartment			
b. Blue: No leaking, discharging in violation of standard			
c. Unlikely to burn, char, or damage the structural wiring, fuel supply, or any combustible part of vehicle			
4. FUEL SYSTEM			
a. No visible leak			
b. Fuel Tank Filler Cap			
c. Fuel tank securely attached			
5. LIGHTING DEVICES			
a. All required lights/reflectors operable			
6. STEERING			
a. Steering Wheel Free Play			
b. Steering Column			
c. Front Axle Assembly			
d. Other Steering Components			
e. Steering Gear Box			
f. Pitman Arm			
7. OTHER			
a. Ball and Socket Joints			
b. Tie Rods and Drag Links			
c. Nuts			
d. Steering System			
8. SUSPENSION			
a. Axle Positioning Parts			
b. Spring Assembly			
c. Torque, Radius or Tracking Components			
9. TIRES			
a. Spare-Axis Tires			
b. All Other Tires			
c. Spind Restricted Tires			
10. WHEELS AND RIMS			
a. Lock or Wheel Ring			
b. Wheel and Rims			
c. Fasteners			
d. Wells			
11. WINDSHIELD GLAZING			
a. No cracks, discoloration, obstructions, etc. (see 393.60 for exceptions)			
12. WINDSHIELD WIPERS			
a. No missing, damaged, or inoperable wipers			
13. MOTORCOACH SEATS			
a. Seats securely fastened to the vehicle structure			
14. REAR IMPACT GUARD			
a. In place, securely attached, proper size, proper placement (see 393.60)			
15. OTHER			
a. List any other condition(s) which may prevent safe operation of this vehicle.			

INSTRUCTIONS: MARK COLUMN ABOVE ONLY IF DEFECT. Z = NO DEFECT. NA = IF ITEM DOES NOT APPLY. REPAIRED DATE

CERTIFICATION: THIS VEHICLE HAS PASSED ALL THE INSPECTION ITEMS FOR THE ANNUAL VEHICLE INSPECTION IN ACCORDANCE WITH 49 CFR PART 395.

VEHICLE COPY

3127 (Rev. 1/22)

Claim Photo

Our File Number: 277-066321
Adjuster: Lee Klokow
Insured: Road Master Group
Date of Loss: 01/14/2026
Customer File Number: 001960-278567-AP-02
Policy Number:




Photo: 7

Date Taken:
01/26/2026

Taken By:
Mike Tope

Description:



Photo: 8

Date Taken:
01/26/2026

Taken By:
Mike Tope

Description:

Claim Photo

Our File Number: 277-066321
Adjuster: Lee Klokow
Insured: Road Master Group
Date of Loss: 01/14/2026
Customer File Number: 001960-278567-AP-02
Policy Number:



Photo: 9

Date Taken:
01/26/2026

Taken By:
Mike Tope

Description:



Photo: 10

Date Taken:
01/26/2026

Taken By:
Mike Tope

Description:

Claim Photo

Our File Number: 277-066321
Adjuster: Lee Klokow
Insured: Road Master Group
Date of Loss: 01/14/2026
Customer File Number: 001960-278567-AP-02
Policy Number:



Photo: 11

Date Taken:
01/26/2026

Taken By:
Mike Tope

Description:



Photo: 12

Date Taken:
01/26/2026

Taken By:
Mike Tope

Description:

Claim Photo

Our File Number: 277-066321
Adjuster: Lee Klokow
Insured: Road Master Group
Date of Loss: 01/14/2026
Customer File Number: 001960-278567-AP-02
Policy Number:



Photo: 13

Date Taken:
01/26/2026

Taken By:
Mike Tope

Description:



Photo: 14

Date Taken:
01/26/2026

Taken By:
Mike Tope

Description:

Claim Photo

Our File Number: 277-066321
Adjuster: Lee Klokow
Insured: Road Master Group
Date of Loss: 01/14/2026
Customer File Number: 001960-278567-AP-02
Policy Number:



Photo: 15

Date Taken:
01/26/2026

Taken By:
Mike Tope

Description:



Photo: 16

Date Taken:
01/26/2026

Taken By:
Mike Tope

Description:

Claim Photo

Our File Number: 277-066321
Adjuster: Lee Klokow
Insured: Road Master Group
Date of Loss: 01/14/2026
Customer File Number: 001960-278567-AP-02
Policy Number:



Photo: 17

Date Taken:
01/26/2026

Taken By:
Mike Tope

Description:



Photo: 18

Date Taken:
01/26/2026

Taken By:
Mike Tope

Description:

Claim Photo

Our File Number: 277-066321
Adjuster: Lee Klokow
Insured: Road Master Group
Date of Loss: 01/14/2026
Customer File Number: 001960-278567-AP-02
Policy Number:



Photo: 19

Date Taken:
01/26/2026

Taken By:
Mike Tope

Description:



Photo: 20

Date Taken:
01/26/2026

Taken By:
Mike Tope

Description:

Claim Photo

Our File Number: 277-066321
Adjuster: Lee Klokow
Insured: Road Master Group
Date of Loss: 01/14/2026
Customer File Number: 001960-278567-AP-02
Policy Number:



Photo: 21

Date Taken:
01/26/2026

Taken By:
Mike Tope

Description:



Photo: 22

Date Taken:
01/26/2026

Taken By:
Mike Tope

Description:

Claim Photo

Our File Number: 277-066321
Adjuster: Lee Klokow
Insured: Road Master Group
Date of Loss: 01/14/2026
Customer File Number: 001960-278567-AP-02
Policy Number:



Photo: 23

Date Taken:
01/26/2026

Taken By:
Mike Tope

Description:



Photo: 24

Date Taken:
01/26/2026

Taken By:
Mike Tope

Description:

Claim Photo

Our File Number: 277-066321
Adjuster: Lee Klokow
Insured: Road Master Group
Date of Loss: 01/14/2026
Customer File Number: 001960-278567-AP-02
Policy Number:



Photo: 25

Date Taken:
01/26/2026

Taken By:
Mike Tope

Description:



Photo: 26

Date Taken:
01/26/2026

Taken By:
Mike Tope

Description:

Claim Photo

Our File Number: 277-066321
Adjuster: Lee Klokow
Insured: Road Master Group
Date of Loss: 01/14/2026
Customer File Number: 001960-278567-AP-02
Policy Number:



Photo: 27

Date Taken:
01/26/2026

Taken By:
Mike Tope

Description:



Photo: 28

Date Taken:
01/26/2026

Taken By:
Mike Tope

Description:

Claim Photo

Our File Number: 277-066321
Adjuster: Lee Klokow
Insured: Road Master Group
Date of Loss: 01/14/2026
Customer File Number: 001960-278567-AP-02
Policy Number:



Photo: 29

Date Taken:
01/26/2026

Taken By:
Mike Tope

Description:



Photo: 30

Date Taken:
01/26/2026

Taken By:
Mike Tope

Description:

Claim Photo

Our File Number: 277-066321
Adjuster: Lee Klokow
Insured: Road Master Group
Date of Loss: 01/14/2026
Customer File Number: 001960-278567-AP-02
Policy Number:



Photo: 31

Date Taken:
01/26/2026

Taken By:
Mike Tope

Description: