

Claim Photo

Our File Number: 277-065561
Adjuster: Scott Syner
Insured: Roberts Environmental Control
Date of Loss: 11/20/2025
Customer File Number: 040238-002065-AD-01
Policy Number:



Photo: 1

Date Taken:
12/16/2025

Taken By:
Gerald Weber

Description:
Odometer




Photo: 2

Date Taken:
12/16/2025

Taken By:
Gerald Weber

Description:
Registration
showing VIN

Claim Photo

Our File Number: 277-065561
Adjuster: Scott Syner
Insured: Roberts Environmental Control
Date of Loss: 11/20/2025
Customer File Number: 040238-002065-AD-01
Policy Number:



Photo: 3

Date Taken:
12/16/2025

Taken By:
Gerald Weber

Description:
Center console area




Photo: 4

Date Taken:
12/16/2025


Taken By:
Gerald Weber

Description:
Inside of vehicle

Claim Photo

Our File Number: 277-065561
Adjuster: Scott Syner
Insured: Roberts Environmental Control
Date of Loss: 11/20/2025
Customer File Number: 040238-002065-AD-01
Policy Number:



	 A close-up photograph of a metal placard mounted on a door jamb. The placard is white with black text and contains the following information: "MANUFACTURED BY PACCAR OF CANADA LTD", "TRUCK MODEL", "CHASSIS NO.", "ENGINE MODEL", "MAIN TRANS", "AUX. TRANS", "REAR AXLE", "AXLE RATIO", "CAUTION OVERLOADING OR OVERSPEEDING WILL VOID YOUR WARRANTY", "NOTE CHASSIS WEIGHT INCLUDES CAB AND CHASSIS, BUT WITHOUT DRIVER, BODY, AND POWER DEVICES OR EQUIPMENT", "SCALE WEIGHT", "GVWR", and "ABOVE INFORMATION VALID AT TIME OF MANUFACTURE".	Photo: 5 Date Taken: 12/16/2025 Taken By: Gerald Weber Description: Placard on door jamb
--	--	--

	 A close-up photograph of a metal plate mounted on a driver's door. The plate is white with black text and contains the number "14873282".	Photo: 6 Date Taken: 12/16/2025 Taken By: Gerald Weber Description: Plate on drivers door
--	---	---

Claim Photo

Our File Number: 277-065561
Adjuster: Scott Syner
Insured: Roberts Environmental Control
Date of Loss: 11/20/2025
Customer File Number: 040238-002065-AD-01
Policy Number:



Photo: 7

Date Taken:
12/16/2025

Taken By:
Gerald Weber

Description:
Front of vehicle



Photo: 8

Date Taken:
12/16/2025

Taken By:
Gerald Weber

Description:
Front damage

Claim Photo

Our File Number: 277-065561
Adjuster: Scott Syner
Insured: Roberts Environmental Control
Date of Loss: 11/20/2025
Customer File Number: 040238-002065-AD-01
Policy Number:



Photo: 9

Date Taken:
12/16/2025

Taken By:
Gerald Weber

Description:
Passenger side
front



Photo: 10

Date Taken:
12/16/2025

Taken By:
Gerald Weber

Description:
Rear passenger side

Claim Photo

Our File Number: 277-065561
Adjuster: Scott Syner
Insured: Roberts Environmental Control
Date of Loss: 11/20/2025
Customer File Number: 040238-002065-AD-01
Policy Number:



Photo: 11

Date Taken:
12/16/2025

Taken By:
Gerald Weber

Description:
Passenger side



Photo: 12

Date Taken:
12/16/2025

Taken By:
Gerald Weber

Description:
Unknown if
existing damage on
passenger side
behind stack

Claim Photo

Our File Number: 277-065561
Adjuster: Scott Syner
Insured: Roberts Environmental Control
Date of Loss: 11/20/2025
Customer File Number: 040238-002065-AD-01
Policy Number:




Photo: 13

Date Taken:
12/16/2025

Taken By:
Gerald Weber

Description:
Passenger side
damage



Photo: 14

Date Taken:
12/16/2025

Taken By:
Gerald Weber

Description:
Front passenger
side damage

Claim Photo

Our File Number: 277-065561
Adjuster: Scott Syner
Insured: Roberts Environmental Control
Date of Loss: 11/20/2025
Customer File Number: 040238-002065-AD-01
Policy Number:



Photo: 15

Date Taken:
12/16/2025

Taken By:
Gerald Weber

Description:
Front passenger
side damage with
hood up



Photo: 16

Date Taken:
12/16/2025

Taken By:
Gerald Weber

Description:
Passenger side
front damage with
hood up

Claim Photo

Our File Number: 277-065561
Adjuster: Scott Syner
Insured: Roberts Environmental Control
Date of Loss: 11/20/2025
Customer File Number: 040238-002065-AD-01
Policy Number:



Photo: 17

Date Taken:
12/16/2025

Taken By:
Gerald Weber

Description:
Passenger side
front damage



Photo: 18

Date Taken:
12/16/2025

Taken By:
Gerald Weber

Description:
Passenger side
front fender and tire
area

Claim Photo

Our File Number: 277-065561
Adjuster: Scott Syner
Insured: Roberts Environmental Control
Date of Loss: 11/20/2025
Customer File Number: 040238-002065-AD-01
Policy Number:




Photo: 19

Date Taken:
12/16/2025

Taken By:
Gerald Weber

Description:
Passenger side step
area




Photo: 20

Date Taken:
12/16/2025

Taken By:
Gerald Weber

Description:
Front passenger
side fender area

Claim Photo

Our File Number: 277-065561
Adjuster: Scott Syner
Insured: Roberts Environmental Control
Date of Loss: 11/20/2025
Customer File Number: 040238-002065-AD-01
Policy Number:



Photo: 21

Date Taken:
12/16/2025

Taken By:
Gerald Weber

Description:
Front passenger
side tire



Photo: 22

Date Taken:
12/16/2025

Taken By:
Gerald Weber

Description:
Stamp on front
passenger tire

Claim Photo

Our File Number: 277-065561
Adjuster: Scott Syner
Insured: Roberts Environmental Control
Date of Loss: 11/20/2025
Customer File Number: 040238-002065-AD-01
Policy Number:



Photo: 23

Date Taken:
12/16/2025

Taken By:
Gerald Weber

Description:
Drivers side



Photo: 24

Date Taken:
12/16/2025

Taken By:
Gerald Weber

Description:
Drivers side

Claim Photo

Our File Number: 277-065561
Adjuster: Scott Syner
Insured: Roberts Environmental Control
Date of Loss: 11/20/2025
Customer File Number: 040238-002065-AD-01
Policy Number:



Photo: 25

Date Taken:
12/16/2025

Taken By:
Gerald Weber

Description:
Rear drivers side



Photo: 26

Date Taken:
12/16/2025

Taken By:
Gerald Weber

Description:
Drivers side front

Claim Photo

Our File Number: 277-065561
Adjuster: Scott Syner
Insured: Roberts Environmental Control
Date of Loss: 11/20/2025
Customer File Number: 040238-002065-AD-01
Policy Number:



Photo: 27

Date Taken:
12/16/2025

Taken By:
Gerald Weber

Description:
Rear of vehicle



Photo: 28

Date Taken:
12/16/2025

Taken By:
Gerald Weber

Description:
Bottom rear

Claim Photo

Our File Number: 277-065561
Adjuster: Scott Syner
Insured: Roberts Environmental Control
Date of Loss: 11/20/2025
Customer File Number: 040238-002065-AD-01
Policy Number:



Photo: 29

Date Taken:
12/16/2025

Taken By:
Gerald Weber

Description:
Placard inside
engine
compartment



Photo: 30

Date Taken:
12/16/2025

Taken By:
Gerald Weber

Description:
Front passenger
side engine
compartment

Claim Photo

Our File Number: 277-065561
Adjuster: Scott Syner
Insured: Roberts Environmental Control
Date of Loss: 11/20/2025
Customer File Number: 040238-002065-AD-01
Policy Number:




Photo: 31

Date Taken:
12/16/2025

Taken By:
Gerald Weber

Description:
Passenger side
engine
compartment



Photo: 32

Date Taken:
12/16/2025

Taken By:
Gerald Weber

Description:
Front passenger
side engine
compartment

Claim Photo

Our File Number: 277-065561
Adjuster: Scott Syner
Insured: Roberts Environmental Control
Date of Loss: 11/20/2025
Customer File Number: 040238-002065-AD-01
Policy Number:



Photo: 33

Date Taken:
12/16/2025

Taken By:
Gerald Weber

Description:
Drivers side engine
compartment




Photo: 34

Date Taken:
12/16/2025

Taken By:
Gerald Weber

Description:
Drivers side engine
compartment

Claim Photo

Our File Number: 277-065561
Adjuster: Scott Syner
Insured: Roberts Environmental Control
Date of Loss: 11/20/2025
Customer File Number: 040238-002065-AD-01
Policy Number:



Photo: 35

Date Taken:
12/16/2025

Taken By:
Gerald Weber

Description:
Photo of
underneath front
passenger side




Photo: 36

Date Taken:
12/16/2025

Taken By:
Gerald Weber

Description:
Front undercarriage
frame cross
member

Claim Photo

Our File Number: 277-065561
Adjuster: Scott Syner
Insured: Roberts Environmental Control
Date of Loss: 11/20/2025
Customer File Number: 040238-002065-AD-01
Policy Number:



Photo: 37

Date Taken:
12/16/2025

Taken By:
Gerald Weber

Description:
Drivers side front
tire



Photo: 38

Date Taken:
12/16/2025

Taken By:
Gerald Weber

Description:
Drivers side rear
tire

Claim Photo

Our File Number: 277-065561
Adjuster: Scott Syner
Insured: Roberts Environmental Control
Date of Loss: 11/20/2025
Customer File Number: 040238-002065-AD-01
Policy Number:



Photo: 39

Date Taken:
12/16/2025

Taken By:
Gerald Weber

Description:
Passenger side
front tire



Photo: 40

Date Taken:
12/16/2025

Taken By:
Gerald Weber

Description:
Passenger side rear
tire